Log No. 4



Midwest Corporate Aviation.

AIRFRAME MAINTENANCE RECORDS

Registration # N414LA

Serial # 414A-0077



AIRFRAME MAINTENANCE RECORDS

| | | | | | Log No. | 4 |
|------|-----------------------|-----------|-----------------|--------------|---------|----------------|
| | Aircraft Registration | n No | N414LA | _ | | |
| | | | <u>AIRCRAFT</u> | | | |
| Mfg | Cessna | _ Model . | 414A | _ Serial No. | 414A | -0077 |
| | | | ENGINE | | | |
| Mfg. | Continental | _ Model_ | TSI0-520-N | _ Serial No. | 5140 | 8/ |
| Mfg. | Continental | _ Model_ | TST0-520-N | _ Serial No. | 2083 | <u> 29-72N</u> |
| | | | PROPELLER | | | |
| Mfg. | McCauley | _ Model_ | 3AF3AC93-NR | _ Serial No. | 76188 | 8 |
| Mfg. | McCauley | _ Model_ | 3AF3ac93-NR | _ Serial No. | 78863 | 36 |
| Date | Opened <u>2-13-9</u> | 7 | | Date Closed | | |

(All applicable information must be filled in)

MIDWEST CORPORATE AVIATION, INC. P.O. BOX 8067 WICHITA, KS. 67208-0067 (316) 636-9700 Page No_____

DATE

TOTAL TIME IN SERVICE

TACH OR RECORDING METER TIME

DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK



N#<u>414LA</u> Hobbs <u>1721.7</u> Date <u>2-13-97</u> **Airframe Log**

Midwest Corporate Aviation.

Airframe TT: 5277.2

Completed Annual inspection in accordance with FAR Part 43 Appendix D. Inspected Emergency Locator Transmitter as per FAR 91.207 para.(d), checked ok. Installed new ELT battery P/N 00-60-62, due again 2/99. Serviced aircraft battery and checked specific gravity, checked ok. Lubed aircraft in accordance with M/M. Cleaned, inspected and lubed all wheel bearings. Checked all cable tensions in accordance with M/M. Changed Air-conditioner drive hydraulic fluid and filter, serviced with 5606. Installed new Brackett induction air filter elements P/N BA-22 on both engines. Installed new Instrument Air Filter P/N AM103435IA. Removed Elevator Trim Actuator P/N TA-495A S/N 3207 and sent to Bevan-Rabell for repair, see yellow tag, reinstalled same unit after repair. Rigged elevator trim cables and set tensions in accordance with M/M, ops checked ok. Removed Co-pilots Directional Gyro P/N 1U262-001-13 S/N T20103E and sent to Kelley Instruments for repair, see form 8130-3, reinstalled same unit after repair. Removed air-conditioner condenser and sent to Drake Air for repair, see form 8130-3, reinstalled same unit after repair. Evacuated air-conditioner system and serviced with R12 freon, operational and leak checked ok. Serviced oxygen system to 1800 psi. Installed Overhauled LH Alternator P/N ALV9510 S/N A-115378 from Aero Electric, see form 8130-3, operational and leak checked ok. Removed RH engine #6 exhaust riser and welded crack at flange, reinstalled using new gasket and nuts. Repaired RH engine induction airbox by welding crack at alternate air door pivot, reinstalled and ops checked ok. Installed new lower cabin door cable support P/N 5111508-42. Installed stainless steel doubler patch on lower cabin door near aft hinge, using standard practices. Installed new bearing P/N LM29749 and race P/N LM29710 on nose wheel. Retracted landing gear through several cycles operational and leak checked ok. Complied with Cessna MEB91-11 by inspecting nose gear drag brace, no cracks found at this time. Complied with Cessna MEB91-12 by performing landing gear actuator control/indicating functional test, system checked ok at this time. Complied with Cessna ME84-07 R1 by pressure testing and inspecting hydraulic system, found to be serviceable at this time. Complied with Cessna ME84-12 by inspecting Fwd carry-thru spar web, no defects found at this time. Complied with AD 90-02-13 by disassembling LH and RH landing gear struts and installing New Inner bearings P/N 5141109-1, reassembled struts using new packing and serviced with 5606 and nitrogen to proper level. AD 90-02-13 is NO LONGER RECURRING. Complied with AD 96-20-07 at Heater Hobbs: 1528.1 by performing Janitrol Pressure Decay Test and testing combustion air pressure switch, both tested within limits at this time. Complied with AD 85-13-03 by having

All Engine Beams Radiographic Inspection performed by Paragon Aerospace Services in accordance with Cessna S/B MEB 85-3, see Paragon's Inspection Report under Job #W-A010297. Removed kit #SK414-17 from LH Inbd engine beam and stop drilled crack .5" long found by Paragon, and reinstalled same kit #SK-414-17 in accordance with procedures in Cessna S/B MEB 85-3. All cracks found were within limits and were previously stop drilled. All 4 engine beams have Cessna Service Kits #SK414-17 installed.

The Inspection per AD 85-13-03 is Due Again at Airframe Total Time: 6877.2 All ADs were checked through this date, see compliance record and recurring sheets. I certify that this Airframe was inspected in accordance with Annual inspection and was determined to be in an airworthy condition.

Pertinent details of the maintenance are on file at this repair station under W/O 18308.

for Midwest Corporate Aviation CRS BVYR-657C.

| | TOTAL | | |
|------|-----------------------|---------------------------------------|--|
| DATE | TIME IN SERVICE | TACH OR RECORDING METER TIME | DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
| | | | AIRFRAME LOG ENTRY |
| | | | Cessna 414 S/N A0077 N414LA |
| | | | May 11, 1997 Hobbs 1756.5 |
| | | | Removed and replaced air conditioner blower fan |
| | | | P/N 1523296-2, installing a new blower fan (same |
| | | | P/N). Operationally checked with no |
| | | | defectsnoted. Replaced LH & RH foul weather |
| | | | window seals P/N 5111141-3. Details on file |
| | | | under WO# 97-1426. |
| | | | |
| | | | Jan P. Kufy 14P173420170 |
| | | | Southern Aviation Technologies, Inc. |
| | | | Hangar 79, 391 Herndon Avenue |
| | | | Orlando, FL 32803 |
| | | | |
| | | Shop Wor 31 O P R 400 498 | Name: Interior Department k Order Reg.No. Make Model Serial Tach Time Closed 40657 N414LA CESSNA 414A 414A-0077 Description Page 1 OLD MATERIAL STRIPPED FROM SIDEPANELS AND RECOVERED WITH REGALIA PEWTER BY PALLAS TEXTILES. MAINTENANCE RELEASE THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL |
| | | | AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NUMBER. #40657 DATE:5-13-97 SIGNED BY: William C FOR EAGLE AVIATION INC. FAA APPROVED REPAIR STATION #FEHR859D RETAIN AS PART OF YOUR PERMANENT RECORDS |
| | | | WEST COLUMBIA, SC 29170 |
| | | | ** |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | 7777 | 1 | |
| | | | |

| DATE | TOTAL TIME IN SERVICE | TACH OR RECORDING METER TIME | SIGNAT | DESCRIPTION OF MAINTENA TURE & CERTIFICATE NO. OF PI | | |
|------|--------------------------------|---------------------------------------|---|--|---|--|
| | | | CRS#: KG2R951K BEVAN-RABELL, INC. 1880 AIRPORT ROAD WICHITA, KS 67209 1AV. G550A/1-3612F Removed evaluation. Reinstalled fol 456570, F/D, autopilot comp | lowing overhaul reference | WO# 14207 CESSNA S/N: HOBBS: dicator for Mid Continent WO | |
| | | | The aircraft or component is accordance with current reg and is approved for return details of this repair are | dentified above was repair ulations of the Federal Av to service for the work pe on file at this repair sta | iation Administration rformed. Pertinent tion. | |
| F | | | KENI MU | INTYRE THISP. CRS KG2R9531 | | |

Aircraft Log Book Entry By Yingling Aircraft Inc.
P.O. Box 9248, Wichita, KS 67277 FAA CRS BWRR668C
For: N414LA

Installed four new surface deice indicator light bulbs. Installed a new right hydraulic flow light pressure switch. Repaired the wire connection at the right nav. light. Installed a new 5117007-12 hydraulic fluid tank sight tube. Installed a new 5111550-16 cover for the emergency exit door handle. Rigged the inter-cooler door control cables as needed. Installed a new transistor for the left instrument panel lights. Installed a freshly overhauled lift detector, P/N 186-14, S/N 763. Installed eight new static wicks. Installed new nose gear turn limit marks as needed. Serviced the oxygen system. Installed two new pressurization hoses, P/N CM3211-10B38.0 & CM3211-10B9.5.

Yingling Aircraft, Inc. Wichita, Kansas FAA CRS# BWRR668C W.O. 12609

Rec. Hrs. 1922.6 Date 01-05-98

Aircraft Log Book Entry By Yingling Aircraft Inc.
P.O. Box 9248, Wichita, KS 67277 FAA CRS BWRR668C
For: N414LA, 414A-0077

| | | For: N414LA, | 414A-0077 | |
|-----------------|--------|--------------|----------------------|--------|
| Recorded Hours: | 1968.6 | | Aircraft Total Time: | 5524.1 |

The <u>LEFT</u> Altimeter S/N <u>5071</u> was tested to 35,000 feet by Kelley Instruments, Inc. on their W.O. 90659, of 03-11-98.

The <u>Right</u> Altimeter S/N <u>M6938</u> was tested to 35,000 feet by Kelley Instruments, Inc. on their W.O. 90658, of 03-11-98.

The static system, and altitude reporting system was tested and all the above items meet the requirements of FAR 91-411.

The TDR459A Transponder, S/N 4657, was tested and inspected IAW FAR 91.143 & FAR 43 APP. F

Yingling Aircraft, Inc. Wichita, Kansas FAA CRS# BWRR668C W.O. 31259

Rec. Hrs. 1968.6 Date 03-11-98

| TOTAL TIME IN SERVICE TACH OR RECORDING METER TIME | | N OF MAINTENANCE/INSPECTIONS PICATE NO. OF PERSON PERFORMING WORK | | | | | |
|--|--|--|--|--|--|--|--|
| Aircraft Log Book Entry By Yingling Aircraft Inc. P.O. Box 9248, Wichita, KS 67277 FAA CRS BWRR668C For: N414LA, S/N 414A-0077 | | | | | | | |
| Recorded Hours: | : 1968.6 | Aircraft Total Time: 5524.1 | | | | | |
| was hydrostatic to system IAW FAI MEB97-09 by in right wing surface Repaired one brobattery vent tube races and a new P/Ns 9910396-5 new wind lacing limits. Installed at the flap pre-select right engine. Instabilizer, using stabilizer, using streaker, and a new broader to the flap pre-select right engine. | tested by Aero Electric on their W.O. R 91.207(d). Installed two new landing aspection of the flap actuator limit sware deice system. Checked for proper oken wire at the left alternator. Clean a fairing, P/N 5118419-2. Installed a axle tube for the nose wheel. Installed & 9910396-6, using two new S1106-for the NLG doors. Installed a new a new spring for the outside handle out switch. Dressed all propeller blade talled new deice brushes for the right installed an factory optional equipment a new 5918718-1 fairing, a 40-0100-ew wire harness. The installation was deference the Weight & Balance Supplication of the control of the con | FT has been inspected in I Inspection and is presently red for Return to Service Wichita, Kansas | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

| DATE | TOTAL TIME IN SERVICE | TACH OR RECORDING METER TIME | DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK | 9 |
|------|--------------------------------|---|---|--------|
| | | 10000000 | | |
| | | JA (E. | Jackson Air Center, Inc. 110 South Hangar Drive Jackson, MS 39208 CRS JC9R175Y Aircraft Log Book Entry Reg. Number: N414LA Date: 6/8/98 Date: 6/8/98 TTAF: 5531.8 | 077 |
| | | Installed J.P. Instru | nellers with McCauley model 3AF32C515 IAW STC SA8728SW. ments Fuel Flow, EGT, CHT, TIT, OAT & Oil Temp indicating systems IAW STC SA2586NM | & h |
| | | Installed RAM Airc Installed RAM Airc Installed American Replaced cabin inte Replaced battery w | craft Corp. wastegate oil supply strainer and bypass valve IAW STC SA0987SC. craft Corp. vacuum pump cooling shroud IAW STC SA3721SW. craft Corp. revised exhaust systems IAW STC SA4331SW. Aviation intercooler airscoop assembly IAW STC SA4956NM. crcooler flex ducts, PN CM3211-10B9.5, CM3211-10B38.0. ith new Gill G246. Installed rebuilt tachometer and operation check satisfactory. See FAA form 337's this date. |) |
| | | I certify that this ai Work Order # 1995 | Signed Michael Piestt for CRS 198175Y | |
| | | _ | Jackson Air Center, Inc. Aircraft Log Book Entry 110 South Hangar Drive Reg. Number: N414LA Serial Number: 414A Hobbs: 1984.4 | .0077 |
| | | JACKSON AIR CEN | Jackson, MS 39208 Date: 01230 CRS JC9R175Y TSN: 2994.8 TTAF: 5539.9 | 210 |
| | | Ops check Ok Replaced thre check OK Repaired left | engine nacelle inboard access door lower forward corner. | ops |
| | | I certify that t service. For a | this aircraft is airworthy with respect to the work performed and is returned to details, see Work Order # 20120. Signed Michael Pigott for CRS JC9R175Y | |
| | | A | ircraft Log Book Entry By Yingling Aircraft Inc. P.O. Box 9248, Wichita, KS 67277 FAA CRS BWRR668C For: N414LA, S/N 414A-0077 | |
| | Instal | led a new left w | indshield, P/N 9910214-200. Installed a new right windshield, P/N 511160 door for the left inter-cooler. Yingling Aircraft, Inc. YAA CRS# BWRR668C W.O. 13231 | 4-200. |

Recorded Hours 2005.2

Date: 07-15-98

| , . b. | OTAL TIME IN ERVICE | TACH OR RECORDING METER TIME | DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
|--------|------------------------------|---------------------------------------|---|
| | | | COMPLIED WITH A.D. 98-04-28 BY INSERTION OF THE A.D. TEXT IN YINGLING AIRCRAFT, INC. WICHITA, KANS. THE P.O. H. FAA CRS#-BWRR668C_W.O. 13.528 |
| | | | REC. HRS. 2095.C DATE 10-12-98 |
| 71 | | | INSTALLED A NEW SEAT BACK ACTUATOR, P.M. LLITSOD-2 FOR TH |
| | | | No. 5 SEAT. THE DUAL TACH_INDICATOR, P.N. C 668016-0101 |
| | | | S.N. 1919 WAS REPAIRED AT THIS TIME BY AERO-MACH CABS |
| | | | ON THEIR WO. 145382 - ADJUSTED THE RUDDER RIGGING AND |
| | | | THE RUDDER TRIM TAB TRAVEL LIMITS INSTALLED A NEW |
| | | | 5 1167-4-0520 LEFT BRAKE HOSE, SHIMMED THE |
| | | | LEFT & RIGHT ENGINE FORWARD SHOCK MOUNTS . DYNAMIC |
| | | | VINGLING AIRCRAFT, INC. FAA CRS# BWRR668C W.O. 13589 |
| | | | REC. HRS. 2107.0 DATE 11-13-98 |
| | | | RECONNECTED THE O.A.T. HARNESS TO THE INDICATOR INSTALLED |
| | | | A SERVICABLE RIGHT FOUL WEATHER WINDOW INSTALLED A |
| | | | 186-14 LIFT DETECTOR WHICH WAS OVERHAULED BY SAFE |
| | | | FLIGHT INSTRUMENT CORP. ON THEIR W.O. 104868 YINGLING AIRCRAFT, INC. FAA CRS# BWRR668C WO. 13857 |
| | | | REC. HRS. 2116.9 DATE 01-06-99 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Desc...: OXYGEN BOTTLE

AE W/O.: AE-31451

AE S/N: AE-31191

DATE

TOTAL TIME IN SERVICE TACH OR RECORDING METER TIME

DESCRIPTION OF MAINTENANCE/INSCRECE S
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

Aircraft Log Book Entry By Yingling Aircraft Inc.
P.O. Box 9248, Wichita, KS 67277 FAA CRS BWRR668C
For N414LA

Recorded Hours:

2133.7

Aircraft Total Time:

5689.2

Completed an Annual Inspection at this time. Installed a new ELT battery pack which has an expiration date of 01-31-01. Inspected and tested the ELT system IAW FAR 91.207 (d). Checked the aircraft equipment for applicability of A.D. Notes 98-23-07, 98-24-14, 98-25-02, & 98-25-10, and found all n/a to the equipment installed. Complied with the following five recurring Cessna Service Bulletins: MEB85-11 by inspection of the main landing gear forward trunnion supports, MEB91-11 by inspection of the nose landing gear drag brace, MEB91-12 by inspection and testing of the landing gear actuators and the control/indicating systems, MEB95-11 by visual inspection and sealing of the bonded wings, and MEB96-04 by inspection of the seat belt/shoulder harness bushings. Complied with the following three "one time compliance" Cessna Service Bulletins: MEB93-11 by installation of the subject warning placards, MEB95-06 by confirmation that the S/B is n/a to the units installed, and MEB95-10 by installation of the SK421-143 tail bumper reinforcement kit. The oxygen bottle was hydrostatic tested at this time by Aero Electric on their W.O. AE-31451, dated 02-10-99. Installed a new right fuel sump drain valve. Resealed the left main gear actuator as needed. Installed new control cable wires for both heat exchanger flapper doors. Installed a new right brake hose, P/N 350-4-0520. Installed a new tail nav. light bulb and cleaned the socket connections. Resealed the left brake caliper. Installed new fuel filler cap o-rings. Installed a new outboard seat track for the copilots seat. Installed a new forward cable for the lower cabin entry door. Installed a new left main tire and adjusted the right MLG alinement. Installed a new inboard surface deice boot for the right wing.

I certify this AIRCRAFT has been inspected in accordance with an Annual Inspection and is presently Airworthy and Approved for Return to Service Yingling Aircraft, Inc. Wichita, Kansas FAA CRS#-BWRR668C W.O. 13968 & 13969

Rec. Hrs. 2133.7 Date 03-02-99

| 4 | |
|---|---|
| | KLNOOB REPAIR KNOB SHAFT ASTEMBLY |
| | Make CESSNA Ser. No. 414A0077 Model 414A Reg. Mark W414LA The aircraft/component identified above was repaired and inspected in accordance with current Regulations of the Federal Aviation Administration and found airworthy, and |
| | is approved for return to service for the work performed. Pertinent details of the repair are on file at the Agency. Work Order No. 2 |

DESCRIPTION OF MAINTENANCE/INSPECTIONS
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

| WICE | TIME | |
|----------------|--------|---|
| | | Service 2218. Le Service Attalon Co. CRS#AJVR135C******* Make Cessh & Ser. No. Acot Model C-4/4 The aircraft/component identified above was repaired and inspected in accordance with current Regulations of the Federal Aviation Administration and found airworthy, and is approved for return to service for the work performed. Pertinent details of the repair are on file at the agency. Work Order No.5-2713 Date 4-20-99 Signed Signed Society Inspector for MUNCIE AVIATION CO CRS#AJVR135C MUNCIE, IN 47308 765-289-7141 |
| 6-V-99 5783N | 2227,6 | L' CONFER AUDICAL, REPAIR CONTERNATE, Britand L' Carlf Atfall 294, NEW EMAJE AIR, CYNTHIANA, KY. W.O. # 1378 — E-d |
| 7-10-98 5900,2 | 2344.7 | OPENED INSPORMELS, LUBED RODE-DS AND CONTROLS, CHEUKED BATTERY, BRAKES, T.RES, LUBED GEAR. CHECKED LIGHTS, BLED BRAKES, SERVICED HYDISYSTEM. ELE AWED OUT Flow VALUE, REPAIRED PARELOW C.D. |
| | | REPAIRED PANEL ON COFFEE CHEST, CHECKED ELLT, PER FAR 91.201-095 V O.K. PERFORMED GEAR RETRALTION AND EXTENSION OCK O.K. ELOSED AIRCRAFT. -AIRCRAFT TELRTIFY THAT THIS, IT AS BEEN INSPECTED T/A/W |
| 1 | | A-160 HR INSPECTION AND WAS FOUND TO BE IN A: 2worthy Condition Britain & lawfor. A+82166394, New almage Air, Cyuthiana, Ky. W.O. # 1353 — E-d — |
| 1 | | |

WEST KENTUCKY AIRMO

162 Airport Road P.O. Box 985 Madison ville, KY 42431 Phone (270) 821-3453

950

C/W MEB98-28, upper trunion insp, by inspection, no defects noted. Replaced de-ice timer with new, pn 99102-1, sn 4285. Engine beam inspection due at 6800 hrs. Saftied LH uplock bolts Replaced battery vent tube with new fairing, pn 5118419-2.
Replaced nutplates behind nose wheel.
Repaired panel by rudder pedals by installing new nut plates.
Installed engine baffling clips by slip joints.

The aircraft or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent W.O. No. 2152

Dated 2-1-0

West Kentucky Airmotive.

Madiscaville, KY. 42431

CRS. 107R0070

| Sept. 19, 2001 | 2638,5 Disassemble R. landing light, clean and Adjust limit switches + reinstall. Lube wastegate on |
|----------------|---|
| | With O.H. unit P/N 24343LAD from Aircraft Accessories of Oklahoma Inc. Test ran Right engine to check for |
| | leaks. Cleaned Interior Carpet, Vacuumed + wiped off Seats. |
| | AP 209524552 |

AIRCRAFT CESSNA Model #414A N414LA S/N # 414A0077 TOTAL TIME hrs. 2649.6 MAINTENANCE RELEASE

- 1. INCOMING INSPECTION: REMOVE ALL Seats, Cabinets and existing carpet from main body, storage area, cock pit, and entrance stair.
- 2. Replace all carpet with Tapis #631 INSPERATION to meet FAR 25.85 Burn certificate on file.
- 3. Replace cabinets and seats per 414 Service manual section 3, Air Frame page 3-10P through 3-18

MAINTENANCE RELEASE

THE AIRCRAFT, AIRFRAME OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY. DATE10-11-01 SIGNED

LEGENDS AIKEN MUNICIPAL AIRPORT

Bruce MacGregor AP 376709935

10 FORWARD COURT **AIKEN, SC 29805** Page 1 of 1

| 1 | IN | METER TIME | DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
|----------|-------------------|---------------|--|
| 12-35 | SERVICE 35 6079.h | | REPLACED RIGHT FUEL BOOST RUMP 8/2 |
| | 70077.0 | | 287-29, 5/2 4ADGI FROM AIRCRAFT ACCESSORIES |
| | | | LEAK + DPS CHECK O.K. Bichon C. Carly |
| | | | AAP 2166294, Eynthiam, Ry New Durage Air, |
| | | | W.O. # 1390 - End - |
| | | | |
| 12-12-99 | 1082.7 | 2527.2 | OPENED INSPECTION PANELS, LUBER Rod Ends And |
| | | | CONTROLS, CHELKED BATTERY, BRAKES + FLUID LIGHTS |
| | | | INSTALLED NEW RIA MAINTIRE, ROTATES 44 |
| | | | MAIN TIRE, REPACKED WHEEL BEARINGS. REPLACED |
| | | | TAIL LIGHT BULB, REPPIRED TAXILIGHT WIRE AT |
| | 7. | - | NOSE STRUT. REPAIRED SEAT ARM RESTS AS |
| | | | NEEDED, Add 2 SEAT BACK RELEASES. E/w 96-20-07 |
| 2.66 | | / | HEATER DELAY TEST-CH OK, EHECKED E.L.T. PER |
| 5.0 | -2 (2) | / | AR91207-EK O.K. SERVEED HYD. RES, WITH MIL |
| | 11 153 | 18 | 5606 Philo PERFORMED GEAR RETRACTION AND |
| | 10/ | 6 | EXTENSION-CK OK. LUBED GEAR, ELOSED PANELS. |
| - 60/ | | | I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSAECHED |
| O IRT | 44 | 7 | I/A/W Ar AnnoAl InspicTion Ard was Found To |
| | 797 | 1 | HP2166294IA. NEW IMAGE Air, Cynthiona, |
| | Sin 5 | / | H82166294IA. NEW IMAGE Air, Cynthiana, |
| 94 | 1 10 | / | ly. W.O. # 1392 - End |
| 100 | | | |
| | | | |
| | | | |

MING WORK

Log Book Insert

Date 3/30/00 Cessna Make 414A 21442 Model W.O. _ 0077 ACTT. 6100 S/N Reg. No N414LA

LDGS.

STEVENS AVIATION

(606) 255-1902 (606) 259-9323 FAX

Serviced L/H Main Gear Strut as required IAW 414 Maindenance Manual

The aircraft, airframe, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to servine. Pertinent details of the repair age on file at this repair station under

STEVENS AVIATION Blue Grass Airport, 4029 Versailles Rd., Suite 300 Lexington, Kentucky 40510

| | | 33 | COMPLIEDWITH B.O.95-09-13 FUELINLET FLOAT VALUES, NEX DUE 67451 |
|------|--------------|--------|---|
| 4-19 | 6145,2 90 | 2527.2 | BEPLACE'd FRONT BEACON BULB, REPPIRED |
| | | 4119 | BROKEN WIRE ON RIAN LIGHT. AIRED LIH |
| | | | MAIN STRUT. REPAIRED BROKEN WIRE |
| | | | on TAXI LIGHT AT STRUT. AdjustEd Hyd |
| | 2 | | BELEASE ON RIGHT REAR SEAT BACK. INSTALL |
| | | | BOTTOM REAR COVER ON PILOTS SEAT |
| | | | Birhard C. Carlfo. AHP 2166294, Carls |
| | | | Air Leavice, Cynthiana, Ry. W.O. # 1409 |
| | | | End- |
| | | | |
| W | THE STATE OF | | |

| DATE | TOTAL TIME IN SERVICE | TACH OR RECORDING METER TIME | DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
|--------|--------------------------------|---------------------------------------|---|
| | | | I certify that the altimeter, encoder, and static system tests required by FAR 91.411 have been performed and meet specifications. Pilot Altimeter tested to 35,000 ft. Co-Pilot Altimeter tested to 35,000 ft. Encoder #1 Lessed to 35,000 ft. Encoder #2 tested to 35,000 ft. Encoder #2 tested to 35,000 ft. System test date 5-4-00 ft. System test date 5-4-00 ft. Cert.# 2541955 Fo Avionics Authority, Inc. C.R.S. # UTYRO15L Lexington, KY 40510 I certify that the ATC Transponder test required by FAR 91.413 was performed this date and found to comply with FAR 43, Appendix F. #1 Make Model K7-76A S/N 1/7285 #2 Make Model K7-76A S/N 1/7230 |
| | 1. | | #2 Make King Model KT-76 A S/N 1/7230 Test Date Self- Tested by For Wionics Authority, Inc. C.R.S. # UTYRO15L Lexington, KY 40510 |
| Hobbas | 2613,7 | | |
| 11 | 6169,2 | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

WEST KENTUCKY AIRMOTIVE

Madisonville, KY 42431 Phone (270) 821-3453 162 Airport Road P.O. Box 985

Date: 2/1/2001 Aircraft: N414LA Type: CESSNA 414A S/N: 414A0077 Hobbs: 2613.7, Tach Time: , Total Time: 6169.2 TSIO-520-NB S/N: 521235 LE Time: 637.4 TSIO-520-NB S/N: 521248 RE Time: 637.4

C/W annual inspection I/A/W maint manual.PERFORMED COMPRESSION CHECK, Li engine results: #1 79/80, #2 72/80, #3 79/80, #4 79/80, #5 79/80, #6 79/80. RH engine results: #1 79/80, #2 79/80, #3 77/80, #4 79/80, #5 79/80, #6 79/80. Drained oil, changed filter, and serviced with Aeroshell 80W.

APPOSNETT 80W.

Removed exhaust system for OH and reinstalled after OH. SEE yello, Tay 5

C/W SB89-02 torque links, by inspection, no cracks noted.

C/W SB85-11R4, main geart upper trunion, by inspection, found to be

servicable, no cracks noted. C/W AD96-20-07 heater , by performed heater PDT test, tested good,

adjusted fuel switch.

C/W ME899-19, vacuum system, by replacing manifold.

C/W ME899-18 by inspection and replaced 2 exhaust springs on each

engine with new. Bled brakes and serviced reservoir.

Soldered wire to de-ice valve on LH engine.
Replaced LH main tire with new Goodyear tire, cleaned and regreased

wheel bearings and reinstalled.
Installed new lower cabin door frame.

Installed placard at beacon switch.

Installed new spark plugs, RHB32E. Removed trim actuators, sent for OH and reinstalled.

Tightened LH alt mounting nuts.
Removed corroded rib and replaced with new. Rebonded upper skin. Removed patch from wing at RH gear door, cleaned corrosion, bonded area and reinstalled patch.
Removed clock, sent for repair and reinstalled.
Cleaned corrosion from O2 line and primed.

Greased cable seals.

Adjusted door latches I/A/W service manual.

Cleaned cabin outflow valve. Tightened heater duct clamps in nose.

Cleaned middle belly drain. Sealed belly blade antenna doubler.

Replaced pressurization cat tubes with new.

Drilled out stripped screws on inspection panels.

Moved LH engine hydro line and installed chafe guard.

Checked and adjusted landing gear alignment I/A/W service manual.

Installed new post light lamps.

Removed LH wing panels, resealed and reinstalled.
Removed N2 bottle, sent for hydro test and reinstalled.

C/W 500hr mag inspection. Replaced points, condensers, and distributor block. This service mexical in 300 hrs. AP Installed new air filters, due replacement in 300 hrs. AP

Replaced central vacuum filter with new.

Installed new mag filters from RAM.

C/W ME92-33, lower cabin door extender mod by installing the

modifications.

Removed bird nest from tail.

Installed new nose wheel turn limits placard. Removed heater combustion blower motor, sent for OH and reinstalled. Removed heater combustion blower motor, sent for OH and reinstalled Replaced nose wheel well wiring grommet.
Cleaned nose compartment.
Repositioned 02 line in RH nose.
Replaced nose tire with new. Replaced nose wheel bearings with new,

greased bearings, balanced assy and reinstalled.
Touched up verticle fin de-ice boot with conductive cement.
Added hydraulic fluid to air cond system.

eaner air cond evaporator coils. Installed placards on rear facing seats and prop sync.

Safety was installed 18 degrees off. Reinstalled RH fuel selector off

safety correctly.

Safety correctly.


Installed new ELT battery and servicable ELT, D&M ELT6, sn 25455. Ops cikd ok I/A/W 91.207D. Due 11-02.

20-96-480B

| | | | Page No. |
|---------------|--------------------------------|---------------------------------------|--|
| DATE | TOTAL TIME IN SERVICE | TACH OR RECORDING METER TIME | DESCRIPTION OF MAINTENANCE INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
| 12 Feb 02 | 6267.9 | 2712.4 | ANNUAL INSPECTION CONFITTEN I/A/W 414 SERVICE MANUAL |
| Aus (| HECKI | IST, C | TW EXHAUST SYSTEM A.D. 2000-02-16 PARTS(b/d)(e), |
| | | | BATTERY INSPECTED ALL ACCESSABLE CABLES + PULLEYS, LUBEN |
| | | | TESTED RED FAR 91.207(1), CHECKED GOOD, WHEEL BEARINGS |
| | | | BRAKES, ROTATED RIGHT MAIN TIRE, REPLACED INDUCTION |
| | | | DING GEAR SYSTEM INSPECTED LUBED + RETRACTION TESTED, |
| | | | TANK, ALL AD'S COMPLIED WITH THEY BI-WESKLY 02-01 (SOE |
| ASTIN | GIN AIR | KRAFT | RECORDS). 1 contry that the AIRFRAME has |
| | 1000 | | an ANNVAL Inspection and was determined to be in Anglucotty |
| | | | - Co 0 |
| | | 0000 | ACD250140715IA FMF0 |
| MARI 2002 | | 2482 | |
| AUTI | PILOT | CENT | PAL FOR REPAIR (SEE TAGS), REINSTALLED UNITS + |
| | 5 3 3 3 3 3 3 | કક્લ | |
| | | 1 | 9 100 |
| 2002 MAR27 | | 2756 | CW AD 2000-01-16 BART (b) RYVISUAL |
| INS | PECTU | n. | 100 A KOOK 1A ZAGO6374 |
| | | | 0 1 3 |
| 2002 | | | |
| MA-130 | | 2900, | |
| SER | NOD | ACS | HSTEM. JORIAZIO6541 |
| | | | |
| | | | |
| | | | |

| | TIME IN SERVICE | TACH OR RECORDING METER TIME | DESCRIPTION OF MAINTENANCE/INSPECTIONS SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK |
|-----------|-----------------------|---------------------------------------|--|
| 1/20/2002 | 6379.9 | 2824.9 | removed 100 1010 Computer |
| | 1981 L | | and Sent For Fepair. Received |
| | | | and re-installed. Checked operation |
| | | | CKIA OK ALAROG370 |
| | | | (#241065+U |
| 2002 | 0-30 | 2826.5 | REPLACED BOTH MAIN TIRES WITH NEW GODYEAR |
| FULL | et cus | Tom Ti | |
| ~ . | | | |
| 290W02 | | | (IN Roboust AD 2000-01-16 by |
| | - | | utoval inspection, |
| | | | Lat O Selvet |
| ? | | | 1002504071524 |
| 6 | | | |
| | | | 3 /A THE A SHEET STATE OF THE S |
| | | | |
| | | | |
| | | | |
| 1 | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| | 1.11 | | Page No. |
|------|----------------------------|--|------------------------------|
| DATE | TOTA TIM IN SERVI | I certify the ATC transponder tests and inspections required by FAR 91.413 were performed this date and found to comply with | SPECTIONS PERFORMING WORK |
| | | FAR 43, Appendix F Make King Model KT 76-4s/N 117230 Work Order No. 2023 Work Order No. 2023 | |
| | | Aircraft Maint. Services, Inc. FAA cert. Repair Station number F07R634N Signature | |
| | | Signature Date 1/20/2002 | 7 |
| | | #1 | |
| | | I certify the ATC transponder tests and inspections required by FAR 91.413 were performed this date and found to comply with FAR 43, Appendix F | |
| | | Work Order No. 2083 Aircraft Maint. Services, Inc. FAA cert. Repair Station number | |
| | | Signature 2, 2002 | |
| | | | |
| | | I certify that the pitot-static system on this aircraft has been checked and has been found to be satisfactory in accordance with FAR part 43. N# 41444 A/C Make Cessna A/C Model C-414 | |
| | | N# 414L# A/C Make CD Serial No. 414A - 0077 Work Order# 2023 Aircraft Maint. Serv. FAA Cert. Repair St. #F07R634N Signature Date 7/30/2002 | |
| | | Pilots | |
| | | The following altimeter was installed: Make ARC Model: PN 425 40 50 507 1 This altimeter was by Repair tested to FAR 43, Appendix E on 7 30 300 by Repair tested to FAR 43, Appendix E on 7 30 000 feet. I certify Station# FO 7RG34 N to 30 000 feet. I certify the altimeter and altitude reporting system tests required by FAR the altimeter and altitude reporting system was | |
| | | the altimeter and altitude reporting system tests required 91.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system tests required as 1.411 have been performed. The altitude reporting system tests required as 1.411 have been performed. The altitude reporting system tests required as 1.411 have been performed. The altitude reporting system tests required as 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed. The altitude reporting system was 1.411 have been performed by 1.411 have been performed. The altitude reporting system was 1.411 have been performed by 1. | |
| | | The following altimeter was installed: Make Cessa a Model: 5734P4-1 S/N M-6966 This altimeter was tested to FAR 43 Appendix E on 7/70/2002 by Repair | |
| | | the altimeter and altitude reporting system tests required by FAR 91.411 have been performed. The altitude reporting system was | |
| | | Aircraft Maintenance Services, Inc. Repair Station #F07R634N Signature Date 7 50 2002 | |



Page No. TOTAL TACH OR RECORDING TIME DATE METER IN SERVICE

Suburban Aviation, Inc.

4383 Section Road Ottawa Lake MI 49267 (734)856-6103 www.suburbanaviation.com

Work Order: 08054

SHOP Department:

Sold To: Rimach Inc. 326 Patillo Rd.

Tecumseh, ON N8N 2L9 CANADA

General Comments:

ual Inspection was completed on 4/22/2004

| Aircraft N | Number | N414LA | Slee Links | Type:C | ESSNA 4 | 114A | S/N: 414A0077 | |
|------------|-------------------|-------------|------------------------|------------|-----------------|------------------------|------------------------|--------------------|
| | | Total Time: | 6,617.1 | Hobbs Time | Time: Cycles | 197.1 Prop Type | Tach Time: Prop S/N | 0.0 Prop Time |
| | ype SIO-520-NB | 521235 | - | 3,972.1 | Ojoico | 3AF32C515 3AF32C515 | 980261 980308 | 1,085.4 1,085.4 |
| 2 TS | SIO-520-NB | 521248 | NAME OF TAXABLE PARTY. | 3,972.1 | WEST VALUE | SAFSZCOTO | | |

Problem:

Completed the Annual Inspection IAW the service manual and check list. AD's week checked per Adlog system. Elt inspections per FAR 91.207(d), battery is due 3/31/2005. Checked the lights and serviced the battery. Serviced the wheel bearings and cleaned the brakes. Checked the controls and lubed. Cleaned the aircraft. Completed the retraction tests and checked the hydraulic filters. Replaced both main tires. Replaced the vacuum regulator filters. Replaced the fwd curtain track mounting rod. Replaced the fwd beacon lamp.

Dressed the propellers and tested the de-ice heaters.

Right Engine:
Completed the engine oil and filter change, filter cut and wear check sent in. Serviced with Phillips 20/50 XC oil. Cleaned the engine down. Completed the Exhaust system inspections and pressure test per AD2000-16-01 parts b.c.d. and e. Compressions were 1-79, 2-79, 3-78, 4-79, 5-79, 6-78/80. Serviced the spark plugs and replaced 2 plugs. Magnetos were at 21 degrees. Replaced the air filter per AD84-26-02. Serviced the fuel screens and nozzles. Leak tested the fluid hoses and lines.

Left Engine:
Completed the engine oil and filter change, filter cut and wear check sent in. Serviced with Phillips 20/50 XC oil. Cleaned the engine down. Completed the Exhaust system inspections and pressure test per AD2000-16-01 parts b.c.c and e. Replaced the tail pipe support clamp. Compressions were 1-72, 2-71, 3-78, 4-78, 5-79, 6-75/80. Serviced the spark plugs, magnetos were at 21 degrees. Replaced the air filter per AD84-26-02. Serviced the fuel screens and nozzles.

LOG ENTRY

N414LA SN: 414A0077 AUGUST 5, 2004

DURING ALTIMETER FOUND PILOT'S ALTIMETER HAD A BAD BARO AND COPILOT'S ALTIMETER HAD A LEAKY BARO KNOB, SUBURBAN AVIATION ORDERED AND INSTALLED NEW ALTIMETERS. FOUND BOTH TRANSPONDERS HAD FREQUENCY PROBLEMS. REMOVED #1 AND #2 TRANSPONDERS TO BENCH FOR ADJUSTMENT. ADJUSTED BOTH UNITS AND REINSTALLED IN AIRCRAFT. PERFORMED PITOT/STATIC LEAK TEST. ALTIMETER CERTIFICATION ON PILOT'S ALTIMETER PN:42540-6128 SN:3104 PERFORMED BY MIDCONTINENT INSTRUMENTS ON 8/10/04 AND CERTIFICATION ON COPILOT'S ALTIMETER PN:UNK SN:3D178 PERFORMED BY METRO AIRCRAFT INSTRUMENTS ON 8/4/04. PERFORMED INTEGRATED SYSTEMS TEST 30,000 FT AS REQUIRED BY F.A.R. 91,411 IN ACCORDANCE WITH F.A.R. 43, APPENDIX (a) AND (c). PERFORMED ATC TRANSPONDER TEST AND INSPECTIONS ON PILOT'S TRANSPONDER KING MODEL KT76A SN:117285 AND COPILOT'S TRANSPONDER KING MODEL KT76A SN:117230 AS REQUIRED BY F.A.R. 91.413 IN ACCORDANCE WITH F.A.R 43, APPENDIX F.

WO# 10160

SIGN

EXPRESS AVIONICS, INC. 11431 W. AIRPORT SVC RD. SWANTON, OH 43558 FAA CRS# XXER854K

| DATE | TOTAL TIME IN SERVICE | TACH OR RECORDING METER TIME | 4. C | 7 PN: 340600-1 809597SN/LOT: N/A DE | AUDITED STESSING AIRCRAFT Company ORGANICASING PARTS DISTRIBUTION Dept. 702 5800 E Pawnee, Wichita, KS 67218 In Item Organicasing Parts Distribution Dept. 702 5800 E Pawnee, Wichita, KS 67218 Item Organicasing Parts Distribution Dept. 702 5800 E Pawnee, Wichita, KS 67218 Item Organicasing Parts Distribution Dept. 702 Item Organicasing Parts Distribution Dept. 702 5800 E Pawnee, Wichita, KS 67218 Item Organicasing Parts Distribution Dept. 702 Organicasing Parts Distribution Dept. 702 | er regulation specified in block in Block 13, the work identified in Block 13, the work identified in 4.3 and in respect to that work, i.e. 21. Approval/Certificate 23. Date (m/d/y): component/assembly. | AL. In block adentified darke we that woo |
|------|--------------------------------|---------------------------------------|------------------------|--|---|---|---|
| | | | | - | - INCTRIME | NSN: 0052-00-012-90 to: 1 | 9. 🖸 |
| 1 | , | | | | LOG ENTRY | | 1 |
| | | 114A0077 | PITOT/ST/ F.A.R. 91 | TIC L | LOG ENTRY | MBER 1, 2004 FT AS | 1 |

1 Form Track


THE SPRINGE

| DATE | TOTAL TIME IN SERVICE | TACH OR RECORDING METER TIME | Suburban Aviation, Inc 4383 Section Road Ottawa Lake MI 49267 (734)856-6103 www.suburbanaviation.com Work Order: 08397 Opened: 10/13/2004 |
|------|--------------------------------|---------------------------------------|--|
| | | | Work Order: 08397 Opened: 10/13/2004 Department: SHOP Closed: 10/20/2004 |
| | | | Sold To: Rimach Inc. 326 Patillo Rd. Tecumseh, ON N8N 2L9 CANADA |
| | | | |
| | | | Aircraft Number: N414LA Type:CESSNA 414A S/N: 414A0077 Total Time: 6,879.9 Hobbs Time: 459.9 Tach Time: 0.0 |
| | | | Eng# Type S/N Time Cycles Prop Type Prop S/N Prop Time 1 TSIO-520-NB 521235 4,234.9 3AF32C515 980261 1,346 2 TSIO-520-NB 521248 4,234.9 3AF32C515 980308 1,346 Discrepancy: 1 Problem: |
| | | | 10/20/2004 1. Right wing De-Ice boots not inflating fully, trouble shot a and found both laft and right engine check valves shot, also right flow valve is frozen. Replaced the flow valve with a overhauled part S/N: BS0403 and 2 new check valves. Teste the system. 2. Bight engine A/C Hydraulic numb is leaving and was englaced with a new 24141 AP was with |
| | | | 2. Right engine A/C Hydraulic pump is leaking and was replaced with a new 2634LAD pump with new gaskets. Service the system with Hydraulic fluid. 3. Replaced both main tires with new and serviced the wheel bearings. 4. Right brake linings were worn and were replaced with new. 5. Cleaned the botton of the aircraft. |
| | | | 6. Replaced the beacon lamp and lubed the motor. 7. Replaced the tail nav lamp. 8. Repaired the right nav light wires and tested. Brian J. Eklund IA370744080 |
| | | | |
| 3 | | | Suburban Aviation, Inc 4383 Section Road Ottawa Lake MI 49267 (734)856-6103 www.suburbanaviation.com |
| | | | Work Order: 08429 O |
| | | | Sold To: Rimach Inc. 326 Patillo Rd. Tecumseh, ON N8N 2L9 CANADA |
| | | | |
| | | | Aircraft Number: N414LA Type:CESSNA 414A S/N: 414A0077 Total Time: 6,893.0 Hobbs Time: 473.0 Tach Time: S/N Time Cycles Prop Type Prop S/N |
| | | | Eng# Type S/N Time Cycles Prop Type Prop S/N 1 TSIO-520-NB 521235 4,248.0 3AF32C515 980368 2 TSIO-520-NB 521248 4,248.0 3AF32C515 980308 • Aircraft Comments: |
| | | | TSMOH:1360.8 both engines Discrepancy: 3 Problem: |
| | | | 11/01/2004 Completed the fuel float valve inspections and tests iaw AD95-09-13 and Cessna Service Bulletin, Res and leak checked. Next Due at Hobbs: 1078.00. Replaced the pilot side Altimeter 42540-6128 with fre S/N:8878 that was Certified to 35000 ff on 10/29/2004. Express Avionics's retested the system and fou sump bottle leaks, replaced the bottle and system tested good for them. Express Avionics with supply Warranty only covers part and labor to remove and install. Outside labor is for system recertification. |
| | | | Sump bottle leaks, replaced the bottle and system tested good for them. Express which warranty only covers part and labor to remove and install. Outside labor is for system recertification. Brian J. Eklund IA370744080 |
| | | | The state of the s |
| 1 | Total Control | | * |
| | 757 | | |

burban Aviation, Inc 83 Section Road Ottawa Lake MI 49267 (734)856-6103 www.suburbanaviation.com Work Order: 08467 Opened: 11/19/2004 Closed: 11/23/2004 Department: SHOP Sold To: Rimach Inc. 326 Patillo Rd. Tecumseh, ON N8N 2L9 CANADA Aircraft Number: N414LA Type:CESSNA 414A S/N: 414A0077 Total Time: 6,902.0 Hobbs Time: 482.0 Tach Time: 0.0 Eng# Type S/N Time Cycles Prop Type Prop S/N 1 TSIO-520-NB 2 TSIO-520-NB **Prop Time** 521235 3AF32C515 3AF32C515 980261 521248 4.257.0 1,370.3 Discrepancy: 1 980308 1,370.3 Problem: 11/23/2004 Cabin Heater Hobbs: 1993.9 11/23/2004

Cabin Heater Hobbs: 1993.9

Trouble shot the cabin heater not firing, found the fuel pump pressure low, the nozzle fouled, and the spark plug worn down. Removed the heater 84050 P/N:02E17-1 S/N:4781219 from aircraft. Replaced the fuel pump AHE05D92 with a new pump S/N:1109041. Opened the heater and cleaned out the combustion tube. Replaced the fuel nozzle with a new AHE-D nozzle S/N: 021403. Replaced the spark plug with a new AHE39D18 S/N:092204 and adjusted the ground electrode. Completed the pressure decay tests and tested the air switch per AD2004-21-05. Due next at hobbs: 2093.9 or 11/23/2006 which ever is first. Reinstalled heater in aircraft and ground test fired heater and cycled 6 times. Completed the close up of access panels. Brian J. Eklund IA370744080 Suburban Aviation, Inc 4383 Section Road Ottawa Lake MI 49267 (734)856-6103 www.suburbanaviation.com Work Order: 08571 Charter and the Department: SHOP Sold To: Rimach Inc. 326 Patillo Rd. Tecumseh, ON N8N 2L9 CANADA Aircraft Number: N414LA Type:CESSNA 414A S/N: 414A0077 Total Time: 6,972.0 Hobbs Time: 552.0 Tach Time: Eng# Type 1 TSIO-520-NB 2 TSIO-520-NB S/N Time Cycles Prop Type Prop S/N Prop Time 521235 4.327.0 521248 4,327.0 3AF32C515 980308 1.440.3 Discrepancy: 1 Engines TSMOH: 1494. 8. Problem: Jacked aircraft to check hydraulic fluid leak, retracted and found the left gear up-lock cylinder leaking, removed cylinder and replaced all seals, and O'rings. Bench tested and reinstalled. Completed 6 retraction cycles and found no leaks. Replaced all 16 brake linings. Serviced the tires with an Cleanad the bottom of both wings and flap bays. Brian J. Eklund IA370744080 Jace Book # 5



P.O. Box 8067 Wichita, KS 67208
The Business Air Center • Col. James Jabara Airport