

Accident No. 1225,9-43

Date 5/25/43

Checked by /

Analyzed by /

Copied for Wright
Filed by /

Ats /

1225,9-43

DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility, and recommendations for action to prevent repetition)

Capt. Lester C. Taylor, Jr., 369th Fighter Squadron, while making a wheel landing hit a soft spot in the field causing the aircraft to nose up slightly. The condition of the field which he practically unscathed because of constant use was poor because of rain. The nosing up of the aircraft caused him to damage two blades of the propeller on his plane. Investigation of the brakes on the plane showed that they had not been used excessively obviating the possibility that they had locked prior to his landing.

FINDINGS:

1. Pilot error. Poor technique exhibited in making wheel landing.
2. Field conditions.

RECOMMENDATIONS:

Pilots should not make wheel landings.

NOTE:

15 July 1944 - 5 day extension granted by Capt. Schlimmeyer, Asst. A-3,
67th Fighter Wing.

NOTE:

21 July 1944 - 5 day extension granted by Capt. Schlimmeyer, Asst. A-3,
67th Fighter Wing.

AP:MSA
CL:MSI
CP:MSI
DD:MSI

Signature *Channing D. Irvine*
CHANNING D. IRVINE, Major, USA

Signature *John T. Peck*
JOHN T. PECK, Capt. AC, R.A.

24 July 1944

卷之三

1000

—
—
—

TOGETHER AGAIN *SECRETARIAT*

Waa. Waa.

3. 電子商務（二）：零售、供應鏈管理、電子商務與資訊

160th Reunion

SOCIOLOGY AND TYPE

卷之三

卷之三

FLIGHT REPORT - OPERATIONS

第十一章 资本主义的经济危机与政治危机 11

CHECKED:
LEGIBLE AND
CORRECT

**TRANSCRIBED
TOTAL FLIGHT
TIME ENTERED
ON FORM 1A**

**TOTAL
FLIGHT
TIME**

10

WAR DEPARTMENT
ARMED FORCES
HEADQUARTERS

FLIGHT REPORT - ENGINEERING

RESTRICTED

INSPECTION STATUS		
DATE OF LAST FLIGHT HOURS DUE	INSPECTED TODAY	
	BY	STATION
PRE FLIGHTS		
ORIGIN	9/7/44	X
24 HOURS	21:15	
48 HOURS	20:00	E-133
100 HOURS	202100	
Latitude	26:15	
Longitude	111:15	

SERVICE	FUEL (GALLONS)		OIL (QUARTS)				RADIATOR CHECKED
	SERV- ICED	IN TANKS	NO. 1	NO. 2	NO. 3	NO. 4	
1ST		50	52				
2ND	200	200	-	52			
3RD							
4TH							
5TH							

INSPECTION OF AUXILIARY EQUIPMENT			
EQUIPMENT	SYMBOL	INSPECTED BY	STATION
AIRCRAFT ARMAMENT			
COMMUNICATIONS	J	Johnson	
PHOTOGRAPHIC			
NAVIGATION			
Oxygen	P	Garrison	E-133
	V	Hair	
		Wade	

STATUS TODAY	EXPLANATION:			
	1.	2.	3.	4.

REMARKS PILOTS AND MECHANICS - SEE INSTRUCTIONS INSIDE FRONT COVER

#1 Prop damaged on landing L.G. TAYLOR

DISMISSED ON 9/7/44

Robert C. Garrison
Major G. TAYLOR,
1st Lt, AFM Corp,
2nd Lt. Operations Officer.

New prop installed (Spart) 9/7/44

AIRCRAFT AND ENGINE TIME RECORD
(ENTER IN HOURS AND MINUTES)

ENGINE	NO. 1	NO. 2	NO. 3	NO. 4
	HOURS TO DATE	310:25		
	HOURS TODAY	310:25		
	TOTAL	310:25		
	OIL CHANGE DUE	10:00		
	COLD CLEANING DUE	10:00		
	HOURS TO DATE	26:25		
AIRCRAFT	HOURS TODAY	310:25		
	TOTAL	310:25		

ENGINE DATA		AIRCRAFT DATA		AIRCRAFT ONGOING DATA	
TYPE	12 CYL. AIR COOLED	TYPE	12 CYL. AIR COOLED	TYPE	12 CYL. AIR COOLED
MANUFACTURER	DETROIT	MANUFACTURER	DETROIT	MANUFACTURER	DETROIT
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2,000 cu. in.
NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12	NUMBER OF CYLINDERS	12
DISPLACEMENT	2,000 cu. in.	DISPLACEMENT	2		

~~RESTRICTED~~

9 July 1944.

C E R T I F I C A T E

I, Lester G. Taylor, Jr. Captain, Air Corps, ASN 0-25618, do certify that on 9 July 1944 at 1510, did damage aircraft P51 D-5 serial number 44-13689.

At about 1510 o'clock I landed at the completion of an Operational mission. My approach and landing were both normal until my wheels hit the ground. As soon as I felt them touch, the aircraft started to nose up. It felt as though either the brakes were locked or the wheels had hit in a hole on the field. I was not holding brakes. I know that the aircraft was not rolling before it started to nose up. I recovered using full throttle with stick back and could feel the aircraft give suddenly as though it had broken loose. I went back into the air again and resettled into a normal landing. Two blades of the prop had barely touched the ground and nicked the ends but it did not bend them. It was raining at the time of landing. Visibility was very poor, though this had no effect on the accident.

Lester G. Taylor, Jr.
LESTER G. TAYLOR JR.
Captain, Air Corps,
Pilot.

~~RESTRICTED~~

Report #2

RESTRICTED

9 July 1944.

12411141

On 9 July 1944 at approximately 1510, Captain Taylor was landing his plane from an operational mission. As he landed the aircraft seemed to nose up as if it had struck hard. At the same time the aircraft began to settle down as if it had struck soft ground. The pilot of the plane thought the ground to be normal position. The vibration of the plane caused the ground to settle down. It seemed as if his wheels got stuck in the ground as soon as he landed. It was raining at the time and thought the ground to be soft in spots.

R. C. Thompson
Major C. Thompson,
1st Lt, Air Corps.

Exct #5

RESTRICTED

RESTRICTED

9 July 1944.

S T A T E M E N T

I, WILLIAM N. WINZELER, Captain, Air Corps, did examine aircraft P51 D-5 44-13689 after the accident which had the propeller damaged. The brakes were inspected by a member of the Engineering department and found to be in good condition. There were no burns or warps on the brakes and they worked very well.

William N. Winzeler
WILLIAM N. WINZELER,
Captain, Air Corps,
Engineering Officer.

Fact #4

20

FLYING CONTROL
AAF Station P-133
AEG 637 U. S. Army

(E-FDF-3)

10 July 1944

FROM: Statement, Landing accident of P-51 #44-13689,
9 July 1944.

TO : Whom It May Concern.

At 1510 hours, 9 July 1944, Capt. Taylor, Tinplate 70, flying P-51 No. 44-13689 partially nosed over while landing on runway 22. No damage to aircraft was noticed from tower. Squadron called and gave details.

John D. Franklin
JOHN D. FRANKLIN,
1st Lt., Air Corps,
Flying Control Officer.

~~RESTRICTED~~

STATION WEATHER OFFICE
AAF-138 APO-637
U. S. ARMY

10 July, 1944.

I CERTIFY, that the weather at this station at 1500 and 1600 hours on 9 July 1944, was as follows:

1500 Hours:

Ceiling 1,500 feet.

Visibility: 2 miles.

Weather: Light continuous rain.

Surface Wind: SW at 8 to 12 mph.

1600 Hours:

Ceiling 1,500 feet.

Visibility: 2 miles.

Weather: Light continuous rain.

Surface Wind: South at 8 to 12 mph.

Ralph E. Platt
RALPH E. PLATT,
1st Lt., Air Corps,
Staff Weather Officer.

Platt

100

10