

Inspection Date:

Prepared For:

Prepared By: Scardaci Home Inspections Inc. 71 Oakdale Ave. Poughkeepsie N.Y. 12601

(845) 489-2452 (845) 452-7259 Fax scardacihomeinspections@gmail.com

Report Number: 00214

Inspector: Chris Scardaci

© 2015 Scardaci Home Inspections Inc.

REPORT OVERVIEW

THE HOUSE IN PERSPECTIVE

This home is older and is in need of maintenance/repairs. This home offers a solid structure and a lot of potential.

CONVENTIONS USED IN THIS REPORT

SATISFACTORY - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the very near future.

MAJOR CONCERNS - A system or component that is considered significantly deficient or is unsafe.

SAFETY HAZARD - Denotes a condition that is unsafe and in need of prompt attention.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI® Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind.

Please refer to the pre-inspection contract for a full explanation of the scope of the inspection.

BUILDING DATA

Approximate Age:	1930
Style:	Single Family
Main Entrance Faces:	North
State of Occupancy:	Vacant
Weather Conditions:	Rain
Recent Rain:	Yes
Ground cover:	Wet Temperature: 30-50°F

	F	RECEIPT	/ INVOICE	1 Page 3 c
71 Oakdale	ie N.Y. 12601	nc.		
Date: April 7	th 2015		Inspection Number	er:
Name:				
Inspection: Other** Total: ☑ Check #: ☑ Cash ☑ Credit Card	 d:			
** 🗹 Radon	🗆 Pool / Hot Tub	□ Shipping	□ Well & Septic	☑ Water
Inspected By License/Certifica	: Chris Scardaci tion #: 16000068246			
	TI	nis confidential re	port is prepared exclusiv	vely for © 2015 Scardaci Home Inspection



ITEMS NOT OPERATING

Electrical outlet in the back corner of west side porch. Windows with missing weight ropes.

MAJOR CONCERNS

Item(s) that have failed or have potential of failing soon.

Roof covering, showings signs of wear and deterioration. Loose motor joints on chimney recommend tuck pointing along with a masonry sealant be applied. Concrete pavers on back south west corner of home, recommend repair of improper pitch towards home. Cedar siding and exterior trim boards recommend scraping and painting, multiple bare wood locations. Recommend repair of loose aluminum trim and fascia wrap around exterior. Basement access entrance, recommend diverting water towards sump pump. Garage roof and back wall structurally unsound, recommend evaluation by licensed contractor.

Boiler on upgrade list, recommend budgeting for replacement. Signs of possible asbestos wrapped pipes recommend further evaluation. Oil storage tank leaking recommend replacement. Kitchen sink faucet leaking recommend repair. Several windows in need of repair, hardware not functioning properly. Bathroom exhaust fan recommended. Signs of air in 2nd floor radiators causing heat flow blockage, recommend repair. Recommend upgrading to 3 prong electrical outlets throughout home. Fuse electrical panel recommend upgrading to 200AMP circuit breakers.

POTENTIAL SAFETY HAZARDS

Garage structure in need of further structural evaluation. Leaking oil tank recommend replacement. Recommend installation of smoke and carbon detectors throughout home.

DEFERRED COST ITEMS

Items that have reached or are reaching their normal life expectancy or show indications that they may require repair or replacement <u>anytime during the next five (5) years</u>.

Roof that is 15+ years. Boiler that is 13+ years. Windows that are 25+ years.

* Items listed in this report may inadvertently have been left off the Summary Sheet. Customer should read the entire report, including the Remarks.

This confidential report is prepared exclusively for

© 2015 Scardaci Home Inspections Inc.



Peeling paint on cedar siding



Loose aluminum fascia wrapping



Loose motor joints around brick chimney



Damaged roofing shingles



Paver blocks pitching towards foundation



Peeling paint on front porch deck



Bare wood exposed on basement entrance



Cracked front stoop



Cracked and leaning retaining wall into basement Evidence of soot back up recommend cleaning




Monitor excessive pitch on side porch




Improper exterior electrical











Evidence of asbestos wrapped piping



Water seepage recommend directing to pit



Leaking oil tank recommend replacement



Monitor evidence of old terminate damage



Recommend service upgrade to breakers





2nd FL evaluate radiators and bleed as necessary Remove extension cord wiring



Recommend installing bathroom exhaust fan



Porch window does not close recommend repair



Loose section of ceiling in back right bedroom



Recommend collar ties every other rafter in attic

					1 Page 9 of 33
			GROU	VNDS	
SERVICE WALL Material: Condition:	✓ Concrete✓ Satisfactory	 Not visible Flagstone Marginal s home (See remarginal 	Gravel Poor ks)	 ✓ Brick □ <i>Trip Hazard</i> □ <i>Settling cracks</i> 	☐ Typical cracks
DRIVEWAY/PA Material: Condition:	□ Concrete ☑ Satisfactory	 □ Not visible ☑ Asphalt □ Marginal s home (See remarginal 	Gravel/Dirt Poor •ks)	 Brick Settling Cracks Trip hazard 	☐ Typical cracks ☐ Fill cracks and seal
PORCH (covered Support Pier: Condition: Floor:	<i>d entrance)</i> □ Concrete ☑ Satisfactory ☑ Satisfactory	 □ Not visible ☑ Wood □ Marginal □ Marginal 	□ Poor □ Poor	□ Railing/Balusters □ Safety Hazard	s recommended
STOOPS/STEPS Material: Condition:	☑ None☑ Concrete☑ Satisfactory	□ Uneven risers □ Wood □ Marginal	 ✓ Rotted/Damag □ ✓ Poor 		Settled sters recommended d
Negative Grade:		✓ West □ <i>Recommend</i> w	(See remarks) North window wells/covers	✓ South □ s □ <i>Trim back trees/s</i>	Satisfactory
GENERAL COM PORCH: Porch	AMENTS appears to have sett	ed, repair and/or re	place as necessary.		
LANDSCAPINO	G AFFECTING FOU	JNDATION: Main	tain a positive drai	nage slope away from	the foundation.

					Page 10 of 3
				ROO	DF
ROOF VISIBI	LITY	☑ All	□ Partial	□ None	□ Limited by:
INSPECTED F	ROM	□ Roof	□ Ladder at e	aves 🗹 Ground (Inspection Limited) With Binoculars
STYLE OF RC	OOF				
Type:	☑ Gable	□ Hip	\square Mansard	□ Shed	□ Flat □
Pitch:	□ Low	□ Medium	☑ Steep	□ Flat	
Roof #1	Type: As	ohalt	Layers: 1+ Lay	yers Approx. age	15-20+Yrs.
FLASHING	Materi	al: 🗆 Not visi		lum 🗆 Asphalt	
Condition:	Not visible	Copper Copper	□ Foam tory □ Margin	$\Box Rubber \\ al \Box Poor$	□ Lead □ <i>Rusted</i> □ Missing
		from chimney/	5 0	mend Sealing	
CONDITION	OF ROOF	COVERINGS	Roof #1:	□ Satisfacto	ory 🗹 Marginal 🗌 Poor
Condition:	🗹 Curling	g 🗹 C	racking	Ponding [□ Burn Spots
	🗆 Nail po	pping 🛛 🖯	ranules missing 🔲 .	Alligatoring [Blistering Missing Tabs/Shingles/Tiles
	Moss b	1			Incomplete/Improper Nailing
	Kecon	umend roofer e		Evidence of Lea	Kage
PLUMBING V	ENTS	🗆 Not Visib	le 🗹 Yes 🛛	No 🗹 Satisfac	tory 🗆 Marginal 🗆 Poor
Conditions repo	orted above	reflect <u>visible p</u>	oortion only. See	additional Com	ments
GENERAL CO	OMMENTS				
			rling, cracking a	nd aging. Roof a	ppeared to be nearing end of its useful life, budget
			and mold off of t		
					-
				EXTI	ERIOR
CHIMNEY(S)			location(s): West		
Viewed From:			adder at eaves		<i>pection Limited</i>) Uith Binoculars
Rain Cap/Spar Chase:	Brick	:		□ No □ Metal	□ Recommended □ Blocks □ Framed
Evidence of:	□ Holes			o 🗹 Loose mortar j	ioints 🗆 Flaking 🛛 Loose Brick 🛛 Rust
Flue:	☑ Tile		Ietal	Unlined	□ Not visible
Evidence of:	□ Scaling	g	racks	Creosote	☐ Not evaluated (See remarks page) Cricket/Saddle/Flashing
	ш nave Ji				
		Т	his confidential	report is prepar	ed exclusively for Andrew and Laura-Beth Jorda © 2015 Scardaci Home Inspections Ir

						Page 11 of 33
GUTTERS/SC Material: Condition:	Copper	OUGH	one □ <i>Needs to</i> ☑ Galvanized/A □ Poor	luminum	d 🗹 Downspouts	s needed
SIDING Material: Condition:	□ Stone □ Slat □ EIFS* Not Inspec □ Typical cracks □ Satisfactory	cted Asphalt	k □ Fiberboard ☑ Wood nt ☑ <i>Monitor</i> □ Poor	□ Metal/ □ Wood	cement □ Stud Vinyl □	ose/Missing/Holes
1.)TRIM 2.)SO Material: Condition:	✓ Recommend repair	☐ Fiberboard	✓ Aluminum/Sta □ Damaged woo □ Poor		□ Vinyl □	□ Stucco
CAULKING Condition:	Recommend arou	✓ Marginal <i>nd windows/doors/ma</i>		rs/utility p	enetrations	
WINDOWS & Material: Screens: Condition:	☑ Wood □ Torn	 □ Failed/fogged ins □ Metal □ Bent ☑ Marginal 	□ Vinyl □ Not installed	Vood rot	☐ Aluminum/Vi ☑ Glazing Comp ☑ <i>Recommend</i>	pound/Caulk needed
STORMS WIN Putty: Condition:	✓ Satisfactory✓ Satisfactory	ne D Not installed Needed Broken/cracked	□ Wood □ C □ N/A □ Wood rot	lad comb.	Wood/metal c <i>Recommend</i>	
	5	Poured concrete Marginal Marginal dition reported abo	☐ Monitor □ Monitor	□ Ha	ave Evaluated ave Evaluated	
GUTTERS AND eight foot extens SIDING: Sidin	MMENTS Missing mortar in the b D DOWNSPOUTS: R sions recommended. g was in need of norma MES: Damaged wood	ecommend adding do	ownspout extension maintenance.	ns to discł		ne house. Six foot -

							Page 12 of 3
					EXTEI	RIOR	
SERVICE ENT	'RY	🗆 Unde	erground	🗹 Ove	rhead	🗌 Weather h	ead/mast needs repair
Exterior receptad	cles:	🗹 Yes	-	🗆 No			
•			Operable:	🗹 Yes	🗆 No	Overhead	wires too low
GFCI present:	□ Yes	🗹 No	Operable:	□ Yes	🗆 No	Safety Haz	zard
•	Rever	se polarity	v -	Ope	n ground(s)		nd GFCI Receptacles
Condition:	🗹 Satisf	actory [] Marginal	D Poor			
			-				
BUILDING(S)	EXTERIC	OR WALI	CONSTRUC	TION			
Туре:	□ Not v	isible	🗹 Framed		/lasonry		
Condition:	\Box Not v	isible	☑ Satisfactory	y □N	/larginal	D Poor	
			-		C		
EXTERIOR DO	OORS	1.) EN	TRANCE 2.)	PATIO	3.)STORM	1	
Weather-stripping	g: 🗹 Satisf	actory	□ Marginal	🗆 F	oor	□ Missing	□ Replace
Door Condition:	🗹 Satisf	actory	□ Marginal	ΠP	oor	-	-
		-	-				

			Page 13 of 33
	CAR	GE/CARPOR'	
TYPE Income Income Income Income Income	✓ 2-car	□ 3-car	□ 4-car
AUTOMATIC OPENER Yes V	No Derable	□ Inoperable	
ROOFING Material: Type: Asphalt A	pprox. Age: 20-25+ Ar	prox. layers: 1+ Layer	s
GUTTERS / EAVESTROUGH Condi			or 🛛 Same as House
FLOOD			
FLOOR Material: Concrete Gravel Condition: Satisfactory Typical c Burners less than 18" above garage floor: I	✓ Asphalt racks □ <i>Large set</i> N/A □ Yes		Cafety hazard
SILL PLATES	or level 🛛 Elevated	Rotted /Damaged	Recommend repair
GENERAL COMMENTS			
GARAGE ROOF: Roof was in poor condition a GARAGE SIDING: Siding had some damage a	nd was in need of repai		
GARAGE TRIM: Trim had some damage and v GARAGE FOUNDATION: Recommend contra		te.	
			2015 Scardaci Home Inspections Inc.

		Page 14 of 33			
		KITCHEN			
COUNTERTO	OPS	factory I Marginal I Recommend repair/caulking			
CABINETS	☑ Sati	sfactory			
PLUMBING C Faucet Leaks: Sink/Faucet: Functional Dra Comments: Fa	☑ Yes □ Satisfac ainage: ☑ Satisfac				
WALLS & CE Condition:	Satisfactory	□ Marginal □ Poor □ Typical cracks □ <i>Moisture stains</i>			
HEATING / C	OOLING SOURC	\mathbf{E} \mathbf{V} Yes $\mathbf{\Box}$ No			
FLOOR	Condition:	Satisfactory Imaginal Impoor Impoor Sloping Impoor			
Comments:					
Comments.					
BATHROOM(S)					
BATH SECO BATH	ND FLOOR				
Sinks:	Faucet leaks:	🗆 Yes 🗹 No Pipes leak: 🗆 Yes 🗹 No			
Tubs:	Faucet leaks:	\Box Yes \blacksquare No Pipes leak: \Box Yes \blacksquare No \Box N/A			
Showers:	Faucet leaks:	\Box Yes \overrightarrow{V} No Pipes leak: \Box Yes \overrightarrow{V} No \Box N/A			
Toilet:	Bowl Loose:	\Box Yes \checkmark No Operable: \checkmark Yes \Box No \Box Cracked bowl \Box Toilet leaks			
Whirlpool:	🗆 Yes 🗹 No	Operable: \Box Yes \Box No \Box Not tested \Box No access door			
Shower/Tub a	rea: 🗹 Ceramic/P	e			
	Condition: Caulk/Grouting N	Satisfactory ☐ Marginal ☐ Poor ☐ Rotted floors Needed: ☐ Yes ☑ No			
Drainage:	✓ Satisfactory				
Water flow:	Satisfactory	$\Box \text{ Marginal } \Box \text{ Poor}$			
	s present: Yes	6			
	Satisfactory	□ Marginal □ Poor			
Receptacles Pr	•	\Box No Operable: \blacksquare Yes \Box No			
GFCI:	🗹 Yes 🛛 No	Operable: Yes No			
	Reverse polarity:	□ Yes ☑ No □ Potential Safety Hazard(s) (See remarks)			
Heat source pr					
Exhaust fan:	\Box Yes	\checkmark No Operable: \Box Yes \Box No \Box Noisy			
CENEDAL CO	MMENTS	See additional commente			

GENERAL COMMENTS See additional comments

EXHAUST: Exhaust fan not present.

		Page 15 of 33
	ROOM	q
Walls & Ceiling: ☑ Satisfactory Moisture stains: ☑ Yes	□ Marginal □ No	\Box Poor \blacksquare Typical cracks \Box Damage
Floor: Satisfactory	\square Marginal	\Box Poor \Box Squeaks \Box Slopes
Ceiling Fan: 🗹 N/A	□ Satisfactory	□ Marginal □ Poor
Electrical: Switches: Yes	□ No Receptacles	
Open ground/Reverse polarity: □ Yes Heating Source Present: ☑ Yes	 ✓ No □ Not visible □ H 	azardCover plates missingIoles:DoorsWallsCeilings
Egress Restricted:	\Box Yes \checkmark No	
•	-	Cracked glass
	f leaking insulated glass	Broken/Missing hardware
		_
	INTERIOR	
INTERIOR WINDOWS / GLASS Condition: Satisfactory	✓ Marginal	□ Poor
Representative number	of windows operated	□ Painted shut (See remarks)
Glazing compound needed Cracke	6	
Evidence of Leaking Insulated Glass: Security Bars Present: 🛛 Yes 🗹 No	□ Yes □ No ☑ N/A □ Not tested □ Safety	Safety Glazing Needed: □ Yes ☑ No hazard □ Test release mechanism before moving in
-		
FIREPLACE □ None Location Type: □ Gas ☑ Wood	(s): Living room Image: Woodburner stove	□ Electric □ Ventless (See remarks)
Material: ☑ Masonry □ Metal (pre-		
No Damper operab		□ No
□ <i>Open joints or cracks in firebrick/panels</i> Damper Modified for Gas Operation:	s should be sealed □ Yes ☑ No □ Damp	☐ Fireplace doors need repair
	\square No Mantel :	\square N/A \blacksquare Secure \square Loose
Physical Condition: V Satisfactory	□ Marginal □ Poor	Recommend having flue cleaned and re-examined
STAIRS / STEPS / BALCONIES		
✓ SatisfactoryHandrail:✓ Satisfactory	e	□ Poor □ None □ Poor □ Safety hazard
	Railing/Balusters Recomm	
Risers/Treads: ☑ Satisfactory		Poor Risers/Treads uneven
ATTIC/STRUCTURE/FRAMING/INSU		A (See remarks)
Access:	Scuttlehole/Hatch	□ No access □
Inspected From: Access panel	✓ In the attic	
•		
Location: Bedroom hall Access Limited By:	□ Bedroom closet	Garage
Location: ☑ Bedroom hall Access Limited By:	Bedroom closet Partial	□ Garage □ ☑ None
Location:Image: Bedroom hallAccess Limited By:Image: DescriptionFlooring:Image: CompleteInsulation:Image: Fiber glass	□ Bedroom closet □ Partial ☑ Batts □ Loose	□ Garage □ □ None □ Cellulose □ Foam □
Location: ☑ Bedroom hall Access Limited By:	□ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6-	☐ Garage □ ✓ None □ Cellulose □ Foam □ -9 □ Recommend Baffles @ Eaves
Location:Image: Bedroom hallAccess Limited By:Image: DescriptionFlooring:Image: CompleteInsulation:Image: Fiber glass	□ Bedroom closet □ Partial ☑ Batts □ Loose	□ Garage □ □ Garage □ □ None □ Cellulose □ Foam □ -9 □ Recommend Baffles @ Eaves □ Missing □ Compressed
Location: ☑ Bedroom hall Access Limited By:	 □ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6- □ Displaced ☑ Between ceiling joists nal insulation (See comme 	Garage □ ✓ None □ Cellulose □ Foam □ -9 □ Recommend Baffles @ Eaves □ Missing □ Compressed □ Underside of Roof Deck □ Not visible ents)
Location: ☑ Bedroom hall Access Limited By:	 □ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6 □ Displaced ☑ Between ceiling joists nal insulation (See commended) □ No □ Recommended 	Garage □ Garage □ Garage □ Garage □ One Gellulose □ Foam □ One Gellulose □ Foam □ One Gentside of Roof Deck □ Not visible Centsion Gentsion Gentsi
Location: ☑ Bedroom hall Access Limited By:	 □ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6 □ Displaced ☑ Between ceiling joists nal insulation (See comme □ No □ Recommend roses ☑ Wood 	Garage □ Garage □ Garage □ One Gellulose □ Foam □ -9 □ Recommend Baffles @ Eaves Onderside of Roof Deck □ Not visible ents) repair □ Recommend Structural Engineer One Metal □
Location: ☑ Bedroom hall Access Limited By:	□ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6 □ Displaced ☑ Between ceiling joists nal insulation (See comme □ No □ Recommend n ses ☑ Wood ns □ Knee Wall □ Not visible	Garage □ Garage □ Garage □ Garage □ One Gellulose □ Foam □ One Gellulose □ Foam □ One Gentside of Roof Deck □ Not visible Gentsion Gentsi
Location: ☑ Bedroom hall Access Limited By:	□ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6: □ Displaced ☑ Between ceiling joists nal insulation (See commend ress □ No □ Recommend ress □ Ses ☑ Wood ns □ Knee Wall I □ Not visible ☑ Planking	Garage □ Garage □ Garage □ Garage □ Garage □ One □ Cellulose □ Foam □ -9 □ Recommend Baffles @ Eaves One □ Underside of Roof Deck □ Not visible One □ Underside of Roof Deck □ Not visible One □ Not visible One □ Not Visible One □ Stained □ Delaminated
Location: ☑ Bedroom hall Access Limited By:	□ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6 □ Displaced ☑ Between ceiling joists nal insulation (See commend reses ☑ Wood ns □ Knee Wall I □ Not visible ☑ Planking ing: □ Yes	Garage □ Ga
Location: ☑ Bedroom hall Access Limited By:	□ Bedroom closet □ Partial ☑ Batts □ Loose □ Rockwoll Depth: 6 □ Displaced ☑ Between ceiling joists nal insulation (See commend reses ☑ No □ Recommend reses ☑ Wood ns □ Knee Wall I □ Not visible ☑ Planking ing: □ Yes □ No □ Needs repair/state	Garage □ Garage □ Garage □ Garage □ One Gellulose □ Foam □ -9 □ Recommend Baffles @ Eaves Onderside of Roof Deck □ Not visible Onderside of Roof Deck □ Not visible Cants) repair □ Recommend Structural Engineer One Metal □ Not Visible Rotted □ Stained □ Delaminated No (See remarks) sealing

BASEMENT STARS Condition: Image: Satisfactory Marginal Poor Typical wear and tear Need reparation FOUNDATION Image: Satisfactory Marginal Have evaluated Monitor Material: ICF Satisfactory Marginal Have evaluated Monitor Material: ICF Satisfactory Marginal Have evaluated Monitor Material: ICF Satisfactory Marginal How evaluated Monitor Condition: ICF Oncrete Dirt/Gravel Not visible Poor Poor Popical cracks Material: Concrete Dirt/Gravel Not visible Poor Typical cracks BANAGE Sump Pump: Yes No Working Not working Needs cleaning Pump not test					
Condition: Image: Satisfactory FOUNDATION Condition: Material: ICF Satisfactory Marginal Have evaluated Marginal Have evaluated Monitor Poured concrete Poured concrete Poured concrete Poor Pump not test					
Condition: Material: □ ICF Imaginal □ Marginal □ Have evaluated □ Monitor Imaginal: □ ICF □ Brick □ Concrete block □ Fieldstone □ Poured concrete FLOOR Imaginal: □ Ort/Gravel □ Dirt/Gravel □ Not visible □ Material: □ Satisfactory □ Dirt/Gravel □ Not visible □ Imaginal: □ Satisfactory □ Marginal □ Poor □ Typical cracks DRAINAGE Imaginal Imaginal □ Not working □ Needs cleaning □ Pump not test					
Material: ✓ Concrete □ Dirt/Gravel □ Not visible □ Condition: ✓ Satisfactory □ Marginal □ Poor ✓ Typical cracks DRAINAGE ✓ ✓ Working □ Not working □ Needs cleaning □ Pump not test					
Sump Pump: ☑ Yes □ No ☑ Working □ Not working □ Needs cleaning □ Pump not test					
GIRDERS / BEAMS Material: □ Steel ☑ Wood □ Concrete □ Block □ LVL □ Not visible Condition: ☑ Satisfactory □ Marginal □ Poor □ Stained/rusted					
COLUMNS Material: Steel Wood Concrete Block Not visible Condition: Satisfactory Marginal Poor Stained/rusted					
JOISTS Material: ☑ Wood □ Steel □ Truss □ Not visible					
Condition: Satisfactory Darginal Door					
GENERAL COMMENTS BASEMENT DRAINAGE/SUMP PUMP: Recommend sealing sump pump crock. Potential safety concern for children.					
PLUMBING WATER SERVICE Main Shut-off Location: In the basement					
Water Entry Piping: Not visible Copper/Galv. Image: Plastic* (PVC, CPVC, Polybutylene, PEX) Lead Lead Other Than Solder Joints: Yes No Unknown Service entry Visible Water Distribution Piping: Copper Galvanized Plastic* (PVC, CPVC, Polybutylene, PEX) Image: Copper Visible Water Distribution Piping: Copper Galvanized Plastic* (PVC, CPVC, Polybutylene, PEX) Image: Copper Condition: Satisfactory Marginal Poor Poor Functional Flow: Satisfactory Marginal Poor Water pressure over 80 psi Drain/Waste/Vent Pipe: Copper Cast iron Galvanized PVC ABS Condition: Satisfactory Marginal Poor PVC ABS					

				Page 17 of 33
Gas Line: Condition:	 ✓ Satisfactory □ Marginal System: □ N/A ✓ Yes □ ✓ N/A □ Copper □ Bras □ Satisfactory □ Marginal 	I No Leaking: ☑ Ye s □ Black iron □ Poor	es □ No □ Stainless steel □ C ☑ <i>Recommend plumbe</i>	
MAIN FUEL SHUT-	OFF LOCATION In 1	the basement \Box N/A	Δ	
WELL PUMP Pressure Gauge Oper		e \Box In basement \Box	Well house 🗹 Well pit	□ Shared well
WATER SOFTENEI Plumbing Hooked U		Loop Installed: • Present: ☑ Yes □	No Plumbing Leaking:	□ Yes ☑ No
BOILER SYSTEM	□ N/A			
BUILER SYSTEM	Approximate age: 15-20+ yea	r(s) 🛛 Unknown		
Energy Source: Distribution: Circulator: Controls: Relief valve: Operated: Operation:	 □ Gas □ LP ☑ Hot water □ Baseboan ☑ Pump Temp/pressure gauge exist: <i>Combustion Air Venting Presentt</i> ☑ Yes □ No □ Mis When turned on by thermost Satisfactory: ☑ Yes □ No 	☐ Gravity ☑ Yes ☐ No : ☐ Yes ssing tat: ☑ Fired	 ✓ Radiator □ Rad □ Multiple zones Operable: ✓ Yes □ No □ Did not fire 	id Fuel diant Floor □ No ☑ N/A □ <i>Before closing</i>

GENERAL COMMENTS

BOILER: Boiler was in normal working order at the time of the inspection. Boiler was fair and aging, unit was nearing end of its useful life.

			Page 18 of 33	
			C/COOLING SYSTEM	
MAIN PANEL	Location: Basement	Condition:	□ Satisfactory ☑ Marginal □ Poor	
Adequate Clearance			age: 100 Volts 120/240 □ Breakers ☑ Fuses	
Appears Grounded:		☑ Not visible	č	
MAIN WIRE:	Copper	🗹 Aluminum	□ Not visible □ Double tapping of the main wire	
Condition:	Satisfactory	D Poor	☐ Federal Pacific Panel Stab Lok [®] (See remarks)*	
BRANCH WIRE:	Copper	□ Aluminum*	□ Not visible	
Condition:	Satisfactory	D Poor	Recommend electrician evaluate/repair*	
	□ Romex	☑ BX cable	□ Conduit □ <i>Knob & tube**</i>	
Double tapping Wires undersized/oversized breaker/fuse				
ELECTRICAL FIX		•	of installed lighting fixtures, switches, and receptacles	
located inside the hou				
Condition:	Satisfactory	□ Marginal	\Box Poor \Box Open grounds \Box Reverse polarity	
	\Box GFCIs not operating		Solid conductor aluminum branch wiring circuits*	
□ Ungrounded 3-prong receptacles		prong receptacles	(See remarks)	
	Recommend el	ectrician evaluate/rep	pair*	



SERVICE WALKS/DRIVEWAYS

Spalling concrete cannot be patched with concrete because the new will not bond with the old. Water will freeze between the two layers, or the concrete will break up from movement or wear. Replacement of the damaged section is recommended. Walks or driveways that are close to the property should be properly pitched away to direct water away from the foundation. Asphalt driveways should be kept sealed and larger cracks filled so as to prevent damage from frost.

PATIOS

that have settled towards the structure should be mudjacked or replaced to assure proper pitch. Improperly pitched patios are one source of wet basements/crawlspaces.

All surfaces of untreated wood need regular applications of paint or special chemicals to resist damage. Porch or deck columns and fence posts which are buried in the ground and made of untreated wood will become damaged within a year or two.

Decks should always be nailed with galvanized, stainless steal or aluminum nails. Decks that are not painted or stained should be treated with a water sealer.

GRADING AND DRAINAGE

Any system of grading or landscaping that creates positive drainage (moving water away from the foundation walls) will help to keep a basement and crawlspace dry. Where negative grade exists and additional backfill is suggested, it may require digging out around the property to get a proper pitch. Dirt shall be approximately 6" below the bottom sill and should not touch wood surfaces.

Flower beds, loose mulched areas, railroad ties and other such landscaping items close to the foundation trap moisture and contribute to wet basements. To establish a positive grade, a proper slope away from the house is 1" per foot for approximately 5-6 feet. Recommend ground cover planting or grass up to foundation.

ROOF AND SURFACE WATER CONTROL

Roof and surface water must be controlled to maintain a dry basement and crawlspace. This means keeping gutters cleaned out and aligned, extending downspouts, installing splashblocks, and building up the grade so that roof and surface water is diverted away from the building.

WINDOW WELLS

The amount of water which enters a window well from falling rain is generally slight, but water will accumulate in window wells if the yard is improperly graded. Plastic window well covers are useful in keeping out leaves and debris.

RETAINING WALLS

Retaining walls deteriorate because of excessive pressure buildup behind them, generally due to water accumulation. Conditions can often be improved by excavating a trench behind the retaining wall and filling it with coarse gravel. Drain holes through the wall will then be able to relieve the water pressure.

Retaining walls sometime suffer from tree root pressure or from general movement of topsoil down the slope. Normally, these conditions require rebuilding the retaining wall.

RAILINGS

It is recommended that railings be installed for any stairway over 3 steps and porches over 30" for safety reasons. Balusters for porches, balconies, and stairs should be close enough to assure children cannot squeeze through.

DEFINITIONS

SATISFACTORY (Sat.) - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL (Marg.) - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the very near future.



<u>Valleys and Flashings</u> that are covered with shingles and/or tar or any other material are considered not visible and are not part of the inspection.

<u>**Tar and Gravel Roofs</u>** - This type of covering on a pitched roof requires ongoing annual maintenance. We recommend that a roofing contractor evaluate this type of roof. Infra-red photography is best used to determine areas of potential leaks.</u>

Flat roofs are very vulnerable to leaking. It is very important to maintain proper drainage to prevent the ponding of water. We recommend that a roofing contractor evaluate this type of roof.

ROOF TYPE	LIFE EXPECTANCY	SPECIAL REMARKS
Asphalt Shingles	15-20 years	Used on nearly 80% of all residential
		roofs; requires little maintenance.
Asphalt Multi-Thickness Shingles*	20-30 years	Heavier and more durable than regular
		asphalt shingles.
Asphalt Interlocking. Shingles*	15-25 years	Especially good in high-wind areas.
Asphalt Rolls	10 years	Used on low slope roofs.
Built-up Roofing	10-20 years	Used on low slope roofs; 2 to 3 times as
		costly as asphalt shingles.
Wood Shingles*	10-40 years	Treat with preservative every 5 years to
		prevent decay.
Clay Tiles*,	20 + years	Durable, fireproof, but not watertight, *
Cement Tiles*	20 + years	requiring a good subsurface base.
Slate Shingles*	30-100 years 2	Extremely durable, but brittle and
		expensive.
Asbestos Cement Shingles*	30-75 years	Durable, but brittle and difficult to
		repair.
Metal Roofing	15-40 + years	Comes in sheets & shingles; should be
		well grounded for protection from
		lightning; certain metals must be painted.
Single Ply	15-25 years	New material; not yet passed test of time.
Membrane (mfgr's claim) Polyurethane	5-10 years 1	Used on low slope roofs.
with Elastomenic Coating		

* Not recommended for use on low slope roof

Depending on local conditions and proper installation

² Depending on quality of slate

Roof coverings should be visually checked in the spring and fall for any visible missing shingles, damaged coverings or other defects. Before re-roofing, the underside of the roof structure and roof sheathing should be inspected to determine that the roof structure can support the additional weight of the shingles.

Wood shakes and shingles will vary in aging, due to the quality of the material, installation, maintenance, and surrounding shade trees. Ventilation and drying of the wood material is critical in extending the life expectancy of the wood. Commercial preservatives are available on the market, which could be applied to wood to impede deterioration.



CHIMNEYS

Chimneys built of masonry will eventually need tuckpointing. A cracked chimney top that allows water and carbonic acid to get behind the surface brick/stone will accelerate the deterioration. Moisture will also deteriorate the clay flue liner. Periodic chimney cleaning will keep you apprised of the chimney's condition. The flashing around the chimney may need resealing and should be inspected every year or two. Fireplace chimneys should be inspected and evaluated by a chimney professional before using. Chimneys must be adequate height for proper drafting. Spark arrestors are recommended for a wood burning chimney, and chimney caps for fossil fuels. **Unlined Chimney** - should be re-evaluated by a chimney technician. Have flue cleaned and re-evaluated. The flue lining is covered with soot or creosote and no representation can be made as to the condition.

NOT EVALUATED

The flue was not evaluated due to inaccessibility such as roof pitch, cap, cleanout not accessible, etc.

CRICKET FLASHING

Small, sloped structure made of metal and designed to drain moisture away from a chimney. Usually placed at the back of a chimney.

GUTTERS AND DO

This is an extremely important element in basement/crawlspace dampness control. Keep gutters clean and downspout extensions in place (4' or more). Paint the inside of galvanized gutters, which will extend the life. Shortly after a rain or thaw in winter, look for leaks at seams in the gutters. These can be recaulked before they cause damage to fascia or soffit boards. If no gutters exist, it is recommended that they be added.

SIDING

Wood siding should not come in contact with the ground. The moisture will cause rotting to take place and can attract carpenter ants. See page 34 for siding that have known problems, but are not always recognizable. Brick and stone veneer must be monitored for loose or missing mortar. Some brick and stone are susceptible to spalling. This can be caused when moisture is trapped and a freeze/thaw situation occurs. There are products on the market that can be used to seal out the moisture. This holds true for brick and stone chimneys also. Metal siding will dent and scratch. Oxidation is a normal reaction in aluminum. There are good cleaners on the market and it is recommended that they be used occasionally. Metal siding can be painted.

EIFS This type of siding is a synthetic stucco and has experienced serious problems. It requires a certified EIFS inspector to determine condition.

DOORS AND WINDOWS

These can waste an enormous amount of energy. Maintain the caulking around the frames on the exterior. Check for drafts in the winter and improve the worst offenders first. Windows that have leaky storm windows will usually have a lot of sweating. Likewise, well-sealed storms that sweat indicate a leaky window. It is the tighter unit that will sweat (unless the home has excess humidity to begin with).

Wood that exhibits blistering or peeling paint should be examined for possible moisture sources: roof leaks, bad gutters, interior moisture from baths or laundry or from a poorly vented crawl space. Some paint problems have no logical explanation, but many are a symptom of an underlying problem. A freshly painted house may mask these symptoms, but after you have lived in the home for a year or two, look for localized paint blistering (peeling). It may be a clue.

New glazing will last longer if the raw wood is treated with boiled linseed oil prior to glazing. It prevents the wood from drawing the moisture out of the new glazing.

CAULKING

Many different types of caulk are available on the market today. Check with a paint or hardware store for the kind of application you need.



OVERHEAD DOOR OPENERS

We recommend that a separate electrical outlet be provided. Openers that do not have a **safety reverse** are considered a safety hazard. Small children and pets are especially vulnerable. We recommend the operating switches be set high enough so children cannot reach them. If a electric sensor is present, it should be tested occasionally to ensure it is working.

GARAGE SILL PLATES should be elevated or treated lumber should be used. If this is not the case, try to direct water away to prevent rotting.

BURNERS

Any appliance such as a water heater, furnace, etc. should have the flame a minimum of 18" above the floor. Any open flame less



PLASTER ON WOOD LATH

Plaster on wood lath is an old technique and is no longer in general use. Wood lath shrinks with time and the nails rust and loosen. As a result, the plaster may become fragile and caution is needed in working with this type of plastering system. Sagging ceilings are best repaired by laminating drywall over the existing plaster and screwing it to the ceiling joists.

PLASTER ON GYPSUM LATH (ROCK LATH)

Plaster on gypsum lath will sometimes show the seams of the 16" wide gypsum lath, but this does not indicate a structural fault. The scalloping appearance can be leveled with drywall joint compound and fiberglass mesh joint tape or drywall can be laminated over the existing plaster on the ceiling.

WOOD FLOORING

Always attempt to clean wood floors first before making the decision to refinish the floor. Wax removers and other mild stripping agents plus a good waxing and buffing will usually produce satisfactory results. Mild bleaching agents help remove deep stains. Sanding removes some of the wood in the floor and can usually be done safely only once or twice in the life of the floor.

NAIL POPS

Drywall nail pops are due to normal expansion and contraction of the wood members to which the drywall is nailed and are usually of no structural significance.

CARPETING

Where carpeting has been installed, the materials and condition of the floor underneath cannot be determined.

APPLIANCES (If report indicated appliances were operated, the following applies) Dishwashers are tested to see if the motor operates and water sprays properly. Stoves are tested to see that burners are working and oven and broiler get hot. Timer and controls are not tested. Refrigerators are not tested. Most new Dishwashers have the drain line looped automatically and may not be visible on the day of inspection. It is essential for the dishwasher drain line to have an anti-siphon break to prevent backflow. A drain line loop or Dishwasher air gap should be installed if found to be missing. No representation is made to continued life expectancy of any appliance.

ASBESTOS AND OTHER HAZARDS

Asbestos fibers in some form are present in many homes, but are often not visible and cannot be identified without testing.

If there is reason to suspect that asbestos may be present and if it is of particular concern, a sample of the material in question may be removed and analyzed in a laboratory. However, detecting or inspecting for the presence or absence of asbestos is not a part of our inspection.

Also excluded from this inspection and report are the possible presence of, or danger from, radon gas, lead-based paint, urea formaldehyde, toxic or flammable chemicals and all other similar or potentially harmful substances and environmental hazards.

WINDOWS

A representative number of windows are inspected.



STALL SHOWER

The metal shower pan in a stall shower has a potential or probable life of 10-20 years depending on quality of the pan installed. Although a visible inspection is made to determine whether a shower pan is currently leaking, it cannot be stated with certainty that no defect is present or that one may not soon develop. Shower pan leaks often do not show except when the shower is in actual use.

CERAMIC TILE

Bathroom tile installed in a mortar bed is excellent. It is still necessary to keep the joint between the tile and the tub/shower caulked or sealed to prevent water spillage from leaking through and damaging the ceilings below.

Ceramic tile is often installed in mastic. It is important to keep the tile caulked or water will seep behind the tile and cause deterioration in the wallboard. Special attention should be paid to the area around faucets and other tile penetrations.

EXHAUST FANS

Bathrooms with a shower should have exhaust fans when possible. This helps to remove excess moisture from the room, preventing damage to the ceiling and walls and wood finishes. The exhaust fan should not be vented into the attic. The proper way to vent the fan(s) is to the outside. Running the vent pipe horizontally and venting into a gable end or soffit is preferred. Running the vent pipe vertically through the roof may cause condensation to run down the vent pipe, rusting the fan and damaging the wallboard. Insulating the vent pipe in the attic will help to reduce this problem.

SLOW DRAINS on sinks, tubs, and showers are usually due to build up of hair and soap scum. Most sink popups can be easily removed for cleaning. Some tubs have a spring attached to the closing lever that acts as a catch for hair. It may require removing a couple of screws to disassemble. If you cannot mechanically remove the obstruction, be kind to your pipes. *Don't use a caustic cleaner*. There are several bacteria drain cleaners available. They are available at hardware stores in areas where septic tanks are used. These drain cleaners take a little longer to work, but are safe for you and your pipes.

SAFETY HAZARDS

Typical safety hazards found in bathrooms are open grounds or reverse polarity by water. Replacing these outlets with G.F.C.I.'s are recommended. (See page 28)

WHIRLPOOL TUBS

This relates to interior tubs hooked up to interior plumbing. Where possible, the motor will be operated to see that the jets are working. Hot tubs and spas are not inspected.



DOOR STOPS

All swinging doors should be checked for door stops. Broken or missing door stops can result in door knobs breaking through drywall or plaster.

CLOSET GUIDES

Sliding closet doors should be checked to see that closet guides are in place. Missing or broken closet guides can cause scratches and damage to doors.

COLD AIR RETURNS

Bedrooms that do not have cold air returns in them should have a 3/4" gap under the doors to allow cold air to be drawn into the hall return.

AN INSPECTION VERSUS A WARRANTY

A home inspection is just what the name indicates, an inspection of a home...usually a home that is being purchased. The purpose of the inspection is to determine the condition of the various systems and structures of the home. While an inspection performed by a competent inspection company will determine the condition of the major components of the home, no inspection will pick up every minute latent defect. The inspector's ability to find all defects is limited by access to various parts of the property, lack of information about the property and many other factors. A good inspector will do his or her level best to determine the condition of the home. This opinion is arrived at by the best technical methods available to the home inspection industry. It is still only an opinion.

A warranty is a policy sold to the buyer that warrants that specific items in the home are in sound condition and will remain in sound condition for a specified period of time. Typically, the warranty company never inspects the home. The warranty company uses actuarial tables to determine the expected life of the warranted items and charges the customer a fee for the warranty that will hopefully cover any projected loss and make a profit for the warranty seller. It is essentially an insurance policy.

The service that we have provided you is an inspection. We make no warranty of this property. If you desire warranty coverage, please see your real estate agent for details about any warranty plan to which their firm may have access.



WINDOW FRAMES AND SILLS

Window frames and sills are often found to have surface deterioration due to condensation that has run off the window and damaged the varnish. Usually this can be repaired with a solvent style refinisher and fine steel wool. This is sometimes a sign of excess humidity in the house. See comments regarding caulking doors and windows, page 8.

FIREPLACES

It is important that a fireplace be cleaned on a routine basis to prevent the buildup of creosote in the flue, which can cause a chimney fire. Masonry fireplace chimneys are normally required to have a terra cotta flue liner or 8 inches of masonry surrounding each flue in order to be considered safe and to conform with most building codes. During visual inspections, it is not uncommon to be unable to detect the absence of a flue liner either because of stoppage at the firebox, a defective damper or lack of access from the roof.

WOODBURNERS

Once installed, it can be difficult to determine proper clearances for woodburning stoves. Manufacturer specifications, which are not usually available to the inspector, determine the proper installation. We recommend you ask the owner for paperwork, verifying that it was installed by a professional contractor.

VENTILATION

Ventilation is recommended at the rate of one square foot of vent area to 300 square feet of attic floor space, this being divided between soffit and rooftop. Power vents should ideally have both a humidistat and a thermostat, since ventilation is needed to remove winter moisture as well as summer heat. Evidence of condensation such as blackened roof sheathing, frost on nail heads, etc. is an indication that ventilation may have been or is blocked or inadequate.

INSULATION

The recommended insulation in the attic area is R-38, approximately 12". If insulation is added, it is important that the ventilation is proper.

SMOKE DETECTORS

Smoke detectors should be tested monthly. At least one detector should be on each level. CO detectors are not required by most states, but for safety reasons, are highly recommended.

VAPOR BARRIERS

The vapor barrier should be on the warm side of the surface. Most older homes were built without vapor barriers. If the vapor barrier is towards the cold side of the surface, it should be sliced or removed. Most vapor barriers in the attic are covered by insulation and therefore, not visible.

SAFETY GLAZING

Safety glazing requirements vary depending on the age of the home. Every attempt is made to identify areas where the lack of safety glazing presents an immediate safety hazard, such as a shower door. In some older homes it is difficult to determine if safety glazing is present, since the glass is not marked. Therefore, no representation is made that safety glazing exists in all appropriate areas.

INSULATED GLASS

Broken seal in thermopane/insulated windows are not always visible nor detectible due to humidity and temperature changes during the day. Other factors such as window covering, dirty windows, and lack of accessibility, personal property placed in front of the windows all affect the view of the windows at the time of the inspection.



BASEMENT/CRAWLSPACE

Any basement/crawlspace that has cracks or leaks is technically considered to have failed. Most block basements/crawlspace have step cracks in various areas. If little or no movement has occurred and the step cracks are uniform, this is considered acceptable. Horizontal cracks in the third or fourth block down indicate the block has moved due to outside pressure. They can be attributed to many factors such as improper grading, improperly functioning gutter and downspout system, etc. Normally if little or no movement has taken place and proper grading and downspouts exist, this is considered acceptable. If the wall containing the stress crack(s) has moved considerably, this will require some method of reinforcement. Basements/crawlspace that have been freshly painted or tuckpointed should be monitored for movement. This will be indicated by cracks reopening. If cracks reappear, reinforcement may be necessary. Reinforcing a basement/crawlspace wall can become expensive.

FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult at best to detect these areas when walls are finished off, or basement/crawlspace storage makes areas inaccessible. No representation is made as to the condition of these walls.

INSULATED CONCRETE FORMS (ICF'S) are formwork for concrete that stays in place as permanent building insulation for energy-efficient, cast-in-place, reinforced concrete walls, floors and roofs.

MONITOR indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

HAVE EVALUATED We recommend that the walls be re-evaluated by a structural engineer or basement/crawlspace repair company and estimates be obtained if work is required.

VAPOR BARRIER

Floors that are dirt or gravel should be covered with a vapor barrier.

MOISTURE PRESENT

Basement/crawlspace dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the home. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet. Expensive solutions to basement/crawlspace dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of causes and solutions to the presence of moisture. **No repre-sentation is made to future moisture that may appear.**

PALMER VALVE

Many older homes have a valve in the floor drain. This drain needs to remain operational.

DRAIN TILE

We offer no opinion about the existence or condition of the drain tile, as it cannot be visibly inspected.

BASEMENT ELECTRICAL OUTLETS

We recommend that you have an outlet within 6' of each appliance. The appliance you plan to install may be different than what exists, therefore the inspection includes testing a representative number of receptacles that exist. It is also recommended to have ground fault circuit interrupts for any outlet in the unfinished part of the basement and crawl spaces.



CRAWL SPACES

Crawl spaces are shallow spaces between the first level floor joist and the ground. Access to this area may be from the inside, outside or not accessible at all. Ductwork, plumbing, and electrical may be installed in the space in which access may be necessary. The floor of the crawl space may be covered with concrete, gravel, or may be the original soil. A vapor barrier may be a sheet of plastic or tar paper and installed over or under this material. The vapor barrier will deter the moisture from the earth from escaping into the crawl space and causing a musty smell. Ventilation is also important to control excess moisture buildup. Vents may be located on the outside of the house and are normally kept open in the summer and closed for the winter (where freezing may occur). The basement/crawl space diagram indicates areas that are covered and not part of a visual inspection. Every attempt is made to determine if paneling is warped, moisture stains are bleeding through, etc. Storage that blocks the visibility of a wall is not removed to examine that area. Therefore, it is important that on your walk-through before closing, you closely examine these areas. Closed crawl spaces that have vents to the outside should have insulation under the floor above the crawl space.

HAVE EVALUATED

We recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

MONITOR

Indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult at best to detect these areas when walls are finished off, or basement/crawlspace storage makes areas inaccessible. No representation is made as to the condition of these walls.

MOISTURE PRESENT

Basement/crawlspace dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the home. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet. Expensive solutions to basement/crawlspace dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of causes and solutions to the presence of moisture. **No repre-sentation is made to future moisture that may appear.**



WELLS

Examination of wells is not included in this visual inspection. It is recommended that you have well water checked for purity by the local health authorities and, if possible, a check on the flow of the well in periods of drought. A well pit should have a locked cover on it to prevent anyone from falling into the pit.

SEPTIC SYSTEMS

The check of septic systems is not included in our visual inspection. You should have the local health authorities or other qualified experts check the condition of the septic system. In order for the septic system to be checked, the house must have been occupied within the last 30 days.

WATER PIPES

Galvanized water pipes rust from the inside out and may have to be replaced within 20 to 30 years. This is usually done in two stages: horizontal piping in the basement first, and vertical pipes throughout the house later as needed. Copper pipes usually have more life expectancy and may last as long as 60 years before needing to be replaced.

HOSE BIBS

During the winter months it is necessary to make sure the outside faucets are winterized. This can be done by means of a valve located in the basement. Leave the outside faucets open to allow any water standing in the pipes to drain, preventing them from freezing. Hose bibs cannot be tested when winterized.

WATER HEATER

The life expectancy of a water heater is 5-10 years. Water heaters generally need not be replaced unless they leak. It is a good maintenance practice to drain 5-10 gallons from the heater several times a year. Missing relief valves or improper extension present a safety hazard.

WATER SOFTENERS

During a visual inspection it is not possible to determine if water is being properly softened.

PLUMBING

The temperature/pressure valve should be tested several times a year by lifting the valve's handle. Caution: very hot water will be discharged. If no water comes out, the valve is defective and must be replaced.

SHUT-OFF VALVES

Most shut-off valves have not been operated for long periods of time. We recommend operating each shut-off valve to: toilet bowl, water heater, under sinks, main shut-off, hose faucets, and all others. We recommend you have a plumber do this, as some of the valves may need to be repacked or replaced. Once the valves are in proper operating order, we recommend opening and closing these valves several times a year.

POLYBUTYLENE PIPING

This type of piping has a history of problems and should be examined by a licensed plumber and repaired or replaced as necessary.

MECHANICAL DEVICES MAY OPERATE AT ONE MOMENT AND LATER MALFUNCTION; THEREFORE, LIABILITY IS SPECIFICALLY LIMITED TO THOSE SITUATIONS WHERE IT CAN BE CONCLUSIVELY SHOWN THAT THE MECHANICAL DEVICE INSPECTED WAS INOPERABLE OR IN THE IMMEDIATE NEED OF REPAIR OR NOT PERFORMING THE FUNCTION FOR WHICH IS IT WAS INTENDED AT THE TIME OF INSPECTION.

CSST

Corrugated Stainless Steel Tubing is an alternative to traditional black iron gas piping. It is a continuous, flexible, stainless steel pipe with an exterior PVC covering.

© 2015 Scardaci Home Inspections Inc.

Page 30 of 33



HEATING AND AIR CONDITIONING units have limited lives. Normal lives are:

Gas-fired hot air units that are close to or beyond their normal lives have the potential of becoming a source of carbon monoxide in the home. You may want to have such a unit checked every year or so to assure yourself that it is still intact. Of course a unit of such an age is a good candidate for replacement with one of the new, high efficiency furnaces. The fuel savings alone can be very attractive.

Boilers and their systems may require annual attention. If you are not familiar with your system, have a heating contractor come out in the fall to show you how to do the necessary thing **Caution: do not add water to a hot boiler!**

Forced air systems should have filters changed every 30 to 60 days of the heating and cooling season. This is especially true if you have central air conditioning. A dirty air system can lead to premature failure of your compressor - a \$1,500 machine.

Oil-fired furnaces and boilers should be serviced by a professional each year. Most experts agree you will pay for the service cost in fuel saved by having a properly tuned burner.

Read the instructions for maintaining the humidifier on your furnace. A malfunctioning humidifier can rust out a furnace rather quickly. It is recommended that the humidifier be serviced at the same time as the furnace, and be cleaned regularly. **During a visual inspection it is not possible to determine if the humidifier is working.**

Have HVAC technician examine - A condition was found that suggests a heating contractor should do a further analysis. We suggest doing this before closing.

Heat exchangers cannot be examined nor their condition determined without being disassembled. Since this is not possible during a visual, non-technically exhaustive inspection, you may want to obtain a service contract on the unit or contact a furnace technician regarding a more thorough examination.

Testing pilot safety switch requires blowing out the pilot light. Checking safety limit controls requires disconnecting blower motor or using other means beyond the scope of this inspection. If the furnace has not been serviced in last 12 months you may want to have a furnace technician examine.

CO Test - This is not part of a non-technical inspection. If a test was performed, the type of tester is indicated on page 27.


Combustible Gas Detector - If a gas detector was used during the inspection of the furnace and evidence of possible combustible gases was noted, we caution you that our test instrument is sensitive to many gases and not a foolproof test. None-the-less, this presents the possibility that a hazard exists and could indicate that the heat exchanger is, or will soon be, defective.



Every effort has been made to evaluate the size of the service. Three wires going into the home indicate 240 volts. The total amperage can be difficult to determine. We highly recommend that ground fault circuit interrupters (G.F.C.I.) be connected to all outlets around water. This device automatically shuts the circuit off when it senses a current leak to ground. This device can be purchased in most hardware stores. G.F.C.I.'s are recommended by all outlets located near water, outside outlets, or garage outlets. Pool outlets should also be protected with a G.F.C.I.

See diagram below:

If you do have G.F.C.I.'s, it is recommended that you test (and reset) them monthly. When you push the test button, the reset



button should pop out, shutting off the circuit. If it doesn't, the breaker is not working properly. If you don't test them once a month, the breakers have a tendency to stick and may not protect you when eeded.

Knob and tube wiring found in older homes should be checked by an electrician to insure that the wire cover is in good condition. Under no circumstances should this wire be covered with insulation. Recess light fixtures should have a baffle around them so that they are not covered with insulation. The newer recessed fixtures will shut off if they overheat. (no representation is made as to proper recess lighting fixtures).

Federal Pacific Stab-Lok® Electrical panels may be unsafe. See www.google.com (Federal Pacific)

Aluminum wiring in general lighting circuits has a history of over heating, with the potential of a fire. If this type of wiring exists, a licensed electrical contractor should examine the whole system.

ARC FAULTS

In some areas arc Faults are required for bedrooms in new homes starting in 2002. In some areas arc Faults are required for all 120 Volt circuits that are not GFCI protected in new homes starting in 2009. Updrade as desired forenhanced safely.

REVERSE POLARITY

A common problem that surfaces in many homes is reverse polarity. This is a potentially hazardous situation in which the hot and neutral wires of a circuit are reversed at the outlet, thereby allowing the appliance to incorrectly be connected. This is an inexpensive item to correct.

Each receptacle has a brass and silver screw. The black wire should be wired to the brass screw and the white wire should go to the silver screw. When these wires are switched, this is called "reverse polarity." Turning off the power and switching these wires will correct the problem.

Main service wiring for housing is typically 240 volts. The minimum capacity for newer homes is 100 amps though many older homes still have 60 amp service. Larger homes or all electric homes will likely have a 200 amp service.

Main service wiring may be protected by one or more circuit breakers or fuses. While most areas allow up to six main turnoffs, expanding from these panels is generally not allowed.

COOLING

<u>Testing A/C System and Heat Pump</u>- The circuit breakers to A/C should be on for a minimum of 24 hours and the outside temperature at least 60 degrees for the past 24 hours or an A/C system cannot be operated without possible damage to the compressor. Check the instructions in your A/C manual or on the outside compressor before starting up in the summer. Heat pump can only be tested in the mode it's running in. Outside temperature should be at least 65° for the past 24 hours to run in cooling mode.

Temperature differential, between 14°-22°, is usually acceptable. If out of this range, have an HVAC contractor examine it. It is not always feasible to do a differential test due to high humidity, low outside temperature, etc.

A/C CONDENSER COIL They should not become overgrown with foliage. Clearance requirements vary, but 2' on all sides should be considered minimal with up to 6' of air discharge desirable. If a clothes dryer vent is within five to ten feet, either relocate the vent or do not run when the A/C is running. The lint will quickly reduce the efficiency of the A/C unit.

© 2015 Scardaci Home Inspections Inc.

COSTS OF REMODELING OR REPAIR

The prices quoted below include a range of prices based on a typical metropolitan area. Individual prices from contractors can vary substantially from these ranges. We advise that several bids be obtained on any work exceeding several hundred dollars. DO NOT RELY ON THESE PRICES... GET FURTHER ESTIMATES.

ITEM	UNIT	ESTIMATED PRICE
Masonry fireplace	Each	\$3,000 - \$6,000
Install prefab fireplace	Each	2,000 - 4,000
Insulate attic	Square foot	.75 - 1.25
Install attic ventilating fan	Each	200 - 300
Install new drywall over plaster	Square foot	1.75 - 2.75
Install new warm air furnace	Each	2,000 - 3,000
Replace central air conditioning	Each	1,400 - 2,000
Install humidifier	Each	300 - 500
Install electrostatic air cleaner	Each	800 - 1,500
Increase elec. svc. to 60-100 amps	Each	600 - 1,200
Run separate elec. line for dryer	Each	125 - 200
Run separate elec. line for A/C	Each	135 - 200
Install hardwired smoke detector	Each	100 - 180
Install new disposal	Each	250 - 400
Install new dishwasher	Each	500 - 750
Install new hot water boiler	Each	2,000 - 4,000
Install new 30-40 gal water heater	Each	350 - 650
Install new 30 gal. water heater	Each	300 - 500
Dig and install new well	Each	get estimate
Install new septic system	Each	get estimate
Regrade around exterior	Each	500 - 900
Install new sump pump and pit	Each	400 - 600
Build new redwood or pressure-	Square foot	20 - 30
treated deck	•	
Install storm windows	Each	60 - 150
Install wood replacement windows	Each	400 - 800
Install aluminum or vinyl	Each	300 - 800
replacement window		
Install new gutters and downspouts	Linear foot	3.50 - 5.00
Install asphalt shingle o/existing	Square foot	1.20 - 1.70
Tear off existing roof and install	Square foot	2.50 - 4.00
new asphalt shingle roof	1	
Instl 1-ply membrane rubberized roof	Square foot	get estimate
Instl new 4-ply built-up tar & gravel	Square foot	get estimate
Remove asbestos from pipes in bsmt	Linear foot	get estimate
Concrete drive or patio	Square foot	3.00 - 4.00
with removal of old	Square foot	2.25 - 3.00
Clean chimney flue	Each	100 - 200
Add flue liner for gas fuel		900 - 1,200
Add flue liner for oil or wood		2,800 - 3,500
		····

Deferred Costs - It is impossible to determine how long these items will last before needing replacement. The report addresses most of these items from a "condition" standpoint.

Page 33 of 33

PREVENTIVE MAINTENANCE TIPS

I. FOUNDATION and MASONRY: Basements, Exterior Walls: To prevent seepage and

condensation problems.

- a. Check basement for dampness and leakage after wet weather.
- b. Check chimneys, deteriorated chimney caps, loose and missing mortar.
- c. Maintain grading sloped away from foundation walls.

II. **ROOFS, GUTTERS, and EAVESTROUGH:** To prevent roof leaks, condensation, seepage, and decay problems.

a. Check for damaged, loose or missing shingles, blisters.

b. Clean gutters, leaders, strainers, window wells, drains. Be sure downspouts direct water away from foundation. Cut back tree limbs.

c. Check flashings around roof stacks, vents, skylights, chimneys, as sources of leakage. Check vents, louvers and chimneys for birds nests, squirrels, insects.

d. Check fascias and soffits for paint flaking, leakage and decay.

III. **EXTERIOR WALLS:** To prevent paint failure, decay, and moisture penetration problems.

a. Check painted surface for paint flaking or paint failure. Cut back shrubs.

b. Check exterior masonry walls for cracks, looseness, missing or broken mortar.

IV. DOORS AND WINDOWS: To prevent air and weather penetration problems.

a. Check caulking for decay around doors, windows, corner boards, joints. Recaulk and weatherstrip as needed. Check glazing, putty around windows.

V. ELECTRICAL: For safe electrical performance, mark and label each circuit.

a. Trip circuit breakers every six months and ground fault circuit interrupters (G.F.C.I.) monthly.

- b. Check condition of lamp cords, extension cords and plugs. Replace at first sign of wear and damage.
- c. Check exposed wiring and cable for wear or damage.

d. If you experience slight tingling shock from handling or touching any appliance, disconnect the

appliance and have it repaired. If lights flicker or dim, or if appliances go on and off unnecessarily, call a licensed electrician.

VI. **PLUMBING:** For preventive maintenance.

- a. Drain exterior water lines, hose bibbs, sprinklers, pool equipment in the fall.
- b. Draw off sediment in water heaters monthly or per manufacturer's instructions.
- c. Have septic tank cleaned every 2 years.

VII. HEATING and COOLING: For comfort, efficiency, energy conservation and safety.

a. Change or clean furnace filters, air condition filters, electronic filters as needed.

b. Clean and service humidifier. Check periodically and annually.

c. Have oil burning equipment serviced annually.

VIII. INTERIOR: General house maintenance.

a. Check bathroom tile joints, tub grouting and caulking. Be sure all tile joints in bathrooms are kept well sealed with tile grout to prevent damage to walls, floors and ceilings below.

b. Close crawl vents in winter and open in summer.

c. Check underside of roof for water stains, leaks, dampness & condensation, particularly in attics and around chimneys.

IX. Know the location of:

- Main water shutoff valve.
- Main emergency shutoff switch for the heating system.
- Main electrical disconnect or breaker.