



DEPARTMENT OF REGULATORY
AND ECONOMIC RESOURCES


MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING ELECTRICAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022



INSPECTION MADE BY: FLORIN FLOREA P.E.

SIGNATURE:

PRINT NAME: FLORIN FLOREA PE 91966 FLORIDA

TITLE: Sr Electrical Engineer

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

DESCRIPTION OF STRUCTURE

- a. Name on Title: Village at Dadeland Condominiums (B)
- b. Street Address: 7320 SW 82nd St. Miami, Florida 33143
- c. Legal Description: Village at Dadeland Condominiums
- d. Owner's Name: Village at Dadeland Condominiums
- e. Owner's Mailing Address: 7320 SW 82nd St. Miami, Florida 33143
- f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX
- g. Building Code Occupancy Classification: R2 - Residential
- h. Present Use: Condominium, Residential
- i. General Description, Type of Construction, Size, Number of Stories, and Special Features

Additional Comments:

The condominium building was built in 1968. Is a two story building comprised of concrete slab on compacted grade and stucco covered cmu exterior load bearing wall. The second floor catwalk consists of pre-cast concrete slabs, concrete tie columns and tie beams along exterior walls up to the roof level.

The roof is a low slope roof and comprised of timber trusses and plywood decking covered with a bituminous asphalt membrane. At the perimeter of the roof there are timber framed gable ends covered with asphalt shingles that also cover the building balconies and catwalks.

There is a Main Electrical Room at the rear of the building. There are multiple services at the building that are controlled by a main switch contained within the electrical room. The main switch controls power to the House Service Meter and the House Panel. The main switch also controls power to the individual condominium unit meters and breakers. The house panel serves common loads of the building.

**MINIMUM GUIDELINES AND INFORMATION FOR RECERTIFICATION OF ELECTRICAL
SYSTEMS OF FORTY (40) YEAR STRUCTURES**

1. ELECTRIC SERVICE

1. Size: Amperage (400) Fuses (☒) Breakers ()

2. Phase: Three Phase () Single Phase (☒)

3. Condition: Good () Fair () Needs Repair (☒)

Comments: Main Power (1) 400A 120/240V AC 1 Phase 3 Wire - Poor Condition Old with Rust

(1) House Panel is 125A 120/240V AC 1 Phase 3 Wire - Poor Condition Old with Rust

(1) Meter Center 600A 120/240V AC 1 Phase 3 Wire - 8 Meter each serving a 100A Branch Circuit.

2. METER AND ELECTRIC ROOM

1. Clearances: Good () Fair () Requires Correction (☒)

Comments: Main Power - Insufficient Clearance 15.5", House Panel Insufficient Clearance 23.5", and

Meter Center - Insufficient Clearance 22.5". All electrical equipment is old and has corrosion.

All electrical equipment and branch circuits shall be clearly labeled and identified.

3. GUTTERS

Location: Go od () Requires Repair (☒)

Taps and Fill: Good () Requires Repair (☒)

Comments: Observed corrosion, requires maintenance.

4. ELECTRICAL PANELS

Location: Good () Needs Repair (☒)

1. Panel #(House)

 Good () Needs Repair (☒)

2. Panel #()

 Good () Needs Repair ()

3. Panel #()

 Good () Needs Repair ()

4. Panel #()

 Good () Needs Repair ()

5. Panel #()

 Good () Needs Repair ()

Comments: Panel is old and has corrosion.

Insufficient Clearance only 23.5" at Panel. Unknown breaker is broken - Repairs Required.

5. BRANCH CIRCUITS:

1. Identified: Yes () Must be identified (☒)

2. Conductors: Good () Deteriorated () Must be replaced ()

Comments: All branch circuits must be clearly identified. Conductors not visible.

6. GROUNDING SERVICE:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or section loss at the ground bars. We recommend that grounding resistance to be tested by an electrician and repaired/replaced if necessary.

7. GROUNDING OF EQUIPMENT:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or possible section loss at the ground bars. We recommend that the grounding of equipment be replaced/repaired by an electrician.

8. SERVICE CONDUITS/RACEWAYS:

Good (☒) Repairs Required ()

Comments:

9. SERVICE CONDUCTOR AND CABLES:

Good () Repairs Required ()

Comments: Service conductors and cables were concealed.

10. TYPES OF WIRING METHODS:

Conduit Raceways:	Good	()	Repairs Required	(<input checked="" type="checkbox"/>)
Conduit PVC:	Good	()	Repairs Required	()
NM Cable:	Good	()	Repairs Required	()
BX Cable:	Good	()	Repairs Required	()

11. FEEDER CONDUCTORS:

Good	()	Repairs Required	()
------	-----------	------------------	-----------

Comments: Feeder cables were concealed.

12. EMERGENCY LIGHTING:

Good	()	Repairs Required	()
------	-----------	------------------	-----------

Comments: N/A

13. BUILDING EGRESS ILLUMINATION:

Good	()	Repairs Required	(<input checked="" type="checkbox"/>)
------	-----------	------------------	---

Comments: Light out at catwalk and egress sidewalks - Repairs Required

14. FIRE ALARM SYSTEM:

Good () Repairs Required ()

Comments: N/A

15. SMOKE DETECTORS:

Good () Repairs Required (☒)

Comments: All old smoke detectors to be replaced. Smoke detectors to be installed and maintained in all .
main electric rooms. Apartments - Not all apartments have smoke detectors in the living room, hallways,
and/or bedrooms. As observed in Units B201 all other units to be verified for compliance.

16. EXIT LIGHTS:

Good () Repairs Required ()

Comments: N/A

17. EMERGENCY GENERATOR:

Good () Repairs Required ()

Comments: N/A

18. WIRING IN OPEN OR UNDER COVER PARKING GARAGE AREAS:

Require Additional

Go od () Repairs Required ()

Comments: Wiring was concealed

19. OPEN OR UNDERCOVER PARKING GARAGE AREAS AND EGRESS ILLUMINATION:

Require Additional

Go od () Repairs Required (☒)

Comments: Open parking areas have low illumination levels creating unsafe conditions and security concerns. Additional lighting is required to illuminate the parking walking surfaces for safety and security purposes. Parking lights mounted on building is out - Repairs Required.

20. SWIMMING POOL WIRING:

Go od () Repairs Required ()

Comments: N/A

21. WIRING TO MECHANICAL EQUIPMENT:

Go od () Repairs Required (☒)

Comments: 1. Mechanical Rooftop Equipment - Repairs/Replacement Required at all oxidized electrical disconnect boxes, supports, and conduit. All disconnect switches are to be operable and inside electrical components rust free. 2. All Rooftop Mechanical Equipment and Disconnect Switches to be properly identified.

22. ADDITIONAL COMMENTS:

1. Not all apartments have GFCI type outlets in Kitchens, Bathrooms, and or Balconies - Repairs Required
2. Unit B201 - Bathroom outlets are not GFCI type, Repairs Required
3. Unit B201 - Kitchen outlets are not GFCI type, Repairs Required
4. All Kitchen Island Outlets are to be GFCI type, Repairs Required
5. Electrical outlets that have an open ground and/or are hot are to be repaired.
6. All Balcony and Patio outlets to be GFCI type and should be installed in a HD waterproof enclosure.
7. Not all balcony and/or patio outlets are GFCI type outlets, Repairs Required.
8. Not all balcony and/or patio outlets are WP type, Repairs Required.
9. Electrical Panels in the apartments have considerable oxidation and are to be replaced.
10. Electrical Panels in the apartments are missing labels and/or are not properly identified.
11. All Electrical Panels in the apartments are to be properly labeled with branch circuits clearly identified.
12. All Electric Panel covers to properly fit over circuit breakers boards.

13. Some Electrical Panel covers do not fit properly leaving lots of space around the circuit breakers.

14. All electrical panels installed 40 years or later, even though in good working order has passed its useful life and is recommended to be replaced.

SD:rs:vc:mb:js:jg:rtc1:10/12/2015:40yrtrackingsystem

15. All open outlets, switches, or junction boxes are to be repaired.

16. Unit B201 - Change Breaker not properly set in panel, repairs required.

17. Time clocks, Disconnects, and Electric Panel installed too high, repairs required.

18. Fire caulk all wall and ceiling penetrations at electric room.

Photo 1 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
No Storage Permitted

Photo 2 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
Main Switches for Apartments,
Meters, and Gutter.

Photo 3 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
Main Disconnect and Meter
Stacks

Photo 4 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
400A Main Disconnect

Photo 5 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
House Main Meter and Panel
Board - oxidized
50 year old electrical
component.

Time clocks installed too high.

Photo 6 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
House Main Distribution Panel
Board and Breakers - oxidized
50 year old electrical
components.

Covered Name Plate Rating.

Photo 7 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
Apartment Meters and Main
Gutter

Old and oxidized meter stacks.

Photo 8 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
Apartment Meters and Main
Gutter

Old and oxidized meter stacks.

Photo 9 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
Apartment Meters and Main
Gutter

Photo 10 – Village of Dadeland Condominium Association



Existing Electrical Room – 1st FL
Main Distribution – Grounding

Grounding resistance to be
tested to determine if repairs
and /or maintenance are
required.

Photo 11 – Village of Dadeland Condominium Association



Rooftop Condenser Units –
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.

Missing disconnect switches.

Photo 12 – Village of Dadeland Condominium Association



Rooftop Condenser Units –
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.


Missing disconnect switches.

Photo 13 – Village of Dadeland Condominium Association



Parking – Poorly Illuminated
Exterior lights not functional.

Photo 14 – Village of Dadeland Condominium Association




Parking – Poorly Illuminated
Exterior lights not functional.

Photo 15 – Village of Dadeland Condominium Association



Apartments – Old Electrical Panels

Photo 16 – Village of Dadeland Condominium Association



Apartments – Old Electrical Panels

Old, oxidized breaker to be replaced.

Photo 17 – Village of Dadeland Condominium Association



Apartments – Kitchen outlets

Kitchen outlets that are not GFCI type or miswired need to be replaced/corrected.

Photo 18 – Village of Dadeland Condominium Association



Apartments – Bathroom outlets

Bathroom outlets are defective or miswired.

Photo 19 – Village of Dadeland Condominium Association



Apartments – Smoke Detectors

Photo 20 – Village of Dadeland Condominium Association



Apartments – Old Smoke Detectors

Old Smoke Detectors to be replaced.



DEPARTMENT OF REGULATORY
AND ECONOMIC RESOURCES


MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING ELECTRICAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022



INSPECTION MADE BY: FLORIN FLOREA P.E.

SIGNATURE:

PRINT NAME: FLORIN FLOREA PE 91966 FLORIDA

TITLE: Sr Electrical Engineer

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

DESCRIPTION OF STRUCTURE

- a. Name on Title: Village at Dadeland Condominiums (B)
- b. Street Address: 7324 SW 82nd St. Miami, Florida 33143
- c. Legal Description: Village at Dadeland Condominiums
- d. Owner's Name: Village at Dadeland Condominiums
- e. Owner's Mailing Address: 7324 SW 82nd St. Miami, Florida 33143
- f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX
- g. Building Code Occupancy Classification: R2 - Residential
- h. Present Use: Condominium, Residential
- i. General Description, Type of Construction, Size, Number of Stories, and Special Features

Additional Comments:

The condominium building was built in 1968. Is a two story building comprised of concrete slab on compacted grade and stucco covered cmu exterior load bearing wall. The second floor catwalk consists of pre-cast concrete slabs, concrete tie columns and tie beams along exterior walls up to the roof level.

The roof is a low slope roof and comprised of timber trusses and plywood decking covered with a bituminous asphalt membrane. At the perimeter of the roof there are timber framed gable ends covered with asphalt shingles that also cover the building balconies and catwalks.

There is a Main Electrical Room at the rear of the building. There are multiple services at the building that are controlled by a main switch contained within the electrical room. The main switch controls power to the House Service Meter and the House Panel. The main switch also controls power to the individual condominium unit meters and breakers. The house panel serves common loads of the building.

**MINIMUM GUIDELINES AND INFORMATION FOR RECERTIFICATION OF ELECTRICAL
SYSTEMS OF FORTY (40) YEAR STRUCTURES**

1. ELECTRIC SERVICE

1. Size: Amperage (600) Fuses (☒) Breakers ()
2. Phase: Three Phase () Single Phase (☒)
3. Condition: Good () Fair () Needs Repair (☒)

Comments: Main Power (1) 600A 120/240V AC 1 Phase 3 Wire - Poor Condition - Old with Rust

(1) House Panel is 125A 120/240V AC 1 Phase 3 Wire - Fair Condition - 100A Main Breaker

(2) Meter Center 600A 120/240V AC 1 Phase 3 Wire - 6 Meters each serving a 100A Branch Circuit.

2. METER AND ELECTRIC ROOM

1. Clearances: Good () Fair () Requires Correction (☒)

Comments: Main Power - Insufficient Clearance 23.5", House Panel Insufficient Clearance 31.5", and
Meter Center - Insufficient Clearance 23.5". All electrical equipment is old and has corrosion.

All electrical equipment and branch circuits shall be clearly labeled and identified.

3. GUTTERS

Location: Good () Requires Repair (☒)
Taps and Fill: Good () Requires Repair (☒)

Comments: Observed corrosion, requires maintenance.

4. ELECTRICAL PANELS

Location: Good () Needs Repair (☒)

1. Panel #(House)

 Good () Needs Repair (☒)

2. Panel #(LP)

 Good (☒) Needs Repair ()

3. Panel #()

 Good () Needs Repair ()

4. Panel #()

 Good () Needs Repair ()

5. Panel #()

 Good () Needs Repair ()

Comments: LP Panel is missing rating and total amperage.

Insufficient Clearance only 31.5" at House Panel.

5. BRANCH CIRCUITS:

1. Identified: Yes () Must be identified (☒)

2. Conductors: Good () Deteriorated () Must be replaced ()

Comments: All branch circuits must be clearly identified. Conductors not visible.

6. GROUNDING SERVICE:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or section loss at the ground bars. We recommend that grounding resistance to be tested by an electrician and repaired/replaced if necessary.

7. GROUNDING OF EQUIPMENT:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or possible section loss at the ground bars. We recommend that the grounding of equipment be replaced/repaired by an electrician.

8. SERVICE CONDUITS/RACEWAYS:

Good () Repairs Required (☒)

Comments: Corrosion observed on electrical boxes, maintenance required.

9. SERVICE CONDUCTOR AND CABLES:

Good () Repairs Required ()

Comments: Service conductors and cables were concealed.

10. TYPES OF WIRING METHODS:

Conduit Raceways:	Good	()	Repairs Required	(<input checked="" type="checkbox"/>)
Conduit PVC:	Good	()	Repairs Required	()
NM Cable:	Good	()	Repairs Required	()
BX Cable:	Good	()	Repairs Required	()

11. FEEDER CONDUCTORS:

Good () Repairs Required ()

Comments: Feeder cables were concealed.

12. EMERGENCY LIGHTING:

Good () Repairs Required ()

Comments: N/A

13. BUILDING EGRESS ILLUMINATION:

Good (☒) Repairs Required ()

Comments:

14. FIRE ALARM SYSTEM:

Good (☒) Repairs Required ()

Comments: Fire Alarm panel located in Laundry Room Water Heater Room

15. SMOKE DETECTORS:

Good () Repairs Required (☒)

Comments: All old smoke detectors to be replaced. Smoke detectors to be installed and maintained in all .
main electric rooms. Apartments - Not all apartments have smoke detectors in the living room, hallways,
and/or bedrooms. As observed in Units B108, B210 all other units to be verified for compliance.

16. EXIT LIGHTS:

Good () Repairs Required ()

Comments: N/A

17. EMERGENCY GENERATOR:

Good () Repairs Required ()

Comments: N/A

18. WIRING IN OPEN OR UNDER COVER PARKING GARAGE AREAS:

Require Additional

Go od () Repairs Required ()

Comments: Wiring was concealed

19. OPEN OR UNDERCOVER PARKING GARAGE AREAS AND EGRESS ILLUMINATION:

Require Additional

Go od () Repairs Required (☒)

Comments: Open parking areas have low illumination levels creating unsafe conditions and security concerns. Additional lighting is required to illuminate the parking walking surfaces for safety and security purposes. Parking light mounted on building is out - Repairs Required.

20. SWIMMING POOL WIRING:

Go od () Repairs Required ()

Comments: N/A

21. WIRING TO MECHANICAL EQUIPMENT:

Go od () Repairs Required (☒)

Comments: 1. Mechanical Rooftop Equipment - Repairs/Replacement Required at all oxidized electrical disconnect boxes, supports, and conduit. All disconnect switches are to be operable and inside electrical components rust free. 2. All Rooftop Mechanical Equipment and Disconnect Switches to be properly identified.

22. ADDITIONAL COMMENTS:

1. Not all apartments have GFCI type outlets in Kitchens, Bathrooms, and or Balconies - Repairs Required
2. Unit B210 - Bathroom outlets are not GFCI type, Repairs Required
3. Unit B210 - Kitchen outlets are not GFCI type, Repairs Required
4. All Kitchen Island Outlets are to be GFCI type, Repairs Required
5. Electrical outlets that have an open ground and/or are hot are to be repaired.
6. All Balcony and Patio outlets to be GFCI type and should be installed in a HD waterproof enclosure.
7. Unit B210 - Not all balcony and/or patio outlets are GFCI type outlets, Repairs Required.
8. Not all balcony and/or patio outlets are WP type, Repairs Required.
9. Electrical Panels in the apartments have considerable oxidation and are to be replaced.
10. Electrical Panels in the apartments are missing labels and/or are not properly identified.
11. All Electrical Panels in the apartments are to be properly labeled with branch circuits clearly identified.
12. All Electric Panel covers to properly fit over circuit breakers boards.

13. Some Electrical Panel covers do not fit properly leaving lots of space around the circuit breakers.

14. All electrical panels installed 40 years or later, even though in good working order has passed its useful life and is recommended to be replaced.

SD:rs:vc:mb:js:jg:rtc1:10/12/2015:40yrtrackingsystem

15. All open outlets, switches, or junction boxes are to be repaired.

16. Unit B108, B209 - Open Neutral Wiring or Open Ground at bathroom or Kitchen outlet, repairs required.

17. Time clocks, Disconnects, and Electric Panel installed too high, repairs required.

18. Outlets in laundry room and water heater room are not GFCI - Repairs Required.

19. Fire caulk all wall and ceiling penetrations at electric room.

Photo 1 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
No Storage Permitted

Building Number sign is missing.

Photo 2 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Switches for Apartments,
Meters, and Gutter.

Photo 3 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Disconnect and Meter
Stacks

Photo 4 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Building Main Disconnect -
considerably oxidized.
50 year old electrical
component.

Photo 5 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Building Main Disconnect (top
view) - considerably oxidized.
50 year old electrical
component.

Photo 6 – Village of Dadeland Condominium Association




Existing Electrical Room - 1st FL
Building Main Disconnect (front
view)-oxidized.
50 year old electrical
component.

Photo 7 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Main Meter and Panel
Board

Photo 8 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Main Distribution Panel
Board and Breakers

Name Plate Rating Covered.


Photo 9 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters and switches

Old and oxidized meter stacks.


Photo 10 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters and Main
Gutter

Old and oxidized meter stacks
and breakers.

Photo 11 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters and Main
Gutter

Old and oxidized meter stacks
and gutter.


Photo 12 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Distribution – Grounding

Grounding resistance to be
tested to determine if repairs
and /or maintenance are
required.

Photo 13 – Village of Dadeland Condominium Association



Rooftop Condenser Units -
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.

Missing disconnect switches.

Photo 14 – Village of Dadeland Condominium Association



Rooftop Condenser Units -
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.


Missing disconnect switches.

Photo 15 – Village of Dadeland Condominium Association



Laundry/Water heater room:
Fire Alarm Panel

Photo 16 – Village of Dadeland Condominium Association



Existing Main electrical room:
Fire Alarm - Old and Weathered
Fire Alarm Devices and Control
Center

All old Smoke Alarm Devices to
be replaced.
This device is not properly
connected.
All wall penetrations to be fire
caulked.

Photo 17 – Village of Dadeland Condominium Association




Level 1:

Fire Alarm - Old and Weathered
Fire Alarm Devices and Control
Center

Old Strobe Horn/Strobe Device
and Pull Stations

Photo 18 – Village of Dadeland Condominium Association



Level 2

Fire Alarm - Old and Weathered
Fire Alarm Devices and Control
Center


Old Strobe Horn/Strobe Device
and Pull Stations

Photo 19 – Village of Dadeland Condominium Association



Parking:
Poorly Illuminated
Exterior lights not functional.

Photo 20 – Village of Dadeland Condominium Association




Laundry Room - Outlets are not
GFCI type.

Photo 21 – Village of Dadeland Condominium Association



Laundry Room - Outlets are not GFCI type.

Photo 22 – Village of Dadeland Condominium Association



Laundry Room:
Old smoke detector

Photo 23 – Village of Dadeland Condominium Association




Apartments - Old Electrical
Panels

Photo 24 – Village of Dadeland Condominium Association



Apartments - Old Electrical
Panels

Photo 25 – Village of Dadeland Condominium Association




Apartments - Kitchen outlets
not GFCI type

Photo 26 – Village of Dadeland Condominium Association



Apartments - the GFCI outlets in
bathroom are defective or
miswired.

Photo 27 – Village of Dadeland Condominium Association



Apartments - Balcony/Patio outlets not GFCI type.

Photo 28 – Village of Dadeland Condominium Association



Apartments - Old Smoke Detectors

Old Smoke Detectors to be replaced.



DEPARTMENT OF REGULATORY
AND ECONOMIC RESOURCES


MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING ELECTRICAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022



INSPECTION MADE BY: FLORIN FLOREA P.E

SIGNATURE:

PRINT NAME: FLORIN FLOREA PE 91966 FLORIDA

TITLE: Sr Electrical Engineer

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

DESCRIPTION OF STRUCTURE

- a. Name on Title: Village at Dadeland Condominiums (B)
- b. Street Address: 7328 SW 82nd St. Miami, Florida 33143
- c. Legal Description: Village at Dadeland Condominiums
- d. Owner's Name: Village at Dadeland Condominiums
- e. Owner's Mailing Address: 7328 SW 82nd St. Miami, Florida 33143
- f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX
- g. Building Code Occupancy Classification: R2 - Residential
- h. Present Use: Condominium, Residential
- i. General Description, Type of Construction, Size, Number of Stories, and Special Features

Additional Comments:

The condominium building was built in 1968. Is a two story building comprised of concrete slab on compacted grade and stucco covered cmu exterior load bearing wall. The second floor catwalk consists of pre-cast concrete slabs, concrete tie columns and tie beams along exterior walls up to the roof level.

The roof is a low slope roof and comprised of timber trusses and plywood decking covered with a bituminous asphalt membrane. At the perimeter of the roof there are timber framed gable ends covered with asphalt shingles that also cover the building balconies and catwalks.

There is a Main Electrical Room at the rear of the building. There are multiple services at the building that are controlled by a main switch contained within the electrical room. The main switch controls power to the House Service Meter and the House Panel. The main switch also controls power to the individual condominium unit meters and breakers. The house panel serves common loads of the building.

**MINIMUM GUIDELINES AND INFORMATION FOR RECERTIFICATION OF ELECTRICAL
SYSTEMS OF FORTY (40) YEAR STRUCTURES**

1. ELECTRIC SERVICE

1. Size: Amperage (600) Fuses (☒) Breakers ()

2. Phase: Three Phase () Single Phase (☒)

3. Condition: Good () Fair () Needs Repair (☒)

Comments: Main Power (1) 400A 120/240V AC 1 Phase 3 Wire - Poor Condition Old with Rust

(1) House Panel is 125A 120/240V AC 1 Phase 3 Wire - Poor Condition Old with Rust

(1) Meter Center 600A 120/240V AC 1 Phase 3 Wire - 8 Meters each serving a 100A Branch Circuit.

2. METER AND ELECTRIC ROOM

1. Clearances: Good () Fair () Requires Correction (☒)

Comments: Main Power - Insufficient Clearance 24", House Panel Insufficient Clearance 31" and 80"H, and

Meter Center - Insufficient Clearance 22" & 24". All electrical equipment is old and has corrosion.

All electrical equipment and branch circuits shall be clearly labeled and identified.

3. GUTTERS

Location: Good () Requires Repair (☒)

Taps and Fill: Good () Requires Repair (☒)

Comments: Observed corrosion, requires maintenance.

4. ELECTRICAL PANELS

Location: Good () Needs Repair (☒)

1. Panel #(House)

 Good () Needs Repair (☒)

2. Panel #()

 Good () Needs Repair ()

3. Panel #()

 Good () Needs Repair ()

4. Panel #()

 Good () Needs Repair ()

5. Panel #()

 Good () Needs Repair ()

Comments: Panel is old and has corrosion. Panel door falling off.

Insufficient Clearance only 31" at Panel and panel is installed 80" above the finished floor.

5. BRANCH CIRCUITS:

1. Identified: Yes () Must be identified (☒)

2. Conductors: Good () Deteriorated () Must be replaced ()

Comments: All branch circuits must be clearly identified. Conductors not visible.

6. GROUNDING SERVICE:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or section loss at the ground bars. We recommend that grounding resistance to be tested by an electrician and repaired/replaced if necessary.

7. GROUNDING OF EQUIPMENT:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or possible section loss at the ground bars. We recommend that the grounding of equipment be replaced/repaired by an electrician.

8. SERVICE CONDUITS/RACEWAYS:

Good (☒) Repairs Required ()

Comments:

9. SERVICE CONDUCTOR AND CABLES:

Good () Repairs Required ()

Comments: Service conductors and cables were concealed.

10. TYPES OF WIRING METHODS:

Conduit Raceways:	Good	()	Repairs Required	(<input checked="" type="checkbox"/>)
Conduit PVC:	Good	()	Repairs Required	()
NM Cable:	Good	()	Repairs Required	()
BX Cable:	Good	()	Repairs Required	()

11. FEEDER CONDUCTORS:

Good () Repairs Required ()

Comments: Feeder cables were concealed.

12. EMERGENCY LIGHTING:

Good () Repairs Required ()

Comments: N/A

13. BUILDING EGRESS ILLUMINATION:

Good () Repairs Required (☒)

Comments: Insufficient light at catwalks - Repairs Required

14. FIRE ALARM SYSTEM:

Good () Repairs Required ()

Comments: N/A

15. SMOKE DETECTORS:

Good () Repairs Required (☒)

Comments: All old smoke detectors to be replaced. Smoke detectors to be installed and maintained in all .
main electric rooms. Apartments - Not all apartments have smoke detectors in the living room, hallways,
and/or bedrooms. All units to be verified for compliance.

16. EXIT LIGHTS:

Good () Repairs Required ()

Comments: N/A

17. EMERGENCY GENERATOR:

Good () Repairs Required ()

Comments: N/A

18. WIRING IN OPEN OR UNDER COVER PARKING GARAGE AREAS:

Require Additional

Go od () Repairs Required ()

Comments: Wiring was concealed

19. OPEN OR UNDERCOVER PARKING GARAGE AREAS AND EGRESS ILLUMINATION:

Require Additional

Go od () Repairs Required (☒)

Comments: Open parking areas have low illumination levels creating unsafe conditions and security concerns. Additional lighting is required to illuminate the parking walking surfaces for safety and security purposes. Parking lights mounted on other buildings are out - Repairs Required.

20. SWIMMING POOL WIRING:

Go od () Repairs Required ()

Comments: N/A

21. WIRING TO MECHANICAL EQUIPMENT:

Go od () Repairs Required (☒)

Comments: 1. Mechanical Rooftop Equipment - Repairs/Replacement Required at all oxidized electrical disconnect boxes, supports, and conduit. All disconnect switches are to be operable and inside electrical components rust free. 2. All Rooftop Mechanical Equipment and Disconnect Switches to be properly identified.

22. ADDITIONAL COMMENTS:

1. Not all apartments have GFCI type outlets in Kitchens, Bathrooms, and or Balconies - Repairs Required
2. Unit B212 - Bathroom outlets are not GFCI type, Repairs Required
3. Unit B212, B213 - Kitchen outlets are not GFCI type, Repairs Required
4. All Kitchen Island Outlets are to be GFCI type, Repairs Required
5. Electrical outlets that have an open ground and/or are hot are to be repaired.
6. All Balcony and Patio outlets to be GFCI type and should be installed in a HD waterproof enclosure.
7. Unit B210 - Not all balcony and/or patio outlets are GFCI type outlets, Repairs Required.
8. Not all balcony and/or patio outlets are WP type, Repairs Required.
9. Electrical Panels in the apartments have considerable oxidation and are to be replaced.
10. Electrical Panels in the apartments are missing labels and/or are not properly identified.
11. All Electrical Panels in the apartments are to be properly labeled with branch circuits clearly identified.
12. All Electric Panel covers to properly fit over circuit breakers boards.

13. Some Electrical Panel covers do not fit properly leaving lots of space around the circuit breakers.

14. All electrical panels installed 40 years or later, even though in good working order has passed its useful life and is recommended to be replaced.

SD:rs:vc:mb:js:jg:rtc1:10/12/2015:40yrtrackingsystem

15. All open outlets, switches, or junction boxes are to be repaired.

16. All Open Neutral Wiring or Open Ground at bathrooms or Kitchens outlet, repairs required.

17. Time clocks, Disconnects, and Electric Panel installed too high, repairs required.

18. Fire caulk all wall and ceiling penetrations at electric room.

Photo 1 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
No storage permitted.

Photo 2 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Switches for Apartments,
Meters, and Gutter.

Photo 3 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Building Disconnect
considerably oxidized.
50 year old electrical
component.

Photo 4 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Main Meter and Panel
Board oxidized.
50 year old electrical
component.

Photo 5 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Main Meter and Panel
Board are oxidized.
50 year old electrical
component.

Oxidized time clock

Photo 6 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Panel Board and breakers
are oxidized.
50 year old electrical
components.

Missing Name Plate Rating.


Photo 7 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters and Main
Switches.

Old and oxidized meter stacks.

Photo 8 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters, Main
Switches and Gutter.

Old and oxidized meter stacks.

Photo 9 – Village of Dadeland Condominium Association




Existing Electrical Room - 1st FL
Apartment Meters, Main
Switches and Gutter.

Old and oxidized meter stacks.

Insufficient clearance at meters
and main disconnect switches.

Photo 10 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Service – Grounding

Grounding resistance to be
tested to determine if repairs
and /or maintenance are
required.

Photo 11 – Village of Dadeland Condominium Association



Rooftop Condenser Units -
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.

Missing disconnect switches.

Photo 12 – Village of Dadeland Condominium Association



Rooftop Condenser Units -
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.

Missing disconnect switches.

Photo 13 – Village of Dadeland Condominium Association



Parking - Poorly Illuminated
Exterior light not functional.

No light fixture over section of
the catwalk.

Photo 14 – Village of Dadeland Condominium Association



Parking - Poorly Illuminated
Exterior light not functional.

No light fixture over section of
the catwalk.

Photo 15 – Village of Dadeland Condominium Association



Apartments - Old Electrical
Panels

Photo 16 – Village of Dadeland Condominium Association




Apartments - Old Electrical
Panels

Photo 17 – Village of Dadeland Condominium Association



Apartments - Kitchen outlets
not GFCI type.

Photo 18 – Village of Dadeland Condominium Association



Apartments - Bathroom outlets
not GFCI type.

Photo 19 – Village of Dadeland Condominium Association



Apartments - Old Smoke
Detectors

Old Smoke Detectors to be
replaced.
This photo is an example.



DEPARTMENT OF REGULATORY
AND ECONOMIC RESOURCES


MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING ELECTRICAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022



INSPECTION MADE BY: FLORIN FLOREA P.E.

SIGNATURE: _____

PRINT NAME: FLORIN FLOREA PE 91966 FLORIDA

TITLE: Sr Electrical Engineer

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

DESCRIPTION OF STRUCTURE

a. Name on Title: Village at Dadeland Condominiums (B)

b. Street Address: 7330 SW 82nd St. Miami, Florida 33143

c. Legal Description: Village at Dadeland Condominiums

d. Owner's Name: Village at Dadeland Condominiums

e. Owner's Mailing Address: 7330 SW 82nd St. Miami, Florida 33143

f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX

g. Building Code Occupancy Classification: R2 - Residential

h. Present Use: Condominium, Residential

i. General Description, Type of Construction, Size, Number of Stories, and Special Features

Additional Comments:

The condominium building was built in 1968. Is a two story building comprised of concrete slab on compacted grade and stucco covered cmu exterior load bearing wall. The second floor catwalk consists of pre-cast concrete slabs, concrete tie columns and tie beams along exterior walls up to the roof level.

The roof is a low slope roof and comprised of timber trusses and plywood decking covered with a bituminous asphalt membrane. At the perimeter of the roof there are timber framed gable ends covered with asphalt shingles that also cover the building balconies and catwalks.

There is a Main Electrical Room at the rear of the building. There are multiple services at the building that are controlled by a main switch contained within the electrical room. The main switch controls power to the House Service Meter and the House Panel. The main switch also controls power to the individual condominium unit meters and breakers. The house panel serves common loads of the building.

**MINIMUM GUIDELINES AND INFORMATION FOR RECERTIFICATION OF ELECTRICAL
SYSTEMS OF FORTY (40) YEAR STRUCTURES**

1. ELECTRIC SERVICE

1. Size: Amperage (400) Fuses (☒) Breakers ()

2. Phase: Three Phase () Single Phase (☒)

3. Condition: Good () Fair () Needs Repair (☒)

Comments: Main Power (1) 600A 120/240V AC 1 Phase 3 Wire - Poor Condition - Old with Rust

(1) House Panel is 125A 120/240V AC 1 Phase 3 Wire - Poor Condition - Old with Rust

(1) Meter Center 600A 120/240V AC 1 Phase 3 Wire - 8 Meters each serving a 100A Branch Circuit.

2. METER AND ELECTRIC ROOM

1. Clearances: Good () Fair () Requires Correction (☒)

Comments: Main Power - Insufficient Clearance 18", House Panel Insufficient Clearance 30" and 82"H, and
Meter Center - Insufficient Clearance 25". All electrical equipment is old and has corrosion.

All electrical equipment and branch circuits shall be clearly labeled and identified.

3. GUTTERS

Location: Go od () Requires Repair (☒)

Taps and Fill: Good () Requires Repair (☒)

Comments: Observed corrosion, requires maintenance.

4. ELECTRICAL PANELS

Location: Good () Needs Repair (☒)

1. Panel #(House)

Good () Needs Repair (☒)

2. Panel #()

Good () Needs Repair ()

3. Panel #()

Good () Needs Repair ()

4. Panel #()

Good () Needs Repair ()

5. Panel #()

Good () Needs Repair ()

Comments: Panel is missing branch circuit directory. Panel is old and has corrosion. Panel door is falling off.

Insufficient Clearance only 30" at Panel. Panel is installed at 82" above the finished floor to the top breaker.

5. BRANCH CIRCUITS:

1. Identified: Yes () Must be identified (☒)

2. Conductors: Good () Deteriorated () Must be replaced ()

Comments: All branch circuits must be clearly identified. Conductors not visible.

6. GROUNDING SERVICE:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or possible section loss at the ground bars. We recommend that the grounding of equipment be replaced/repared by an electrician.

7. GROUNDING OF EQUIPMENT:

Good () Repairs Required (☒)

Comments: Observed corrosion and/or section loss at the ground bars. We recommend that this system be megger tested by an electrician and replaced if necessary.

8. SERVICE CONDUITS/RACEWAYS:

Good (☒) Repairs Required ()

Comments:

9. SERVICE CONDUCTOR AND CABLES:

Good () Repairs Required ()

Comments: Service conductors and cables were concealed.

10. TYPES OF WIRING METHODS:

Conduit Raceways:	Good	()	Repairs Required	(<input checked="" type="checkbox"/>)
Conduit PVC:	Good	()	Repairs Required	()
NM Cable:	Good	()	Repairs Required	()
BX Cable:	Good	()	Repairs Required	()

11. FEEDER CONDUCTORS:

Good () Repairs Required ()

Comments: Feeder cables were concealed.

12. EMERGENCY LIGHTING:

Good () Repairs Required ()

Comments: N/A

13. BUILDING EGRESS ILLUMINATION:

Good () Repairs Required (☒)

Comments: Light Out at catwalk - repairs required

14. FIRE ALARM SYSTEM:

Good () Repairs Required ()

Comments: N/A

15. SMOKE DETECTORS:

Good () Repairs Required (☒)

Comments: All old smoke detectors to be replaced. Smoke detectors to be installed and maintained in all .
main electric rooms. Apartments - Not all apartments have smoke detectors in the living room, hallways,
and/or bedrooms. As observed in Units B218 all other units to be verified for compliance.

16. EXIT LIGHTS:

Good () Repairs Required ()

Comments: N/A

17. EMERGENCY GENERATOR:

Good () Repairs Required ()

Comments: N/A

18. WIRING IN OPEN OR UNDER COVER PARKING GARAGE AREAS:

Require Additional

Go od () Repairs Required ()

Comments: Wiring was concealed

19. OPEN OR UNDERCOVER PARKING GARAGE AREAS AND EGRESS ILLUMINATION:

Require Additional

Go od () Repairs Required (☒)

Comments: Open parking areas have low illumination levels creating unsafe conditions and security concerns. Additional lighting is required to illuminate the parking walking surfaces for safety and security purposes. Parking lights mounted on other buildings are out - Repairs Required.

20. SWIMMING POOL WIRING:

Go od () Repairs Required ()

Comments: N/A

21. WIRING TO MECHANICAL EQUIPMENT:

Go od () Repairs Required (☒)

Comments: 1. Mechanical Rooftop Equipment - Repairs/Replacement Required at all oxidized electrical disconnect boxes, supports, and conduit. All disconnect switches are to be operable and inside electrical components rust free. 2. All Rooftop Mechanical Equipment and Disconnect Switches to be properly identified.

22. ADDITIONAL COMMENTS:

1. Not all apartments have GFCI type outlets in Kitchens, Bathrooms, and or Balconies - Repairs Required
2. Unit B218 - Bathroom outlets are not GFCI type, Repairs Required
3. Unit B218 - Kitchen outlets are not GFCI type, Repairs Required
4. All Kitchen Island Outlets are to be GFCI type, Repairs Required
5. Electrical outlets that have an open ground and/or are hot are to be repaired.
6. All Balcony and Patio outlets to be GFCI type and should be installed in a HD waterproof enclosure.
7. Not all balcony and/or patio outlets are GFCI type outlets, Repairs Required.
8. Not all balcony and/or patio outlets are WP type, Repairs Required.
9. Electrical Panels in the apartments have considerable oxidation and are to be replaced.
10. Electrical Panels in the apartments are missing labels and/or are not properly identified.
11. All Electrical Panels in the apartments are to be properly labeled with branch circuits clearly identified.
12. All Electric Panel covers to properly fit over circuit breakers boards.
13. Some Electrical Panel covers do not fit properly leaving lots of space around the circuit breakers.
14. All electrical panels installed 40 years or later, even though in good working order has passed its useful life and is recommended to be replaced.
15. All open outlets, switches, or junction boxes are to be repaired.
16. Unit B218 - Open Neutral Wiring or Open Ground at bathroom or Kitchen outlet, repairs required.
17. Time clocks, Disconnects, and Electric Panel installed too high, repairs required.
18. Electric Panel in Unit B218 is blocked, all panels to have unobstructed clearance - Repairs Required.
19. Fire caulk all wall and ceiling penetrations at electric room.


SD:rs:vc:mb:js:jg:rtc1:10/12/2015:40yrtrackingsystem

Photo 1 – Village of Dadeland Condominium Association




Existing Electrical Room - 1st FL
No storage permitted.

Photo 2 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Switches for Apartments,
Meters, and Gutter.

Photo 3 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Building Main Disconnect
considerably oxidized.
50 year old electrical
component.

Photo 4 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Main Meter and Panel
Board are oxidized.
50 year old electrical
component.

Broken Panel Door.

Severely oxidized top of Main
Disconnect.

Photo 5 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
House Panel Board and Meter –
oxidized.

50 year old electrical
component.

Missing Name Plate Rating.

Photo 6 – Village of Dadeland Condominium Association




Existing Electrical Room - 1st FL
House Panel Board and
Breakers are oxidized.

50 year old electrical
components.

Broken panel door.

Photo 7 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters, Main
Switches and Gutter

Old and oxidized meter stacks.

Photo 8 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Apartment Meters and Main
Gutter

Old and oxidized meter stacks.

Photo 9 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL

Insufficient clearance at meters and Main Disconnect Switch.

Photo 10 – Village of Dadeland Condominium Association



Existing Electrical Room - 1st FL
Main Service - Grounding

Grounding resistance to be tested to determine if repairs and /or maintenance are required.

Photo 11 – Village of Dadeland Condominium Association



Rooftop Condenser Units -
Oxidized junction boxes and
conduits.

Junction boxes not properly
supported.

Missing disconnect switches.

Photo 12 – Village of Dadeland Condominium Association



Parking/Catwalks/ Sidewalks -
Poorly Illuminated
Exterior light not functional.

Photo 13 – Village of Dadeland Condominium Association



Catwalks - Poorly illuminated.
Exterior light not functional.


No light fixture over this section
of the catwalk.

Photo 14 – Village of Dadeland Condominium Association



Apartments - Old Electrical
Panels

Photo 15 – Village of Dadeland Condominium Association



Apartments - Old Electrical Panels

Panel is not accessible as it is blocked by cabinet/shelves.

Photo 16 – Village of Dadeland Condominium Association



Apartments - Kitchen outlets not GFCI type.

Photo 17 – Village of Dadeland Condominium Association



Apartments - Balcony/Patio outlets not GFCI type.

Photo 18 – Village of Dadeland Condominium Association



Apartments - Old Smoke Detectors

Old Smoke Detectors to be replaced.
Photo is an Example

October 3, 2022

To: Building Department Official

City of Miami-Dade, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominiums
7320 SW 82nd St, Miami, FL 33143
Structural Repairs for Building Recertification
Parcel #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge based on the visual inspection of exposed structural members, the building located at said address is structurally safe for continued occupancy while the concrete repairs are performed.

The association of Village at Dadeland Condominiums must submit all necessary repairs documents and specifications to the City Miami Dade Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered structural members could be visual inspected.

Please contact me with any concerns at (305) 676-9888.

Digitally signed by Jason Borden
Contact Info: 305-676-9888
Date: 2023.05.19 16:04:51-04'00'

Respectfully,

Jason Borden, P.E.

Regional Director

O&S Associates, Inc. – Engineers & Architects

jborden@OandSassociates.com

October 3, 2022

To: Building Department Official

City of Miami-Dade, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominiums
7324 SW 82nd St, Miami, FL 33143
Structural Repairs for Building Recertification
Parcel #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge based on the visual inspection of exposed structural members, the building located at said address is structurally safe for continued occupancy while the concrete repairs are performed.

The association of Village at Dadeland Condominiums must submit all necessary repairs documents and specifications to the City Miami Dade Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered structural members could be visual inspected.

Please contact me with any concerns at (305) 676-9888.

Digitally signed by Jason Borden
Contact Info: 305-676-9888
Date: 2023.05.19 16:04:32-04'00'

Respectfully,

Jason Borden, P.E.

Regional Director

O&S Associates, Inc. – Engineers & Architects

jborden@OandSassociates.com

October 3, 2022

To: Building Department Official

City of Miami-Dade, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominiums
7328 SW 82nd St, Miami, FL 33143
Structural Repairs for Building Recertification
Parcel #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge based on the visual inspection of exposed structural members, the building located at said address is structurally safe for continued occupancy while the concrete repairs are performed.

The association of Village at Dadeland Condominiums must submit all necessary repairs documents and specifications to the City Miami Dade Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered structural members could be visual inspected.

Please contact me with any concerns at (305) 676-9888.

Digitally signed by Jason Borden
Contact Info: 305-676-9888
Date: 2023.05.19 16:05:51-04'00'



Respectfully,

Jason Borden, P.E.

Regional Director

O&S Associates, Inc. – Engineers & Architects

jborden@OandSassociates.com

October 3, 2022

To: Building Department Official

City of Miami-Dade, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominiums
7330 SW 82nd St, Miami, FL 33143
Structural Repairs for Building Recertification
Parcel #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge based on the visual inspection of exposed structural members, the building located at said address is structurally safe for continued occupancy while the concrete repairs are performed.

The association of Village at Dadeland Condominiums must submit all necessary repairs documents and specifications to the City Miami Dade Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered structural members could be visual inspected.

Please contact me with any concerns at (305) 676-9888.

Digitally signed by Jason Borden
Contact Info: 305-676-9888
Date: 2023.05.19 16:07:01 -04'00'

Respectfully,

Jason Borden, P.E.

Regional Director

O&S Associates, Inc. – Engineers & Architects

jborden@OandSassociates.com

May 24, 2023

To: Building Department Official

Miami-Dade County, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominium Association
7320 SW 82nd St, Miami, FL 33143
Electrical Repairs for Building Recertification
Folio #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge, based on the visual inspection of observable elements of the building electrical system, the building located at the above noted address is safe for continued occupancy while the electrical repairs are performed.

The Village at Dadeland Condominium Association must submit all necessary repairs documents and specifications to the Miami-Dade County Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the electrical system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered electrical conduits or wiring could be visually inspected.

Please contact me with any concerns at (305) 676-9888.

Respectfully,
Florin Florea, P.E.
Electrical Engineer

O&S Associates, Inc. – Engineers & Architects



May 24, 2023

To: Building Department Official

Miami-Dade County, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominium Association
7324 SW 82nd St, Miami, FL 33143
Electrical Repairs for Building Recertification
Folio #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge, based on the visual inspection of observable elements of the building electrical system, the building located at the above noted address is safe for continued occupancy while the electrical repairs are performed.


The Village at Dadeland Condominium Association must submit all necessary repairs documents and specifications to the Miami-Dade County Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the electrical system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered electrical conduits or wiring could be visually inspected.

Please contact me with any concerns at (305) 676-9888.

Respectfully,
Florin Florea, P.E.
Electrical Engineer

O&S Associates, Inc. – Engineers & Architects



May 24, 2023

To: Building Department Official

Miami-Dade County, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominium Association
7328 SW 82nd St, Miami, FL 33143
Electrical Repairs for Building Recertification
Folio #: 30-4035-047-XXXX


Dear Recipient,

To the best of my knowledge, based on the visual inspection of observable elements of the building electrical system, the building located at the above noted address is safe for continued occupancy while the electrical repairs are performed.

The Village at Dadeland Condominium Association must submit all necessary repairs documents and specifications to the Miami-Dade County Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the electrical system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered electrical conduits or wiring could be visually inspected.

Please contact me with any concerns at (305) 676-9888.



Respectfully,
Florin Florea, P.E.
Electrical Engineer

O&S Associates, Inc. – Engineers & Architects

May 24, 2023

To: Building Department Official

Miami-Dade County, FL
11805 SW 26th Street,
Miami, FL 33175.

RE: Village at Dadeland Condominium Association
7330 SW 82nd St, Miami, FL 33143
Electrical Repairs for Building Recertification
Folio #: 30-4035-047-XXXX

Dear Recipient,

To the best of my knowledge, based on the visual inspection of observable elements of the building electrical system, the building located at the above noted address is safe for continued occupancy while the electrical repairs are performed.

The Village at Dadeland Condominium Association must submit all necessary repairs documents and specifications to the Miami-Dade County Building Department within 180 days as described in the Miami-Dade County Building Safety Inspection requirements.

As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the electrical system. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible. There was no destructive testing done at the building and none of the covered electrical conduits or wiring could be visually inspected.

Please contact me with any concerns at (305) 676-9888.

Respectfully,
Florin Florea, P.E.
Electrical Engineer

O&S Associates, Inc. – Engineers & Architects





REGULATORY AND ECONOMIC RESOURCES
DEPARTMENT

MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING STRUCTURAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022

Digitally signed by

Jason Borden

Contact Info:

305-676-9888

Date: 2022.10.13

11:37:23-04'00'

INSPECTION MADE BY: JASON BORDEN P.E.

SIGNATURE:

PRINT NAME: JASON BORDEN P.E.

TITLE: REGIONAL MANAGER

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

1. DESCRIPTION OF STRUCTURE

a. Name on Title: Village at Dadeland Condominiums (B)

b. Street Address: 7320 SW 82nd St. Miami, Florida 33143

c. Legal Description: Village at Dadeland Condominiums

d. Owner's Name: Village at Dadeland Condominiums

e. Owner's Mailing Address: 7320 SW 82nd St. Miami, Florida 33143

f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX

g. Building Code Occupancy Classification: Condominium, Residential

h. Present Use: Condominium, Residential

i. General Description: The 2-story eight unit building at the Village at Dadeland Condominium has an approximate footprint of 90ftx35ft. Building 7320

is 1 of 4 buildings that comprise the VILLA "B" area of the community and was constructed circa 1970. Two stairs located on the south front elevation.

of the building provide access to the 2nd floor catwalk. The building has a bituminous built-up flat roof with perimeter shingled mansard roof elements.

Addition Comments: The roof is supported by 2ft tall wood trusses spaced at approximately 2ft on center. Interior main drain lines are located throughout

the roofs with emergency scuppers/openings located at the mansard roof elements. The interior main drain lines are protected with metal strainers.

The exterior concrete/masonry are covered with a flat stucco finish. The 2nd floor is supported by concrete slabs that bear on concrete beams/columns/walls.

Cantilevered concrete beams support the 2nd floor catwalk. Concrete walls and beams support the rear concrete floor balconies. Small mechanical equipment

sits atop the steel dunnage systems above the main flat roof.

j. Additions to original structure:	N/A

2. PRESENT CONDITION OF STRUCTURE	
a. General alignment (Note: good, fair, poor, explain if significant)	
1. Bulging	None observed
2. Settlement	None observed
3. Deflections	None observed
4. Expansion	None observed
5. Contraction	None observed
b. Portion showing distress (Note, beams, columns, structural walls, floor, roofs, other)	
1.Hairline to Fine Cracks noted on the exterior walls. 2.Extensive ponding and weathering of the built-up bituminous roof was noted 3.The shingles of the mansard roofs are weathered down 4.Isolated/small unsound areas of the wall stucco/concrete/masonry surfaces were discovered by our visual and sounding inspection efforts. 5.Some unsound areas detected on the front and rear exterior concrete beams. 6.Clogged drain strainers were observed at different locations. 7.The protective paint/membrane of concrete catwalks have begun to chip away exposing the concrete below.	
c. Surface conditions – describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration and stains.	
1. The exterior stucco finish was found to be generally in fair condition. Localized isolated small to moderate size areas of unsound stucco/concrete/masonry surfaces were discovered.	
2. Heavy staining and small unsound areas of the exterior concrete beams detected.	
d. Cracks – note location in significant members. Identify crack size as HAIRLINE if barely discernible; FINE if less than 1 mm in width; MEDIUM if between 1 and 2 mm width; WIDE if over 2 mm.	
Hairline and fine cracks noted on the stucco finish on the ceiling and wall surfaces.	

e. General extent of deterioration – cracking or spalling of concrete or masonry, oxidation of metals; rot or borer attack in wood.
No significant deterioration or deficiencies were noted on the main structural concrete, masonry or wood elements. Miscellaneous minor to moderate damage was noted previously on other building components.
f. Previous patching or repairs
No previous repair were observed
g. Nature of present loading indicate residential, commercial, other estimate magnitude.
Residential use, 40 psf live load.

3. INSPECTIONS	
a. Date of notice of required inspection	Unknown
b. Date(s) of actual inspection	January 17, 2022
c. Name and qualifications of individual submitting report:	Jason Borden, FL P.E. No. 83583
d. Description of laboratory or other formal testing, if required, rather than manual or visual procedures	
Our structural assessment was based on non destructive visual and acoustical sounding techniques to identified areas of distress. No additional laboratory or destructive techniques were used for our assessment.	
e. Structural repair-note appropriate line:	
1. None required	
2. Required (describe and indicate acceptance)	No immediate structural repair are required but a stucco/paint maintenance program is necessary to safeguard the integrity of the concrete/masonry structural elements.

4. SUPPORTING DATA	
a.	N/A sheet written data
b.	Attached photo document photographs
c.	N/A drawings or sketches

5. MASONRY BEARING WALL = Indicate good, fair, poor on appropriate lines:	
a. Concrete masonry units	Good
b. Clay tile or terra cotta units	N/A
c. Reinforced concrete tie columns	N/A
d. Reinforced concrete tie beams	N/A
e. Lintel	N/A
f. Other type bond beams	N/A
g. Masonry finishes -exterior	
1. Stucco	Recommend maintenance in all elevations
2. Veneer	N/A
3. Paint only	N/A
4. Other (describe)	
h. Masonry finishes - interior	
1. Vapor barrier	None observed
2. Furring and plaster	None observed
3. Paneling	N/A
4. Paint only	Fair
5. Other (describe)	
i. Cracks	
1. Location – note beams, columns, other	
2. Description	Minor surface cracks notified on exterior finish
j. Spalling	
1. Location – note beams, columns, other	
2. Description	Minor surface spalls notice on exterior
k. Rebar corrosion-check appropriate line	
1. None visible	x
2. Minor-patching will suffice	N/A
3. Significant-but patching will suffice	N/A

4. Significant-structural repairs required N/A
I. Samples chipped out for examination in spall areas:
1. No x
2. Yes – describe color, texture, aggregate, general quality

6. FLOOR AND ROOF SYSTEM
a. Roof The building has a bituminous built-up flat roof with perimeter shingled mansard roof elements.
1. Describe (flat, slope, type roofing, type roof deck, condition)
The roof is flat in shape and in comprised of timber trusses and plywood decking with a bituminous asphalt membrane.
2. Note water tanks, cooling towers, air conditioning equipment, signs, other heavy equipment and condition of support:
Each unit has a roof mounted AC unit that sit on top of small steel dunnage systems. In general dunnage are in fair condition, However,
approximately 5-10% of the metal straps that secure the AC units to the steel members will need to be replace, because of corrosion.
3. Note types of drains and scuppers and condition:
The interior main drain lines are protected with metal strainers. The strainers require maintenance and/or replacement
b. Floor system(s)
1. Describe (type of system framing, material, spans, condition)
The elevated floors and roof are supported by concrete slabs that bear on concrete beams/columns/wall structural elements.
The exterior concrete/masonry surfaces are covered with stucco finish.
c. Inspection – note exposed areas available for inspection, and where it was found necessary to open ceilings, etc. for inspection of typical framing members.
The structural assessment process consisted of visually examining the exterior columns, beams, catwalks handrails and stairs,
to detect evident areas of distress. Non destructive sounding inspection techniques were implemented to sample the accessible exterior
concrete and masonry elements to locate areas of distress/delamination not detectable by visual observation only.

7. STEEL FRAMING SYSTEM
a. Description 1. The building is concrete framed and have no main steel structural components that support the building.
2. The steel dunnage above the roof have moderate corroded conditions.
Proximately 5%-10% of the steel straps that anchor down the roof mechanical equipment must be replace.

b. Exposed Steel- describe condition of paint and degree of corrosion
Proximately 5%-10% of the steel straps that anchor down the roof mechanical equipment must be replace.
c. Concrete or other fireproofing – note any cracking or spalling and note where any covering was removed for inspection
N/A
d. Elevator sheave beams and connections, and machine floor beams – note condition:
N/A

8. CONCRETE FRAMING SYSTEM
a. Full description of structural system As noted in the general description, the main floors and roof of the building are concrete slabs supported on concrete/masonry load bearing components. The stairs are concrete framed.
b. Cracking
1. Not significant
2. Location and description of members affected and type cracking The concrete catwalks displayed fine cracks originating mostly from various corners of the building profile. The concrete surfaces of the catwalk were sounded using a delamination tool.
c. General condition The concrete elements were deemed to be in fair condition with localized unsound/spalled areas that require remedial work. The precast exterior treads should be replaced in the near future.
d. Rebar corrosion – check appropriate line
1. None visible N/A
2. Location and description of members affected and type cracking
3. Significant but patching will suffice
4. Significant – structural repairs required (describe)
e. Samples chipped out in spall areas:
1. No x
2. Yes, describe color, texture, aggregate, general quality:

9. WINDOWS	
a. Type (Wood, steel, aluminum, jalousie, single hung, double hung, casement, awning, pivoted, fixed, other)	
Aluminum single hung windows and awning windows. All the windows are in fair condition.	
b. Anchorage- type and condition of fasteners and latches	Typical masonry anchors in fair condition
c. Sealant – type of condition of perimeter sealant and at mullions:	Fair condition
d. Interiors seals – type and condition at operable vents	N/A
e. General condition:	The window and door sealant were generally noted in fair condition.

10. WOOD FRAMING	
a. Type – fully describe if mill construction, light construction, major spans, trusses:	
The roof is flat in shape and comprised of timber and plywood decking covered with a bituminous asphalt membrane.	
b. Note metal fitting i.e., angles, plates, bolts, split pintles, other, and note condition:	
N/A	
c. Joints – note if well fitted and still closed:	N/A
d. Drainage – note accumulations of moisture	N/A
e. Ventilation – note any concealed spaces not ventilated:	N/A
f. Note any concealed spaces opened for inspection:	Small roof access panels were opened to view condition
of roof wood trusses.	

VILLAGE OF DADELAND - BUILDING 7320 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION




OCTOBER 3, 2022

Photo #1:



Front elevation of building 7320 (Villa B)

Photo #2:



Water ponding observed on the roof.

OCTOBER 3, 2022

Photo #3:



The strainers for the interior drain lines were found to be rusted or non-functional since many of them are missing or not in their proper position.

Photo #4:



The bituminous roof membrane was deemed to be in fair condition but sign of weathering/distress are evident.

VILLAGE OF DADELAND - BUILDING 7320 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION



OCTOBER 3, 2022

Photo #5:



Where accessible the roof structure was observed and found to be in fair condition.


Photo #6:



Staining and vegetation growth was observed at the exposed edges of the concrete beams supporting the catwalks. The members are still sound but maintenance of the paint/waterproofing is required to prevent deterioration of the concrete.

OCTOBER 3, 2022

Photo #7:



The precast steps are heavily weathered down and should be replaced in the next exterior repair/maintenance cycle of the building.

Photo #8:



Miscellaneous wall penetrations should be properly sealed to prevent water infiltration into the building, and/or surface decay of the stucco membrane in the vicinity of the penetration.



REGULATORY AND ECONOMIC RESOURCES
DEPARTMENT

MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING STRUCTURAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022

Digitally signed
by Jason Borden

Contact Info:

305-676-9888

Date: 2022.10.13

11:36:58-04'00'

INSPECTION MADE BY: JASON BORDEN P.E.

SIGNATURE:

PRINT NAME: JASON BORDEN P.E.

TITLE: REGIONAL MANAGER

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

1. DESCRIPTION OF STRUCTURE

a. Name on Title: Village at Dadeland Condominiums (B)

b. Street Address: 7324 SW 82nd St. Miami, Florida 33143

c. Legal Description: Village at Dadeland Condominiums

d. Owner's Name: Village at Dadeland Condominiums

e. Owner's Mailing Address: 7324 SW 82nd St. Miami, Florida 33143

f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX

g. Building Code Occupancy Classification: Condominium, Residential

h. Present Use: Condominium, Residential

i. General Description: The 2-story twelve unit building at the Village at Dadeland Condominium has an approximate footprint of 150ftx40ft.

Building 7324 is 1 of 4 buildings that comprise the VILLA "B" area of the community and was constructed circa 1970. Two stairs located on the west

front elevation of the building provide access to the 2nd floor catwalk. The building has a bituminous built-up flat roof with perimeter

Addition Comments: shingled mansard roof elements. The roof is supported by 2ft tall wood trusses spaced at approximately 2ft on center.

. Interior main drain lines are located throughout the roofs with emergency scuppers/openings located at the mansard roof elements. The interior

The 2nd floor is supported by concrete slabs that bear on concrete beams/columns/walls. Cantilevered concrete beams support the 2nd floor catwalk.

Concrete walls and beams support the rear concrete floor balconies. Small mechanical equipment sits atop the steel

dunnage systems above the main flat roof.

j. Additions to original structure:	N/A

2. PRESENT CONDITION OF STRUCTURE	
a. General alignment (Note: good, fair, poor, explain if significant)	
1. Bulging	None observed
2. Settlement	None observed
3. Deflections	None observed
4. Expansion	None observed
5. Contraction	None observed
b. Portion showing distress (Note, beams, columns, structural walls, floor, roofs, other)	
1.Hairline to Fine surface cracks were noted on the exterior walls 2.Small unsound and spalled areas noted on the stucco/concrete surfaces of the balcony ceilings and/or side masonry enclosure walls. 3.Extensive ponding and weathering of the built-up bituminous roof was noted 4.The shingles of the mansard roofs are weathered down 5.Isolated/small unsound areas of the wall stucco/concrete/masonry surfaces were discovered by our visual and sounding inspection efforts. 6.Clogged drain strainers were observed at different locations. 7.The protective paint/membrane of concrete catwalks have begun to chip away exposing the concrete below. 8.Some of the patio concrete floors are cracked 9.The precast exterior treads are starting to show sign of distress 10. Some of the balconies have torn membrane	
c. Surface conditions – describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration and stains.	
1.The exterior textured stucco finish was found to be generally in fair condition. Localized isolated small to moderate size areas of unsound stucco/concrete/masonry surfaces were discovered.	
d. Cracks – note location in significant members. Identify crack size as HAIRLINE if barely discernible; FINE if less than 1 mm in width; MEDIUM if between 1 and 2 mm width; WIDE if over 2 mm.	
Hairline and fine cracks noted on the stucco finish on the ceiling and wall surfaces.	

e. General extent of deterioration – cracking or spalling of concrete or masonry, oxidation of metals; rot or borer attack in wood.
No significant deterioration or deficiencies were noted on the main structural concrete, masonry or wood elements. Miscellaneous minor to moderate damage was noted previously on other building components.
f. Previous patching or repairs
No previous repair were observed
g. Nature of present loading indicate residential, commercial, other estimate magnitude.
Residential use, 40 psf live load.

3. INSPECTIONS
a. Date of notice of required inspection Unknown
b. Date(s) of actual inspection January 17, 2022
c. Name and qualifications of individual submitting report: Jason Borden, FL P.E. No. 83583
d. Description of laboratory or other formal testing, if required, rather than manual or visual procedures
Our structural assessment was based on non destructive visual and acoustical sounding techniques to identified areas of distress. No additional laboratory or destructive techniques were used for our assessment.
e. Structural repair-note appropriate line:
1. None required
2. Required (describe and indicate acceptance) No immediate structural repair are required but a stucco/paint maintenance program is necessary to safeguard the integrity of the concrete/masonry structural elements.

4. SUPPORTING DATA
a. <u>N/A</u> sheet written data
b. <u>Attached photo document</u> photographs
c. <u>N/A</u> drawings or sketches

5. MASONRY BEARING WALL = Indicate good, fair, poor on appropriate lines:	
a. Concrete masonry units	Good
b. Clay tile or terra cotta units	N/A
c. Reinforced concrete tie columns	N/A
d. Reinforced concrete tie beams	N/A
e. Lintel	N/A
f. Other type bond beams	N/A
g. Masonry finishes -exterior	
1. Stucco	Recommend maintenance in all elevations
2. Veneer	N/A
3. Paint only	N/A
4. Other (describe)	
h. Masonry finishes - interior	
1. Vapor barrier	None observed
2. Furring and plaster	None observed
3. Paneling	N/A
4. Paint only	Fair
5. Other (describe)	
i. Cracks	
1. Location – note beams, columns, other	
2. Description	Minor surface cracks notified on exterior finish
j. Spalling	
1. Location – note beams, columns, other	
2. Description	Minor surface spalls notice on exterior
k. Rebar corrosion-check appropriate line	
1. None visible	N/A
2. Minor-patching will suffice	N/A
3. Significant-but patching will suffice	N/A

4. Significant-structural repairs required N/A
I. Samples chipped out for examination in spall areas:
1. No x
2. Yes – describe color, texture, aggregate, general quality

6. FLOOR AND ROOF SYSTEM
a. Roof The building has a bituminous built-up flat roof with perimeter shingled mansard roof elements.
1. Describe (flat, slope, type roofing, type roof deck, condition)
The roof is flat in shape and in comprised of timber trusses and plywood decking with a bituminous asphalt membrane.
2. Note water tanks, cooling towers, air conditioning equipment, signs, other heavy equipment and condition of support:
Each unit has a roof mounted AC unit that sit on top of small aluminum/steel dunnage systems. In general dunnage are in fair condition. However, approximately 5-10%
of the metal straps that secure the AC units to the steel/ aluminum members will need to be replaced because of the severity of corrosion or they are no longer connected/ missing
3. Note types of drains and scuppers and condition:
The interior main drain lines are protected with metal strainers. The strainers require maintenance and/or replacement.
b. Floor system(s)
1. Describe (type of system framing, material, spans, condition)
The elevated floors and roof are supported by concrete slabs that bear on concrete beams/columns/wall structural elements.
The exterior concrete/masonry surfaces are covered with stucco finish.
c. Inspection – note exposed areas available for inspection, and where it was found necessary to open ceilings, etc. for inspection of typical framing members.
The structural assessment process consisted of visually examining the exterior columns, beams, catwalks, handrails and stairs,
to detect evident areas of distress. Non destructive sounding inspection techniques were implemented to sample the accessible exterior
concrete and masonry elements to locate areas of distress/delamination not detectable by visual observation only.

7. STEEL FRAMING SYSTEM
a. Description 1. The building is concrete framed and have no main steel structural components that support the building.
2. The steel dunnage above the roof have moderate corroded conditions.

b. Exposed Steel- describe condition of paint and degree of corrosion
Approximately 5%-10% of the steel straps that anchor down the roof mechanical equipment must be replaced.
c. Concrete or other fireproofing – note any cracking or spalling and note where any covering was removed for inspection
N/A
d. Elevator sheave beams and connections, and machine floor beams – note condition:
N/A

8. CONCRETE FRAMING SYSTEM
a. Full description of structural system As noted in the general description, the main floors and roof of the building are concrete slabs supported on concrete/masonry load bearing components. The stairs are concrete framed with masonry walls.
b. Cracking
1. Not significant
2. Location and description of members affected and type cracking The concrete catwalks displayed fine cracks originating mostly from various corners of the building profile. The concrete surfaces of the catwalk were sounded using a delamination tool.
c. General condition The concrete elements were deemed to be in fair condition with localized unsound/spalled areas that require minor remedial work.
d. Rebar corrosion – check appropriate line
1. None visible N/A
2. Location and description of members affected and type cracking
3. Significant but patching will suffice
4. Significant – structural repairs required (describe)
e. Samples chipped out in spall areas:
1. No X
2. Yes, describe color, texture, aggregate, general quality:

9. WINDOWS	
a. Type (Wood, steel, aluminum, jalousie, single hung, double hung, casement, awning, pivoted, fixed, other)	
Aluminum single hung windows and awning windows. All the windows are in fair condition.	
b. Anchorage- type and condition of fasteners and latches	Typical masonry anchors in fair condition
c. Sealant – type of condition of perimeter sealant and at mullions:	Fair condition
d. Interiors seals – type and condition at operable vents	N/A
e. General condition:	The window and door sealant were generally noted in fair condition.

10. WOOD FRAMING	
a. Type – fully describe if mill construction, light construction, major spans, trusses:	
The roof is flat in shape and comprised of timber and plywood decking covered with a bituminous asphalt membrane.	
b. Note metal fitting i.e., angles, plates, bolts, split pintles, other, and note condition:	
N/A	
c. Joints – note if well fitted and still closed:	N/A
d. Drainage – note accumulations of moisture	N/A
e. Ventilation – note any concealed spaces not ventilated:	N/A
f. Note any concealed spaces opened for inspection:	Small roof access panels were opened to view condition
of roof wood trusses.	

VILLAGE OF DADELAND - BUILDING 7324 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION



OCTOBER 3, 2022

Photo #1:



Front elevation of building 7324 (Villa B)

Photo #2:



Water ponding observed on the roof.

VILLAGE OF DADELAND - BUILDING 7324 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION




OCTOBER 3, 2022

Photo #3:



The strainers for the interior drain lines were found to be rusted or non-functional since many of them are missing or not in their proper position.


Photo #4:



The bituminous roof membrane was deemed to be in fair condition but sign of weathering/distress are evident.

OCTOBER 3, 2022

Photo #5:



Where accessible the roof structure was observed and found to be in fair condition.

Photo #6:



Cracks and small spalls were observed near the ends of the cantilevered concrete beams.


VILLAGE OF DADELAND - BUILDING 7324 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION



OCTOBER 3, 2022

Photo #7:



Cracking and unsound surface areas observed on the catwalk surfaces in the vicinity of the cantilevered beams

Photo #8:



Miscellaneous penetrations of the exterior walls should be properly sealed to prevent water infiltration into the building and/or surface decay of the stucco membrane in the vicinity of the penetration.



REGULATORY AND ECONOMIC RESOURCES
DEPARTMENT

MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING STRUCTURAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022

Digitally signed by

Jason Borden

Contact Info:

305-676-9888

Date: 2022.10.13

11:36:25-04'00'

INSPECTION MADE BY: JASON BORDEN P.E.

SIGNATURE:

PRINT NAME: JASON BORDEN P.E.

TITLE: REGIONAL MANAGER

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

1. DESCRIPTION OF STRUCTURE

a. Name on Title: Village at Dadeland Condominiums (B)

b. Street Address: 7328 SW 82nd St. Miami, Florida 33143

c. Legal Description: Village at Dadeland Condominiums

d. Owner's Name: Village at Dadeland Condominiums

e. Owner's Mailing Address: 7328 SW 82nd St. Miami, Florida 33143

f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX

g. Building Code Occupancy Classification: Condominium, Residential

h. Present Use: Condominium, Residential

i. General Description: The 2-story eight unit building at the Village at Dadeland Condominium has an approximate footprint of 115ftx35ft. Building

7328 is 1 of 4 buildings that comprise the VILLA "B" area of the community and was constructed circa 1970. Two stairs located on the north front elevation

of the building provide access to the 2nd floor catwalk. The building has a bituminous built-up flat roof with perimeter shingled mansard roof elements

Addition Comments: The roof is supported by 2ft tall wood trusses spaced at approximately 2ft on center. Interior main drain lines are located throughout

are protected with metal strainers. The exterior concrete/masonry are covered with a flat stucco finish. The 2nd floor is supported by concrete

walls and beams support the rear concrete floor balconies. Small mechanical equipment sits atop the steel dunnage systems above the main flat roof.

j. Additions to original structure:	N/A

2. PRESENT CONDITION OF STRUCTURE	
a. General alignment (Note: good, fair, poor, explain if significant)	
1. Bulging	None observed
2. Settlement	None observed
3. Deflections	None observed
4. Expansion	None observed
5. Contraction	None observed
b. Portion showing distress (Note, beams, columns, structural walls, floor, roofs, other)	
1.Small unsound and spalled areas noted on the stucco/concrete surfaces of the balcony ceilings and/or side masonry enclosure walls. 2.Extensive ponding and weathering of the built-up bituminous roof was noted 3.The shingles of the mansard roofs are weathered down 4.Isolated/small unsound areas of the wall stucco/concrete/masonry surfaces were discovered by our visual and sounding inspection efforts. 5.Clogged drain strainers were observed at different locations. 6.The protective paint/membrane of concrete catwalks have begun to chip away exposing the concrete below. 7.Some of the patio concrete floors are cracked	
c. Surface conditions – describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration and stains.	
1. The exterior stucco finish was found to be generally in fair condition. Localized isolated small to moderate size areas of unsound stucco/concrete/masonry surfaces were discovered.	
No large spalls were noted on the exterior slab and wall surfaces.	
2.Some cracks/spalls were noted on the concrete posts for the rear balconies.	
d. Cracks – note location in significant members. Identify crack size as HAIRLINE if barely discernible; FINE if less than 1 mm in width; MEDIUM if between 1 and 2 mm width; WIDE if over 2 mm.	
Hairline and fine cracks noted on the stucco finish on the ceiling and wall surfaces.No significant structural cracks noted on the concrete slab, column and wall surfaces. Large cracks noted on the concrete posts for the rear balconies.	

e. General extent of deterioration – cracking or spalling of concrete or masonry, oxidation of metals; rot or borer attack in wood.
No significant deterioration or deficiencies were noted on the main structural concrete, masonry or wood elements. Miscellaneous minor to moderate damage was noted previously on other building components.
f. Previous patching or repairs
No previous repair were observed
g. Nature of present loading indicate residential, commercial, other estimate magnitude.
Residential use, 40 psf live load.

3. INSPECTIONS
a. Date of notice of required inspection Unknown
b. Date(s) of actual inspection January 17, 2022
c. Name and qualifications of individual submitting report: Jason Borden, FL P.E. No. 83583
d. Description of laboratory or other formal testing, if required, rather than manual or visual procedures
Our structural assessment was based on non destructive visual and acoustical sounding techniques to identified areas of distress. No additional laboratory or destructive techniques were used for our assessment.
e. Structural repair-note appropriate line:
1. None required
2. Required (describe and indicate acceptance) No immediate structural repair are required but a stucco/paint maintenance program is necessary to safeguard the integrity of the concrete/masonry structural elements.

4. SUPPORTING DATA
a. N/A sheet written data
b. Attached photo document photographs
c. N/A drawings or sketches

5. MASONRY BEARING WALL = Indicate good, fair, poor on appropriate lines:	
a. Concrete masonry units	Good
b. Clay tile or terra cotta units	N/A
c. Reinforced concrete tie columns	N/A
d. Reinforced concrete tie beams	N/A
e. Lintel	N/A
f. Other type bond beams	N/A
g. Masonry finishes -exterior	
1. Stucco	Recommend maintenance in all elevations
2. Veneer	N/A
3. Paint only	N/A
4. Other (describe)	
h. Masonry finishes - interior	
1. Vapor barrier	None observed
2. Furring and plaster	None observed
3. Paneling	N/A
4. Paint only	Fair
5. Other (describe)	
i. Cracks	
1. Location – note beams, columns, other	
2. Description	Minor surface cracks notified on exterior finish
j. Spalling	
1. Location – note beams, columns, other	
2. Description	Minor surface spalls notice on exterior
k. Rebar corrosion-check appropriate line	
1. None visible	N/A
2. Minor-patching will suffice	N/A
3. Significant-but patching will suffice	N/A

4. Significant-structural repairs required N/A
I. Samples chipped out for examination in spall areas:
1. No x
2. Yes – describe color, texture, aggregate, general quality

6. FLOOR AND ROOF SYSTEM
a. Roof The building has a bituminous built-up flat roof with perimeter shingled mansard roof elements.
1. Describe (flat, slope, type roofing, type roof deck, condition)
The roof is flat in shape and in comprised of timber trusses and plywood decking with a bituminous asphalt membrane.
2. Note water tanks, cooling towers, air conditioning equipment, signs, other heavy equipment and condition of support:
Each unit has a roof mounted AC unit that sit on top of small aluminum/steel dunnage systems. In general dunnage are in fair condition. However, approximately 5-10%
of the metal straps that secure the AC units to the steel/ aluminum members will need to be replaced because of the severity of corrosion or they are no longer connected/ missing
3. Note types of drains and scuppers and condition:
The interior main drain lines are protected with metal strainers. The strainers require maintenance and/or replacement.
b. Floor system(s)
1. Describe (type of system framing, material, spans, condition)
The elevated floors and roof are supported by concrete slabs that bear on concrete beams/columns/wall structural elements.
The exterior concrete/masonry surfaces are covered with stucco finish.
c. Inspection – note exposed areas available for inspection, and where it was found necessary to open ceilings, etc. for inspection of typical framing members.
The structural assessment process consisted of visually examining the exterior columns, beams, catwalks, handrails and stairs,
to detect evident areas of distress. Non destructive sounding inspection techniques were implemented to sample the accessible exterior
concrete and masonry elements to locate areas of distress/delamination not detectable by visual observation only.

7. STEEL FRAMING SYSTEM
a. Description 1. The building is concrete framed and have no main steel structural components that support the building.
2. The steel dunnage above the roof have moderate corroded conditions.

b. Exposed Steel- describe condition of paint and degree of corrosion
Approximately 5%-10% of the steel straps that anchor down the roof mechanical equipment must be replaced.
c. Concrete or other fireproofing – note any cracking or spalling and note where any covering was removed for inspection
N/A
d. Elevator sheave beams and connections, and machine floor beams – note condition:
N/A

8. CONCRETE FRAMING SYSTEM
a. Full description of structural system As noted in the general description, the main floors and roof of the building are concrete slabs supported on concrete/masonry load bearing components. The stairs are concrete framed with masonry walls.
b. Cracking
1. Not significant
2. Location and description of members affected and type cracking The concrete catwalks displayed fine cracks originating mostly from various corners of the building profile. The concrete surfaces of the catwalk were sounded using a delamination tool.
c. General condition The concrete elements were deemed to be in fair condition with localized unsound/spalled areas that require minor remedial work.
d. Rebar corrosion – check appropriate line
1. None visible N/A
2. Location and description of members affected and type cracking
3. Significant but patching will suffice
4. Significant – structural repairs required (describe)
e. Samples chipped out in spall areas:
1. No X
2. Yes, describe color, texture, aggregate, general quality:

9. WINDOWS	
a. Type (Wood, steel, aluminum, jalousie, single hung, double hung, casement, awning, pivoted, fixed, other)	
Aluminum single hung windows and awning windows. All the windows are in fair condition.	
b. Anchorage- type and condition of fasteners and latches	Look in fair condition
c. Sealant – type of condition of perimeter sealant and at mullions:	Generally in fair condition, some need replacement
d. Interiors seals – type and condition at operable vents	N/A
e. General condition:	The window and door sealant were generally noted in fair condition.

10. WOOD FRAMING	
a. Type – fully describe if mill construction, light construction, major spans, trusses:	
The roof is flat in shape and comprised of timber and plywood decking covered with a bituminous asphalt membrane.	
b. Note metal fitting i.e., angles, plates, bolts, split pintles, other, and note condition:	
N/A	
c. Joints – note if well fitted and still closed:	N/A
d. Drainage – note accumulations of moisture	N/A
e. Ventilation – note any concealed spaces not ventilated:	N/A
f. Note any concealed spaces opened for inspection:	Small roof access panels were opened to view condition
of roof wood trusses.	

VILLAGE OF DADELAND - BUILDING 7328 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION




OCTOBER 3, 2022

Photo #1:



Front elevation of building 7328 (Villa B)

Photo #2:



Water ponding stains observed on the roof.

OCTOBER 3, 2022

Photo #3:



The strainers for the interior drain lines were found to be rusted or non-functional since many of them are missing or not in their proper position. Others need maintenance to remove debris.


Photo #4:



The bituminous roof membrane was deemed to be in fair condition but sign of weathering/distress are evident.

OCTOBER 3, 2022

Photo #5:



Where accessible the roof wood structure was observed and found to be in fair condition.


Photo #6:



Cracks and small spalls were observed near the ends of the cantilevered concrete beams.

OCTOBER 3, 2022

Photo #7:



Fine surfaces cracks observed on the stucco membrane. Areas were sounded and still considered to be sound.

Photo #8:



Step cracks observed between the window lines at the south/east corner of the building.

OCTOBER 3, 2022

Photo #9:



A small spalled area
underneath the window
observed



REGULATORY AND ECONOMIC RESOURCES
DEPARTMENT

MINIMUM INSPECTION PROCEDURAL GUIDELINES
FOR BUILDING STRUCTURAL RECERTIFICATION

INSPECTION COMMENCED

Date: 1/17/2022

INSPECTION COMPLETED

Date: 1/28/2022

Digitally signed by

Jason Borden

Contact Info:

305-676-9888

Date: 2022.10.13

11:35:58-04'00'

INSPECTION MADE BY: JASON BORDEN P.E.

SIGNATURE:

PRINT NAME: JASON BORDEN P.E.

TITLE: REGIONAL MANAGER

ADDRESS: 2500 Hollywood Blvd, Suite 212

Hollywood, FL 33020

1. DESCRIPTION OF STRUCTURE

a. Name on Title: Village at Dadeland Condominiums (B)

b. Street Address: 7330 SW 82nd St. Miami, Florida 33143

c. Legal Description: Village at Dadeland Condominiums

d. Owner's Name: Village at Dadeland Condominiums

e. Owner's Mailing Address: 7330 SW 82nd St. Miami, Florida 33143

f. Folio Number of Property on which Building is Located: 30-4035-047-XXXX

g. Building Code Occupancy Classification: Condominium, Residential

h. Present Use: Condominium, Residential

i. General Description: The 2-story eight unit building at the Village at Dadeland Condominium has an approximate footprint of 115ftx35ft

Building 7330 is 1 of 4 buildings that comprise the VILLA "B" area of the community and was constructed circa 1970. Two stairs located on the east

front elevation of the building provide access to the 2nd floor catwalk. The building has a bituminous built-up flat roof with perimeter shingled mansard

Addition Comments: roof elements. The roof is supported by 2ft tall wood trusses spaced at approximately 2ft on center.

Interior main drain lines are located throughout the roofs with emergency scuppers/openings located at the mansard roof elements.

The interior main drain lines are protected with metal strainers. The exterior concrete/masonry are covered with a flat stucco finish.

The 2nd floor is supported by concrete slabs that bear on concrete beams/columns/walls. Cantilevered concrete beams support the 2nd

floor catwalk. Concrete walls and beams support the rear concrete floor balconies. Small mechanical equipment sits

atop the steel dunnage systems above the main flat roof.

j. Additions to original structure:

2. PRESENT CONDITION OF STRUCTURE	
a. General alignment (Note: good, fair, poor, explain if significant)	Fair
1. Bulging	None observed
2. Settlement	None observed
3. Deflections	None observed
4. Expansion	None observed
5. Contraction	None observed
b. Portion showing distress (Note, beams, columns, structural walls, floor, roofs, other)	
1.Hairline to Fine surface cracks were noted on the balcony slabs. 2.Hairline to Fine Cracks noted on the side walls of the balconies 3.Small unsound and spalled areas noted on the stucco/concrete surfaces of the balcony ceilings and/or side masonry enclosure walls. 5.The shingles of the mansard roofs are weathered down. 6.Small to moderate sized unsound areas of the wall stucco/concrete/masonry surfaces were discovered by our visual and sounding inspection efforts. 7.The protective paint/membrane of concrete catwalks have begun to chip away exposing the concrete below. 8.Clogged drain strainers were observed at different locations. 9.Some of the patio concrete floors are cracked	
c. Surface conditions – describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration and stains.	
The exterior stucco finish was found to be generally in fair condition. Localized isolated small	
areas of unsound stucco/concrete/masonry surfaces were discovered.	
Moderate size spalls noted beneath some of the window sills	
d. Cracks – note location in significant members. Identify crack size as HAIRLINE if barely discernible; FINE if less than 1 mm in width; MEDIUM if between 1 and 2 mm width; WIDE if over 2 mm.	
Hairline and fine cracks noted on the stucco finish on the ceiling and wall surfaces. Step cracks noted on	
various locations near the corners of the elevations and between vertically aligned windows.	

e. General extent of deterioration – cracking or spalling of concrete or masonry, oxidation of metals; rot or borer attack in wood.	
No significant deterioration or deficiencies were noted on the main structural concrete, masonry or wood elements. Miscellaneous minor to moderate damage was noted previously on other building components.	
f. Previous patching or repairs	No previous repair were observed
g. Nature of present loading indicate residential, commercial, other estimate magnitude.	
Residential use, 40 psf live load.	

3. INSPECTIONS	
a. Date of notice of required inspection	Unknown
b. Date(s) of actual inspection	1/17/2022
c. Name and qualifications of individual submitting report:	
Jason Borden, FL P.E. No. 83583	
d. Description of laboratory or other formal testing, if required, rather than manual or visual procedures	
Our structural assessment was based on non destructive visual and acoustical sounding techniques to identified areas of distress. No additional laboratory or destructive techniques were used for our assessment.	
e. Structural repair-note appropriate line:	
1. None required	x
2. Required (describe and indicate acceptance)	No immediate structural repair are required but a stucco/paint maintenance program is necessary to safeguard the integrity of the concrete/masonry structural elements.

4. SUPPORTING DATA	
a.	N/A sheet written data
b.	Attached photo document photographs
c.	N/A drawings or sketches

5. MASONRY BEARING WALL = Indicate good, fair, poor on appropriate lines:	
a. Concrete masonry units	Good
b. Clay tile or terra cotta units	N/A
c. Reinforced concrete tie columns	N/A
d. Reinforced concrete tie beams	N/A
e. Lintel	N/A
f. Other type bond beams	N/A
g. Masonry finishes -exterior	
1. Stucco	Recommend maintenance in all elevations
2. Veneer	N/A
3. Paint only	N/A
4. Other (describe)	
h. Masonry finishes - interior	
1. Vapor barrier	None observed
2. Furring and plaster	None observed
3. Paneling	N/A
4. Paint only	N/A
5. Other (describe)	
i. Cracks	
1. Location – note beams, columns, other	
2. Description	Minor surface cracks noticed on exterior finish
j. Spalling	
1. Location – note beams, columns, other	
2. Description	Minor surface spalls noticed on exterior
k. Rebar corrosion-check appropriate line	
1. None visible	x
2. Minor-patching will suffice	N/A
3. Significant-but patching will suffice	N/A

4. Significant-structural repairs required N/A
I. Samples chipped out for examination in spall areas:
1. No x
2. Yes – describe color, texture, aggregate, general quality

6. FLOOR AND ROOF SYSTEM
a. Roof The building has a bituminous built-up flat roof with perimeter shingled mansard roof elements.
1. Describe (flat, slope, type roofing, type roof deck, condition)
The roof is flat in shape and in comprised of timber trusses and plywood decking with a bituminous asphalt membrane.
2. Note water tanks, cooling towers, air conditioning equipment, signs, other heavy equipment and condition of support:
Each unit has a roof mounted AC unit that sit on top of small aluminum/steel dunnage systems. In general dunnage are in fair condition. However, approximately 5-10%
of the metal straps that secure the AC units to the steel/ aluminum members will need to be replaced because of the severity of corrosion or they are no longer connected/ missing
3. Note types of drains and scuppers and condition:
The interior main drain lines are protected with metal strainers. The strainers require maintenance and/or replacement.
b. Floor system(s)
1. Describe (type of system framing, material, spans, condition)
The elevated floors and roof are supported by concrete slabs that bear on concrete beams/columns/wall structural elements.
The exterior concrete/masonry surfaces are covered with stucco finish.
c. Inspection – note exposed areas available for inspection, and where it was found necessary to open ceilings, etc. for inspection of typical framing members.
The structural assessment process consisted of visually examining the exterior columns, beams, catwalks, handrails and stairs,
to detect evident areas of distress. Non destructive sounding inspection techniques were implemented to sample the accessible exterior
concrete and masonry elements to locate areas of distress/delamination not detectable by visual observation only.

7. STEEL FRAMING SYSTEM
a. Description 1. The building is concrete framed and have no main steel structural components that support the building.
2. The steel dunnage above the roof have moderate corroded conditions.

b. Exposed Steel- describe condition of paint and degree of corrosion
Proximately 5%-10% of the steel straps that anchor down the roof mechanical equipment must be replace.
c. Concrete or other fireproofing – note any cracking or spalling and note where any covering was removed for inspection
N/A
d. Elevator sheave beams and connections, and machine floor beams – note condition:
N/A

8. CONCRETE FRAMING SYSTEM
a. Full description of structural system As noted in the general description, the main floors and roof of the building are concrete slabs supported on concrete/masonry load bearing components. The stairs are concrete framed.
b. Cracking
1. Not significant X
2. Location and description of members affected and type cracking The concrete catwalks displayed fine cracks originating mostly from various corners of the building profile. The concrete surfaces of the catwalk were sounded using a delamination tool.
c. General condition The concrete elements were deemed to be in fair condition with localized unsound/spalled areas that require remedial work.
d. Rebar corrosion – check appropriate line
1. None visible
2. Location and description of members affected and type cracking
3. Significant but patching will suffice Window & wall small spalls.
4. Significant – structural repairs required (describe)
e. Samples chipped out in spall areas:
1. No
2. Yes, describe color, texture, aggregate, general quality:
N/A

9. WINDOWS
a. Type (Wood, steel, aluminum, jalousie, single hung, double hung, casement, awning, pivoted, fixed, other)
Aluminum single hung windows and awning windows. All the windows are in fair condition.
b. Anchorage- type and condition of fasteners and latches Look in fair condition
c. Sealant – type of condition of perimeter sealant and at mullions: Generally in fair condition, some need replacement
d. Interiors seals – type and condition at operable vents N/A
e. General condition: The window and door sealant were generally noted to be in fair condition.

10. WOOD FRAMING
a. Type – fully describe if mill construction, light construction, major spans, trusses:
The roof is flat in shape and comprised of timber and plywood decking covered with a bituminous asphalt membrane.
b. Note metal fitting i.e., angles, plates, bolts, split pintles, other, and note condition:
N/A
c. Joints – note if well fitted and still closed: N/A
d. Drainage – note accumulations of moisture N/A
e. Ventilation – note any concealed spaces not ventilated: N/A
f. Note any concealed spaces opened for inspection: Small roof access panels were opened to view condition
of roof wood trusses.

VILLAGE OF DADELAND - BUILDING 7330 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION



OCTOBER 3, 2022

Photo #1:



Front elevation of building 7330 (Villa B)

Photo #2:



Water ponding stains observed on the roof.

The bituminous roof membrane was deemed to be in fair condition but sign of weathering/distress are evident.

The shingles of the mansard roof are also heavily weathered down.

VILLAGE OF DADELAND - BUILDING 7330 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION



OCTOBER 3, 2022

Photo #3:



Previous exterior wall repair/patches observed in the front elevation. The stucco has begun to fall off exposing the wood sheathing beneath. Areas need to be properly repaired to maintain water tightness of the exterior envelope.

Photo #4:



Where accessible the roof structure was observed and found to be in fair condition.

OCTOBER 3, 2022

Photo #5:



Miscellaneous penetrations of the exterior walls should be properly sealed to prevent water infiltration into the building and/or surface decay of the stucco membrane in the vicinity of the penetration.

Photo #6:



Some decay/spalling observed at the base of the patio exterior walls.

VILLAGE OF DADELAND - BUILDING 7330 (VILLA B)

REPORT PHOTOGRAPHIC DOCUMENTATION



OCTOBER 3, 2022

Photo #7:



Fine surfaces cracks observed on the stucco membrane. Areas were sounded and still considered to be sound.

Photo #8:



A small spalled area underneath the window observed. The exposed rebar is heavily corroded



**CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION
STANDARDS IN CHAPTER 8C-3 OF THE CODE OF MIAMI-DADE COUNTY**

Date: 5/22/2023

Case No. _____ FYear 2018

Property Address: 7320 SW 82nd St. Miami, Florida 33143, Bldg. No.: N/A, Sq. Ft.: 6500

Folio Number: 30-4035-047-XXXX

Building Description: 2-story, eight unit building.

1. I am a Florida registered professional ☒ engineer ☐ architect with an active license.
2. On, 20 22 Sept. at 9 ☐ AM ☒ PM, I measured the level of illumination in the parking lot(s) serving the above referenced building.
3. Maximum 9.50 foot candle
Minimum 1.30 foot candle
Maximum to Minimum Ratio 7.31 : 1, foot candle
4. The level of illumination provided in the parking lot ☒ meets ☐ does not meet the minimum standards for the occupancy classification of the building as established in Section 8C-3 of Miami-Dade County Code.



Signature and Seal of Professional

Digitally signed by Florin Florea
Location: Hollywood, FL
Contact Info:
fflorea@oandsassociates.com
Date: 2023.06.07
11:20:38-04'00'

Florin Florea, PE

Print Name Engineer or Architect



**CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION
STANDARDS IN CHAPTER 8C-3 OF THE CODE OF MIAMI-DADE COUNTY**

Date: 5/22/2023

Case No. _____ FYear 2018

Property Address: 7324 SW 82nd St. Miami, Florida 33143, Bldg. No.: N/A, Sq. Ft.: 12000

Folio Number: 30-4035-047-XXXX

Building Description: 2-story, twelve unit building.

1. I am a Florida registered professional ☒ engineer ☐ architect with an active license.
2. On, 20 22 Sept. at 9 ☐ AM ☒ PM, I measured the level of illumination in the parking lot(s) serving the above referenced building.
3. Maximum 6.40 foot candle
Minimum 1.10 foot candle
Maximum to Minimum Ratio 5.82 : 1, foot candle
4. The level of illumination provided in the parking lot ☒ meets ☐ does not meet the minimum standards for the occupancy classification of the building as established in Section 8C-3 of Miami-Dade County Code.



Digitally signed by Florin Florea
Location: Hollywood, FL
Contact Info:
fflorea@oandsassociates.com
Date: 2023.06.07
10:19:33-04'00'

Signature and Seal of Professional

Florin Florea, PE

Print Name Engineer or Architect



**CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION
STANDARDS IN CHAPTER 8C-3 OF THE CODE OF MIAMI-DADE COUNTY**

Date: 5/22/2023

Case No. _____ FYear 2018

Property Address: 7328 SW 82nd St. Miami, Florida 33143, Bldg. No.: N/A, Sq. Ft.: 8000

Folio Number: 30-4035-047-XXXX

Building Description: 2-story, eight unit building.

1. I am a Florida registered professional ☒ engineer ☐ architect with an active license.
2. On, 20 22 Sept. at 9 ☐ AM ☒ PM, I measured the level of illumination in the parking lot(s) serving the above referenced building.
3. Maximum 5.50 foot candle
Minimum 1.00 foot candle
Maximum to Minimum Ratio 5.50 : 1, foot candle
4. The level of illumination provided in the parking lot ☒ meets ☐ does not meet the minimum standards for the occupancy classification of the building as established in Section 8C-3 of Miami-Dade County Code.



Signature and Seal of Professional

Digitally signed by Florin Florea
Location: Hollywood, FL
Contact Info:
fflorea@oandsassociates.com
Date: 2023.06.07
10:33:41 -04'00'

Florin Florea, PE

Print Name Engineer or Architect



**CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION
STANDARDS IN CHAPTER 8C-3 OF THE CODE OF MIAMI-DADE COUNTY**

Date: 5/22/2023

Case No. _____ FYear 2018

Property Address: 7330 SW 82nd St. Miami, Florida 33143, Bldg. No.: N/A, Sq. Ft.: 8000

Folio Number: 30-4035-047-XXXX

Building Description: 2-story, eight unit building.

1. I am a Florida registered professional ☒ engineer ☐ architect with an active license.
2. On, 20 22 Sept. at 9 ☐ AM ☒ PM, I measured the level of illumination in the parking lot(s) serving the above referenced building.
3. Maximum 10.60 foot candle
Minimum 0.90 foot candle
Maximum to Minimum Ratio 11.78 : 1, foot candle
4. The level of illumination provided in the parking lot ☐ meets ☒ does not meet the minimum standards for the occupancy classification of the building as established in Section 8C-3 of Miami-Dade County Code.



Signature and Seal of Professional

Digitally signed by Florin Florea
Location: Hollywood, FL
Contact Info:
fflorea@oandsassociates.com
Date: 2023.06.07 10:55:45-04'00'

Florin Florea, PE

Print Name Engineer or Architect