

**15 7217 0313 0001**  
Hess Mill Road  
over  
West Branch of White Clay Creek

Franklin Township  
Chester County, Pennsylvania



POSTING: 17 Tons Except Combinations 28 Tons

HANDS-ON INSPECTION: No

LOAD RATING REVIEW RECOMMENDED: No

MAP: 3909-G8, ADC 2008

INSPECTED: January 3, 2018 - Interim

INSPECTED BY:  
Kevin E. Gross, P.E., C.B.S.I.  
Blake Z. Fink

FRACTURE CRITICAL: No

PREPARED FOR:  
Pennsylvania Dept. of Transportation  
Engineering District 6-0

PREPARED BY:  
Pickering, Corts & Summerson, Inc.  
642 Newtown-Yardley Road, Suite 300  
Newtown, PA 18940



**Not for Public Record - Structure Safety Inspection Study**

This document is the property of Franklin Township. The data and information contained herein are part of a structure safety inspection study. This safety study is only provided to those official agencies or persons who have responsibility in the highway transportation system and may only be used by such agencies or persons for safety-related planning or research. The document and information are not public pursuant to 65 P.S. §67.101 et seq. and 23 U.S.C. §409 and may not be published, released or disclosed without the written permission of Franklin Township.

BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

**TABLE OF CONTENTS**

Location Map

Bridge Information

Inspection Summary

Load Rating Summary and Posting Evaluation

Recommendations

Field Inspection Notes


    iForms Printout

    Field Sketches

Photographs

BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

**LOCATION MAP**



BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

**BRIDGE DESCRIPTION**

<b>Year Built:</b>	1974
<b>Structure Type:</b>	Nail Laminated Timber
<b>Category:</b>	D-1
<b>Structure Length:</b>	25.5'
<b>Number of Spans:</b>	1
<b>Curb-Curb Width:</b>	25.2'
<b>Approach Roadway Width:</b>	20.0'
<b>Underclearance:</b>	N/A
<b>Skew Angle:</b>	76°
<b>S.C.B.I:</b>	4

**INSPECTION SUMMARY**

An interim inspection was completed on January 3, 2018 as per PennDOT Publication 238, Part IP, Chapter 2, Section 2.3.2.4., Table IP 2.3.2.4-1, Maximum Interval of Routine Inspections. Interim inspections required due to the 17 Tons Except Combinations 28 Tons posted weight limit.

<b><u>Approach Slab:</u></b>	<b>Prior Condition Rating</b>	<b>N</b>
	<b>Current Condition Rating</b>	<b>N</b>

None.

<b><u>Approach Roadway:</u></b>	<b>Prior Condition Rating</b>	<b>7</b>
	<b>Current Condition Rating</b>	<b>N/A</b>

The approach roadway condition was not evaluated as part of the January 3, 2018 interim inspection. Only problem areas and elements related to the bridge posting were evaluated. The following approach roadway condition description is taken from the 2017 NBIS inspection report.

The bituminous approach roadway is in overall good condition. There is moderate wear and sealed and unsealed fine to medium longitudinal cracking along the centerline of the roadway beyond the repaved portions. The new bituminous patches along the left travel lane of the deck extend up to 4.0' into both approach roadways. There previously reported minor roadway

BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

embankment erosion at the far left corner, adjacent to the bridge has been repaired with small placed rock.

**Deck Wearing Surface:**

**Prior Condition Rating** 7  
**Current Condition Rating** N/A

The deck wearing surface condition was not evaluated as part of the January 3, 2018 interim inspection. Only problem areas and elements related to the bridge posting were evaluated. The following deck wearing surface condition description is taken from the 2017 NBIS inspection report.

The bituminous wearing surface is in overall good condition with minor to moderate wear and a few sealed/unsealed (up to 1/4" wide) longitudinal cracks in the right travel lane. A large bituminous patch in the left travel lane is new since the 1/20/16 interim inspection.

**Deck:**

**Prior Condition Rating** 4  
**Current Condition Rating** 4

The top of deck is not visible due to the bituminous wearing surface overlay. There is no separate structural deck for this bridge type. The deck rating is controlled by the superstructure rating.

**Superstructure:**

**Prior Condition Rating** 4  
**Current Condition Rating** 4

The 3" x 12" nail laminated longitudinal treated timbers on edge are in overall poor condition. There is typical tar seepage and misalignment between the planks and active water leakage. The planks exhibit several splits and checks throughout with random areas of rot with up to 3/8" awl penetrations. There is a 12" x 6" transverse timber tie that spans the full-width at mid-span. The tie has a split with propagating cracks at the right end.

**Paint Condition:**

**Prior Condition Rating** N N  
**Current Condition Rating** N N

None.

**Substructure:**

**Prior Condition Rating** 5  
**Current Condition Rating** N/A

The substructure condition was not evaluated as part of the January 3, 2018 interim inspection. Only problem areas and elements related to the bridge posting were evaluated. The following substructure condition description is taken from the 2017 NBIS inspection report.

BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

The substructure is in overall fair condition and is comprised of timber lagging spanning between timber piles. There are a few small gaps between lagging boards and misalignment (up to 1/2"). Since the 1/20/16 interim inspection, additional new piles and new timber caps were installed along the wingwalls. The original exposed tops of the piles exhibit center rot, up to 6" deep.

**Channel:**

**Prior Condition Rating    6**  
**Current Condition Rating N/A**

The channel condition was not evaluated as part of the January 3, 2018 interim inspection. Only problem areas and elements related to the bridge posting were evaluated. The following channel condition description is taken from the 2017 NBIS inspection report.

The channel flows from left to right with a 30 degree skew upstream, flows parallel to the abutments and continues straight downstream. The streambed material is comprised of large stones, cobbles and sand. The deepest section of the channel is at the 2/3 point. Placed rock protection is in place at both upstream wingwalls and at the downstream far wing. There is placed rock along the abutments. Timber debris was observed along the near left (upstream) bank (5 CY) and the far left (upstream) bank (1 CY).

The S.C.B.I. was calculated in iForms on 2/6/17 and returned a code of '8'. Based on the S.C.B.I. code of '8', the bridge is not considered scour critical.

**Safety Features:**

**Prior Condition Rating    4888**  
**Current Condition Rating    N/A**

The traffic safety features were not evaluated as part of the January 3, 2018 interim inspection. Only problem areas and elements related to the bridge posting were evaluated. The following traffic safety feature condition description is taken from the 2017 NBIS inspection report.

The bridge railing consists of structure mounted timber guiderail that is in overall good condition. The far left (northeast) post is slightly out of plumb. The transitions consist of 2'-8" high, 25' long, gradually stiffened, double nested Type 2SC W-beam guiderail with timber and plastic offsets and rubrail. The approach guiderail is comprised of 2'-5" high, 25' long, Type 2S W-beam guiderail with plastic offsets. There are SKT-350 end treatments in the clear zone at each corner.

**Additional Notes:**

Based on the superstructure and deck condition ratings ('4 - Poor'), the bridge is considered structurally deficient.

Only problem areas and elements related to the bridge posting were evaluated during the 2018 interim inspection.

Work done since the 1/25/17 routine inspection:

- None.

BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

**LOAD RATING SUMMARY**

The chart shown below is a summary of the current ratings. These ratings are based upon an allowable stress analysis performed during a previous inspection cycle. A copy of that analysis is not included in this report. These ratings are still valid, as the current condition of the bridge is similar to the condition noted during the previous inspection cycle.

LOAD RATING SUMMARY			
	INV RATING (TONS)	OPR RATING (TONS)	SLC RATING (TONS)
H20	12	18	18
HS20	21	32	28
ML80	13	19	17
TK527	15	23	20

**POSTING REVIEW**

The bridge is currently posted for 17 Tons Except Combinations 28 Tons. This posting level may remain until the next inspection. At that time, the posting level should be reviewed again.

BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

**RECOMMENDATIONS**

**Maintenance**

The following maintenance program is provided for the bridge. The estimated costs listed below are based on PennDOT Bridge Management System unit costs. The actual costs will vary due to site-specific conditions.

Priority Code 0 - Critical

None.				\$0
-------	--	--	--	-----

Priority Code 1 - High Priority

None.				\$0
-------	--	--	--	-----

Priority Code 2 - Priority

Repair/replace the cracked superstructure timbers.				
21 EA	x	\$1,165		\$24,465

Mill existing bituminous, install waterproof membrane and repave the deck wearing surface (thickness not to exceed 3").				
72 SY	x	\$48		\$3,456

Reset the leaning near advance posting signs at Newark Road.				
1 EA	x	\$360		\$360

Priority Code 3 - Schedule

Repair the rotted piles where exposed.				
6 EA	x	\$2,120		\$12,720

Priority Code 4 - Program

Seal the cracks in both approach roadways.				
1 SY	x	\$75		\$75

Remove the timber debris from the near left and far left (upstream) banks.				
6 CY	x	\$24		\$144

Priority Code 5 - Routine

None.				\$0
-------	--	--	--	-----

<b>Total Repair Costs</b>				<b>\$41,220</b>
---------------------------	--	--	--	-----------------



BMS No. 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek

**Inspection Schedule:**

In addition to the regular biennial NBIS inspections, interim/partial inspections are required on a twelve month cycle in accordance with the PennDOT Bridge Safety Inspection Manual, Pub 238, 2nd edition, March 2010, Part IP, Chapter 2, Table 2.3.2.4-1. The shortened interval is recommended due to the 17 Tons Except Combinations 28 Tons posted weight restriction.

**Inspection Equipment:**

Special inspection equipment was not required for the interim inspection.

**Waterway Information:**

The substructure units were fully accessible for the interim inspection. An underwater inspection is not warranted at this time.

**5A01** SR ID: 15721703130001 **5A03** BR Key: 45932 **7A01** Inspection Date: January 03, 2018

**1A09** Inspection Status: 2 - Submitted  
**7A02** Team Leader: 2126 Pickering, Corts & S Gross  
**7A03** Inspection Type: I - Interim (special)  
**7A05** Inspected By: 8 - Consulting Firm

### Structure Description

**5A08** FHWA Facility Carried: Hess Mill Road  
**5A07** Features Intersected: W. Br. White Clay Creek  
**5A09** Location: 1/4 Mi W PA-841 3909-G8  
**5C01** Roadway Name: Hess Mill Road  
**5A06** City / Borough Name: 15/217 - FRANKLIN  
**6B48** Combust. Mat. Under Bridge:  
 Combust. Mat. Under Bridge Note:

### Structure Type

Main	Approach
<b>6A26</b> Material Makeup: 5 - Timber	<b>6A26</b> Material Makeup:
<b>6A27</b> Physical Makeup: 9 - Other or none	<b>6A27</b> Physical Makeup:
<b>6A28</b> Span Interaction: 1 - Simple, non-comp	<b>6A28</b> Span Interaction:
<b>6A29</b> Structural Config: 99 - Other	<b>6A29</b> Structural Config:

### Sign Information

ID01	ID02	ID03	ID04	ID06	ID07	ID05	Comments
Type of Sign	Sign Needed	Sign Message	Near Adv	Bridge Site Near	Far	Far Adv	
0 - Bridge	Yes		D	G	G	G	N ADV (Newark Road Intersection): "1 1/4 MILE AHEAD". Signs leaning.
1 - Bridge Weight Limit	Yes	17 Tons	D	G	G	G	
2 - Except Combinations	Yes	28 Tons	D	G	G	G	N ADV (Conard Mill Road intersection): "1 MILE AHEAD".
3 - One Truck at a Time	No						NEAR: Good condition; no problems noted. FAR: Good condition; no problems noted.
4 - Vertical Clearance On	No						F ADV (South Guernsey Road intersection): "500 FT AHEAD".
5 - Vertical Clearance Under	No						
6 - One Lane Bridge	No						
7 - Narrow Bridge	No						
8 - Hazardous Clearance	No						
9 - Other	No						

**5A01** SR ID: 15721703130001 **5A03** BR Key: 45932 **7A01** Inspection Date: January 03, 2018

### Features Intersected

6C02		5C03		5B09		5C06		5C29		4A20		4A19		6C18		6C19		6C20		6C21		6C22		6C23		6C24		6B17	
SR ID		On/		Skew						Min Lat CI				Tot Hor CI				Min Vrt CI Rdwys				Vrt CI Over 10ft				VT			
SR	Seg	Under		Angle		Dir		NHS		Left		Right		Left		Right		Left		Right		Left		Right		Sign		ADT	
-	-	1		-1		N/A		0 - Not on NHS		-1.0		0.0		-1.0		25.2		99.9		99.9		99.9		99.9		0		500	
		2		-1		N/A				-1.0		0.0		-1.0		-1.0		-1.0		-1.0		-1.0		-1.0				-1	

**6B15** Design Exceptions:

**6A50** Sup Latent Problem:

**6A51** Sub Latent Problem:

### Deck Geometry

Table Used for Appraisal: 1 - 2A/2B

#### Controlling Values

**5C10** ADT: 500  
**5C27** Bridge Road Width: 25.2

**4A10** Appraisal: 4 - Tolerable

**Notes:** Bridge Roadway width 25' - 3" curb to curb. Use estimated 500 vpd for ADT. (estimated from PennDOT Traffic Volume Map - 2009)

**4A11** Underclr Appr: N - Not applicable (NBI)

**6B13** Controlling Vertical: 0.0 FT

Controlling Lateral:

### Traffic Safety Features

<b>IA01</b>	<b>IA02</b>	<b>IA03</b>	<b>5C08</b>
Feature Type	Location	Adequacy Rating	Posted Spd Lmt (mph)
1 - Railing		4 - does not meet code 6	35

**Comment:** The far left (northeast) post is slightly out of plumb.

Bridge Rail - 24" high x 5" wide timber rail with 6' center to center post spacing mounted on 5" high x 11" wide timber rail with an additional 4" high x 11" wide timber blocks firmly mounted to the timber deck planks.

End Posts - 12" x 12"

Interior Posts - 6" x 12"

Timber Spacers - 11" high x 2 1/4" thick (new in 2013)

Curbs - 4" high x 11" wide

2 - Transition 8 - good cond/meets stds 35

**Comment:** NL, NR, FL, FR: 2'-8" high, 25' long gradually stiffened, nested Type 2SCC & 2SC W-beam guiderail with timber and plastic offsets and rubrail.

3 - Approach Guiderail 8 - good cond/meets stds 35

**Comment:** NL, NR, FL, FR: 2'-5" high, 25' long Type 2S W-beam guiderail with plastic offsets.

4 - Approach railend 8 - good cond/meets stds 35

**Comment:** NL, NR, FL, FR: SKT-350 in the clear zone. All corners considered continuous at 87.5' or greater from the bridge.

5A01

SR ID: 15721703130001

5A03

BR Key: 45932

7A01

Inspection Date: January 03, 2018

**Approach Alignment**

4A02

Code: 8 - Equal Desirable Crit

Comment: No sight restrictions. No speed reduction required.

**Approach Roadway**

6B39

Code: 7 - Good

**Pavement:** THE APPROACH ROADWAY CONDITION WAS NOT EVALUATED AS PART OF THE JANUARY 3, 2018 INTERIM INSPECTION. ONLY PROBLEM AREAS AND ELEMENTS RELATED TO THE BRIDGE POSTING WERE EVALUATED. THE FOLLOWING APPROACH ROADWAY CONDITION DESCRIPTION IS TAKEN FROM THE 2017 NBIS INSPECTION REPORT.

Moderate wear and sealed and unsealed fine to medium longitudinal cracking along the centerline of roadway beyond the repaved portions. New bituminous patches along left travel lane of deck extend up to 4.0' into approaches.

**Drainage:** Natural with small rock protection. The minor erosion at far left corner at the bridge (1 CY) has been repaired with small rock protection.

**Shoulders:** None.

**Approach Slab**

6B38

Code: N - N/A

**Pavement:**

6B04

**Bump at Bridge:** No Bump

6A39

**Relief Joints:** 0 - Joints not present

6A41

**Number of Joints:** 0**Comment:**

6B02

**New Wearing Surface Under Bridge:** No

5A01

SR ID: 15721703130001

5A03

BR Key: 45932

7A01

Inspection Date: January 03, 2018

## Deck Wearing Surface

### Main

5B02 Type of Wearing Surface: 6 - Bituminous

5B03 Type of Memb. Water-Proof: 0 - None

5B04 Deck Corrosion Protection: 8 - Unknown

6A33 Thickness: 3.0

6A34 Date Recorded: 02/17/2011

6B40 Condition Rating: 7 - Good-some minor problems

IC02 Dk WS Notes: THE DECK WEARING SURFACE CONDITION WAS NOT EVALUATED AS PART OF THE JANUARY 3, 2018 INTERIM INSPECTION. ONLY PROBLEM AREAS AND ELEMENTS RELATED TO THE BRIDGE POSTING WERE EVALUATED. THE FOLLOWING DECK WEARING SURFACE CONDITION DESCRIPTION IS TAKEN FROM THE 2017 NBIS INSPECTION REPORT.

(Bituminous) Minor to moderate wear. Few sealed/unsealed (up to 1/4" wide) longitudinal cracks in right travel lane (45 LF). Large bituminous patch (200 SF) in left travel lane is new since the 1/20/16 interim inspection.

### Approach

6A30 Type of Wearing Surface:

6A31 Type of Memb. Water-Proof:

6A32 Deck Corrosion Protection:

6A33 Thickness: -1.0

6A34 Date Recorded: 01/01/1901

## Expansion Joints

6A41 Number of Expansion Joints: 0

Joint Number	Joint Type	Movement Class	Manufacture Code	Bridge Seat Cleaning	Bridge Seat Cleaning Note	Scuppers w/ Downspouts	Scuppers w/o Downspouts
0				0		0	0

## Deck

1A01 Condition Rating: 4 - Poor-advanced section loss, deterioration, spalling or scour.

6B07 Est. Spall Delamination: 0.00 %

6B10 Est. Chloride Content: 0.00 %

6B08 Date: 01/01/1901

6B11 Date: 01/01/1901

1A07 Unrepaired Spalls: 0.00 SF

6B47 Deck Cracking Metric: 0.00 YD/SY

Deck Top: The top of the deck is not visible due to the bituminous wearing surface overlay.

Top of deck was visible in 11/2010 during repaving:

Throughout - top 1/8" - 1/4" of timber was soft.

NL Quadrant - top 1/2" of timber was soft.

FAR Center - top 3/4" of timber was soft.

Deck Underside: See superstructure. There is no separate deck for this structure type.

Deck Drainage: Scuppers spaced under curbs are open and functional.

Expansion Joints: N/A

Deck Notes: N/A

## Superstructure

1A04 Condition Rating: 4 - Poor-adv. section loss, deterioration, spalling or scour.



5A01

SR ID: 15721703130001

5A03

BR Key: 45932

7A01

Inspection Date: January 03, 2018

**Narrative:** The 3"x12" nail laminated longitudinal treated timbers on edge (105 planks in total) exhibit typical checks, splits and knots throughout with random areas of soft timber with up to 3/8" awl penetrations. There are several areas of soft rot, tar seepage and active water leakage.

**BAY 1 -**

Plank 30 - Full-width diagonal split located 39" from midspan with no deflection.  
Plank 35 - Diagonal split in bottom 90" from NAB with no deflection.  
Plank 36 - Full-width horizontal split located 70' from NAB with 1" deflection from plank 35.  
Plank 38 - Full-width diagonal split with 1" downward vertical displacement located 24" from NAB.  
Plank 41 - Full-width horizontal split located 3' from midspan.  
Plank 44 - Full-width horizontal split located 34" from NAB.  
Plank 45 - Full-width horizontal split located 2' from midspan with 3/4" deflection from plank 44.  
Plank 47 - Full-width diagonal split with 2" downward vertical displacement located 8' from NAB. Full-width horizontal split located 50" from the NAB.  
Plank 49 - Horizontal split at midspan.  
Plank 51 - 10" long diagonal split with 3/4" downward vertical displacement from plank 52 located 32" from the NAB.  
Plank 53 - Diagonal split 1/4" deflection, located 75" from NAB.  
Plank 55 - Full-width diagonal split with 1/2" downward vertical displacement located 75" from the NAB.  
Plank 57 - Full-width diagonal split with 1" downward vertical displacement located 9' from the NAB.  
Plank 64 - Full-width horizontal split located 9' from the NAB with 1/2" deflection from plank 63.  
Plank 66 - Full-width intermittent horizontal split at 74" from the NAB.  
Plank 79 - 40" long longitudinal split with a 12" x 1" wide x 1" deep void at 32" from the NAB.  
Plank 95 - Horizontal split 92" from the NAB with 3/4" deflection from plank 96.

**Girders/Beams: BAY 2 -**

Plank 6 - 4' longitudinal split from midspan toward FAB.  
Plank 35 - Diagonal split extending 1' toward to the FAB located at the middle diaphragm.  
Plank 38 - Horizontal split with 1" deflection, 6" from midspan.  
Plank 43 - Full-width horizontal split with 1 1/2" downward vertical displacement located 5' from FAB.  
Planks 44, 48, 49 - Full-width horizontal splits with 1" vertical displacement located 5' from the FAB.  
Plank 61 - 12" long longitudinal split 60" from the FAB.  
Plank 93 - Diagonal split with 1" deflection, 8" from midspan.

**Floorbeams:** N/A

**Stringers:** N/A

**Diaphragms:** Full-width 12" high x 6" wide lateral bracing across midspan. There is a split with propagating checks at right end and several checks throughout.

**Truss Members:** N/A

**Portals/Bracings:** N/A

**Bearings:** Pile caps exhibit random checks.

**Drainage System:** N/A

**5A01** SR ID: 15721703130001**5A03** BR Key: 45932**7A01** Inspection Date: January 03, 2018**1A02** Substructure Condition Rating: 5 - Fair-all primary structural elements are sound but may have minor section loss, cracking, spalling.

**Notes:** THE SUBSTRUCTURE CONDITION WAS NOT EVALUATED AS PART OF THE JANUARY 3, 2018 INTERIM INSPECTION. ONLY PROBLEM AREAS AND ELEMENTS RELATED TO THE BRIDGE POSTING WERE EVALUATED. THE FOLLOWING SUBSTRUCTURE CONDITION DESCRIPTION IS TAKEN FROM THE 2017 NBIS INSPECTION REPORT.

**Near Abutment****Backwall:** Not visible.**Bridge Seats:** Treated timber, 12 1/4" x 12 1/4". Active water stains and random checks throughout.**Cheekwalls:** None.**Stem:** 3" x 12" timber lagging with 12" diameter treated timber piles with aluminum caps. Pile spacing ranges from 56" to 65". Lagging board one row up from stream is displaced 1/2" outward from the other lagging boards with a void behind board. 1/2" and 1/4" gap between some boards with stone fill visible. Area behind right side of abutment was excavated, plywood placed against back of lagging to help retain new geotextile wrapped stone fill. The previous undermining along the near abutment is now filled with silt and placed rock with isolated 1" vertical gaps.**Wings:** Treated timber lagging behind treated timber piles. Lagging boards 12" x 3". Since the 1/20/16 interim inspection, additional new piles and new timber caps were installed along the wingwalls. The original exposed tops of the piles exhibit center rot, up to 6" deep. Rock protection lines the left wingwall.**Footing:** Not visible.**Piles:** 12" diameter timber with a few checks throughout. The pile at the left end of the near left wingwall has center rot at the top up to 6" deep x full diameter. Piles 2 & 6 are out of plumb (from construction).**IN20** Scour Undermine: 0 - No**Settlement:** None observed.**Embank Slope-wall:** N/A**Wall Drainage:** 4" pipe at base of WNR - Appears clear and functional.**Far Abutment****Backwall:** Not visible.**Bridge Seats:** Treated timber, 12 1/4" x 12 1/4". Active water leakage and checks throughout.**Cheekwalls:** None.**Stem:** 3" x 12" timber lagging with 12" diameter treated timber piles with aluminum caps. Pile spacing ranges from 56" to 65". The previous undermining along the far abutment is now filled with placed rock.**Wings:** Treated timber lagging behind treated timber piles. Lagging boards 12" x 3". WFL 12' long. Since the previous (1/20/16) interim inspection, additional new piles and new timber caps were installed along the wingwalls. The original exposed tops of the piles exhibit center rot, up to 6" deep. Placed rock lines the wingwall.**Footing:** Not visible.**Piles:** 12" diameter treated timber. Far left pile is split 18" x 2" at the top along the back. Piles 3 & 4 are sistered. Piles 1, 2, 4 and 5 are out of plumb (from construction).**IN20** Scour Undermine: 0 - No**Settlement:** None observed.**Embank Slope-wall:** N/A**Wall Drainage:** None.



**5A01**

SR ID: 15721703130001

**5A03**

BR Key: 45932

**7A01**

Inspection Date: January 03, 2018

**Main**

**6A44**

Group: 9 - Group 9

**6A45 - 6A48**

Critical Ranking Factor: 9993

**6A49**

Total Critical Ranking Factor: 30

**Structure Type (Dept)**

**6A26**

Material Makeup: 5 - Timber

**6A27**

Physical Makeup: 9 - Other or none

**6A28**

Span Interaction: 1 - Simple, non-comp

**6A29**

Structural Config: 99 - Other

**Approach**

**6A44**

Group:

**6A45 - 6A48**

Critical Ranking Factor: 000

**6A49**

Total Critical Ranking Factor: 0

**Structure Type (Dept)**

**6A26**

Material Makeup:

**6A27**

Physical Makeup:

**6A28**

Span Interaction:

**6A29**

Structural Config:

**Fracture Critical Details**

**IF01**

Location:

**IF02**

Type:

**IF05**

FC Stress Category:

**IF03**

Member:

**IF04**

Member Detail:

**IF06**

Notes:



**5A01** SR ID: 15721703130001 **5A03** BR Key: 45932 **7A01** Inspection Date: January 03, 2018

**IU00a** UW Reviewer Action:

**IU00b** Reviewer Comments:

**IU02** Number of Units: 0 **IU01** Recalculate SCBI: 0 - no recalc needed

**IU03** SCBI Source: O - observed **4A08** SCBI: 8 - Stable Above Footing

**IU04** Overall SCBI: 8 **IU05** SAR: 78.00

**IU04b** SCBI Recalculated: ☐

**IU06** Streambed Material #1: A5 - Stable nat alluvium

**IU06** Streambed Material #2:

**IU07** Notes: Boulders, gravel and sand.

#### Current Countermeasures

CM Num	Type	Location	Condition	Subunit
	<b>IU21</b>	<b>IU22</b>	<b>IU23</b>	<b>IU24</b>

#### Possible Countermeasures

PCM Num	Location	Work Candidate
	<b>IU25</b>	<b>IU26</b>

#### SAR Calculation Data

**IU08** Debris Potential: 1 - Medium

**IU09** Trapping Potential: 2 - High

**IU10** Pressure Flow: 0 - No

**IU11** NAB Location: 2 - Right **IU12** FAB Location: 1 - Left

##### US Left Wingwall

**IU13** Presence: 1 - Yes **IU14** Condition: 1 - Good

##### US Right Wingwall

**IU15** Presence: 1 - Yes **IU16** Condition: 1 - Good

##### Horizontal Debris Blockage

**IU17** Start: 0 **IU18** End: 0

##### Vertical Debris Blockage

**IU19** Start: 0 **IU20** End: 0

**5A01** SR ID: 15721703130001 **5A03** BR Key: 45932 **7A01** Inspection Date: January 03, 2018

**Sub Unit OSA Data**

**Observed Scour Rating Components**

<b>IN01</b>	<b>IN12</b>	<b>IN13</b>	<b>IN14</b>	<b>IN15</b>	<b>IN19</b>	<b>IN04</b>	<b>IN05</b>	<b>IN06</b>	<b>IN07</b>	<b>IN08</b>	<b>IN09</b>	<b>IN10</b>	<b>IN11</b>	<b>IN03</b>
Sub	Pier/	Inv.								Opening			Velocity/	Observed
Unit	Abut	Found	Found	Strmbd	Move	Chg Since	Scour	Debris	Scour-	Adeq. /	Sediment	Alignment	Stream	Scour
	Type	Type	Type	Mat	Ind	Last Insp	Hole	Potential	ability	Channel			Slope	Rating
FAB	7	G	3	A5	0	8	9	6	5	8	8	6	7	6
NAB	7	G	3	A5	0	8	9	6	5	8	7	5	7	6

**Other Subunit Details**

<b>IN01</b>	<b>IN16</b>	<b>IN18</b>	<b>IN17</b>	<b>IN20</b>	<b>IN21</b>	<b>IN02</b>	<b>IN22</b>	<b>IN23</b>	<b>IU27</b>
Sub	UW	Water	Observed	Scour	Counter-	Info from	100 yr	500 yr	SCBI
Unit	Insp	Dept	Scour	Undermine	measures	Current Insp	Flood Calc	Flood Calc	Code
	Type		Depth				Scour Depth	Scour Depth	
FAB	E	0.0	0.0	0	0	0	0.0	0.0	8

**IN24** Notes: THE UNDERWATER CONDITION WAS NOT EVALUATED AS PART OF THE JANUARY 3, 2018 INTERIM INSPECTION. ONLY PROBLEM AREAS AND ELEMENTS RELATED TO THE BRIDGE POSTING WERE EVALUATED. THE FOLLOW UNDERWATER CONDITION DESCRIPTION IS TAKEN FROM THE 2017 NBIS INSPECTION REPORT. No scour. Previous undermining of lagging boards is protected with placed rock.

NAB E 0.0 0.0 0 0 0 0.0 0.0 8

**IN24** Notes: THE UNDERWATER CONDITION WAS NOT EVALUATED AS PART OF THE JANUARY 3, 2018 INTERIM INSPECTION. ONLY PROBLEM AREAS AND ELEMENTS RELATED TO THE BRIDGE POSTING WERE EVALUATED. THE FOLLOW UNDERWATER CONDITION DESCRIPTION IS TAKEN FROM THE 2017 NBIS INSPECTION REPORT. No scour. Previous undermining of lagging boards is protected with placed rock.

**Underclearance**

<b>IL09</b>	Origin Description:
<b>IL10</b>	Horizontal:
<b>IL11</b>	Vertical:
<b>IL12</b>	Notes:

**5A01**

SR ID: 15721703130001

**5A03**

BR Key: 45932

**7A01**

Inspection Date: January 03, 2018

**Channel****1A05**

Channel/ Channel Protection Cond. Rating: 6

**Channel:** THE CHANNEL CONDITION WAS NOT EVALUATED AS PART OF THE JANUARY 3, 2018 INTERIM INSPECTION. ONLY PROBLEM AREAS AND ELEMENTS RELATED TO THE BRIDGE POSTING WERE EVALUATED. THE FOLLOWING CHANNEL CONDITION DESCRIPTION IS TAKEN FROM THE 2017 NBIS INSPECTION REPORT.

No scour. The channel flows left to right and enters from a 30 degree skew upstream toward the far abutment, flows parallel to the far abutment and exits straight. The thalweg is at the 2/3 point.

**Banks:** Moderately sloped, well vegetated with medium to large trees and moderate to severe erosion downstream.

**Streambed Movements:** Near 1/4 of span silted to depth of 1', about 3" below the waterline.

**Debris, Vegetation:** Timber debris accumulation at the near left (upstream) bank (5 C.Y.) and far left (upstream) bank (1 C.Y.).

**River Control Devices:** None.

**Embank/Strmbd Contr:** Placed rock at upstream wings in place; placed rock at both abutments about 1' into channel and downstream far wing. At wings the placed rock is 1.5' to 2.5' diameter and abutments 0.5' to 1.0' diameter.

**Drift Other:** None.

**Waterway Adequacy****1A06**

Appraisal Code: 7

**Notes:** Approaches level with the deck.

**IL02**

Overtop Risk: S - Slight

**IL03**

Traffic Delay: I - Insignificant

**5C22**

Functional Class: 09 - Rural Local

**High Water Mark****IL05**

Elevation: -1.0

**IL06**

Date: January 01, 1901

**IL07**

New High Water Mark: No

**Notes:** Near approach washed out behind abutment during Tropical Storm Nicole 10-30-2010.

High water mark unknown. Reference datum: Underside of left fascia to water surface at mid-span = 6.8'.



**5A01** SR ID: 15721703130001

**5A03** BR Key: 45932

**7A01** Inspection Date: January 03, 2018

### Paint Condition

**6B36** Paint Cond Rating: N - Not Applicable

**6B37** Ext of Paint Cond: N - Not Applicable

**6B35** New Paint: 0 - no new paint

Int Beam / Gird: N/A

Fascias: N/A

Splash Zone Truss Gird: N/A

Truss: N/A

Bearings: N/A

Other: N/A

**4B03** Bdrge Cap. Appraisal: 0 - >39.9% below

**6B19** Controlling: 3 - ML80

### Load Ratings

**4B15** Load Rating Review Recommended: Recalc not required  
Due To:

**IR03** Calculation Date: June 07, 2011

**IR02** Rating Approval Date: June 23, 2011

### Load Rating Details

	IR10	IR11	IR11a	IR05	IR06	IR07	IR16	IR14	IR15	IR13	IR12
	IR	OR	SLC	NBI	RTNG	CONT		AASHTO	AASHTO	OPR	INV
LOAD	LOAD	LOAD	RATING	IND	ANAL	MEM	ANALYSIS	MANUAL	SPEC	GOV	GOV
TYPE					METH	TYPE	ENGINEER	YEAR	YEAR	CRITERIA	CRITERIA
2	21	32	28	1	1	5	McCormick Taylor	2004	1996	M	M
Notes Description: allowable stress method											
1	12	18	18	0	5	5	McCormick Taylor	2004	1996	M	M
Notes Description:											
8	13	19	17	0	5	5	McCormick Taylor	2004	1996	M	M
Notes Description:											
0	15	23	20	0	5	5	McCormick Taylor	2004	1996	M	M
Notes Description:											

**MAINTENANCE NEEDS DATA**  
**Form M**

**5A01** SR ID: 15721703130001

**5A03** BR Key: 45932

**7A01** Inspection Date: January 03, 2018

**Proposed Maintenance Items :-**

IM01	IM03	IM04	IM05	IM06	IM08	IM11	
Type of Work	Action	Est Qty	UOM	Priority	Init Recm'd Date	Target Year	Ass. WK
Flexible	70 -	1	EA	2	01/03/2018	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: Reset leaning near advance posting signs at Newark Road.				
IM09	Location: N. Advance						
Flexible	62 -	21	EA	2	01/20/2016	0	No
IM07	Status: 2 - Work planned/Contr	IM15	Notes: Repair/replace split superstructure timbers.				
Previous (12/14/10) quantity '15' changed based on 1/20/16 inspection.							
#1 The maintenance item has been changed from a "1 - High Priority" to a "2 - Priority" due to the current bridge posting of 17 Tons Except Combinations 28 Tons taking into account the cracked deck members.							
#2 A letter was sent to the township on March 10, 2011.							
IM09	Location: 1						
Flexible	10 -	72	SY	2	01/13/2015	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: Mill existing bituminous, install waterproof membrane and repave (thickness not to exceed 3").				
IM09	Location: 1						
Flexible	67 -	6	EA	3	02/26/2014	0	No
IM07	Status: 2 - Work planned/Contr	IM15	Notes: Repair the rotted piles where exposed.				
IM09	Location: N F						
Flexible	3 -	6	CY	4	01/13/2015	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: Remove timber debris from upstream channel.				
IM09	Location: UP						
Flexible	40 - Pr Maint	1	SY	4	01/13/2015	0	No
IM07	Status: 0 - Work not planned	IM15	Notes: Seal cracks.				
IM09	Location: N F						

**MAINTENANCE NEEDS DATA**  
**Form M**

**5A01** SR ID: 15721703130001

**5A03** BR Key: 45932

**7A01** Inspection Date: January 03, 2018

**Completed Maintenance Items :-**

IM01	IM03	IM04	IM05	IM06	IM08	IM11	
Type of Work	Action	Est Qty	UOM	Priority	Completed Date	Target Year	Ass. WK
Flexible	70 -	1.00	EA	0	02/29/2016	0	No
IM07	Status: 5 - Completed/Dept	IM15	Notes: Replace incorrect near advance load posting signs at Newark Road. Weight values should be 17 Tons Except Combinations 28 Tons.  #1 N/A #2 Priority notification letter sent to Joan McVaugh of Franklin Township on 2/29/2016. #3 Prior to the 1/25/17 routine inspection, the incorrect near advance weight limit signs at Newark Road were replaced with the correct weight limits.				
IM09	Location: N. Advance						
Flexible	47 -	1.00	EA	3	01/13/2015	0	No
IM07	Status: 5 - Completed/Dept	IM15	Notes: Repair the erosion at the bridge at the far left corner.  #1 N/A #2 Prior to the 1/25/17 routine inspection, rock was placed in the eroded area.				
IM09	Location: FLt						
Flexible	70 -	3.00	EA	5	02/26/2014	0	No
IM07	Status: 5 - Completed/Dept	IM15	Notes: The Supplemental Near Advance posting is not within 25' of the Newark Road intersection and the distance plaque should read "1 1/4 MILE AHEAD" instead of "1 2/10 MILE AHEAD. Replace the non-standard white distance plaques at the Supplemental Near Advance, Near Advance, and Far Advance with standard yellow background distance plaques.  #1 N/A #2 Prior to the 1/13/15 inspection, the supplemental near advance was moved to within 25' of the intersection. Also the distance plaques were replaced with standard yellow background signs.				
IM09	Location:						
Flexible	70 -	1.00	EA	0	02/24/2012	0	No
IM07	Status: 6 - Completed/Contr	IM15	Notes: FADV - replace the non-standard "485 FT AHEAD" distance plaque to read "500 FEET AHEAD" at the South Guernsey Road intersection.  #1 The Township replaced the sign on February 20, 2013. #2 Priority notification letters were sent to Ms. Joan McVaugh, Franklin Township's Township Manager, on February 28, 2012 and February 4, 2013.				
IM09	Location:						

**MAINTENANCE NEEDS DATA**  
**Form M**

**5A01** SR ID: 15721703130001

**5A03** BR Key: 45932

**7A01** Inspection Date: January 03, 2018

Flexible 24 - Scour-

1.00 EA 0 02/24/2012 0 No

**IM07** Status: 6 - Completed/Contr

**IM15** Notes: NADV - Cut/Remove the vegetation blocking the load posting located at the Conard Mill Road intersection.

#1 Observed completed during the 2013 NBIS Inspection.

#2 A priority notification letter was sent to Ms. Joan McVaugh, Franklin Township's Township Manager, on February 28, 2012.

**IM09** Location:

Flexible 70 -

2.00 EA 0 06/23/2011 0 No

**IM07** Status: 5 - Completed/Dept

**IM15** Notes: NADV - Cut/Remove the vegetation blocking the load posting located at the Conard Mill Road intersection.

FADV - replace the non-standard "485 FT AHEAD" distance plaque to read "500 FEET AHEAD" at the South Guernsey Road intersection.

#1

#2 A priority notification letter was sent to Ms. Joan McVaugh, Franklin Township's Township Manager, on February 28, 2012.

**IM09** Location:

Flexible 22 - Raise-

1.00 CY 2 02/14/2011 0 No

**IM07** Status: 6 - Completed/Contr

**IM15** Notes: Repair undermining below timber lagging boards at both abutments.

#1 Observed completed during 2013 NBIS Inspection.

**IM09** Location:

Flexible 60 - Other-

3.00 EA 3 02/14/2011 0 No

**IM07** Status: 5 - Completed/Dept

**IM15** Notes: Repair/replace the timber caps at the far wingwalls.

#1 N/A

#2 Prior to the 1/25/17 routine inspection, the timber caps on the wingwalls were replaced.

**IM09** Location: FAB

Flexible 27 -

4.00 EA 2 12/14/2010 0 No

**IM07** Status: 6 - Completed/Contr

**IM15** Notes: Install standard transitions, approach guiderail and end treatments at each corner.

#1 Observed completed during 2013 NBIS inspection.

**IM09** Location:

Flexible 10 -

70.00 SY 3 12/14/2010 0 No

**IM07** Status: 6 - Completed/Contr

**IM15** Notes: replace wearing surface

**IM09** Location:

**MAINTENANCE NEEDS DATA**  
**Form M**

**5A01**

SR ID: 15721703130001

**5A03**

BR Key: 45932

**7A01**

Inspection Date: January 03, 2018

Flexible 13 -~~Remove~~

10.00 CY

3

12/14/2010

0

No

**IM07**

Status: 6 - Completed/Contr

**IM15**

Notes: Install rock protection along both abutments.

#1 Observed completed during 2013 NBIS Inspection.

**IM09**

Location:



5A01

SR ID: 15721703130001

5A03

BR Key: 45932

7A01

Inspection Date: January 03, 2018

**Current Inspection**

7A03 Primary Type: I - Interim (special)

7A06 Types of Inspections Performed:

NBI	Underwater	Element	Fracture Critical	Other Special
No	No	No	No	Yes

**Inspection Man Hours**

6B26	NBI Crew:	14.00	6B30	Underwater:	0.00
6B28	Fracture Critical:	0.00	6B29	Other 1:	0.00
6B27	Crane:	0.00	6B31	Other 2:	0.00

**Inspection Costs (Entered to nearest dollar)**

6B32	Engineering:	1,925	6B33	Rigging:	0
			6B34	Office:	0

**Special Equip Used:**

6B12	Temperature:	15.0	6B09	Weather:	1 - Clear
6B03	Inventory Review Recommended:	No			

**Change Notes:**

**Inspection Team**

7A05	Inspected By:	8 - Consulting Firm
7A02	Team Leader:	Pickering, Corts & S Gross
6B23	Team Member:	B. Fink
6B24	Hired By:	1
6B25	Insp Contract Num:	E03654
2A02	Inspection Notes:	No utilities. No asbestos.

Based on the superstructure and deck condition ratings ('4 - Poor'), the bridge is considered structurally deficient.

Bridge requires a 12 month interim inspection due to being load posting.

The S.C.B.I. was calculated in iForms on 2/6/17 and returned a code of '8'. Based on the S.C.B.I. code of '8', the bridge is not considered scour critical.

Only problem areas and elements related to the bridge posting were evaluated during the 2018 interim inspection.

Work done since the 1/25/17 routine inspection:  
- None.



5A01

SR ID: 15721703130001

5A03

BR Key: 45932

7A01

Inspection Date: January 03, 2018

### Next Inspection

7A14

Next Inspection By: 8 - Consulting Firm

6B20

Next Insp Type: R - Regular (routine)

### Schedule

Insp Types	7A07 Required	7A09 Frequency	7A10 Next Date
NBI	----	24	January 25, 2019
Fractural Critical	No	-1	January 01, 1901
Underwater	No	-1	January 01, 1901
Other Special	Yes	12	January 25, 2019
Element	No	-1	January 01, 1901
Crane	----		6B18 January 01, 1901

6B01

Special InspType: 4 - Problem areas only

### Estimated Inspection Man Hours

7A12

NBI Crew: 0.00

7A17

Underwater: 0.00

7A15

Fracture Critical: 0.00

7A16

Other 1: 0.00

7A13

Crane: 0.00

7A18

Other 2: 0.00



# FIELD NOTES

BMS No. 15-7217-0313-0001

District 6-0  
Chester County

By M.J.H. Date 1/13/15  
Sheet 1 of 1

VERIFIED KEG 1/20/16  
UPDATED 1/25/17 JK  
MODIFIED KEG 1/31/18

LOAD POSTING SIGNAGE DETAIL

BRIDGE (A)  
WEIGHT LIMIT  
17 (B)  
TONS

EXCEPT COMBINATIONS (C)  
28 TONS

1/4 MILES AHEAD (D)

1 MILE AHEAD (E)

500 FT AHEAD (F)

NEWARK ROAD (S.R. 896)  
SPEED  
SIGNS LEADING

CONARD MILL ROAD

(A)(B)(E)(F)

← HESS MILL ROAD

NEAR

(A)(B)(E)

FAR

(A)(B)(E)

WHITE CLAY CREEK

BMS  
15-7217-0313-0001

(A)(B)(E)(F)

SOUTH GUERASEY ROAD


CHESTERVILLE ROAD (S.R. 841)



BMS ID: 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek



1. Near approach, looking ahead.



2. Far approach, looking back.

**BMS ID: 15 7217 0313 0001**  
**Hess Mill Road over West Branch of White Clay Creek**



3. Left (upstream) elevation.



4. Right (downstream) elevation.



BMS ID: 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek




5. General view of the deck wearing surface, looking ahead.



6. General view of the superstructure, looking ahead.

BMS ID: 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek



7. Timber plank 35 in bay 2, looking back. Note the diagonal split with vertical displacement.




8. Timber plank 36 in bay 1, looking back. Note the horizontal split with vertical displacement.



BMS ID: 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek




9. Timber plank 38 in bay 1, looking left. Note the diagonal split with vertical displacement.



10. Timber planks 43 and 44 in bay 2, looking back. Note the splits with vertical displacement.



BMS ID: 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek




11. Timber plank 45 in bay 1, looking right. Note the horizontal split with vertical displacement.



12. Timber plank 47 in bay 1, looking left. Note the diagonal split with vertical displacement.

BMS ID: 15 7217 0313 0001  
Hess Mill Road over West Branch of White Clay Creek



13. Timber plank 51 in bay 1, looking ahead. Note the diagonal split with vertical displacement.



14. Timber plank 57 in bay 1, looking right. Note the diagonal split with vertical displacement.



**BMS ID: 15 7217 0313 0001**  
**Hess Mill Road over West Branch of White Clay Creek**



15. Near advance load posting sign at Newark Road (S.R. 0896). Note the sign is leaning.