Lake Service Report

		Airror Lake		AES Representative:		Greg B. &Cody W.
Service Date:	11/2	21/18		Service Time:		8:56 a.m. –
						10:24a.m.
Water Temperature:		56 Degrees				
Visibility:		24"				
Water Level		Full Pool				
Trash Collected:		Abundant				
Weather Conditions		sunny				
Outlet Debris Cleared:		Clear				
Lake Dye Applied:		N/A	Amo	ount Applied:	N/A	
Pond Fertilizer Applied:		N/A	Amo	ount Applied:	N/A	
Fish Feeders Checked:		N/A	Amo	ount Applied:	N/A	

Aquatic Vegetation Identified: None

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man - made debris removed

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed man-made debris from the shore line of the lake, water is turbid due to recent rains.



Figure 1



Fig

Picture 2



