Lake Service Report

Property Name:	Mirror Lake	AES Represen	tative:	Greg B. &Rick G.	
Service Date:	10/18/17	Service Time:		11:38 pm – 1:17 pn	n
Water Temperature:	47 Degrees				
Visibility:	24"				
Water Level	Full Pool				
Trash Collected:	Abundant				
Weather Conditions	sunny				
Outlet Debris Cleared	: Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applied	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked	: N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: None

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, manmade debris removed

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in good overall condition. We removed man made debris from the perimeter, most notably from around the area's closet to the dam area. There is a good phytoplankton bloom, and good fish activity. No other issues found



Figure 1



Figure 2



Figure 3



Figure 4



Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com