Lake Service Report

Property Name:	Mirror Lake	AES Represen	tative:	Greg B. & Philip	R
Service Date:	4/18/19	Service Time:		9:05 a.m. –	
				10:48a.m.	
Water Temperature:	60 Degrees				
Visibility:	18"				
Water Level	Full Pool				
Trash Collected:	Abundant				
Weather Conditions	sunny				
Outlet Debris Cleared	: Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applie	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked	: N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, a large amount of man -made debris removed, good plankton bloom at this time.

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed manmade debris from the shore line of the lake. The phytoplankton bloom is in process. No other issues found.



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



Fig



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC