

AFRI

SUGGESTED STRATEGY FOR PILOT UNEXPLAINED PHYSIOLOGICAL EVENT INVESTIGATION

OXYGEN STANDARDIZATION COORDINATING GROUP MEETING 20-22 AUGUST 2024, BUFFALO NY

GEORGE MILLER, OXYGEN SYSTEMS RESEARCH LAB, TEAM LEAD
HUMAN EFFECTIVENESS DIRECTORATE, 711 HUMAN PERFORMANCE WING, WRIGHT-PATTERSON AFB OH



Overview

- BLUF: Suggest pilot UPE investigation includes operational flights with minimal sensors —
 goal is to collect critical life support system data during pilot UPE
- Introduction
- New Strategy
- Sensors 711 HPW OBOGS Pressure Monitor (OPM) and Eaton Respiratory Sensor Block (RSB)
- Est. Schedule
- Est. UPE Occurrences
- Est. Cost
- Conclusions

Disclaimer: "The views expressed are those of the author and do not reflect the official views of the United States Air Force, nor the Department of Defense. Mention of trade names, commercial products, or organizations do not imply endorsement by the U.S. Government. Unless otherwise noted, imagery in this document are property of the U.S. Air Force."

DISTRIBUTION STATEMENT A. Approved for public release: distribution is unlimited. SAF/PA cleared 31 July 2024; Case 2024-0734.


INNOVATE, ACCELERATE, THRIVE – THE AIR FORCE AT 75





Typical OBOGS Integration

Concern: Inlet air low pressure transients can upset OBOGS operation and performance



ABOS = Automatic Backup Oxygen System

EOS = Emergency Oxygen System

DISTRIBUTION STATEMENT A. Approved for public release: distribution is unlimited. SAF/PA cleared 31 July 2024; Case 2024-0734.

INNOVATE, ACCELERATE, THRIVE - THE AIR FORCE AT 75





New Strategy

- Most critical parameter for OBOGS and life support system performance is OBOGS inlet air pressure
 - Fighter OBOGS typically need 1 to 4 pounds air/minute at minimum pressure of 25-30 psig
 - ECS air supply low pressure transients (even for short periods, several seconds)
 can cause OBOGS performance issues, such as, degraded oxygen and
 restricted breathing flow
- Past UPE investigations using lab studies and limited flight testing haven't been successful in discovering causal factor -- concern current investigation approach will not resolve pilot UPE problem
 - Lab studies are valuable to provide in-sight but can't exactly duplicate the highly variable in-flight operating conditions and therefore are not viewed as conclusive
 - Past limited flight testing (~40-60 sorties) with significant aircraft modification (multitude of sensors and data acquisition system) on one or two aircraft was costly and resulted in limited flying hours – UPEs didn't occur





New Strategy (cont.)

- Data shows ECS low pressure transients can occur at any altitude (even on the ground) – their occurrence tends to be unpredictable and generally ECS experts can't explain why they occur
 - ECS low pressure transients observed on multiple USAF aircraft
 - U.S. Navy observed ECS pressure issues on aircraft
 - Netherlands noted ECS low pressure transients on F-16 test aircraft
 - Lab unmanned research data have shown effects of inlet air low pressure transients on research OBOGS – degraded oxygen% and restricted breathing gas flow
 - Lab human testing of aircraft life support system has not observed UPEs because testing uses stable and within specification OBOGS inlet air pressures



New Strategy (cont.)

- Objective: To capture life support system (LSS) data during pilot UPE
 - Currently, we get limited or no LSS data after pilot UPE generally get several sentences
 - Data gap has hindered progress on this issue
- Plan to add sensors at LSS inlet and outlet one at OBOGS air inlet and one pilot mounted
- Critical parameters recorded:
 - OBOGS Pressure Monitor:
 - OBOGS Inlet Air Pressure (pounds/square inch gauge referenced to aircraft pressure altitude)
 - OBOGS Vent or Exhaust Pressure (pounds/square inch absolute)
 - Respiratory Sensor Block:
 - Pilot Oxygen% prior to oxygen mask
 - Pilot Breathing Gas Flow in ambient liters/minute
 - Mask Cavity Pressure in mm Hg gauge referenced to cabin pressure
 - Cabin Pressure





New Strategy (cont.)

- Modify ~25 aircraft (one squadron) of the same type at one base with OPM and RSB
- Aircraft modifications would be executed by TBD (most likely aircraft prime, SPO, and 711 HPW)
- Aircraft will fly normal operational sorties
- Sensor data downloaded if UPE occurs plan to do periodic sensor inspections and data checks

DISTRIBUTION STATEMENT A. Approved for public release: distribution is unlimited. SAF/PA cleared 31 July 2024; Case 2024-0734.

THE AIR FORCE RESEARCH LABORATORY



OBOGS Pressure Monitor (OPM)

- Device measures and records OBOGS inlet air pressure and vent pressure
- Device "wakes-up" from "sleep mode" when air pressure is applied to OBOGS
- Plan limited flight qualification testing -- altitude-ok, EMI-ok, temperature, vibration, humidity, and acceleration
- Mounted to OBOGS or installed in OBOGS bay
- Collects data at 20Hz and overwrites data after 23 operational hours
- No aircraft wiring changes device powered by long duration battery pack



OBOGS Pressure Monitor






OBOGS Pressure Monitor (OPM)

- Example installation on F-15E OBOGS
- Worked with F-15 SPO to devise installation approach and SPO conducted fit test





DISTRIBUTION STATEMENT A. Approved for public release: distribution is unlimited. SAF/PA cleared 31 July 2024; Case 2024-0734.

THE AIR FORCE RESEARCH LABORATORY



Eaton Respiratory Sensor Block (RSB)

- Pilot mounted device installs between ITB and oxygen mask hose
- Similar to Eaton Inhalation Sensor Block (ISB) -- RSB has mask pressure sensor
- Key parameters:
 - Pilot Oxygen%
 - Pilot Breathing Gas Flow in ambient liters/minute
 - Mask Cavity Pressure in mm Hg gauge
 - Cabin pressure




Eaton Inhalation Sensor Block* (predecessor to Eaton RSB)

<u>https://www.eaton.com/us/en-us/catalog/life-support-systems/vigiloxtm-pilot-breathing-sensors.html</u> DISTRIBUTION STATEMENT A. Approved for public release: distribution is unlimited. SAF/PA cleared 31 July 2024; Case 2024-0734.

^{*} Source:



Estimated Schedule




DISTRIBUTION STATEMENT A. Approved for public release: distribution is unlimited. SAF/PA cleared 31 July 2024; Case 2024-0734.

INNOVATE, ACCELERATE, THRIVE – THE AIR FORCE AT 75



Estimate of UPE Occurrences (Specific aircraft is TBD.)

Assumed an UPE Rate of 10 UPEs/100000 flight hours





Estimate of UPE Occurrences

- Assumed UPE Rate = 10 UPEs/100000 Flight Hours
- Assumed Flight Hours Per UPE: 10000 Flight Hours
- Assume 25 aircraft, 36 months of flying, each aircraft flies 3 sorties/week, and each sortie is 1.5 hours: 16200 Flight Hours
- Estimated Number of UPE Occurrences = 16200 Flight Hours/10000 Flight
 Hours/UPE = ~2 UPEs

INNOVATE, ACCELERATE, THRIVE – THE AIR FORCE AT 75



Estimated Cost

Item	Total (\$K)
Hardware (sensors, etc.)	1700
Personnel Man-hours	1100
Aircraft Modifications (\$50K/aircraft + eng. design drawings)	1800
Travel	300
Total	4900



Summary

- When UPEs occur we get no or very limited/insufficient data to investigate event this data gap has slowed progress in understanding causal factor
- Proposed effort minimizes number of aircraft, number of sensors, and cost yet has reasonable probability for capturing critical data during UPE
- Existing evidence points to aircraft ECS low pressure transients could be causal for UPEs
- UPE issue has persisted for ~15 years
 - UPE rates tend to fluctuate but UPEs continue with moderate improvement
 - When PEs occur on LOX aircraft they are generally explainable -- we find LSS equipment issue
 - OBOGS equipped aircraft tend to have UPEs but LSS equipment generally checks good
 - Concern is pilot UPEs likely to continue until we identify causal factor

