#### **Lake Service Report**

Property Name:	Mirror Lake	AES Represen	tative:	Greg B., Rich J.	
Service Date:	5/17/18	Service Time:		10:50 a.m. –	
				11:06a.m.	
Water Temperature:	68 Degrees				
Visibility:	18"				
Water Level	Full Pool				
Trash Collected:	Abundant				
Weather Conditions	Rain				
Outlet Debris Cleared	: Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applie	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked	: N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man-made debris removed, removed fallen limbs, plankton in full bloom

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed a large amount of man-made debris from the shore line of the lake. Good fish activity noted, pennywort found but no at a nuisance level, no algae at this time, water green due to planktonic bloom.



Figure 1



Picture 2



Picture 3



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC