#### **Lake Service Report**

Property Name:		Mirror Lake	AES Representative:
Drew E & Ryan S			
Service Date: 8:45 am to 11:30 am	88 Deg <24	09/12/2016	Service Time:
Water Temperature: Visibility:	low Moderate		
Water Level Trash Collected: Weather	Sunny Clear N/A N/A	_N/A	<u> </u>
Conditions	<u>N/A</u>	_N/A	<u> </u>
Outlet Debris Cleared: YE	S Lake Dye	Applied: N/A	<u> </u>
Amount Applied: Pond Fe	ertilizer Applied:	Amount Applied: Fish Fe	eeders
Checked: Amount A	pplied:		

Aquatic Vegetation Identified: Minor shoreline pennywort.

Action Performed: Inspected for nuisance vegetation, inspected outflow structure, and removed man-made trash also treated shoreline pennywort.

Erosion/Sedimentation Observations: No significant Changes.

Dam Observations: N/A

Fish/Wildlife Observations: Noted good fish activity especially in the shallow areas

Comments: Lake is in overall good condition. Water level this visit seemed to be a bit higher than previous visit. We performed spot treatments around the shoreline and golf course area to manage vegetation that may not be aesthetically pleasing.

Figure 1





Figure 2





Figure 5