

**West Virginia Department of Health &
Human Resources
Berkeley County Health Department**

No image found with name:
Berkeley.png. Image files
needed to be generated.

CHILD CARE CENTER INSPECTION REPORT

Establishment Information	
Facility Name Step Ahead Preschool	Facility Type Child Care Center
Licensee Name Lisa Carpenter	Facility Telephone # 304 263-6181
Facility Address 418 Stribling Rd Martinsburg , WV	Licensee Address ,

Establishment Details		
Adult to Child Ratio	3:9 pre-k, 2:11 school age, 2:10 2-3, 7 adults to 30 children	
Inspection Information		
Inspection Type Routine	Inspection Date 03/01/2019	Total Time Spent 1.25

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 13 Repeated # 6</p> <p>14.1 - All areas and equipment of the child care center shall be kept clean and in good repair and in a neat and orderly condition at all times. Indoor environmental surfaces associated with children's activities, such as table tops, shall be cleaned and disinf OBSERVATION: Wall vents near craft sink in pre school room need cleaned, dust</p> <p>14.1 - All areas and equipment of the child care center shall be kept clean and in good repair and in a neat and orderly condition at all times. Indoor environmental surfaces associated with children's activities, such as table tops, shall be cleaned and disinf OBSERVATION: Wall vents in 2's room need cleaned, dust</p> <p>5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair. REPEAT OBSERVATION Paint chipping off of walls near cots in pre k room</p> <p>5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair. OBSERVATION: Light not working in 2's room restroom needs repaired</p> <p>5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair. OBSERVATION: Small hole in 2's room restroom needs repaired</p> <p>5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.</p>

REPEAT OBSERVATION Coving near front windows in 2's room needs repaired

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

REPEAT OBSERVATION Coving near back windows in 2's room needs repaired

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: Large area of chipped off paint near door in school age room needs repainted

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: Door to school age room from main lobby needs repaired

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

REPEAT OBSERVATION Hole in school age restroom wall needs repaired

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

REPEAT OBSERVATION Coving near front windows of school age room coming apart from walls needs repaired

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: Paint chipping on front window sills in 2's room

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

REPEAT OBSERVATION Holes in wall in restroom of pre-k need repaired

Inspection Outcome

Follow-up Required – A reinspection of this facility is necessary to assess correction of (a) violation(s) and/or compliance.

Comments

Disclaimer

A re-inspection to assess your correction of these violations will be conducted on, or about, 04/01/2019

Person in Charge



Sanitarian



Luke Hartley