

North Carolina
Code Officials
Qualification Board





# Sam Whittington, PE Investigator

Standard Level III's in Building, Fire Prevention, and Plumbing



#### Review of Complaints for last 10 years

The goal was to develop empirical data on the number and nature of the complaints, the issues most involved, and the nature of disciplinary actions taken by the Board.



A Complaint may contain multiple allegations of both violations of Technical Codes and of Administrative Codes and Policies, and may pertain to multiple trades and/or Inspectors.



### Technical Code (Code)

- Missing Flashing
- Wall not Bearing on Piers
- Over-notched Floor Joist
- No Dishwasher Disconnect
- Clearances not Met
- Inadequate Drainage

### Administrative Code and Policies (Admin)

- No Inspections
- Insufficient Inspections
- No Certifications
- Above Certifications
- Failure to Perform Duties
- No Records
- Conflict of Interest



#### **Complaints**

Reviewed 139

• Basis 52 (37%)

• No Basis 87 (63%)

• Code 36 (26%)

• Admin 63 (45%)

• Both 40 (29%)

#### **Allegations**

• Total 988

• Code 724 (73%)

• Admin 264 (27%)



- Number of Complaints that Allege a Code Violation
  - **>** 76 (55%)
- Number of Complaints that Allege an Administrative violation
  - **>** 103 (74%)
- Why is this, Code Complaints average 9.7 allegations per complaint while Admin Complaints only average 2.6 allegations per complaint



All Cases (regardless of Ba	Basis Cases		
<ul> <li>Failure to Perform Duties</li> </ul>	32	<ul> <li>Failure to Perform Duties</li> </ul>	1
<ul> <li>No / insufficient Inspections</li> </ul>	31	<ul> <li>No / insufficient Inspections</li> </ul>	14
• Ethics	28	<ul> <li>Actions Above / No Cert</li> </ul>	1
<ul> <li>No Permit</li> </ul>	23	• Ethics	10
<ul> <li>Actions Above / No Cert</li> </ul>	16	<ul> <li>Records</li> </ul>	8
<ul> <li>Cert. of Occupancy Issues</li> </ul>	14	<ul> <li>No Permit</li> </ul>	7
<ul> <li>Records</li> </ul>	10	<ul> <li>Plan Review</li> </ul>	6
<ul> <li>Plan Review</li> </ul>	9	<ul> <li>Cert. of Occupancy Issues</li> </ul>	6
<ul> <li>Stop Work</li> </ul>	7	Stop Work	1
• NOV	2	• NOV	1



Cases where the Inspectors Certificates were Reduced in Level, Suspended, or Revoked/surrendered.

•	No / Insufficient Inspections	8
•	Ethics	7
•	Failure to Perform Duties	6
•	Actions Above / No Cert	6
•	Records	6
•	No Permit	4
•	Cert. of Occupancy Issues	4
•	Plan Review	3
•	Stop Work	1



### Disciplinary Actions Taken by the Board over the last 10 years

```
    Letter of Caution/Reprimand 7 (13%)
```

- Class, Training, or Testing 28 (54%)
- Reduced Level of Cert 4 (8%)
  - Suspension 8 (15%)
- Lost or Surrendered Certs 9 (17%)



Of the Nine Inspectors whose Certificates were revoked/surrendered.

•	Actions Above / No Cert	3
•	No / Insufficient Inspections	3
•	Records	3
•	Ethics	3
•	No Permit	2
•	Failure to Perform Duties	1
•	Cert. of Occupancy Issues	1
•	Plan Review	1
•	Stop Work	1



- What guides the level of disciplinary action taken
  - Nature and number of violations
  - Past cases



# Disciplinary Actions Taken by COQB

- Inspector M
  - Did not verify all inspections passed prior to issuing CO
  - Crawlspace Access
  - Law and Admin
  - Mechanical I Course



# Disciplinary Actions Taken by COQB

- Inspector W
  - Did not inspect Floor framing system
  - Improper foundation vent to Interior
  - Stairway Clearance
  - Crawlspace Access
  - Building I suspended until inspector passes Law & Admin and Building I Standard Course, but not less than three months.



# Disciplinary Actions Taken by COQB

- Inspector D
  - Conducting Inspections with Suspended Certification
  - (Law and Admin, retake Fire III, 80 hours training with another jurisdiction)
- Inspector S
  - Inadequate Record Keeping (No Records)
  - Failure to Conduct Required Inspections.
  - (Law and Admin, Permanently Surrendered Fire III, retained BMPE III's)



- Item 1 Inadequate Foundation System
- Item 3 Inadequate Beams
- Item 4 Insufficient Girder Bearing
- Item 5 Inadequate Foundation Anchorage
- Item 6 Foundation Not Dampproofed
- Item 8 No Crawl Space Drain
- Item 10 Missing Beams
- Item 11 Inadequate Wall Support
- Item 13 Missing Bearing Wall
- Item 14 Inadequate Floor Framing and Pier Supports
- Item 15 Egress Window Height Insufficient
- Item 16 Inadequate Ceiling Joist Support
- Item 18 Inadequate Bearing Wall Support
- Item 19 No Engineering for Holes Drilled in LVL Beams
- Item 21 Inadequately Nailed Sheathing
- Item 22 Inadequate Stud Bearing

### Inspector Lost Certifications

- Item 25 Inadequate Rafter Support Above Bedroom
- Item 26 Rafter Support Installed Incorrectly
- Item 27 Rafters Not Tied to Ceiling Joists
- Item 30 Inadequate Rafter Support
- Item 31 Rafters Not Nailed to Support
- Item 32 Rafters Missing Ties
- Item 33 Ceiling Joists Over-Notched
- Item 34 Ceiling Joists Notched Incorrectly
- Item 35 Rafters Not Nailed to the Band
- Item 36 Column Anchored Inadequately
- Item 37 Water Intrusion
- Item 42 Voids in Bed Joints at Pier
- Item 44 Safety Glazed Window Required for Master Bath Tub
- Item 45 Safety Glazed Window Required at Stairs
- Item 47 No Toilet Facilities for Workers
- Item 49 Ridge Board Inadequate



#### Complaint Process

- Complaint received, checked and processed
- Complaint forwarded to inspector to respond
- Site Visit
- Report
  - No Basis => present to Board
  - Basis => VSA



