

### **PHASE IX Part II Program**





The Second Part of the Phase IX Program was conducted in September 2021 in Eastern Madagascar in villages in the Mananjary area. Seven wells were drilled in the following four villages:

Anilavinany | Mahela | Pangalana Sud | Ambalavontaka


This phase of the project provides clean water to an estimated 8000 new recipients




**MWP134 MWP 135** 

#### **ANILAVINANY**

Lat 20°59'04.7"S Long 48°26'35.9"E





- Source of water: Canzee Pumps, Bucket Well
- Existing water infrastructure: 1 Bucket Well, 4 Canzee Pumps – all working
- MWP Well installed: MWP134, MWP-135

- **Region: Vatovavy**
- **District: Mananjary**
- **Commune: Mahela**
- **Fonkotany: Anilavinany**
- Number of Households: 413
- Number of population: 2065



#### **ANILAVINANY**

Lat 20°59'04.7"S Long 48°26'35.9"E



Quality: Fresh

• Date of installation: September 2021

• Pump Type: XL Pump

Pedestal: Standard

• Screen / Well Point: Steel

• Pipe: Steel





#### **ANILAVINANY**

Lat 20°59'00.6"S Long 48°26'36.2"E



• Date of installation: September 2021

• Pump Type: XL Pump

• Pedestal: Standard

• Screen / Well Point: Steel

• Pipe: Steel







#### **PANGALANA SUD**

Lat 21°18′15.13"S Long 48°20′1.59"E





- Region: Vatovavy
- District: Mananjary
- Commune: Ankatafana
- Fonkotany: Pangalana Sud
- Number of Households: 200
- Number of population: 1629

- Source of revenue: Fishing, Farming
- Source of water: Canzee Pumps, Private Wells
- Existing water infrastructure: 4 CanzeePumps
- MWP Well installed: MWP136



Pedestal: Standard

• Pipe: Steel

• Screen / Well Point: Steel

# **The Madagascar Water Project**

#### **PANGALANA SUD**

Lat 21°18'15.13"S Long 48°20'1.59"E



• WT: 2.2m | TD: 5.2m BGL

• Flow: 25 liters per minute

• Quality: Fresh







MWP137 MWP 138

#### **AMBALAVONTAKA**

Lat 21°19'31.6"S Long 48°19'38.9"E





• Region: Vatavavy

• District: Mananjary

• Commune: Ankatafana

• Fonkotany: Ambalavontaka

• Number of Households: 270

• Number of population: 2400

• Source of revenue: Fishing, Farming

• Source of water: Pangalana channel

• Existing water infrastructure: 4 Canzee Pumps – all broken

• MWP Well installed: MWP137, MWP-138



### **AMBALAVONTAKA**

Lat 21°19'31.6"S Long 48°19'38.9"E



• Date of installation: September 2021

• Pump Type: XL Pump

Pedestal: Standard

• Screen / Well Point: Steel

Pipe: Steel

• WT: 2.0m | TD: 5.2m BGL

• Flow: 25 liters per minute

Quality: Fresh





#### **AMBALAVONTAKA**

Lat 21°19'28.2"S Long 48°19'39.2"E



- Date of installation: September 2021
- Pump Type: XL Pump
- Pedestal: Standard
- Screen / Well Point: Steel
- Pipe: Steel
- WT: 1.8m | TD: 4.2m BGL
- Flow: 25 liters per minute
- Quality: Fresh


Well point had to be worked about 1 meter to find permeability. Check valve could not be installed due to interference with the pedestal.



MWP139 MWP 140

#### **MAHELA**

Lat 20°58'09.9"S Long 48°26'29.9"E



- Existing water infrastructure: 1 Bucket Well
   3 Canzee Pumps all broken
- MWP Wells installed: MWP139, MWP-140





### **MAHELA**

Lat 20°58'09.9"S Long 48°26'29.9"E





• Date of installation: September 2021

• Pump Type: XL Pump

Pedestal: Standard

• Screen / Well Point: Steel Pipe: Steel

WT: 1.7m | TD: 4.2m BGL Flow: 25 liters per minute

Quality: Fresh, Brownish Color

Penetration stopped at 4.8m BGL.
Well point had to be worked about 1 meter to find permeability.





### **MAHELA**

Lat 20°58'10.9"S Long 48°26'32.0"E





- Date of installation: September 2021
- Pump Type: XL Pump
- Pedestal: Standard
- Screen / Well Point: Steel
- Pipe: Steel

- WT: 1.8m | TD: 5.2m BGL
- Flow: 25 liters per minute
- **Quality: Fresh**