


# Machinist Tap Wrenches with Guide



Manually thread perfectly straight tap holes without removing your workpiece from the machine setup. Just put the guide spindle into drill press or lathe chuck and insert the tap wrench into the guide. Thread depth is easily gauged as the wrench works its way out of the guide. The sliding style handle moves from side to side for easy access to tight spaces. You can also use them as regular T-handle tap wrenches. Taps not included.

Tapping Capacity		Handle Lg.	Guide Spindle Dia.	Part Number
Machine Screw and Fractional	Metric, mm			
0 - 1/4"	1.6 - 6.3	3 1/2"	1/2"	51014
1/4" - 1/2"	6 - 12.5	4"	1/2"	51412
1/2" - 3/4"	12 - 18	4 1/2"	5/8"	51234
3/4" - 1"	20 - 25	5"	3/4"	51341

Sold At: