### **Lake Service Report**

Property Name:	Mirror Lake	AES Represent	AES Representative:		Greg B. & Philip R	
Service Date:	6/21/18	Service Time:		8:42 a.m	_	
				10:20a.m.		
Water Temperature:	78 Degrees					
Visibility:	30''					
Water Level	Full Pool					
Trash Collected:	Abundant					
Weather Conditions	sunny					
<b>Outlet Debris Cleared</b>	: Clear					
Lake Dye Applied:	N/A	Amount Applied:	N/A			
Pond Fertilizer Applie	d: <u>N/A</u>	Amount Applied:	N/A			
Fish Feeders Checked	: <u>N/A</u>	Amount Applied:	N/A			

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man-made debris removed, good fish activity

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed large amounts of manmade debris from the shore line of the lake. No other issues found.



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com