Lake Service Report

Property Name:	Mirror Lake	AES Representative:		Greg B. & Philip R.	
Service Date:	8/17/18	Service Time:		8:19 a.m 9:19 a.m.	
Water Temperature:	88 Degrees				
Visibility:	36"				
Water Level	Full Pool				
Trash Collected:	Large				
	amount				
Weather Conditions	Cloudy				
Outlet Debris Cleared	: Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applie	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked	: N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man - made debris removed, large limbs removed from water, treated the boat launch area up to the outflow for blue/green algae.

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed manmade debris from the shore line of the lake, and treated an isolated area of blue/green algae.



Figure 1

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



Fig

Picture 2

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com