Lake Service Report

Property Name:	Mirror Lake	AES Represen	AES Representative:		Greg B. & Adam R	
Service Date:	3/19/20	Service Time:		12:05 p.m. – 2:06		
				p.m.		
Water Temperature:	60 Degrees					
Visibility:	24"					
Water Level	Full Pool					
Trash Collected:	Abundant					
Weather Conditions	sunny					
Outlet Debris Cleared	: Clear					
Lake Dye Applied:	N/A	Amount Applied:	N/A			
Pond Fertilizer Applie	d: N/A	Amount Applied:	N/A			
Fish Feeders Checked	: N/A	Amount Applied:	N/A			

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man-made debris removed.

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed manmade debris from the shore line of the lake, over all condition is good today.



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

Fig



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC