

# SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

---

**Structure Name:** FULLERTON D 1

---

**Reported By:** Daniel Boyes

---

**Date:** July 3, 2019

---

Headgate	Latitude	Longitude
Location:	38.107391	-106.233985

---

**Headgate Type:** Manually operated 2' wide rectangular screw gate

---

<b>Headgate Condition:</b>	A <input type="checkbox"/>	<b>Diversion and Other Condition:</b>	A <input type="checkbox"/>	<b>Stream Miles From Werner Arroyo Terminus (Point Of Diversion):</b>	<b>Structure Submerged:</b> Yes <input type="checkbox"/>
	B <input checked="" type="checkbox"/>		B <input checked="" type="checkbox"/>	24.42 mi	No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>		

---

**Repair(s) or Improvement(s) Currently Needed:** No immediate repair needs were identified. Fish passage should be maintained and riparian restoration should be considered as part of any future repairs or improvements.

---

**Structure Description:** This is the first ditch on the Werner Arroya. The diversion dam is a checkboard structure that directs flow to the headgate, located on the north bank of the Werner Arroya. This structure functions effectively.

---

**Comments:** This ditch is a priority 11.

---

**Notes:**

---

**Estimated Range of Cost:** Low

---

Headgate looking downstream



Headgate outlet



Headgate and diversion dam



Diversion dam



Flume looking downstream



Flume looking upstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

FULLERTON DITCH 1

PHOTO LOG

Saguache Creek Stream Management Plan