

# CONEJOS RIVER

## DIVERSION INFRASTRUCTURE INVENTORY

---

**Structure Name:** CORDOVA D

---

**Reported By:** Daniel Boyes

---

**Date:** April 15, 2019

---

Headgate	Latitude	Longitude
Location:	37.130605	-105.963272

---

**Headgate Type:** Manually operated 3' wide steel slide gate

---

<b>Headgate Condition:</b>	A <input type="checkbox"/>	<b>Diversion and other Conditions:</b>	A <input type="checkbox"/>	<b>River Miles From North Branch Conejos Terminus (Point Of Diversion):</b>	<b>Structure Submerged:</b> Yes <input type="checkbox"/>
	B- <input checked="" type="checkbox"/>		B <input type="checkbox"/>		No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input checked="" type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>	7.85 mi	

---

**Repair(s) or Improvement(s) Completed Since 2006:** A small stacked rock diversion dam was installed.

**Repair(s) or Improvement(s) Currently Needed:** The headgate needs to be reset. The diversion dam should be improved to reduce maintenance and to divert water at low flows. Fish passage and riparian restoration should be considered as part of any future repairs or improvements. This structure also needs regular debris clearing. The river channel here also needs bank stabilization work.

---

**Structure Description:** Located on the North Branch of Conejos River. The headgate sits along the east bank of the river. There is a trash rack consisting of a log boom, t-posts, and checkboards upstream of the headgate. The structure has a very minimal stacked rock diversion dam. Woody debris and sediment accumulation is an issue at this structure.

---

**Comments:** This ditch is a priority 53.

---

**Notes:**

---

**Estimated Range of Cost:** Moderate

---

Headgate looking downstream



Headgate outlet



Headgate and trash rack structure



Diversion dam and headgate



Flume looking downstream



Flume looking upstream



CONEJOS RIVER DIVERSION INFRASTRUCTURE INVENTORY

CORDOVA DITCH

PHOTO LOG

Conejos River Stream  
Management Plan