

# RIO GRANDE DIVERSION INFRASTRUCTURE INVENTORY

---

**Structure Name:** ANTLERS PARK D

---

**Reported By:** Daniel Boyes

---

**Date:** April, 2019

---

Headgate	Latitude	Longitude
Location:	37.804463	-106.985115

---

**Headgate Type:** N/A

---

<b>Headgate Condition:</b>	A <input type="checkbox"/>	<b>Diversion and other Condition:</b>	A <input type="checkbox"/>	<b>River Miles From New Mexico State Line (Point of Diversion):</b> 148.15 mi	<b>Structure Submerged:</b> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
	B <input type="checkbox"/>		B <input type="checkbox"/>		
	C <input checked="" type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input checked="" type="checkbox"/>		

---

**Repair(s) or Improvement(s) Completed Since 2006:**

**Repair(s) or Improvement(s) Currently Needed:** The primary recommendation is to relocate the point of diversion for this ditch. Existing fish and boat passage should be maintained and riparian restoration should be considered as part of any future repairs or improvements.

---

**Upstream Configuration:** This ditch is located ~1 mile downstream of Marshall Park Campground. There is no diversion dam serving this structure. The structure is located on the east bank of the river. The water rights holder cannot access the ditch's full decree due to the ditch's location on the river and the poor condition of the headgate. According to the water commissioner, the point of diversion will likely move in the future.

---

**Comments:** This ditch is a priority 1903-51

---

**Notes:**

---

---

**Estimated Range of Cost:** Moderate

---

<p>Headgate looking downstream</p>	<p>Headgate and diversion dam</p>	
<p>Headgate outlet</p>	<p>Diversion dam</p>	
<p>RIO GRANDE DIVERSION INFRASTRUCTURE INVENTORY</p>		<p>Rio Grande Stream Management Plan</p>
<p>ANTLERS PARK DITCH</p>		
<p>PHOTO LOG</p>		



Antlers Park Ditch point of diversion location