Lake Service Report

Property Name:	Mirror Lake	AES Represen	tative:	Greg B., Philip F	₹.
Service Date:	5/16/19	Service Time:		9:16 a.m. –	
				10:44a.m.	
Water Temperature:	69 Degrees				
Visibility:	28"				
Water Level	Full Pool				
Trash Collected:	Abundant				
Weather Conditions	Sunny				
Outlet Debris Cleared:	Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applied	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked:	N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man-made debris removed, removed fallen limbs, plankton in full bloom

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed a large amount of man-made debris from the shore line of the lake. Good fish activity noted, pennywort found but no at a nuisance level, no algae at this time, water green due to planktonic bloom.



Figure 1



Picture 2



Picture 3



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC