Lake Service Report

Property Name:	Mirror Lake	AES Represen	tative:	Greg B. & Philip R	
Service Date:	6/20/19	Service Time:		8:50 a.m. –	
				10:05a.m.	
Water Temperature:	78 Degrees				
Visibility:	36"				
Water Level	Full Pool				
Trash Collected:	Abundant				
Weather Conditions	Cloudy				
Outlet Debris Cleared:	Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applied	d: N/A	Amount Applied:	N/A	<u> </u>	
Fish Feeders Checked:	N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man-made debris removed, good fish activity, no algae at this time.

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed large amounts of manmade debris from the shore line of the lake. No other issues found.

Fig



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC