#### **Lake Service Report**

Property Name:	Mirror Lake	AES Representative:		Greg B. & Philip R.	
Service Date:	1/16/20	Service Time:		9:48 a.m.– 12:52a.m.	
Water Temperature:	54 Degrees				
Visibility:	24"				
Water Level	Full Pool				
Trash Collected:	Large				
	amount				
Weather Conditions	Sunny				
Outlet Debris Cleared:	Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applied	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked.	N/Δ	Amount Applied:	Ν/Δ		

Aquatic Vegetation Identified: Pennywort, parrotfeather

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man - made debris removed.

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes

Comments: Today the lake looked to be in great condition. We removed man-made debris from the shore line of the lake, no algae at this time, some beaver activity found, minimal fish activity noted, water turbid due to recent rains.



Figure 1

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



Fig

Picture 2

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com