

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: FULLERTON D 1

Reported By: Daniel Boyes

Date: July 3, 2019

Headgate	Latitude	Longitude
Location:	38.107391	-106.233985

Headgate Type: Manually operated 2' wide rectangular screw gate

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	Stream Miles From Werner Arroyo Terminus (Point Of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input checked="" type="checkbox"/>		B <input checked="" type="checkbox"/>	24.42 mi	No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>		

Repair(s) or Improvement(s) Currently Needed: No immediate repair needs were identified. Fish passage should be maintained and riparian restoration should be considered as part of any future repairs or improvements.

Structure Description: This is the first ditch on the Werner Arroya. The diversion dam is a checkboard structure that directs flow to the headgate, located on the north bank of the Werner Arroya. This structure functions effectively.

Comments: This ditch is a priority 11.

Notes:

Estimated Range of Cost: Low

Headgate looking downstream



Headgate outlet



Headgate and diversion dam



Diversion dam



Flume looking downstream



Flume looking upstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

FULLERTON DITCH 1

PHOTO LOG

Saguache Creek Stream Management Plan