

820 TRACKER SENSOR MOUNTING INSTRUCTIONS



SHOWN IS LEFT SIDE



SHOWN IS RIGHT SIDE

Mount sensor brackets so that the threaded rod with two yoke ends is parallel with the platforms vertical control rods. Two holes for each bracket will need to be drilled for mounting. Platform must be on the combine and held in the air before attaching bracket with cable clamp to the control rod. Once platform is in the air and the sensor bracket mounted, adjust sensor arm upward so that it is in straight line with sensor mounting screws. The cable clamp can now be attached to control rod and tightened.