Lake Service Report

Property Name:	Mirror Lake	AES Represen	tative:	Greg B, Phil R	
Service Date:	9/19/19	Service Time:		8:50 a.m. –	
				10:15a.m.	
Water Temperature:	84 Degrees				
Visibility:	30"				
Water Level	Full Pool				
Trash Collected:	Abundant				
Weather Conditions	sunny				
Outlet Debris Cleared	: Clear				
Lake Dye Applied:	N/A	Amount Applied:	N/A		
Pond Fertilizer Applie	d: N/A	Amount Applied:	N/A		
Fish Feeders Checked	: N/A	Amount Applied:	N/A		

Aquatic Vegetation Identified: Pennywort

Action Performed: Inspected Lake for nuisance vegetation, inspected outflow structure, large amounts of man -made debris removed

Erosion/Sedimentation Observations: No substantial differences.


Dam Observations: Good with no significant changes, removed man-made debris build-up.

Comments: Today the lake looked to be in great condition. We removed a large amount of man-made debris from the shore line of the lake, and dam area, good fish activity noted, turtles spotted, no algae at this time.



Figure 1

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



Picture 2

Picture 3

AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com



AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC

8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230 Fax: 770-737-5135 Email: aquadocga@gmail.com Website: www.aquadocinc.com