

Mitsubishi 09232019

Mitsubishi does not have any position statement regarding pre- and post- repair scanning. This does not mean that a scan tool will not be needed to repair Mitsubishi vehicles. As with most electrical problems on a vehicle, Mitsubishi's service manual references the use of a scan tool in many procedures. A scan tool is required for diagnosis, troubleshooting, calibrations, and checking for DTC after a collision.

The 2019 Mitsubishi Eclipse Cross has a document titled Post-Collision Diagnosis. Per the 2019 Mitsubishi Eclipse Cross service manual: "Perform the inspection and service on post-collision vehicles according to the procedures below regardless of the deployment or activation statuses of air bags and seat belt pretensioner."

The procedure involves hooking up a scan tool and reading recording and clearing all of the DTCs and then waiting a period of time and scanning for DTCs again. As stated, this is to be performed on this vehicle after a collision. A similar document can be found in many different Mitsubishi models service manuals.