

FROTH PAK™ Refill - Set Up

Supplies

- Safety glasses or goggles – goggles are better!
- ½ face respirator (or full face) – Filters to handle organic compounds - check hours of use/filter set. Respirator should also include a particulate filter.
- Chemical resistant gloves made from nitrile, neoprene, butyl, or PVC.
- Protective “Over-alls” for clothing and skin protection.
- 1 small scale that measures in grams for calibration. Battery powered is more convenient.
- 1 small calculator to do calibration ratio math.
- 1 roll of blue electrical tape to mark Polyol hoses.
- 1 roll of red electrical tape to mark ISO hoses.
- 1 roll of black electrical tape to tape hoses together.
- Small lunch bags – for calibration.
- Marker to label lunch bags “A” and “B”.
- Pen or pencil to mark down weights of each chemical when calibrating.
- Calibration Worksheet

