

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: GOTTHELF SAMORA D

Reported By: Daniel Boyes

Date: April 11, 2019

Headgate	Latitude	Longitude
Location:	38.069166	-106.161863

Headgate Type: Manually operated 2' wide screw gate

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	Stream Miles From Werner Arroyo Terminus (Point Of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input checked="" type="checkbox"/>		B <input checked="" type="checkbox"/>	18.28 mi	No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>		

Repair(s) or Improvement(s) Currently Needed: A measurement device should be installed at this structure. Fish passage and riparian restoration should be considered as part of any future repairs or improvements.

Structure Description: The diversion dam is made up of boulders and directs water to the headgate. The channel is relatively stable in this location. No measurement device exists - flow is estimated.

Comments: This ditch is a priority 36.

Notes:

Estimated Range of Cost: Low

Headgate looking downstream



Headgate outlet



Headgate and diversion dam



Diversion dam



Flume looking downstream



Measurement location



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

GOTTHELF SAMORA DITCH

PHOTO LOG

Saguache Creek Stream
Management Plan