### **Lake Service Report**

Property Name:	Mirror Lake	AES Represen	_ AES Representative:		Greg B. and Philip R.	
Service Date:	10/17/19	Service Time:		9:45 a.m	-	
				10:49a.m.		
M/stssTsssssst	70 0					
Water Temperature:	79 Degrees					
Visibility:	30"					
Water Level	Full Pool					
Trash Collected:	Abundant					
Weather Conditions	Cloudy					
<b>Outlet Debris Cleared</b>	: Clear					
Lake Dye Applied:	N/A	Amount Applied:	N/A			
Pond Fertilizer Applie	d: <u>N/A</u>	Amount Applied:	N/A			
Fish Feeders Checked	: <u>N/A</u>	Amount Applied:	N/A			


Aquatic Vegetation Identified: Pennywort

Action Performed: Inspected Lake for nuisance vegetation, inspected outflow structure, large amounts of man -made debris removed.

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes, removed man-made debris build-up.

Comments: Today the lake looked to be in great condition. We removed a large amount of man-made debris from the shore line of the lake, and dam area, good fish activity noted, turtles spotted, no algae at this time.



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC



#### AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC