



www.flylightning.net email: info@flylightning.net phone: 931-680-1781
2842 Highway 231 North, Shelbyville, TN 37160

NOTIFICATION	
Service Bulletin #	AA-N001
Superseded Bulletin #	None
Issue Date	05/13/2012
Effective Date	05/13/2012
Limitations for Completion	At Owner / Operator Option
Make & Model Affected	Lightning LS-1
	Serial # 76 through 154
Page 1 of 1	

1 Applicability

This "Notification" is informational.

2 Background

2.1 General

During a recent FAA practice audit it was pointed out that the portable GPS installed in the panel obscured the required passenger warning placard and the operational limitations placards.

3 Compliance – Implementation Schedule:

Owners and operators of Lightning LS-1 aircraft are advised not to mount portable devices in such a way as to obscure any of the placards on the instrument panel.

If any device is already mounted and does obscure the placards those devices should be relocated so to not block the view of the placards by pilot or passenger.