





OHIO HISTORIC INVENTORY

1. No. ERI-1605		4. Present Name(s) Paul Mack Residence		ERI-1605
2. County ERIE		5. Other Name(s) George Gerlach House		
3. Location of Negatives O.H.S.				
6. Specific Location East side of Division St., third house south of Estes School		16. Thematic Category Industry/trades		28. No. of Stories 2
7. City or Town If Rural, Township & Vicinity Kelleys Island, Ohio		17. Date(s) or Period 1902		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
8. Site Plan with North Arrow 		18. Style or Design Vernacular		30. Foundation Material Limestone ashlar
9. U.T.M. Reference 17 35 76 10 46 07 03 0		19. Architect or Engineer		31. Wall Construction Wood frame
10. Easting Northing Site <input type="checkbox"/> Structure <input type="checkbox"/> Building <input checked="" type="checkbox"/> Object <input type="checkbox"/>		20. Contractor or Builder George Gerlach		32. Roof Type & Material Gable/asph. shingle
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		21. Original Use, if apparent Residence		33. No. of Bays Front Side
12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use Residence		34. Wall Treatment alum. sid/o. bev. bd.
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>		35. Plan Shape
14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, if known Paul Mack Sandusky, Ohio		36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>
15. Name of Established District N/A		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		37. Condition Interior Exterior Good
42. Further Description of Important Features (Continue on separate sheets) This steeply pitched cross gable house features multi-level eaves and a continuous roof over the front porch. A brick chimney is located near the gable intersection. A hipped dormer is highlighted by a finial. Windows on west and south walls are paired 1/1, and on north wall are single 1/1; single front gable window is detailed with triangular pediment. Porch detailing includes		26. Local Contact Person or Organization Kevin Pape:KI.Hist.Survey		38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
43. History and Significance George Gerlach, long time resident of Kelleys Island built this house in 1903. A house carpenter, George had come to the island in 1893 with his wife and 3 children, first building a house on Huntington Rd. He built two other houses on Huntington, one in 1896 for his brother, Henry, and the second in 1899. When the quarry claimed that section of Huntington Rd., and		27. Other Surveys in Which Included N/A		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
44. Description of Environment and Outbuildings Located on the east side of Division St., the house sits closer to the road than many of the others to the south. There are two outbuildings in the rear yard. Both are board-and-batten construction with gabled/slate roofs. The		46. Prepared by Kevin Pape		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
45. Sources of Information Census Records F. & L.J. Pohorence O.H. Lange		47. Organization K.I. Planning Commis		41. Distance from and Frontage on Road 40'
				48. Date 8/85
				49. Revision Date(s)

ERI-1605

Erie

Paul Mack Residence

George Gerlach House

50. House Type No.

Code No. Name

51. Historic Outbuildings and Dependencies

Barn Type(s)

Code No. Type

Corn Crib or Shed Smoke House Privy
 Silo Spring House Carriage House
 Summer Kitchen or Ice House

Other _____

52. Archaeological Site on Property?

Yes
No

Basis for Information

Owner Collection
 Above Ground Earthworks or Mound
 Cultural Materials Noted OAI No. _____

53. Farmstead Plan



54. Photo

Roll No. 25BPicture No(s). 33-342117

42. (Cont'd)

turned columns, sawn balustrades, and lattice work beneath the floor. A single-story, shed roofed addition is built onto the rear gable end. Original details shown by historical photo: (R12 #17) no dormer; corbelled brick chimney; 3-sided bay window on the south gable wall with pent roof; cornice returns on gable eaves; continuous lintel trim bandon first floor; end and frieze boards; projecting window with concave hood in front gable; polychrome paint job highlighting details.

43. (Cont'd.)

removed these houses, Gerlach built his present house on Division St. As an independent house carpenter, Gerlach played an important role at a time when population growth coinciding with the growth KIL&T Co's quarry operations, demanded a great increase in new and remodeled housing. Some of the building attributed to Mr. Gerlach are listed below:

1903 rebuilds Meyers/Lange house ERI-1603
 1904 converted old high school for A. Ranft ERI-1606
 1906 converted Mischler's meat mkt. to dwell ERI-1587
 1915 assisted in remodeling of St. Michael Ch ERI-1558
 1927 rebuilt Elfer's first store for work shop ERI-1626
 using lumber salvaged from west quarry
 "incubator"
 1927 built bleachers for Chapel St. ball field
 using lumer from above source.

44. (Cont'd.)

smaller building is single story and has a cistern next to its south wall. The larger building is 1½ stories with a loft and loft door in the gable. It has two large doors in the north eave wall and two, single-sash, 6-light windows.