

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: HODDING D 3

Reported By: Daniel Boyes

Date: April 12, 2019

Headgate	Latitude	Longitude
Location:	38.127	-106.35309

Headgate Type: There is no headgate for this ditch.

Headgate Condition:	A <input type="checkbox"/>	Diversion and other Condition:	A <input type="checkbox"/>	Stream Miles From Saguache Creek Terminus (Point of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input type="checkbox"/>		B <input type="checkbox"/>		No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input checked="" type="checkbox"/>		D <input type="checkbox"/>	55.57 mi	
	F <input type="checkbox"/>		F <input type="checkbox"/>		
			N/A <input checked="" type="checkbox"/>		

Repair(s) or Improvement(s) Currently Needed: Some vegetation should be selectively removed to improve access to this structure.

Structure Description: This ditch down not have a headgate. Instead, a culvert directs flow to the ditch. This ditch receives water from Hodding Creek, but, similar to the Hougland Creek Ditch, it affects flows and administration of Saguache Creek. The flume could not be located at the time of inspection.

Comments: This ditch is a priority 21.

Notes:

Estimated Range of Cost: Low

Culvert looking downstream



Ditch looking upstream



Ditch looking downstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

HODDING D 3

PHOTO LOG

Saguache Creek Stream
Management Plan