

*Aquatic Environmental Services of AQUA DOC*

**Lake Service Report**

Property Name: Mirror Lake AES Representative: Greg B. & Philip R.  
Service Date: 2/21/19 Service Time: 10:09 a.m. – 12:03 p.m.

Water Temperature: 59 Degrees  
Visibility: 24"

Water Level: Full Pool  
Trash Collected: Abundant  
Weather Conditions: sunny  
Outlet Debris Cleared: Clear

Lake Dye Applied: N/A Amount Applied: N/A  
Pond Fertilizer Applied: N/A Amount Applied: N/A  
Fish Feeders Checked: N/A Amount Applied: N/A

Aquatic Vegetation Identified: Pennywort

Action Performed: inspected Lake for nuisance vegetation, inspected outflow structure, man-made debris removed

Erosion/Sedimentation Observations: No substantial differences.

Dam Observations: Good with no significant changes, we did remove some man-made debris and fallen wood from the grating

Comments: Today the lake looked to be in good condition. We removed a large amount of man-made debris from the shore line of the lake, water is turbid due to recent rains. Note: The pictures are from a previous visit, due to rain, no photos were taken from this visit.

*Aquatic Environmental Services of AQUA DOC*



Figure 1

*Aquatic Environmental Services of AQUA DOC*



Fig

Picture 2

*Aquatic Environmental Services of AQUA DOC*



**AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC**  
8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230  
Fax: 770-737-5135 Email: [aquadocga@gmail.com](mailto:aquadocga@gmail.com) Website: [www.aquadocinc.com](http://www.aquadocinc.com)

*Aquatic Environmental Services of AQUA DOC*



**AQUATIC ENVIRONMENTAL SERVICES OF AQUA DOC**  
8302 Ball Ground Hwy, Ball Ground, GA 30107 Office: 770-833-9230  
Fax: 770-737-5135 Email: [aquadocga@gmail.com](mailto:aquadocga@gmail.com) Website: [www.aquadocinc.com](http://www.aquadocinc.com)