Lake Service Report

Property Name:	Mirror Lake	AES Represen	AES Representative:		Josh F. and Philip R.	
Service Date:	8/15/19	Service Time:		9:07 a.m. – 9:59 a.m.		
Water Temperature:	84 Degrees					
Visibility:	19"					
Water Level	Full Pool					
Trash Collected:	Moderate					
Weather Conditions	Partly					
	Cloudy					
Outlet Debris Cleared:	Clear					
Lake Dye Applied:	N/A	Amount Applied:	N/A			
Pond Fertilizer Applied	d: N/A	Amount Applied:	N/A			
Fish Feeders Checked:	N/A	Amount Applied:	N/A	_		

Aquatic Vegetation Identified: None

Actions Performed: Inspected lake for aquatic vegetation, collected a moderate amount of trash, cleared debris from outflow structure.

Erosion/Sedimentation Observations: None.

Dam Observations: No issues with dam.

Comments: Lake looked great overall. There were no weed or algae issues. The color and clarity of the water was excellent. A very healthy phytoplankton bloom is present. Fish and wildlife are healthy and abundant with many fish, ducks, and turtles seen.

Please let me know if you have any questions or concerns.

Thank you!

Joshua Fowler - Aquatic Specialist





