

JOB BANK REQUEST FOR WORKERS 1750 NEW YORK AVENUE, NW WASHINGTON, D.C. 20006

Office Use Only Job ID Number

2018-0066

Brad Plueger, Chief International Representative Charles Mulcahy, Director of Craft Services Patti Shoap pshoap@smart-union.org

1.	Local Union Number: 085		
2.	Company Name: Various Contrators - Vogtle Nuclear New Const.		
3.	City and State (where job is available): Waynesboro, GA		
4.	(a) Number of positions available: 6 Field Welding & Installation (Sample Positions: Field, Shop, Architectural Field, Air Balancing, Detailing, Lagging, etc.)		
	(b) Number of DRAFTING positions available:		
	Benchmark, Auto Cad required? Other?		
	(c) Number of WELDING positions available:		
	• Type of Material: 1/2"CS & 16 ga galv Gauge(s):		
	Certification Needed:		
	 Process? (tig, mig, stick): Stick. Fluxcore, Mig Additional welding requirements: 		
3 position-Hor, Vert. and Overhead on 1/2"CS in Flux-core and or Stick. 16 ga Galv Mig overhead only.			
5. Hourly Wage Rate: Contributions \$ \$36.22 On Check \$ \$50.12 Total Package NPF \$ \$5.94 H&W \$ \$5.55			
Working Assessment or \$25.00 Fee: Yes No			
	If yes, \$\\$1.64\] or \[\textsquare \% \text{Hourly } \varpsyle \widetilde{\varpsilon} \text{Weekly } \] Monthly \[\textsquare \]		

6. Hours Per Week: 5-10's			
7. Shift: 1st 2nd 3rd 8. C	Overtime: Yes No Maybe		
9. Are you a SASMI Local Union? Yes V	о 🗌		
10. Has SASMI contractor stipulated to guarantee minimum days? Yes Days No			
If not, what is the approximate duration of the job? potential for 1-2 years			
11. Are you signatory to the SMART Reciprocal Agreen	ment? Yes 🔽 No		
If yes, check all that apply:			
A Defined Benefit Pension Funds	C Health & Welfare Funds		
B Defined Contribution Pension Funds	D Training Funds		
12. Who should workers report to? Eric Herfu	urth / Mike Patron CWI		
13. Where should they report? 7825 River Road. Wayneboro, GA			
Phone Number: (404)	4) 520-5886		
14. When should they report?	ASAP		
15. What is the last day a member(s) can report? Until filled			
16. Is a security clearance required? Yes No	Type? Southern Company/ Nuclear PADS		
17. Is a drug test required? Yes No			
18. Do any other tests need to be taken/passed? Yes	No L		
If yes, others required. FFD/ Orientation	on Tests		
19. Additional Comments/Information:			
Welders initially report to Atlanta or Augusta Weldingte testing. Bring DL, SS, OSHA card along with Welding hood required. Once on site weld tests are passed orientation can or Wednesday depending on circumstance.	d with Hard hat attachment. Safety boots		
Signature: Eric Herfurth	Data: 9/20/2019		
Signature: Eric Herfurth (May be typed)	Date: 8/20/2018		