

Proposed MAXIMO Work Orders



Wipe down stainless, panel doors, etc
along West wall (line 42)
Every Two Months

1



Scrub floor @ battery station, wipe down
yellow railings
Monthly

2



Plant wide -top of cabinets should be clear
Bi-Monthly

3



Wipe down stainless, panel doors, etc
along South wall (side that has steps to offices)
Every Two Months

4



Wipe down plexiglass Horix Filler

5



Scrub steps, platform, railings, etc
leading to offices upstairs
Monthly

6



Sweep up cigarette butts outside door
Every Two Weeks

7



Wipe down stainless, panel doors, etc
along East walkway by line 40
Every Two Months

8



Maintenance items outside shop should be
arranged neatly and area clean
Bi-Monthly

9

Proposed MAXIMO Work Orders



Plant-wide, yellow protectors should be wipe down - free of dirt and dust
Monthly

10



Wipe down piping leading to Shipping

11



Drips pans are to be cleaned **Monthly**

12



All bottles disposed of in Shipping tunnel to Shipping Two
Bi-Monthly

13




Run floor scrubber around green mile
Weekly

14



All Fans cleaned and wiped down
Every Two Months

15



Outside door swept, stadium chairs wiped down
Monthly

16



Second Level above bottling floor - all YELLOW railings wiped down, floor cleaned - **Every Two Months**

17



Scrub steps, platform, railings, etc leading to break area
Monthly

18

Proposed MAXIMO Work Orders



19

Tunnels in Shipping and to Main offices
should be policed for trash and debris -
A good sweep can be done during shutdown*
Every Quarter



20

ALL strap machines AND motors
along the bottling lines should
be wiped down
Monthly



21

All bailers are to be wiped down
from top to bottom
Monthly