


# East Lake Tarpon Special Fire Control District

	<b><i>SOP 927 Foam Inductor</i></b>	
	<b>Implementation Date: 11/2000</b>	<b>Revision Date(s): 09/2004</b>
		<b>Reviewed Date(s):</b>
	<b>Forms or Attachments: None</b>	

## Monthly Check and After Each Use

1. Wash in mild detergent and water. Dry completely.
2. Check all moving parts.
3. Check induction hose for cracks or damage. Report any damage.