

Cohn Motorsports Appraisal

27943 Seco Canyon Road #149 Santa Clarita, Ca. 91350

(661) 263-9935
alan@cohnmotorsports.com
Alan Cohn

Date: 4/23/2019

CMA File #1904-006AC

Insurance company:	Insured:
Examiner:	Claim #
	Policy #
	Date of Loss: 4/12/2019
	Claimant:

Attached: <input checked="" type="checkbox"/> estimate <input checked="" type="checkbox"/> photos <input type="checkbox"/> rep. order <input type="checkbox"/> tow bill <input type="checkbox"/> registration <input type="checkbox"/> other repair shop tax ID:	Invoice: fee \$ transport \$ tow / storage \$ other \$ _____ total \$
--	--

inspection notes:

Inspected insured's motorcycle at the repair shop on 4/23/2019. We see frontal and mainly left side damage in the form of abrasions, scratches and dents.

Appears the engine guard made contact with the front fender & right side exhaust shields at time of impact.

Damaged parts include the front fender, primary cover, foot peg bracket, engine guard, exhaust covers and left rear saddlebag.

Parts prices are set to current MSRP. Accessory damage is far under policy limits. Able to source only the left saddlebag from the complete accessory kit.

Agreed repairs amount to \$ 3,340.29 less \$500 deductible.

Note: The insured mentioned that adverse carrier handled towing costs (from residence to shop). Suggest Examiner reach out to the insured, verify if he is pursuing this loss as a Claimant on adverse policy.

signed: **Alan Cohn**
Apr 23, 2019

Insurance Company
 Claim Number
 Policy Number
 Type & Date of Loss Collision, 4/12/2019
 Insured
 Address
 Repair Shop
 Address
 Tax ID

Make & Model HARLEY-DAVIDSON FXDL
 VIN
 Mileage 33,262 Year 2014
 Color BLACK Lic.

Labor Rate \$125.00

Qty	Description	Part Number	Unit Price	Labor	Ext Price	Sublet
1	1 front fender	60139-06DH	535.92	0.50	535.92	
2	1 repair engine guard hangar brkt.	IN HOUSE REPAIR		2.00		
3	1 emissions cannister	60800006	113.77	0.50	113.77	
4	1 horn	69000051	22.11	0.50	22.11	
5	1 primary cover	60764-06A	349.95	1.50	349.95	
6	1 gasket	60547-06	31.99		31.99	
7	1 gasket	17369-06	5.31		5.31	
8	1 fluids	...	8.49		8.49	
9	1 L/H rider step brkt.	50500279	231.67	0.30	231.67	
10	1 heat shield, fwd	64819-08	129.80	0.50	129.80	
11	1 heat shield, rear	65400147	138.82	0.50	138.82	
12						
13	ACCESSORIES:					
14	1 engine guard kit	49010-06	219.95	0.70	219.95	
15	1 helmet lock	45732-86	27.95	0.50	27.95	
16	1 L/H saddlebag (sourced via accessories kit)	90373-06	366.36	0.50	366.36	
Totals				8.00	\$2,182.09	

NOTE: This estimate is not an authorization to repair. Always wait for an insurance draft or obtain insured authorization prior to making any repairs.

\$500 deductible

LABOR \$1,000.00
 PARTS \$2,182.09
 MISC.
 SUBLET

TAX 7.25% \$158.20

GRAND TOTAL \$3,340.29

Cohn Motorsports Appraisal - claim diary

Appraiser: Alan Cohn

Assignment received: 4/15/2019

Examiner:

Assignment completed: 4/23/2019

Insured's name:

Claim Number:

Date of Loss: 4/12/2019

Status: appraisal complete

Notes

4/15/2019 2:45pm called insd @#... advised take to shop and call me... SVHD

4/17/2019 insd called.. mentioned motorcycle arriving at shop later today.. will inspect beginning of next week... other carrier paid for towing

4/23/2019 insp @ repair shop.. agreed repair

















390 LB) WITH 100/90B19 MIC 57H TIRE

PSI COLD
35 LB) WITH 160/70B17 MIC 73V TIRE

MS TO ALL APPLICABLE US FEDERAL MOTOR
DARDS IN EFFECT ON
TURE SHOWN ABOVE V.I.N. *







MI 000000

HARLEY-DAVIDSON

Old Road

SEP

CA 2019 ACTM
N 1455491

CAL

HARLEY-DAVIDSON















UNDER ENGINE COVER (UNDER FUEL TANK) (SEE USER MANUAL FOR LOCATION OF SLIDE). IT IS NOT MADE NOR INTENDED TO PROVIDE PROTECTION FROM BODY INJURY IN A COLLISION WITH ANOTHER VEHICLE OR ANY OTHER OBJECT.





















