

Cohn Motorsports Appraisal
27943 Seco Canyon Road #149 Santa Clarita, Ca. 91350
(661) 263-9935
cohnmotorsports@socal.rr.com

Date: 8/29/2015
CMA File #1508-017AC

Insurance company:	Policy #
Examiner:	Insured:
	Date of Loss: 8/20/2015
	Claim #
	Claimant:

Attached: <input checked="" type="checkbox"/> estimate <input checked="" type="checkbox"/> photos <input type="checkbox"/> ccc form <input type="checkbox"/> tow bill <input type="checkbox"/> registration <input type="checkbox"/> other repair shop tax ID: 95-2470218	Invoice: fee \$ 200.00 transport \$ tow / storage \$ other \$ <hr/> total \$ 200.00
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------

inspection notes:

Inspected insured's motorcycle at the repair shop on 8/26/2015. Damages are to both sides as it appears the vehicle "flipped" from the left to right, coming to a stop on the right side.

Damaged parts include the engine guard, left board mounting. bracket, primary cover, both saddlebags and mufflers and rear fender / rear turn signal areas.

Unable to provide a copy of the vehicle registration.

Parts prices are set to current MSRP. Accessory damage amounts to \$1,033.79 (included in estimate).

Agreed repairs are per my estimate of \$ 3,795.41 less \$ 1,000 deductible = \$ 2,795.41 payable to listed repairer.

signed: **Alan S. Cohn**
Aug 29, 2015

Insurance Company
 Claim Number
 Policy Number
 Type & Date of Loss Collision, 8/20/2015
 Insured
 Address
 Repair Shop
 Address
 Tax ID

Make & Model HARLEY-DAVIDSON FLHX
 VIN 1HD1KB
 Mileage 25,598 Year 2008
 Color BLACK Lic. *

Labor Rate \$85.00

Qty	Description	Part Number	Unit Price	Labor	Ext Price	Sublet
1	1	L/H rear board mntg. brkt.	50622-83C	67.90	0.20	67.90
2						
3	1	primary cover	60553-07A	349.95	0.80	349.95
4	1	gasket	25416-99C	8.12		8.12
5	1	gasket	34901-07	35.68		35.68
6						
7	1	L/H saddlebag bottom	90867-95DH	277.56	1.00	277.56
8						
9	1	R/H saddlebag assy	90828-06DH	524.76	0.50	524.76
10	1	R/H rear saddlebag mntg brkt.	90801-06	15.24		15.24
11	1	R/H reflector	59287-92	5.64		5.64
12	2	bail head studs	90834-95B	8.37		16.74
13						
14	1	rear fender	59731-06DH	540.39	2.00	540.39
15	1	R/H rear fascia	59739-06DH	119.47		119.47
16	1	rear bumper	59581-05	8.63		8.63
17	1	turn signal brkt, rear	68629-05	117.45	0.30	117.45
18	1	tail lens	68245-03	53.57		53.57
19	2	recepticle, stud	70909-95	4.82		9.64
20						
21		fluids, supplies, misc.	UNDER MISC	9.32		
22						
23		ACCESSORIES: \$ 1,033.79				
24	1	engine guard kit	46549-03	214.95	0.70	214.95
25	1	turn signal lens, smoked	69304-02	39.95		39.95
26	1	Rhinehart mufflers	RE-100-0160	599.95	0.50	599.95

Totals	6.00	\$3,005.59
---------------	-------------	-------------------

NOTE: This estimate is not an authorization to repair. Always wait for an insurance draft or obtain insured authorization prior to making any repairs.

\$1,000 deductible

LABOR	\$510.00
PARTS	\$3,005.59
MISC.	\$9.32
SUBLET	

TAX 9%	\$270.50
--------	----------

GRAND TOTAL	\$3,795.41
--------------------	-------------------

































