Major Components:

Rockwell 440 2-Stroke Engine

- Disassembly
- Inspect for wear
- Order new parts
 - This also includes interacting with the machine shop
- Engine assembly
 - o Piston Rings
 - o Cylinders
 - Heads
 - Set timing
 - Test run



Borg/Warner T-20 Transmission

- Disassembly
- Inspect for wear
- Order new parts
 - Seals
 - o O-Rings
 - Send bands out for relining
- Reassembly
- Test

Roll Cage Fabrication

- Partner with Welding
- Partner with Precision Manufacturing

