



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
053445 2	INSPECT LEVEL 2 SELF TEST-KGP860	KRBD		MTH 28-May-2019 HRS 9464.6 LDG 7636		12 100		31-May-2020 9564.6	9 m 4 d 82.3
053450	INSPECT NAVIGATION COMPUTER PER ICA: CHECK FOR INTEGRITY AND SECURITY	KDAL		MTH 13-Feb-2018 HRS 9232.8 LDG 7501		36 1200		28-Feb-2021 10432.8	18 m 1 d 950.5
055013	EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED CHECK			MTH 15-Dec-1996		A/R			
055604 LEFT	INSPECT COCKPIT SIDE WINDOW INSPECTION	RBD		MTH 15-May-2019 HRS 9464.6 LDG 7636		24 300		31-May-2021 9764.6	21 m 4 d 282.3
5-12-01 051201	PHASE 1	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24 300		31-Mar-2021 9723.7	19 m 4 d 241.4
5-12-02 051202	PHASE 2	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24 300		31-Mar-2021 9723.7	19 m 4 d 241.4
5-12-03 051203	PHASE 3	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24 300		31-Mar-2021 9723.7	19 m 4 d 241.4
5-12-04 051204	PHASE 4	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24 300		31-Mar-2021 9723.7	19 m 4 d 241.4
5-12-05 051205	PHASE 5	SHV		MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		36 1200		31-Dec-2020 10399.2	16 m 4 d 916.9
5-12-0B 051200B	PHASE B	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		150		9573.7	91.4
5-12-11 051211	PHASE 11	KDAL		MTH 23-Apr-2019 HRS 9459.7 LDG 7632		6		31-Oct-2019	2 m 4 d
5-12-13 051213	PHASE 13	TEB		MTH 29-Nov-2004 HRS 4987		5000		9987	504.7
5-12-14 051214	PHASE 14	*CF		MTH 15-Dec-1996 HRS 0		12000		12000	2517.7
5-12-15 051215	PHASE 15	*CF		MTH 15-Dec-1996 HRS 0		10000		10000	517.7
5-12-16 051216	PHASE 16	*CF		MTH 15-Dec-1996 HRS 0		10000		10000	517.7
5-12-17 051217	PHASE 17	*CF		MTH 15-Dec-1996 HRS 0		10000		10000	517.7
5-12-18 051218	PHASE 18	KDAL		MTH 16-Jan-2019 HRS 9409.5 LDG 7593		12		31-Jan-2020	5 m 4 d
A262003 CABIN 051208D : A	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER : PHASE 18	KDAL	C352TS Y-95358	MTH 16-Jan-2019 HRS 9409.5 LDG 7593		12		31-Jan-2020	5 m 4 d
A262003 COCKPIT 051208D : F	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER : PHASE 18	KDAL	C352TS Y-95353	MTH 16-Jan-2019 HRS 9409.5 LDG 7593		12		31-Jan-2020	5 m 4 d



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KRBD		MTH 30-Nov-2018 HRS 9393.7 LDG 7587		24			
A341008 051220	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0260 AND ON CERTIFIED FOR RVSM); PHASE 20	KRBD		MTH 30-Nov-2018 HRS 9393.7 LDG 7587		24		30-Nov-2020	15 m 3 d
B341010 NO. 1 051220 : ADC	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0260 THRU -0643: PHASE 20	KRBD	7014700-601 95080556	MTH 30-Nov-2018		24		30-Nov-2020	15 m 3 d
B341010 NO. 2 051220 : ADC#2	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0260 THRU -0643: PHASE 20	KRBD	7014700-601 97031094	MTH 30-Nov-2018		24		30-Nov-2020	15 m 3 d
B345001 NO. 1 051220 : XPDR1	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): PHASE 20	KRBD	7517400-902 99042899	MTH 30-Nov-2018		24		30-Nov-2020	15 m 3 d
B345001 NO. 2 051220 : XPDR2	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): PHASE 20	KRBD	7517400-902 96051978	MTH 30-Nov-2018		24		30-Nov-2020	15 m 3 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24			
A237003 051221 : CVR	INSPECT CVR UNDERWATER LOCATOR BEACON : PHASE 21	KDAL	DK120 SD40924	MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24		31-Mar-2021	19 m 4 d
B237004 051221 : CVR	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON : PHASE 21	KDAL	DK120 SD40924	MTH 11-Mar-2019 HRS 9423.7 LDG 7608		24		31-Mar-2021	19 m 4 d
5-12-30 051230	PHASE 30	KDAL		MTH 28-Aug-2017 HRS 9134.5 LDG 7448 ACH 464.3		600		9734.5	252.2
5-12-32 051232	PHASE 32	*CF		MTH 15-Dec-1996 LDG 0		15000		15000	7348
5-12-33 051233	PHASE 33	*CF		MTH 15-Dec-1996 LDG 0		15000		15000	7348
5-12-34 051234	PHASE 34	TEB		MTH 19-Jan-2007 HRS 6713		6725		13438	3955.7
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 15-Dec-1996		72			
B262004 CABIN	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	SHV	C352TS Y-95358	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		72		31-Dec-2023	52 m 4 d
B262004 COCKPIT	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	SHV	C352TS Y-95353	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		72		31-Dec-2023	52 m 4 d
5-12-49 051249	PHASE 49	RBD		MTH 15-May-2019 HRS 9464.6 LDG 7636		36 1200		31-May-2022 10664.6	33 m 4 d 1182.3



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-54	PHASE 54	KIKV		MTH 12-Dec-2014 HRS 8544.7 LDG 6948		N/A			
5-12-55	PHASE 55 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KRBD		MTH 18-Dec-2018 HRS 9399 LDG 7589		3 200			
D243003 051255 : CON	INSPECT MAIN SHIP BATTERY LEAD ACID BATTERY: PHASE 55	KRBD	RG-380E/44 40784760	MTH 28-May-2019 HRS 9464.6 LDG 7636		4 200		30-Sep-2019 9664.6	1 m 3 d 182.3
5-12-56 051256	PHASE 56	KRBD		MTH 15-Aug-2019 HRS 9482.3 LDG 7652		12		31-Aug-2020	12 m 4 d
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 15-Dec-1996 HRS 0 LDG 0		A/R			
A561004 RIGHT INBOARD	PERFORM CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION : PHASE 59		5511285-6 SN-UNKNOWN	MTH 15-Dec-1996		A/R			
A561004 RIGHT OUTBOARD	PERFORM CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION : PHASE 59		5511285-200 N/A	MTH 15-Dec-1996		A/R			
5-12-60	PHASE 60	SHV		MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		500		9699.2	216.9
5-12-61	PHASE 61			MTH 15-Dec-1996 HRS 0		13200		13200	3717.7
5-12-62	PHASE 62			MTH 15-Dec-1996 HRS 0		15600		15600	6117.7
5-12-63	PHASE 63			MTH 15-Dec-1996 HRS 0		15600		15600	6117.7
5-12-64	PHASE 64	KRBD		MTH 28-May-2019 HRS 9464.6 LDG 7636		6		30-Nov-2019	3 m 3 d
5-12-65	PHASE 65	KDAL		MTH 08-May-2017 HRS 9089.3 LDG 7415 ACH 450		500		950	338.6
5-12-66	PHASE 66			MTH HRS		6000		14030.72	4548.42
5-12-67	PHASE 67			MTH HRS		10000		10000	517.7
5-12-MC 0512MC	PHASE MC	KIKV		MTH 13-Oct-2016 HRS 8988.4 LDG 7340 ACH 338.8		1456		10444.4	962.1
5-12-MD 0512MD	PHASE MD	KIKV		MTH 04-Mar-2014 HRS 8244.7 LDG 6682		2523		10767.7	1285.4
5-12-ME 0512ME	PHASE ME	KPBI		MTH 05-Jan-2012 HRS 7886.7 LDG 6399		4450		12336.7	2854.4
5-12-MF 0512MF	PHASE MF	KIKV		MTH 04-Mar-2014 HRS 8244.7 LDG 6682		5000		13244.7	3762.4

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-MG	PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 15-Dec-1996 LDG 0		10000			
A325009 <i>0512MG</i>	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK: PHASE MG *CF		6642000-3 NSN	MTH 15-Dec-1996 LDG 0		10000		10000	2348
5-12-MI <i>0512MI</i>	PHASE MI	KDAL		MTH 16-Jan-2019 HRS 9409.5 LDG 7593		5130		14539.5	5057.2
5-12-MJ <i>0512MJ</i>	PHASE MJ	TEB		MTH 17-Jan-2006 HRS 5897		5900		11797	2314.7
5-12-MK <i>0512MK</i>	PHASE MK			MTH 19-Jan-2007 HRS 6713		6725		13438	3955.7
5-12-ML	PHASE ML	KDAL		MTH 11-Mar-2019 HRS 9423.7 LDG 7608		300		9723.7	241.4
051204 E1	MINOR INSPECTION	KRDB		MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
051204 E2	MINOR INSPECTION	KRDB		MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY)	KRBD	1134104-1 5702	MTH 15-Aug-2019 HRS 9482.3 LDG 7652 ACH 611.4				500 1111.4	500
263005 FORWARD LEFT <i>262003 : FL</i>	REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE	BHM	873364-1 0310011945			N/A			
263007 FORWARD RIGHT <i>262003 : FR</i>	REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE	BHM	873364-1 0310011946			N/A			
263009 AFT LEFT <i>262003 : AL</i>	REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE	BHM	873364-1 0310011942			N/A			
263011 AFT RIGHT <i>262003 : AR</i>	REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE	BHM	873364-1 0310011943			N/A			
B262002 AFT <i>051223 : A</i>	HYDROSTATIC TEST ENGINE FIRE BOTTLE	SHV	32700015 58651	MTH 06-Dec-2017		60		31-Dec-2022	40 m 4 d
B262002 FORWARD <i>051223 : F</i>	HYDROSTATIC TEST ENGINE FIRE BOTTLE	SHV	32700015 19676	MTH 06-Dec-2017		60		31-Dec-2022	40 m 4 d
B262003 CABIN	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER	KPBI	C352TS Y-95358	MTH 30-Dec-2011		144		31-Dec-2023	52 m 4 d
B262003 COCKPIT	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER	KPBI	C352TS Y-95353	MTH 30-Dec-2011		144		31-Dec-2023	52 m 4 d
B326003 <i>051222 : GEAR</i>	HYDROSTATIC TEST PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE	KDAL	212940-2 1388	MTH 21-Apr-2017		36		30-Apr-2020	8 m 3 d
350004 <i>051222 : OXY</i>	HYDROSTATIC TEST OXYGEN CYLINDER	KDAL	176176-64 533316	MTH 22-Apr-2017		36		30-Apr-2020	8 m 3 d
710020 E1	HOT SECTION INSPECTION	KIKV		MTH 06-Jun-2016 HRS 8860.5 LDG 7230		1750		10610.5	1128.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
710020 E2	HOT SECTION INSPECTION	KIKV		MTH 06-Jun-2016 HRS 8858.5 LDG 7230		1750		10608.5	1126.2
720010 E1	OVERHAUL			MTH 06-Jul-2007 HRS 7068.6 LDG 5832		3500		10568.6	1086.3
720010 E2	OVERHAUL			MTH 06-Jul-2007 HRS 7068.6 LDG 5832		3500		10568.6	1086.3
720020 E1	OIL ANALYSIS	KIKV		MTH 06-Jun-2016 HRS 8858.5 LDG 7230		A/R			
720020 E2	OIL ANALYSIS	KIKV		MTH 06-Jun-2016 HRS 8858.5 LDG 7230		A/R			
720100 E1	ENGINE OVERTEMPERATURE					A/R			
720100 E2	ENGINE OVERTEMPERATURE			MTH 07-Dec-2002		A/R			
720110 E1	FOREIGN OBJECT DAMAGE					A/R			
720110 E2	FOREIGN OBJECT DAMAGE			MTH 07-Dec-2002		A/R			
720120 E1	LOSS OF OIL					A/R			
720120 E2	LOSS OF OIL			MTH 07-Dec-2002		A/R			
720130 E1	ENGINE OVERSPEED					A/R			
720130 E2	ENGINE OVERSPEED			MTH 07-Dec-2002		A/R			
720140 E1	ENGINE WINDMILLING					A/R			
720140 E2	ENGINE WINDMILLING			MTH 07-Dec-2002		A/R			
720150 E1	ENGINE IMMERSION IN WATER					A/R			
720150 E2	ENGINE IMMERSION IN WATER			MTH 07-Dec-2002		A/R			
720160 E1	ENGINE DROPPED DURING HANDLING					A/R			
720160 E2	ENGINE DROPPED DURING HANDLING			MTH 07-Dec-2002		A/R			
720170 E1	LIGHTNING STRIKE					A/R			
720170 E2	LIGHTNING STRIKE			MTH 07-Dec-2002		A/R			
720180 E1	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT					A/R			
720180 E2	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT			MTH 07-Dec-2002		A/R			
720190 E1	HEAVY/HARD LANDING					A/R			
720190 E2	HEAVY/HARD LANDING			MTH 07-Dec-2002		A/R			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
720200 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH					A/R			
720200 E2	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 07-Dec-2002		A/R			
720210 E1	STARTER GENERATOR FAIL INDICATION					A/R			
720210 E2	STARTER GENERATOR FAIL INDICATION			MTH 07-Dec-2002		A/R			
720220 E1	HYDRAULIC PUMP FAILURE					A/R			
720220 E2	HYDRAULIC PUMP FAILURE			MTH 07-Dec-2002		A/R			
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER		D2397-10A 47895	HRS 434.3		3500		10570.3	1088
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER		D2397-10A 47696	MTH 07-Dec-2002 HRS 278.1		3500		10568.1	1085.8
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE		PN SN-UNKNOWN	HRS 434.3		3500		10570.3	1088
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE		PN SN-UNKNOWN	MTH 07-Dec-2002 HRS 278.1		3500		10568.1	1085.8
731060 E1	VISUAL INSPECT BLEED VALVE ACTUATOR KRDB		9912402-12 0576C	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
731060 E2	VISUAL INSPECT BLEED VALVE ACTUATOR KRDB		9912402-12 0585C	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE		26395-2 0910	HRS 434.3		3500		10570.3	1088
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE		26395-2 0186	MTH 07-Dec-2002 HRS 278.1		3500		10568.1	1085.8
732035 E1	VISUAL INSPECT ELECTRONIC BLEED VALVE CONTROL KRDB		815625-1-002 C96031939	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
732035 E2	VISUAL INSPECT ELECTRONIC BLEED VALVE CONTROL KRDB		815625-2-002 C96051945	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
732060 E1	VISUAL INSPECT MAIN WIRING HARNESS KRDB		PN SN-UNKNOWN	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
732060 E2	VISUAL INSPECT MAIN WIRING HARNESS KRDB		PN SN-UNKNOWN	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
741002 E1 INBOARD	VISUAL INSPECT IGNITION EXCITER KRDB		9049770-3 NN02317242	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
741002 E1 OUTBOARD	VISUAL INSPECT IGNITION EXCITER KRDB		9049770-3 98055507	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
741002 E2 INBOARD	VISUAL INSPECT IGNITION EXCITER KRDB		9049770-3 NN01508262	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
741002 E2 OUTBOARD	VISUAL INSPECT IGNITION EXCITER	KRDB		9049770-3 NN97290915	MTH 18-Apr-2019 HRS 9454 LDG 7628		24 300		30-Apr-2021 9754	20 m 3 d 271.7
792010 E1	DRAIN & REFILL OIL SYSTEM	KIKV			MTH 06-Jun-2016 HRS 8858.5 LDG 7230		O/C			
792010 E2	DRAIN & REFILL OIL SYSTEM	KIKV			MTH 06-Jun-2016 HRS 8858.5 LDG 7230		O/C			
792020 E1	CLEAN/INSPECT/REPLACE OIL FILTER	KRBD			MTH 28-May-2019 HRS 9464.6 LDG 7636		200		9664.6	182.3
792020 E2	CLEAN/INSPECT/REPLACE OIL FILTER	KRBD			MTH 28-May-2019 HRS 9464.6 LDG 7636		200		9664.6	182.3





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	EMERGENCY PRESSURE VALVE TEB			27441482-06 9BC20	MTH 25-Jan-2008 HRS 7447		O/C	0		
211004	S243 PRIMARY PRESSURE SWITCH KIKV			1103P240-1 1557	MTH 30-Oct-2014 HRS 8535.9 LDG 6942		O/C	0 0		
211005	S244 SECONDARY PRESSURE SWITCH *CF			1103P240-2 845	MTH 15-Dec-1996		O/C			
212001	INSTRUMENT PANEL FAN *CF			4124X SN-UNKNOWN	MTH 15-Dec-1996		O/C			
212002	AVIONICS BAY COOLING BOX FAN TEB			032105 SN-UNKNOWN	MTH 19-Sep-2006 HRS 6520		O/C	0		
212004	OVERHEAD CABIN FAN KLIT			MB38A-1 1265	MTH 11-Aug-2016 HRS 8951.8 LDG 7321 ACH 338.8		1000	0	9951.8	469.5
212006	COCKPIT DEFOGGER FAN SWF			5703-4 1503	MTH 31-Jul-2008 HRS 7541		3500	0	11041	1558.7
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466 1325	MTH 15-Dec-1996		O/C			
212010	AVIONICS BAY VANE AXIAL BLOWER *CF			19A827 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
212011	TEMP DUCT SENSOR 9912085-3	*CF		27221274 6AM160	MTH 15-Dec-1996		O/C			
213001	CABIN PRESSURE INDICATOR 3001J50	*CF		C668511-0103 20205	MTH 15-Dec-1996		O/C			
213003	RATE OF CHANGE INDICATOR 35060-1128	UNK		C668513-0101 351349	MTH 16-Jan-2013 HRS 7953.8 LDG 6440		O/C			
213006	CABIN ALTITUDE CONTROLLER TEB			130620-2 61-C0323	MTH 31-Jan-2007 HRS 6734		O/C	0		
213007 NO. 1	PRIMARY OUTFLOW VALVE MCO			103648-14 16-L0313	MTH 22-Oct-2008 HRS 7549		O/C	0		
213007 NO. 2	SECONDARY OUTFLOW VALVE *CF			103648-14 16LO304	MTH 15-Dec-1996		O/C			
213009 NO. 1	FLOW CONTROL PRESSURE REGULATOR VALVE MCO			1988-00-1 2005A	MTH 27-Oct-2008 HRS 7551		O/C	0		
213009 NO. 2	FLOW CONTROL PRESSURE REGULATOR VALVE			1988-00-1 0131A	MTH 07-Apr-2008 HRS 7532		O/C	0		
213013	PNEUMATIC RELAY *CF			130358-1 162201	MTH 15-Dec-1996		O/C			
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY 9912069-27	*CF		782343-3 960749	MTH 15-Dec-1996		O/C			
215004	AIR CYCLE MACHINE *CF			738384-26 960796	MTH 15-Dec-1996 HRS 0		5000	0	5000	-4482.3
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	ACM BYPASS VALVE FPR			754751-2 80053029	MTH 11-Jan-2010 HRS 7662		O/C	0		<b>Over Due</b>





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215007	COMPRESSION ACTUATOR 9912294-1	KIKV		BYLB50907 232	MTH 30-Oct-2014 HRS 8535.9 LDG 6942		O/C	0 0		
215008	DUCT OVERHEAT SENSOR *CF			1173T42-1 2552	MTH 15-Dec-1996		O/C			
215009	ACM OVERHEAT SWITCH FPR			1173T0635 N/A	MTH 02-Sep-2009 HRS 7635		O/C	0		
215016	AC COMPRESSOR	KDAL		1134162 SA2943	MTH 08-May-2017 HRS 9089.3 LDG 7415 ACH 450		O/C			
215017	AC CONDENSER *CF			1134400-9 229488	MTH 15-Dec-1996		O/C			
215018	ACM CONTROL UNIT *CF			C35020A 2068	MTH 15-Dec-1996		O/C			
215021	MOTOR	KRBD		1134104-1 5702	MTH 15-Aug-2019 HRS 9482.3 LDG 7652		O/C			
215022	AFT EVAPORATOR *CF			1134240-3 215	MTH 15-Dec-1996		O/C			
215023	FWD EVAPORATOR *CF			1134240-2 213	MTH 15-Dec-1996		O/C			
215024	PRESSURE SWITCH *CF			1250232-4 2635	MTH 15-Dec-1996		O/C			
215025	BAROMETRIC SWITCH *CF			GBC300-140 9621117	MTH 15-Dec-1996		O/C			
215026	FREON A/C-HOBBS METER FPR			1250703-3 SN-UNKNOWN	MTH 23-Feb-2010 HRS 7677		O/C	0		
216001	CABIN TEMPERATURE SENSOR TEB			1942T100-11 1487	MTH 23-Mar-2007 HRS 6895		O/C	0		
216002	CABIN TEMPERATURE CONTROLLER 9912069-22	KDAL		754661-5 980884623	MTH 13-Oct-2017 HRS 9168.8 LDG 7467 ACH 464.3		O/C			
216003	DUCT TEMPERATURE SENSOR SHV			9912069-14 N0904	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		O/C	0 0		
216005	CENTRIFUGAL BLOWER *CF			3A1003-10 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
216006	CABIN TEMP INDICATOR TEB			0221-007 85180	MTH 23-Mar-2007 HRS 6895		O/C	0		
216010	DOOR ACTUATOR MOTOR ASSEMBLY 9910059-3			5A3032 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
217001	WATER SEPARATOR 9912069-13			738386-3 960710	MTH 15-Dec-1996		O/C			
221009	AUTOPILOT CONTROL PC-400			7003897-923 96070990	MTH 15-Dec-1996		O/C			
221010 AILERON	SERVO SM-200	TEB		4006719-906 91095677	MTH 09-Jun-2007 HRS 7042		O/C	4989		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
221010 ELEVATOR	SERVO SM-200	KIKV		4006719-904 78122955	MTH 20-Jul-2014 HRS 8392.9 LDG 6812		O/C			
221010 RUDDER	SERVO SM-200	KIKV		4006719-906 01076029	MTH 25-Mar-2016 HRS 8828.2 LDG 7204 ACH 324.6		O/C			
230002	SELCAL TRANCEIVER CSD-714	*CF		1200008-000 436	MTH 15-Dec-1996		O/C			
231003	KTR953 HF RECEIVER/EXCITER KTR-953	*CF		064-01015-0001 29532	MTH 15-Dec-1996		O/C			
231004	KAC952 HF POWER AMP COUPLER KAC-952	*CF		064-01017-0001 14462	MTH 15-Dec-1996		O/C			
231005	KCU951/KFS594 HIGH FREQUENCY CONTROLLER KFS-594	*CF		071-01274-0002 3679	MTH 15-Dec-1996		O/C			
231007	KA594 HIGH FREQUENCY ADAPTER KA-594	*CF		071-01268-0001 2920	MTH 15-Dec-1996		O/C			
232002 NO. 2	VHF COMM ANTENNA	TEB		17-50-01 1857	MTH 06-Oct-2004 HRS 4870		O/C		0	
232003 NO. 1	VHF COMM ANTENNA	*CF		VFS10-90-7 266	MTH 15-Dec-1996		O/C			
232004	TRANSCIEVER PHONE AIRCELL ST-3100	LNK		400-10680-001 1068012636	MTH 07-Nov-2006 HRS 6551		O/C		0	
232005 CABIN	HANDSET PHONE AIRCELL	LNK		310-10590-002 1059011373	MTH 07-Nov-2006 HRS 6551		O/C		0	
232005 COCKPIT	CONTROL PHONE	LNK		400-10001-102 1000114107	MTH 07-Nov-2006 HRS 6551		O/C		0	
232005	SATELITE ANTENNA	LNK		015-10306-001 4545	MTH 07-Nov-2006 HRS 6551		O/C		0	
232008 NO. 1	VHF INTEGRATED CONTROL UNIT RCZ-851	KDSM		7510700-806 01076706	MTH 26-Jan-2015 HRS 8602.7 LDG 6989		O/C			
232008 NO. 2	VHF INTEGRATED CONTROL UNIT RCZ-851	*CF		7510700-806 96021841	MTH 15-Dec-1996		O/C			
232010 NO. 1	VHF COMMUNICATION TRANSCEIVER TR-850	SMF		7510764-902 95031477	MTH 21-Aug-2011 HRS 7790.9 LDG 6322		O/C			
232010 NO. 2	VHF COMMUNICATION TRANSCEIVER TR-850	*CF		7510764-902 96021861	MTH 15-Dec-1996		O/C			
232013 NO. 1	COMM CLUSTER MODULE XC-850	*CF		7510784-904 96052030	MTH 15-Dec-1996		O/C			
232013 NO. 2	COMM CLUSTER MODULE XC-850	*CF		7510784-904 96021878	MTH 15-Dec-1996		O/C			
235001 NO. 1	AUDIO AMPLIFIER AV-850A	TEB		7511001-915 01107649	MTH 03-Dec-2001 HRS 3049		O/C		0	
235001 NO. 2	AUDIO AMPLIFIER AV-850A	TEB		7511001-915 0115723	MTH 30-Jul-2004 HRS 4675		O/C		0	



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
237001	COCKPIT VOICE RECORDER A200S	TEB		S200-0012-00 366	MTH 20-Aug-1999 HRS 1801		O/C	1877		
237004	CVR CONTROLLER	KIKV		S200-0012-00 02190	MTH 09-Apr-2013 HRS 7974.4 LDG 6457		O/C			
237006	CVR UNDERWATER LOCATOR BEACON 266-E0305-00	KDSM		DK120 SD40924	MTH 26-Jan-2015 HRS 8602.7 LDG 6989		O/C	0 0		
237006A	REPLACE ULB (CVR) BATTERY KDSM			810-2007 NSN	MTH 26-Jan-2015 HRS 8602.7 LDG 6989	1	72	0	28-Feb-2021	18 m 1 d
242001 NO. 1	STATIC INVERTER S3100-1	KIKV		PC251-123E 10190	MTH 20-Aug-2015 HRS 8714 LDG 7111 ACH 292.8		O/C	0 0		
242001 NO. 2	STATIC INVERTER S3100-1	KIKV		PC251-123E 8801	MTH 20-Oct-2016 HRS 8993.2 LDG 7346 ACH 338.8		O/C	0 0		
243001 LEFT	STARTER/GENERATOR 9912125-3	KIKV		23085-004-1 94215	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		1000	0	9709.6	227.3
243001 RIGHT	STARTER/GENERATOR 9912125-1	KLAN		23085-004 393	MTH 09-Mar-2015 HRS 8533 LDG 7025		1000	0	9533	50.7
243003 NO. 1	GENERATOR CONTROL UNIT SWF			51525-001F Y0138	MTH 06-Aug-2008 HRS 7541		O/C	255		
243003 NO. 2	GENERATOR CONTROL UNIT SWF			51525-001F 96238	MTH 22-Jan-2000 HRS 2031		O/C	0		
243004 NO. 1	AMMETER NO. 1	*CF		C662501-0104 1121	MTH 15-Dec-1996		O/C			
243004 NO. 2	AMMETER NO. 2	TEB		C662501-0104 204	MTH 03-Mar-2000 HRS 2114		O/C	0		
243005	DC VOLTMETER	*CF		C662502-0101 1161	MTH 15-Dec-1996		O/C			
243007	MAIN SHIP BATTERY	KDAL		RG-380E/44 40784760	MTH 13-Feb-2018 HRS 9232.8 LDG 7501		O/C			
BATTERY SHOULD BE REPLACED EVERY 60 MONTHS OR 5000 HOURS PER CONCORDE BATTERY MANUAL.										
243008	BATTERY TEMP MONITOR- *CF			1529-1 2446	MTH 15-Dec-1996		O/C			
243009	BATTERY TEMP GAGE *CF			1229-1 2031	MTH 15-Dec-1996		O/C			
243010	BATTERY TEMP SENSOR *CF			1166-1 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
243015	BATTERY DISCONNECT RELAY *CF			A876K CL76071	MTH 15-Dec-1996		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243016	CURRENT/VOLTAGE SENSOR KIKV			1645-1-3 2596	MTH 06-Jun-2016 HRS 8858.5 LDG 7230 ACH 338.8		O/C	0 0		
245002	CABIN ALTITUDE SWITCH 9910095-6	*CF		GB300NA161 9513787	MTH 15-Dec-1996		O/C			
252005	TRUE AIRSPEED/AIRTIME DISPLAY S2800-159	*CF		15000-003 84601	MTH 15-Dec-1996		O/C			
252006	JETMAP PROCESSOR -- KFPR			990-4180-001 01120013218	MTH 28-Jul-2010 HRS 7725.7 LDG 6285		O/C	4096.7		
252010	CABIN BRIEFER COMPUTER *CF			PBS250-1-S8-C560 97	MTH 15-Dec-1996		O/C			
252012 252011	ARINC 429 COMPUTER TEB			90001-003 119757	MTH 11-Jun-2004 HRS 4570		O/C	0		
256002	EMERGENCY LOCATOR TRANSMITTER KGGG			51220-042 161020-1107	MTH 25-Jul-2017 HRS 9113.9 LDG 7435 ACH 464.3		O/C	0 0		
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY KGGG			217-406-001 NONE	MTH 25-Jul-2017 HRS 9113.9 LDG 7435 ACH 464.3		24	0	12-Dec-2021	27 m 15 d
Expiration Date: 12-Dec-2021										
256004 NO. 1	ELT ANTENNA KGGG			114-042-600 SN-UNKNOWN	MTH 25-Jul-2017 HRS 464.3 LDG 7435 ACH 464.3		O/C	0 0		
256006	COFFEE POT TEB			81319A0500G1100 359	MTH 13-Oct-1999 HRS 1888		O/C	0		
256010 NO. 10	LIFE VEST SHV			PO723E105P 062368	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
256010 NO. 1	LIFE VEST KIKV			P0723-123 J72988	MTH 01-Feb-2016 HRS 8782.5 LDG 7167		60	10	30-Apr-2020	8 m 3 d
256010 NO. 2	LIFE VEST KIKV			P0723-123 J79803	MTH 01-Feb-2016 HRS 8782.5 LDG 7167		60	10	30-Apr-2020	8 m 3 d
256010 NO. 3	LIFE VEST SHV			PO723E105P 062715	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
256010 NO. 4	LIFE VEST SHV			PO723E105P 062643	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
256010 NO. 5	LIFE VEST SHV			PO723E105P 062570	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
256010 NO. 6	LIFE VEST	SHV		PO723E105P 062677	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
256010 NO. 7	LIFE VEST	SHV		PO723E105P 062594	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
256010 NO. 8	LIFE VEST	SHV		PO723E105P 062676	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
256010 NO. 9	LIFE VEST	SHV		PO723E105P 062653	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		60	0	31-Dec-2022	40 m 4 d
261001 NO. 1 ENGINE	FIRE DETECTOR SENSOR 9912036-3	BHM		244-18882 014604	MTH 24-Sep-2002 HRS 3420		O/C	0		
261001 NO. 2 ENGINE	FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
261002 NO. 1	FIRE DETECTOR CONTROL 9912036-8	*CF		377-02830 9619005	MTH 15-Dec-1996		O/C			
261002 NO. 2	FIRE DETECTOR CONTROL 9912036-8	*CF		377-02830 9616002	MTH 15-Dec-1996		O/C			
262001 AFT	ENGINE FIRE BOTTLE 9912048-3	TEB		32700015 58651	MTH 06-Jul-2007 HRS 7068		O/C	0		
262001 FORWARD	ENGINE FIRE BOTTLE 9912048-3	TEB		32700015 19676	MTH 06-Jul-2007 HRS 7068		O/C	0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KPBI		C352TS Y-95358	MTH 05-Jan-2012 HRS 7886.7 LDG 6399		O/C	0 0		
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KPBI		C352TS Y-95353	MTH 05-Jan-2012 HRS 7886.7 LDG 6399		O/C	0 0		
262003 AFT LEFT	(MAX LIFE) CARTRIDGE	KFPR		873364-1 0310011942	MTH 13-Oct-2010 HRS 7733.6 LDG 6291		120		31-Oct-2020	14 m 4 d
Manufacture Date: 05-Oct-2010										
262003 AFT RIGHT	(MAX LIFE) CARTRIDGE	KFPR		873364-1 0310011943	MTH 13-Oct-2010 HRS 7733.6 LDG 6291		120		31-Oct-2020	14 m 4 d
Manufacture Date: 05-Oct-2010										
262003 FORWARD LEFT	(MAX LIFE) CARTRIDGE	KFPR		873364-1 0310011945	MTH 13-Oct-2010 HRS 7733.6 LDG 6291		120		31-Oct-2020	14 m 4 d
Manufacture Date: 05-Oct-2010										
262003 FORWARD RIGHT	(MAX LIFE) CARTRIDGE	KFPR		873364-1 0310011946	MTH 13-Oct-2010 HRS 7733.6 LDG 6291		120		31-Oct-2020	14 m 4 d
Manufacture Date: 05-Oct-2010										
271001	AILERON TRIM ACTUATOR *CF			5565450-72 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
272001	RUDDER TRIM ACTUATOR *CF			5565450-71 SN-UNKNOWN	MTH 15-Dec-1996		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
273002	TRIM MIXER ACTUATOR TEB			44430-3657 T762	MTH 21-Sep-2002 HRS 3417		O/C	0		
273003 LEFT	ELEVATOR TRIM ACTUATOR			5565450-81 SN-UNKNOWN	MTH 12-Nov-1997 HRS 660		O/C	0		
273003 RIGHT	ELEVATOR TRIM ACTUATOR *CF			5565450-82 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
275001	FLAP CONTROL VALVE *CF			66720 1342	MTH 15-Dec-1996		O/C			
275003 NO. 1	FLAP ACTUATOR 9912007-1	*CF		1535000-1 572	MTH 15-Dec-1996		O/C			
275003 NO. 2	FLAP ACTUATOR 9912007-1	*CF		1535000-1 582	MTH 15-Dec-1996		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER TEB			CC50380 SN-UNKNOWN	MTH 24-Feb-2006 HRS 6000 LDG 4993		5000	0	9993	2341
276001 NO. 1	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 531	MTH 15-Dec-1996		O/C			
276001 NO. 2	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 530	MTH 15-Dec-1996		O/C			
276002	SPEED BRAKE FLAP CONTROL VALVE *CF			66720 1321	MTH 15-Dec-1996		O/C			
276003	SAFETY SPDBK VALVE *CF			68930 548	MTH 15-Dec-1996		O/C			
280001 LEFT	FUEL FLOAT VALVE 9914268-4	*CF		9033-201 586	MTH 15-Dec-1996		O/C			
280001 RIGHT	FUEL FLOAT VALVE 9914268-4	*CF		9033-201 589	MTH 15-Dec-1996		O/C			
280002 LEFT	FUEL VENT FLOAT VALVE 9912016-2	*CF		35C10D SN-UNKNOWN	MTH 15-Dec-1996		O/C			
280002 RIGHT	FUEL VENT FLOAT VALVE 9912016-2	*CF		35C10D SN-UNKNOWN	MTH 15-Dec-1996		O/C			
280003 LEFT	PRESSURE RELIEF VALVE *CF			6526313-804 9924	MTH 15-Dec-1996		O/C			
280003 RIGHT	PRESSURE RELIEF VALVE *CF			6526313-804 9784	MTH 15-Dec-1996		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
280004 LEFT	PILOT HIGH LEVEL VALVE 9914107-1	*CF		61087 1414	MTH 15-Dec-1996		O/C			
280004 RIGHT	PILOT HIGH LEVEL VALVE 9914107-1	*CF		61087 1416	MTH 15-Dec-1996		O/C			
280006 LEFT	SINGLE POINT REFUEL VALVE *CF			80002-51 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
280006 RIGHT	SINGLE POINT REFUEL VALVE *CF			80002-51 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
280007 LEFT	DEFUEL SINGLE PT VALVE 9914107-2	*CF		61084 996	MTH 15-Dec-1996		O/C			
280007 RIGHT	DEFUEL SINGLE PT VALVE 9914107-2	*CF		61084 995	MTH 15-Dec-1996		O/C			
280008 LEFT	MANUAL FUEL SHUTOFF VALVE 9914107-3	*CF		61086 1492	MTH 15-Dec-1996		O/C			
280008 RIGHT	MANUAL FUEL SHUTOFF VALVE 9914107-3	*CF		61086 1474	MTH 15-Dec-1996		O/C			
282001 NO. 1	ELECTRIC FUEL BOOST PUMP 9912017-2	*CF		1C7-12 6AM70	MTH 15-Dec-1996		O/C			
282001 NO. 2	ELECTRIC FUEL BOOST PUMP 9912017-2	*CF		1C7-12 7AM77	MTH 15-Dec-1996		O/C			
282010 LEFT	MOTIVE FUEL VALVE 3037075	TEB		3244850-1 C29258	MTH 06-Jul-2007 HRS 7068		O/C	0		
282010 RIGHT	MOTIVE FUEL VALVE	TEB		3244850-1 C29257	MTH 06-Jul-2007 HRS 7068		O/C	0		
284001 NO. 1	FUEL LOW LEVEL SWITCH *CF			L15H-3 4896	MTH 15-Dec-1996		O/C			
284001 NO. 2	FUEL LOW LEVEL SWITCH SHV			L15H-3 7501	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		O/C	0	0	
284002 LEFT	FUEL QTY COMPENSATOR 9912019-4	*CF		300047-13001 17142	MTH 15-Dec-1996		O/C			
284002 RIGHT	FUEL QTY COMPENSATOR 9912019-4	*CF		300047-13001 17129	MTH 15-Dec-1996		O/C			
291001	MAIN HYD RESERVOIR 9912052-12	*CF		40500-7 686	MTH 15-Dec-1996		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 1915	MTH 15-Dec-1996		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 1917	MTH 15-Dec-1996		O/C			
291005 NO. 1	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 3875	MTH 15-Dec-1996		O/C			
291005 NO. 2	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 3871	MTH 15-Dec-1996		O/C			
291007 NO. 1	MOTOR ACTUATOR VALVE *CF			AV24B1325C5 P7880	MTH 15-Dec-1996		O/C			
291007 NO. 2	MOTOR ACTUATOR VALVE *CF			AV24B1325C5 P7889	MTH 15-Dec-1996		O/C			
291008	THERMAL RELIEF VALVE *CF			OAS5322-3-1700 449	MTH 15-Dec-1996		O/C			
291009	PRESSURE RELIEF VALVE *CF			4614 1493A	MTH 15-Dec-1996		O/C			
291012	SOLENOID BYPASS VALVE *CF			61510-1 1231	MTH 15-Dec-1996		O/C			
301001 LEFT	TEMP CONTROL SL002 SWITCH *CF			1173T42-3 2011	MTH 15-Dec-1996		O/C			





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301001 NO. 1	OUTBRD WING DEICE BOOT ICT			P35-5D5230-01 MZX600	MTH 05-Nov-2007 HRS 7236		O/C	0		
301001 NO. 2	OUTBRD WING DEICE BOOT ICT			P35-5D5230-02 MZX710	MTH 05-Nov-2007 HRS 7236		O/C	0		
301001 RIGHT	TEMP CONTROL SR002 SWITCH *CF			1173T42-3 1998	MTH 15-Dec-1996		O/C			
301001 WING	ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE 9914121-1	*CF		1H123-1 7AM27	MTH 15-Dec-1996		O/C			
301002 NO. 1	HORIZONTAL STABILIZER DEICE BOOT SWF			P29S-5D5225-05 MZTT230	MTH 31-Jul-2008 HRS 7541		O/C	0		
301002 NO. 2	HORIZONTAL STABILIZER DEICE BOOT SWF			P29S-5D5225-06 MZQM090	MTH 31-Jul-2008 HRS 7541		O/C	0		
301004 LEFT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 9912086-4	*CF		67410-2 3001	MTH 15-Dec-1996		O/C			
301004 RIGHT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 9912086-4	*CF		67410-2 3004	MTH 15-Dec-1996		O/C			
301007 LEFT	RAM AIR MODULATING TEMP CONTROL VLV 9912362-1	*CF		27441500-01 8AM67	MTH 15-Dec-1996		O/C			
301007 RIGHT	RAM AIR MODULATING TEMP CONTROL VLV 9912362-1	*CF		27441500-01 8AM64	MTH 15-Dec-1996		O/C			
301008 LEFT	DEICE CONTROL SLV19 VLV *CF			3D2353-06 N13727	MTH 15-Dec-1996		O/C			
301008 RIGHT	DEICE CONTROL SLV18 VLV *CF			3D2353-06 N13730	MTH 15-Dec-1996		O/C			
301009 LEFT	TEMP CONTROL S95 SENSOR 9912362-3	*CF		27431501-04 7AM69	MTH 15-Dec-1996		O/C			
301009 RIGHT	TEMP CONTROL S94 SENSOR 9912362-3	*CF		27431501-04 7AM64	MTH 15-Dec-1996		O/C			
302003 LEFT ENGINE	ANTI-ICE SOLENOID VLV 9912402-12	*CF		1946-00-12 576C	MTH 15-Dec-1996		O/C			
302003 RIGHT ENGINE	ANTI-ICE SOLENOID VLV 9912402-12	*CF		1946-00-12 585C	MTH 15-Dec-1996		O/C			
302005 LEFT	ANTI ICING VALVE 31J2879-03	TEB		540-0406-3 1208	MTH 06-Jul-2007 HRS 7068		O/C	0		
302005 RIGHT	ANTI ICING VALVE 31J2879-03	TEB		540-0406-3 1181	MTH 06-Jul-2007 HRS 7068		O/C	0		
302006 LEFT	BLEED VALVE ACTUATOR 3037074	TEB		800888-1 F37059	MTH 06-Jul-2007 HRS 7068		O/C	0		
302006 RIGHT	BLEED VALVE ACTUATOR 3037074	TEB		800888-1 F18018	MTH 06-Jul-2007 HRS 7068		O/C	0		
303001 LEFT	PITOT TUBE TEB			PH502 6873	MTH 22-Jun-2006 HRS 6267		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
303001 RIGHT	PITOT TUBE	LNK		PH502 SN-UNKNOWN	MTH 07-Nov-2006 HRS 6551		O/C	0		
304001	BLEED AIR MONITOR-			1169-1 2367	MTH 15-Dec-1996		O/C			
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER 9912041-4	*CF		10663A 896	MTH 15-Dec-1996		O/C			
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP	*CF		476411 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
304005	TEMP CONTROL VALVE 9912085-1	*CF		27241287 7AM64	MTH 15-Dec-1996		O/C			
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR 9912085-6	*CF		27231272-20A 7AM31	MTH 15-Dec-1996		O/C			
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH	*CF		1115P25 2698A	MTH 15-Dec-1996		O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 9912086-4	*CF		67410-2 3000	MTH 15-Dec-1996		O/C			
312001 PILOT	DIGITAL CLOCK	UNK		M877A-5V 21708	MTH 14-Jan-2013 HRS 7953.8 LDG 6440		O/C	0 0 0		
313001	FLIGHT HOUR RECORDER 85071	*CF		C664503-0104 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
313003 NO. 1	ACCELEROMETER AG-222	*CF		7000992 7486	MTH 15-Dec-1996		O/C			
313003 NO. 2	ACCELEROMETER AG-222	*CF		7000992 7490	MTH 15-Dec-1996		O/C			
313008	FDR IMPACT SWITCH	*CF		6895-D-2-X-5-5 990	MTH 15-Dec-1996		O/C			
315001	MASTER WARNING ANNUNCIATOR 9912119-17	KIKV		465-1-17 704	MTH 12-Apr-2013 HRS 7974.4 LDG 6457		O/C			
321001 <i>321001T : T-L</i>	MAIN LANDING GEAR ASSEMBLY LEFT	*CF		6641000-35 228	MTH 15-Dec-1996 LDG 0		11425	0	11425	3773
321002 <i>321002T : T-R</i>	MAIN LANDING GEAR ASSEMBLY RIGHT	*CF		6641000-36 228	MTH 15-Dec-1996 LDG 0		11425	0	11425	3773
321003 LEFT MAIN LANDING GEAR <i>321003T : T-L</i>	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		9510	0	9510	1858
321003 RIGHT MAIN LANDING GEAR <i>321003T : T-R</i>	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		9510	0	9510	1858
322001 <i>322001T : T</i>	NOSE LANDING GEAR ASSEMBLY	*CF		6642000-48 38	MTH 15-Dec-1996 LDG 0	4	23100	0	23104	15452
322002	NOSE SHIMMY DAMPER TEB			5543001-11 69911X	MTH 22-Nov-2005 HRS 5748 LDG 4807		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322004 <i>322004T : T</i>	NOSE GEAR FORK/PISTON MCO			6642000-3 NSN	MTH 22-Oct-2008 HRS 7549 LDG 6193		13061	906	18348	10696
323001 LEFT <i>323001T : T-L</i>	MAIN LANDING GEAR ACTUATOR 9912111-3	*CF		1523100-7 516	MTH 15-Dec-1996 LDG 0		15000	0	15000	7348
323002 RIGHT <i>323002T : T-R</i>	MAIN LANDING GEAR ACTUATOR 9912111-4	*CF		1523100-8 516	MTH 15-Dec-1996 LDG 0		15000	0	15000	7348
323003 <i>323003T : T</i>	NOSE LANDING GEAR ACTUATOR 9912120-4	TEB		1523200-9 1610	MTH 10-Mar-2005 HRS 5160 LDG 4337		15000	0	19337	11685
323004 LEFT	MLG UPLOCK ACTUATOR *CF			5527504-2 1775	MTH 15-Dec-1996		O/C			
323004 NOSE	UPLOCK ACTUATOR TEB			5527504-2 3474	MTH 22-Nov-2005 HRS 5748 LDG 4807		O/C	0		
323004 RIGHT	MLG UPLOCK ACTUATOR TEB			5527504-2 WM3316	MTH 22-Nov-2005 HRS 5748 LDG 4807		O/C	0		
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912103-3	SWF		212940-2 1388	MTH 31-Jul-2008 HRS 7541		288	142	30-Sep-2020	13 m 3 d
323007	LANDING GEAR CONTROL VALVE *CF			66710 743	MTH 15-Dec-1996		O/C			
323008	DUMP VALVE *CF			OAS5319-1 436	MTH 15-Dec-1996		O/C			
323019	EMERGENCY AIR BOTTLE GAUGE *CF			2341128 61094A	MTH 15-Dec-1996		O/C	0		
324001 LEFT	MLG WHEEL ASSEMBLY 9912222-11	KIKV		3-1490-1 3984	MTH 20-Oct-2016 HRS 8993.2 LDG 7346 ACH 338.8		O/C	0 0		
324001 RIGHT	MLG WHEEL ASSEMBLY 9912222-11	PWK		3-1490-1 3134	MTH 27-Mar-2018 HRS 9251.2 LDG 7510		O/C	3 0 0		
324002	NOSE WHEEL ASSEMBLY 9914069-2	KDAL		3-1418 7592	MTH 16-Jan-2019 HRS 9409.5 LDG 7593		O/C			
324003 LEFT	MLG BRAKE ASSEMBLY 9912222-17	KIKV		2-1529-7 1193	MTH 14-Mar-2014 HRS 8246.6 LDG 6685		O/C	0 0 0		
324004 RIGHT	MLG BRAKE ASSEMBLY 9912222-17	KIKV		2-1529-7 3307	MTH 14-Mar-2014 HRS 8246.6 LDG 6685		O/C	0 0 0		
324005 LEFT	MLG TIRE KDAL			220K28-1 62612559	MTH 29-Jun-2018 HRS 9325.3 LDG 7550		O/C	0 0		
324005 RIGHT	MLG TIRE PWK			220K28-1 52802756	MTH 27-Mar-2018 HRS 9251.2 LDG 7510		O/C	0 0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324006	NOSE TIRE	KDAL		184F13-5 80872866	MTH 16-Jan-2019 HRS 9409.5 LDG 7593		O/C	0 0 0		
324010 LEFT	MLG SHUTTLE VALVE	SWF		195-183 3850	MTH 07-Dec-2002 HRS 3573 LDG 3115		O/C	0		
324010 RIGHT	MLG SHUTTLE VALVE	SWF		195-183 SN-UNKNOWN	MTH 19-Jul-2000 HRS 2312 LDG 2045		O/C	0		
324011 LEFT	MLG INBOARD BRAKE MASTER CYLINDER	*CF		9912050-11 1111	MTH 15-Dec-1996		O/C			
324011 RIGHT	MLG INBOARD BRAKE MASTER CYLINDER	*CF		9912050-11 1113	MTH 15-Dec-1996		O/C			
324012 LEFT	MLG OUTBOARD MASTER BRAKE CYLINDER	*CF		9912050-12 1589	MTH 15-Dec-1996		O/C			
324012 RIGHT	MLG OUTBOARD MASTER BRAKE CYLINDER	*CF		9912050-12 1584	MTH 15-Dec-1996		O/C			
324019	BRAKE PRESS PUMP ASSEMBLY	*CF		634343 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
324021	POWER BRAKE ANTISKID VALVE	KTE		38-707-2 1165	MTH 12-Aug-2002 HRS 3392		O/C	0		
324022	BRAKE CONTROL BOX	KDAL		42-927-1 206	MTH 23-May-2018 HRS 9299.5 LDG 7534		O/C			
324023	ANTISKID ACCUMULATOR	*CF		57C57652 RH0897	MTH 15-Dec-1996		O/C			
324024 LEFT	MLG WHEEL TRANSDUCER	KDAL		40-955 738	MTH 29-Jun-2018 HRS 9325.3 LDG 7550		O/C			
324024 RIGHT	MLG WHEEL TRANSDUCER	KDAL		40-955 3666	MTH 29-Jun-2018 HRS 9325.3 LDG 7550		O/C			
324025	PRESSURE SWITCH	KIKV		9912163-1 3519	MTH 12-Dec-2014 HRS 8544.7 LDG 6948		O/C	0 0		
324026	POWER BRAKE ASSEMBLY MOTOR	*CF		MP50B1 642	MTH 15-Dec-1996		O/C			
324027	FAULT DISPLAY UNIT	*CF		42-92750 231A	MTH 15-Dec-1996		O/C			
324101	PARKING BRAKE VALVE	*CF		95905 354A	MTH 15-Dec-1996		O/C			
325001	NOSE STEERING BUNGEE ASSEMBLY	*CF		5565624-19 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
326003 LEFT	MAIN GEAR DOWN & LOCK SWITCH	*CF		1EN118-6 SN-UNKNOWN	MTH 15-Dec-1996		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
326003 RIGHT	MAIN GEAR DOWN & LOCK SWITCH SWF			1EN118-6 SN-UNKNOWN	MTH 23-Jul-1998 HRS 1177 LDG 985		O/C	0		
326003	NOSE GEAR DOWN & LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
326005	NOSE GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
331001 NO. 1	LIGHT PANEL DIMMER *CF			273-1 4103	MTH 15-Dec-1996		O/C			
331001 NO. 2	LIGHT PANEL DIMMER *CF			273-1 4108	MTH 15-Dec-1996		O/C			
331001 NO. 3	LIGHT PANEL DIMMER *CF			273-1 4109	MTH 15-Dec-1996		O/C			
331011	INVT-115V EL PANEL TEB			EM2044-1 3792A	MTH 18-Oct-2002 HRS 3476		O/C	0		
332001 NO. 10	CF001 INDIRECT LIGHT POWER UNIT *CF			AL-5112 24053	MTH 15-Dec-1996		O/C			
332001 NO. 1	CU31 INDIRECT LIGHT POWER UNIT *CF			AL-5112 24069	MTH 15-Dec-1996		O/C			
332001 NO. 2	CU30 INDIRECT LIGHT POWER UNIT SWF			AL-5112 24054	MTH 31-Jul-2008 HRS 7541		O/C	0		
332001 NO. 3	CU29 INDIRECT LIGHT POWER UNIT KIKV			AL-5112 46733	MTH 12-Dec-2014 HRS 8544.7 LDG 6948		O/C	0 0		
332001 NO. 4	CU28 INDIRECT LIGHT POWER UNIT KIKV			AL-5112 46655	MTH 12-Dec-2014 HRS 8544.7 LDG 6948		O/C	0 0		
332001 NO. 5	CU27 INDIRECT LIGHT POWER UNIT KIKV			AL-5112 46731	MTH 12-Dec-2014 HRS 8544.7 LDG 6948		O/C	0 0		
332001 NO. 6	CU26 INDIRECT LIGHT POWER UNIT KIKV			AL-5112 46656	MTH 12-Dec-2014 HRS 8544.7 LDG 6948		O/C	0 0		
332001 NO. 7	CU25 INDIRECT LIGHT POWER UNIT *CF			AL-5112 24052	MTH 15-Dec-1996		O/C			
332001 NO. 8	CU24 INDIRECT LIGHT POWER UNIT *CF			AL-5112 23426	MTH 15-Dec-1996		O/C			
332001 NO. 9	CF002 INDIRECT LIGHT POWER UNIT *CF			AL-5112 23404	MTH 15-Dec-1996		O/C			
332002 AFT	INDIRECT LIGHTING INVERTER SWF			AL0581 8727	MTH 07-Dec-2002 HRS 3573		O/C	0		
334002	ROTATING/FLASHING BEACON TEB			30-2140-5 0668	MTH 17-Nov-2006 HRS 6575		O/C	0		
334003 NO. 1	STROBE POWER SUPPLY ICT			01-0790101-04 296	MTH 15-Dec-1996 HRS 4		O/C	4		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
334003 NO. 2	STROBE POWER SUPPLY TEB			01-0790101-04 SN-UNKNOWN	MTH 07-Feb-2003 HRS 3657		O/C	0		
335001	EMERGENCY BATTERY PACK SWF			CBS28 11152008	MTH 31-Jul-2008 HRS 7541		O/C	0		
341006	PITOT PRESSURE SWITCH MCO			D45C31 784	MTH 22-Oct-2008 HRS 7549		O/C	0		
341010	ANGLE OF ATTACK INDICATOR *CF			C11605-1 546	MTH 15-Dec-1996		O/C			
341011	ANGLE OF ATTACK STALL WARNING COMPUTER ICT			C11606-8 581	MTH 23-Jul-1998 HRS 1177		O/C	454		
341013	ANGLE OF ATTACK TRANSMITTER *CF			1703-15 524	MTH 15-Dec-1996		O/C			
341014	ANGLE OF ATTACK INDEXER *CF			965-0113-008 1462	MTH 15-Dec-1996		O/C			
341015 PILOT	RADIO ALTIMETER ALT-55B INDICATOR ALI-55	SWF		622-2937-009 2829	MTH 31-Jul-2008 HRS 7541		O/C	0		
341019 STANDBY <i>341001 : STDBY</i>	ALTIMETER	SWF		WL102AMS6 AL618	MTH 14-Dec-2004 HRS 4989		O/C	1755		
341022 <i>341025</i>	OAT INDICATOR	*CF		C307FCL A2731	MTH 15-Dec-1996		O/C			
341035	ANGLE OF ATTACK HEAT MONITOR- *CF			1703-147-2 540	MTH 15-Dec-1996		O/C			
342001	MAGNETIC COMPASS *CF			C660501-0301 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
342023	RADAR CONTROLLER WC-650	*CF		7008471-607 96062464	MTH 15-Dec-1996		O/C			
342042 NO. 1	MODE FLIGHT DIRECTOR SELECTOR MS-560	SWF		7018341-909 94110357	MTH 19-Jul-2000 HRS 2312		O/C	2253		
342042 NO. 2	MODE FLIGHT DIRECTOR SELECTOR MS-560	SWF		7018341-909 96030564	MTH 19-Jul-2000 HRS 2312		O/C	0		
342043 NO. 1	VERTICAL FLIGHT DIRECTOR GYRO VG-14A	TEB		7000622-901 96057971	MTH 06-Feb-2006 HRS 5949		O/C	3652		
342043 NO. 2	VERTICAL FLIGHT DIRECTOR GYRO VG-14A	TEB		7000622-901 96057970	MTH 06-Feb-2006 HRS 5949		O/C	2273		
342044 NO. 1	RATE OF TURN GYRO RG-204	TEB		7007453-903 06065781	MTH 05-May-2007 HRS 6946		O/C	0		
342048 NO. 1	AIR DATA COMPUTER AZ-850	KIKV		7014700-601 95080556	MTH 30-Apr-2015 HRS 8667.1 LDG 7057		O/C			
342048 NO. 2	AIR DATA COMPUTER AZ-850	KMCO		7014700-601 97031094	MTH 10-Aug-2010 HRS 7726.9 LDG 6286		O/C			
342049 NO. 1	DIRECTIONAL GYRO C-14D	TEB		4020577-3 80011547	MTH 26-Aug-2003 HRS 4023		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342049 NO. 2	DIRECTIONAL GYRO C-14D	TEB		4020577-3 89014324	MTH 11-Apr-2004 HRS 4507		O/C	1434		
342050 NO. 1	FLUX DETECTOR FX-220	*CF		2594484 96061707	MTH 15-Dec-1996		O/C			
342050 NO. 2	FLUX DETECTOR FX-220	*CF		2594484 96061710	MTH 15-Dec-1996		O/C			
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 96062107	MTH 15-Dec-1996		O/C			
342053 STANDBY	HSI INDICATOR HSI-315A	*CF		520-3150-003 15278	MTH 15-Dec-1996		O/C			
342063 NO. 1	REMOTE COURSE CONTROL RI-553	*CF		7016954-903 96040438	MTH 15-Dec-1996		O/C			
342065	STANDBY GYRO AI-804	TEB		501-1197-05 5509	MTH 25-Sep-2000 HRS 2435		O/C	0		
342069	MULTIFUNCTION DISPLAY CONTROLLER MC-800	KDAL		7007062-941 95006109	MTH 27-Apr-2018 HRS 9281.9 LDG 7524		O/C			
342072	STATIC CONVERTER	*CF		501-1318-01 4406	MTH 15-Dec-1996		O/C			
342078 NO. 1	DISPLAY GUIDANCE COMPUTER IC-600	KIKV		7017000-80162 94020241	MTH 09-Apr-2013 HRS 7974.4 LDG 6457		O/C			
342078 NO. 2	DISPLAY GUIDANCE COMPUTER IC-600	KIKV		7017000-81162 96060781	MTH 09-Apr-2013 HRS 7974.4 LDG 6457		O/C			
342079 COPILOT	PRIMARY FLIGHT DISPLAY CONTROLLER DC-550	*CF		7016986-707 96070766	MTH 15-Dec-1996		O/C			
342079 PILOT	PRIMARY FLIGHT DISPLAY CONTROLLER DC-550	*CF		7016986-707 96070765	MTH 15-Dec-1996		O/C			
342080 CNTR	EFIS DISPLAY DU-870	SHV		7014300-901 0208B844	MTH 20-Dec-2017 HRS 9199.2 LDG 7485		O/C			
342080 NO. 1	EFIS DISPLAY DU-870	KFPR		7014300-901 0410E066	MTH 08-Nov-2010 HRS 7749.3 LDG 6299		O/C			
342080 NO. 2	EFIS DISPLAY DU-870	KIKV		7014300-901 98103859	MTH 13-Aug-2013 HRS 8032.7 LDG 6519		O/C			
342081 NO. 1	BEZEL DISPLAY UNIT BL-870	*CF		7014331-921 95090478	MTH 15-Dec-1996		O/C			
342081 NO. 2	BEZEL DISPLAY UNIT BL-870	*CF		7014331-921 96050622	MTH 15-Dec-1996		O/C			
342081	MFD BEZEL DISPLAY UNIT BL-871	TEB		7014332-941 94010260	MTH 25-May-2005 HRS 5361		O/C	2813		
342176	PS-835 EMERGENCY POWER SUPPLY	KIKV		501-1228 2318	MTH 22-Dec-2015 HRS 8750.2 LDG 7145		O/C			





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER WU-650	KPBI		7008470-822 95111602	MTH 05-Jan-2012 HRS 7886.7 LDG 6399		O/C			
344022	RADIO ALT TRANSCEIVER ALT-55B	*CF		622-2855-011 10510	MTH 15-Dec-1996		O/C			
344023	RECEIVER RADIO ALT ANTENNA AFT	*CF		622-0954-001 5988	MTH 15-Dec-1996		O/C			
344023	TRANSMITTER RADIO ALT ANTENNA FORWARD	*CF		622-0954-001 5964	MTH 15-Dec-1996		O/C			
344024	GROUND PROXIMITY WARNING SYS COMPUTER KGP-860	TEB		965-1199-005 2265	MTH 01-Feb-2005 HRS 5083		O/C	9		
344025	CONFIGURATION MODULE EGP860	SWF		700-1710-021 5654	MTH 14-Dec-2004 HRS 4989		O/C	0		
344025U	CONFIGURATION MODULE -- LNK			11921 6464	MTH 07-Nov-2006 HRS 6551		O/C	0		
345004	TRANSPONDER ANTENNA AFT	*CF		DMNI50-2-2 62597	MTH 15-Dec-1996		O/C			
345004	TRANSPONDER ANTENNA FORWARD	*CF		DMNI50-2-2 62601	MTH 15-Dec-1996		O/C			
345004	DIV TRANSPONDER ANTENNA TOP AFT	*CF		DMNI50-2-2 62725	MTH 15-Dec-1996		O/C			
345004	DIV TRANSPONDER ANTENNA TOP FORWARD	*CF		DMNI50-2-2 62723	MTH 15-Dec-1996		O/C			
345005	TEMPERATURE PROBE *CF			102DB1AG A11712	MTH 15-Dec-1996		O/C			
345007	DME ANTENNA AFT	*CF		DMNI50-2-2 62612	MTH 15-Dec-1996		O/C			
345007	DME ANTENNA FORWARD	*CF		DMNI50-2-2 62604	MTH 15-Dec-1996		O/C			
345014	ADF ANTENNA NO. 1	LNK		7510300-901 0511A030	MTH 07-Nov-2006 HRS 6551		O/C	0		
345014	ADF ANTENNA NO. 2	SWF		7510300-901 99103836	MTH 06-Aug-2008 HRS 7541		O/C	1346		
345017	MARKER BEACON ANTENNA TEB			31-10-01 2931	MTH 18-Jun-1999 HRS 1670		O/C	0		
345018	GLIDESLOPE ANTENNA *CF			RGS10-48 AA474	MTH 15-Dec-1996		O/C			
345027	NAV MODULE NO. 1	*CF		7510134-931 96021929	MTH 15-Dec-1996		O/C			
345027	NAV MODULE NO. 2	*CF		7510134-931 95111808	MTH 15-Dec-1996		O/C			
345028	ADF MODULE NO. 1	*CF		7510114-901 96021637	MTH 15-Dec-1996		O/C			
345028	ADF MODULE NO. 2	*CF		7510114-901 95111530	MTH 15-Dec-1996		O/C			
345029	NAV CLUSTER MODULE NO. 1	*CF		7510164-921 96021842	MTH 15-Dec-1996		O/C			
345029	NAV CLUSTER MODULE NO. 2	*CF		7510164-921 95101708	MTH 15-Dec-1996		O/C			
345030	CLEARANCE DELIVERY CONTROL CD-850	SWF		7513000-805 97091683	MTH 31-Jul-2008 HRS 7541		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345031	NAVIGATION(FMS) COMPUTER UNS-1L	KDAL		2116-40-1116 1015	MTH 16-Jan-2019 HRS 9409.5 LDG 7593		O/C			
345034 NO. 1	ATC TRANSPONDER XS-852	SMF		7517400-902 99042899	MTH 21-Aug-2011 HRS 7790.9 LDG 6322		O/C			
345034 NO. 2	ATC TRANSPONDER XS-852	ICT		7517400-902 96051978	MTH 16-Dec-1996 HRS 5		O/C	0		
345035 NO. 1	DME INDICATOR DI-851	*CF		7513006-911 1303	MTH 15-Dec-1996		O/C			
345035 NO. 2	DME INDICATOR DI-851	TEB		7513006-911 98031535	MTH 10-Jul-2005 HRS 5457		O/C	1735		
345036 NO. 1	DME RECEIVER TRANSMITTER DM-850	MCO		7510184-902 98082752	MTH 19-Aug-2010 HRS 7726.9 LDG 6286		O/C	0 0		
345036 NO. 2	DME RECEIVER TRANSMITTER DM-850	TEB		7510184-902 93081051	MTH 19-May-2000 HRS 2271		O/C	2435		
345038 NO. 1	INTERGRATED NAV UNIT RNZ-850	KIKV		7510100-731 88090181	MTH 02-May-2014 HRS 8328.3 LDG 6740		O/C			
345038 NO. 2	INTERGRATED NAV UNIT RNZ-850	TEB		7510100-931 03067087	MTH 15-Jul-2003 HRS 3936		O/C	0		
345064	FMS-CONFIGURATION MODULE *CF			17680-01 5401	MTH 15-Dec-1996		O/C			
345075 NO. 2 <i>345078 : 2</i>	GPS RECEIVER NAV UNIT GPS-165	LNK		011-00106-00 82650448	MTH 07-Nov-2006 HRS 6551		O/C	4239		
345076 NO. 1	FMS CONTROL DISPLAY UNS1LFPCDU	LNK		1117-1-106 4465	MTH 07-Nov-2006 HRS 6551		O/C	0		
345077	DATA TRANSFER UNIT LNK			1407-01-1 784	MTH 07-Nov-2006 HRS 6551		O/C	0		
345088 NO. 1	RADIO MANAGEMENT UNIT RM-850	KIKV		7012100-805 9807212172	MTH 06-Aug-2013 HRS 8029.6 LDG 6515		O/C			
345088 NO. 2	RADIO MANAGEMENT UNIT RM-850	MCO		7012100-805 95101512	MTH 19-Aug-2010 HRS 7726.9 LDG 6286		O/C	0 0		
345093 NO. 2	GPS ANTENNA KA-92	*CF		071-01553-0200 60000439	MTH 15-Dec-1996		O/C			
345093	GPS ANTENNA LNK			S67-1575-39 49217045	MTH 07-Nov-2006 HRS 6551		O/C	0		
346001	TCAS PROCESSOR TPU-67A	KIKV		066-01146-1111 M10848	MTH 20-Jun-2013 HRS 8005.9 LDG 6498		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
346002 BOTTOM	TCAS ANTENNA	TEB		S72-1735-1 6753	MTH 13-Jan-1998 HRS 803		O/C	0		
346002 TOP	TCAS ANTENNA ANT-67A	*CF		071-01548-0100 6670	MTH 15-Dec-1996		O/C			
346006	TCAS CONFIGURATION MODULE CM2000	KIKV		071-00097-0100 CM 2000-2784	MTH 15-Jul-2013 HRS 8014.8 LDG 6505		O/C	0 0 0		
348021	ARINC CONVERTER	SWF		1226-1-1 131	MTH 14-Dec-2004 HRS 4989		O/C	2677		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 942	MTH 15-Dec-1996		O/C	0		
351002	OXYGEN PRESSURE SWITCH 9912057-5	*CF		P24031 99120575	MTH 15-Dec-1996		O/C			
351004 COPILOT	OXYGEN MASK	SWF		174252-17 3242	MTH 19-Jul-2000 HRS 2312		O/C	0		
351004 PILOT	OXYGEN MASK	TEB		174252-17 01820	MTH 11-Jun-2004 HRS 4570		O/C	0		
351005	OXYGEN SUPPLY REGULATOR *CF			172170-01 1799	MTH 15-Dec-1996		O/C	0		
351006	OXYGEN CYLINDER ZC369-64 PB DOT3HT1850	SWF		176176-64 533316	MTH 31-Jul-2008 HRS 7541		288	153	31-Oct-2019	2 m 4 d
361003	PNEUMATIC REGULATOR 9912043-2	*CF		38E85-5C B2304	MTH 15-Dec-1996		O/C			
361008 NO. 1	VALVE CHECK	*CF		1553-00-18 1193	MTH 15-Dec-1996		O/C			
361008 NO. 2	VALVE CHECK	*CF		1553-00-18 1191	MTH 15-Dec-1996		O/C			
383002	MOTOR AND PUMP TOILET *CF			17200-382 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
521001	CABIN DOOR SEAL 9912075-4	SWF		S15501-1 SN-UNKNOWN	MTH 27-Dec-2002 HRS 3598		O/C	0		
521002	EMERGENCY EXIT SEAL SHV			R841335 SN-UNKNOWN	MTH 20-Dec-2017 HRS 9199.2 LDG 7485		O/C	0 0 0		
531001 LEFT <i>531001T : T-L</i>	NOSE LANDING GEAR TRUNNION SUPPORT	SWF		6613056-3 N/A	MTH 31-Jul-2008 HRS 7541 LDG 6187		11820	0	18007	10355
531001 RIGHT <i>531001T : T-R</i>	NOSE LANDING GEAR TRUNNION SUPPORT	SWF		6613056-6 N/A	MTH 31-Jul-2008 HRS 7541 LDG 6187		11820	0	18007	10355
531202 NOSE LANDING GEAR <i>531202T : T</i>	ACTUATOR FITTING	*CF		6511105-1 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		23100	0	23100	15448
541001 LEFT	INLET ASSEMBLY	*CF		6552500-1 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
541001 RIGHT	INLET ASSEMBLY	*CF		6552500-2 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
561001 NO. 1	LEFTHAND MAIN WINDSHIELD ASSY, (LH) 9912064-15	MCO		E149000-101 1961	MTH 22-Oct-2008 HRS 7549		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
561002 NO. 2	RIGHTHAND MAIN WINDSHIELD ASSY, (LH) 9912064-16	SWF		E149000-102 1680	MTH 31-Jul-2008 HRS 7541		O/C	0		
561003	FOUL WEATHER WINDOW	SHV		5511275-201 9748 EA	MTH 20-Dec-2017 HRS 9199.2 LDG 7485 ACH 464.3		O/C	0		
561005 LEFT INBOARD	PILOTS INNER WINDOW *CF			5511285-5 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
561005 LEFT OUTBOARD	PILOTS OUTER WINDOW *CF			5511285-3 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
561005 RIGHT INBOARD	CO-PILOTS INNER WINDOW *CF			5511285-6 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
561005 RIGHT OUTBOARD	CO-PILOTS OUTER WINDOW SWF			5511285-200 N/A	MTH 31-Jul-2008 HRS 7541		O/C	0		
562001 L1 <i>562002 : L1</i>	CABIN DOOR WINDOW *CF			5512207-1 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 L2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 L3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 L4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 L5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 L6	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 L7	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R1	EMERGENCY DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R6	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
562001 R 7	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
572001 LEFT AFT <i>572003T : L</i>	MLG TRUNNION FITTING ASSEMBLY *CF			5522710-15 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		22900	0	22900	15248
572001 LEFT FORWARD <i>572004T : T-L</i>	MLG TRUNNION FITTING ASSEMBLY *CF			6522057-5 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		22900	0	22900	15248
572001 RIGHT AFT <i>572003T : R</i>	MLG TRUNNION FITTING ASSEMBLY *CF			5522710-15 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		22900	0	22900	15248
572001 RIGHT FORWARD <i>572004T : T-R</i>	MLG TRUNNION FITTING ASSEMBLY *CF			6522057-6 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		22900	0	22900	15248



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
574003 LEFT <i>574003T : T-L</i>	MLG SIDE BRACE SUPPORT FITTING *CF			6522047-1 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		24700	0	24700	17048
574004 RIGHT <i>574004T : T-R</i>	MLG SIDE BRACE SUPPORT FITTING *CF			6522047-2 SN-UNKNOWN	MTH 15-Dec-1996 LDG 0		24700	0	24700	17048
712001 LEFT	ENGINE AFT ISOLATOR 9912455-2	TEB		LM420SA6-1 1621	MTH 06-Jul-2007 HRS 7068		3500	0	10568	1085.7
712001 RIGHT	ENGINE AFT ISOLATOR 9912455-2	TEB		LM420SA6-1 1624	MTH 06-Jul-2007 HRS 7068		3500	0	10568	1085.7
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912455-1	TEB		LM420SA5-1 2733	MTH 06-Jul-2007 HRS 7068		3500	0	10568	1085.7
712002 LEFT TOP	FORWARD ENGINE ISOLATOR 9912455-1	TEB		LM420SA5-1 2770	MTH 06-Jul-2007 HRS 7068		3500	0	10568	1085.7
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912455-1	TEB		LM420SA5-1 2769	MTH 06-Jul-2007 HRS 7068		3500	0	10568	1085.7
712002 RIGHT TOP	FORWARD ENGINE ISOLATOR 9912455-1	TEB		LM420SA5-1 2724	MTH 06-Jul-2007 HRS 7068		3500	0	10568	1085.7
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 3042000	TEB		JT15D-5D JC0274	MTH 06-Jul-2007 HRS 7068.6		E/C	0		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 3042000	TEB		JT15D-5D JC0278	MTH 06-Jul-2007 HRS 7068.6		E/C	0		
721010 E1	ACESSORY DRIVE GEARBOX TEB			3031170 NSN	MTH 06-Jul-2007 HRS 7068		O/C	0		
721010 E2	ACESSORY DRIVE GEARBOX TEB			3031170 NSN	MTH 06-Jul-2007 HRS 7068		O/C	0		
722001 E1	OIL PUMP TEB			3104289-01 OP0979	MTH 06-Jul-2007 HRS 7068		O/C	0		
722001 E2	OIL PUMP TEB			3104289-01 23A861	MTH 06-Jul-2007 HRS 7068		O/C	0		
722608 E1	FAN LOW COMPRESSOR ROTOR TEB			3041231 21B781	MTH 06-Jul-2007 HRS 7068 LDG 5832		30000	5474	30358	22706
722608 E2	FAN LOW COMPRESSOR ROTOR TEB			3041231 32B784	MTH 06-Jul-2007 HRS 7068 LDG 5832		30000	5602	30230	22578
722609 E1	LOW BOOST COMPRESSOR ROTOR TEB			3070232-01 90A251	MTH 06-Jul-2007 HRS 7068 LDG 5832		30000	4222	31610	23958
722609 E2	LOW BOOST COMPRESSOR ROTOR TEB			3070232-01 45B971	MTH 06-Jul-2007 HRS 7068 LDG 5832		30000	2371	33461	25809
723001 E1	LC ROTOR FAN BALANCING ASSEMBLY TEB			3102814-01 NSN	MTH 06-Jul-2007 HRS 7068		O/C	0		
723001 E2	LC ROTOR FAN BALANCING ASSEMBLY TEB			3118976-01 NSN	MTH 06-Jul-2007 HRS 7068		O/C	0		
723705 E1	2ND-STAGE LOW TURBINE ROTOR DISK TEB			3022212 25B218	MTH 06-Jul-2007 HRS 7068 LDG 5832		14000	5474	14358	6706
723705 E2	2ND-STAGE LOW TURBINE ROTOR DISK TEB			3022212 25B221	MTH 06-Jul-2007 HRS 7068 LDG 5832		14000	5602	14230	6578

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
724001 E1	COMBUSTOR LINER 3119770-01	UNK		3119770-01 8L564	MTH 02-Jun-2016 HRS 8858.5		O/C			
724001 E2	COMBUSTOR LINER 3119770-01	UNK		3119770-01 8L567	MTH 02-Jun-2016 HRS 8858.5		O/C			
724006 E1	3RD-STAGE LOW TURBINE ROTOR DISK TEB			3041593 25B236	MTH 06-Jul-2007 HRS 7068 LDG 5832	243	14000	5474	14601	6949
724006 E2	3RD-STAGE LOW TURBINE ROTOR DISK TEB			3041593 25B235	MTH 06-Jul-2007 HRS 7068 LDG 5832	243	14000	5602	14473	6821
724706 E1	HIGH TURBINE ROTOR DISK UNK			3036411 25B225	MTH 02-Jun-2016 HRS 8858.5 LDG 7233		14000	8426.2 6875	14358	6706
724706 E2	HIGH TURBINE ROTOR DISK UNK			3036411 N25B224	MTH 02-Jun-2016 HRS 8858.5 LDG 7361		14000	8580.4 7003	14358	6706
724707 E1	HIGH TURBINE BLADES 3117501-01	TEB		3117501-01 NSN	MTH 06-Jul-2007 HRS 7068		O/C	0		
724707 E2	HIGH TURBINE BLADES 3117501-01	TEB		3117501-01 NSN	MTH 06-Jul-2007 HRS 7068		O/C	0		
724825 E1	CENTRIFUGAL IMPELLER 3040939	TEB		3040939 5F992	MTH 06-Jul-2007 HRS 7068 LDG 5832		12000	5474	12358	4706
724825 E2	CENTRIFUGAL IMPELLER 3040939	TEB		3040939 5F943	MTH 06-Jul-2007 HRS 7068 LDG 5832		12000	5602	12230	4578
731004 NO. 1	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
731004 NO. 2	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
733002	FUEL FLOW/QUANTITY INDICATOR 9912430-3	TEB		10537N01M01 B266	MTH 05-May-2007 HRS 6946		O/C	0		
733003 NO. 1	FUEL FLOW TRANSMITTER 9914413-1	*CF		9-231-28 6455	MTH 15-Dec-1996		O/C			
733003 NO. 2	FUEL FLOW TRANSMITTER 9914413-1	*CF		9-231-28 6330	MTH 15-Dec-1996		O/C			
731001 E1	FUEL PUMP 3037078	TEB		717101-1 0833	MTH 06-Jul-2007 HRS 7068		O/C	0		
731001 E2	FUEL PUMP 3037078	TEB		717101-1 0825	MTH 06-Jul-2007 HRS 7068		O/C	0		
731002 E1	FLOW DIVIDER VALVE 3119573-01	TEB		26395-2 0910	MTH 06-Jul-2007 HRS 7068		O/C	0		
731002 E2	FLOW DIVIDER VALVE 3119573-01	TEB		26395-2 0186	MTH 06-Jul-2007 HRS 7068		O/C	0		
731005 E1	BLEED CONTROL VALVE 3119724-01	TEB		815625-1-002 C96031939	MTH 06-Jul-2007 HRS 7068		O/C	0		
731005 E2	BLEED CONTROL VALVE 3119724-01	TEB		815625-1-002 C96051946	MTH 06-Jul-2007 HRS 7068		O/C	0		



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731006 E1	EFCU WIRING HARNESS	TEB		3119566-01 AA6447	MTH 06-Jul-2007 HRS 7068		O/C	0		
731006 E2	EFCU WIRING HARNESS	TEB		3119566-01 AA6452	MTH 06-Jul-2007 HRS 7068		O/C	0		
731020 E1	FUEL-OIL COOLER 3117056-01	TEB		D2397-10A 47895	MTH 06-Jul-2007 HRS 7068		O/C	3373		
731020 E2	FUEL-OIL COOLER 3117056-01	TEB		D2397-10A 47696	MTH 06-Jul-2007 HRS 7068		O/C	0		
731030 E1	MOTIVE FLOW VALVE			PN SN-UNKNOWN			O/C			
731030 E2	MOTIVE FLOW VALVE			PN SN-UNKNOWN	MTH 07-Dec-2002		O/C	0		
731065 E1	BLEED VALVE ACTUATOR			9912402-12 0576C			O/C			
731065 E2	BLEED VALVE ACTUATOR			9912402-12 0585C	MTH 07-Dec-2002		O/C	0		
731085 E1	SCHEDULE MODULATOR			PN SN-UNKNOWN			O/C			
731085 E2	SCHEDULE MODULATOR			PN SN-UNKNOWN	MTH 07-Dec-2002		O/C	0		
732001 E1	FUEL CONTROL UNIT 3118402-08	TEB		3244880-8 C4307	MTH 06-Jul-2007 HRS 7068		O/C	0		
732001 E2	FUEL CONTROL UNIT	TEB		3244880-9 C4287	MTH 06-Jul-2007 HRS 7068		O/C	0		
732005 E1	N1 SPEED SENSOR *CF			3118403-01 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
732005 E2	N1 SPEED SENSOR *CF			3118403-01 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
732006 E1 BOTTOM	N2 SPEED SENSOR *CF			3032997 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
732006 E1 TOP	N2 SPEED SENSOR *CF			3032997 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
732006 E2 BOTTOM	N2 SPEED SENSOR *CF			3032997 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
732006 E2 TOP	N2 SPEED SENSOR *CF			3032997 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
732030 E1	ELECTRONIC BLEED VALVE CONTROL			815625-1-002 C96031939			O/C			
732030 E2	ELECTRONIC BLEED VALVE CONTROL			815625-2-002 C96051945	MTH 07-Dec-2002		O/C	0		
732065 E1	MAIN WIRING HARNESS			PN SN-UNKNOWN			O/C			
732065 E2	MAIN WIRING HARNESS			PN SN-UNKNOWN	MTH 07-Dec-2002		O/C	0		
741001 E1 INBOARD	IGNITION EXCITER 3041641-01	TEB		9049770-3 NN02317242	MTH 06-Jul-2007 HRS 7068		O/C	0		
741001 E1 OUTBOARD	IGNITION EXCITER 3041641-01	TEB		9049770-3 98055507	MTH 06-Jul-2007 HRS 7068		O/C	0		





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
741001 E2 INBOARD	IGNITION EXCITER 3041641-01	KDAL		9049770-3 NN01508262	MTH 11-Apr-2018 HRS 9268.2 LDG 7519		O/C			
741001 E2 OUTBOARD	IGNITION EXCITER 3041641-01	TEB		9049770-3 NN97290915	MTH 06-Jul-2007 HRS 7068		O/C	0		
742001 E1 INBOARD	IGNITER PLUG 3119400-01	KGGG		CH34659-3 NONE	MTH 25-Jul-2017 HRS 9113.9 LDG 7435		O/C	0		
742001 E1 OUTBOARD	IGNITER PLUG 3119400-01	KGGG		CH34659-3 NONE	MTH 25-Jul-2017 HRS 9113.9 LDG 7435		O/C	0		
742001 E2 INBOARD	IGNITER PLUG 3119400-01	KGGG		CH34659-3 NONE	MTH 25-Jul-2017 HRS 9113.9 LDG 7435		O/C	0		
742001 E2 OUTBOARD	IGNITER PLUG 3119400-01	KGGG		CH34659-3 NONE	MTH 25-Jul-2017 HRS 9113.9 LDG 7435		O/C	0		
742002 E1 INBOARD	IGNITER PLUG CABLE 3118347-01	TEB		53300-1 NSN	MTH 06-Jul-2007 HRS 7068		O/C	3373		
742002 E2 INBOARD	IGNITER PLUG CABLE 3118347-01	TEB		53300-1 NSN	MTH 06-Jul-2007 HRS 7068		O/C	3373		
742003 E1 OUTBOARD	IGNITER PLUG CABLE 3118347-02	TEB		53300-2 NSN	MTH 06-Jul-2007 HRS 7068		O/C	3373		
742003 E2 OUTBOARD	IGNITER PLUG CABLE 3118347-02	TEB		53300-2 NSN	MTH 06-Jul-2007 HRS 7068		O/C	3373		
761002	SYNCHRONIZER CONTROL BOX TEB			213693 00056	MTH 21-Aug-2006 HRS 6443		O/C	0		
761003	ENGINE SYNC ACTUATOR *CF			5485-066 11427949	MTH 15-Dec-1996		O/C			
771004	N1 FAN TACHOMETER INDICATOR 9912430-5	KIKV		10535N03M00 B271A	MTH 20-Jun-2014 HRS 8386.8 LDG 6802		O/C	0		0
771005	N2 TURBINE TACHOMETER INDICATOR 9912430-6	SHV		10536N02M00 08E345A	MTH 20-Dec-2017 HRS 9199.2 LDG 7485		O/C			
783001 LEFT ENGINE	THRUST REVERSER ASSEMBLY 9912377-1	TEB		262-0001-501 3353	MTH 22-Nov-2005 HRS 5748 LDG 4807		O/C			985
783001 RIGHT ENGINE	THRUST REVERSER ASSEMBLY 9912377-2	TEB		262-0001-503 3354	MTH 22-Nov-2005 HRS 5748 LDG 4807		O/C			4807
783002 LEFT ENGINE	THRUST REVERSER CONTROL VALVE *CF			65680 2226	MTH 15-Dec-1996		O/C			
783002 RIGHT ENGINE	THRUST REVERSER CONTROL VALVE *CF			65680 2242	MTH 15-Dec-1996		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783003 LEFT ENGINE	THRUST REVERSER ISOLATION VALVE *CF			13027-4 2918	MTH 15-Dec-1996		O/C			
783003 RIGHT ENGINE	THRUST REVERSER ISOLATION VALVE *CF			13027-4 3003	MTH 15-Dec-1996		O/C			
783005 LEFT	THRUST REVERSER UPPER DOOR ASSEMBLY *CF			202-0001-503 3353	MTH 15-Dec-1996		O/C			
783005 RIGHT	THRUST REVERSER UPPER DOOR ASSEMBLY *CF			202-0001-504 3354	MTH 15-Dec-1996		O/C			
783006 LEFT	THRUST REVERSER LOWER DOOR ASSEMBLY *CF			202-0002-505 3353	MTH 15-Dec-1996		O/C			
783006 RIGHT	THRUST REVERSER LOWER DOOR ASSEMBLY *CF			202-0002-506 3354	MTH 15-Dec-1996		O/C			
783007 LEFT	THRUST REVERSER UPPER MECHANISM *CF			225-0007-513 3353	MTH 15-Dec-1996		O/C			
783007 RIGHT	THRUST REVERSER UPPER MECHANISM *CF			225-0007-513 3354	MTH 15-Dec-1996		O/C			
783008 LEFT	THRUST REVERSER LOWER MECHANISM *CF			225-0007-515 3353	MTH 15-Dec-1996		O/C			
783008 RIGHT	THRUST REVERSER LOWER MECHANISM *CF			225-0007-515 3354	MTH 15-Dec-1996		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT *CF			225-0014-507 3353	MTH 15-Dec-1996		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT *CF			225-0014-508 3354	MTH 15-Dec-1996		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR *CF			62270 4354	MTH 15-Dec-1996		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR *CF			62270 4359	MTH 15-Dec-1996		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR *CF			62270 4356	MTH 15-Dec-1996		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR *CF			62270 4351	MTH 15-Dec-1996		O/C			
783012 LEFT ENGINE	EXHAUST NOZZLE 9912377-13	*CF		9912377-13V7 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
783012 RIGHT ENGINE	EXHAUST NOZZLE 9912377-13	*CF		9912377-13V7 SN-UNKNOWN	MTH 15-Dec-1996		O/C			
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			102-00083 2098	MTH 15-Dec-1996		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			102-00083 2096	MTH 15-Dec-1996		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1	TEB		123479 62685309	MTH 23-Mar-2007 HRS 6895		O/C	0		
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1	TEB		123479 49901	MTH 20-Jan-2005 HRS 5057		O/C	0		
793006 LEFT ENGINE	LOW OIL PRESSURE SWITCH 9912178-3	KIKV		1103P89-2 1608	MTH 30-Aug-2016 HRS 8977.4 LDG 7325 ACH 338.8		O/C	0		



## CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #    City    Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
793006	LOW OIL PRESSURE SWITCH	1103P89-2	MTH	15-Dec-1996		O/C		
RIGHT ENGINE	9912178-3                    *CF	SN-UNKNOWN						



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-03-02 R01	SUPPLEMENTAL TYPE CERTIFICATE (STC) (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	<b>MOC :</b>									
SB 560-03-06 R01	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-03-06	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION (SUPERSEDED BY 560-03-06 R01)			OPTIONAL			-			
	<b>MOC :</b>									
SL CIL-03-01	SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED MTH			-			
	<b>MOC :</b>									
SL CIL-99-03 R01	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	<b>MOC :</b>									
SL CIL-99-03	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)			RECOMMENDED MTH			-			
	<b>MOC :</b>									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560-99-02 R06	CESCOM PRICES (THIS SL CANCELS SL560-99-02 R5 AND PREVIOUS)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 560-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 560-99-07	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	<b>MOC :</b>									
SB 560-11-08 11SB-08	AVIONICS J-BOX & LEFT LOGIC MODULE BOX PLACARD INSTALLATION	TEB		MANDATORY	MTH 11-Jun-2004 HRS 4570		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SB 560-12-01	ADDITIONAL APPROVED FUEL ANTI-ICE ADDITIVES (SUPERSEDED BY 560-12-01 R01)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL						
	<b>MOC :</b>									
SL CIL-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL						
	<b>MOC :</b>									
SL 560-20-01 R25	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560-20-01 R26)			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 560-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL						
	<b>MOC :</b>									
SB 560-21-12 R01 <i>21SB-12 : 560R1</i>	RAM AIR DUCT IMPROVEMENT (SUPERSEDED BY 560-21-12 R02)			OPTIONAL	MTH					
	<b>MOC :</b>									
SB 560-21-12 R02	RAM AIR DUCT IMPROVEMENT			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 560-21-14 <i>21SB-14</i>	FLOOD COOLING DIODE REPLACEMENT	SWF		RECOMMENDED	MTH 27-Jul-2001 HRS 2854					Complete
	<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SB 560-21-15 <i>21SB-15</i>	COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION			OPTIONAL	MTH					
	<b>MOC :</b>									
SB 560-21-16 R01 <i>21SB-16 : 560R1</i>	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT			DISCRETIONARY	MTH					
	<b>MOC :</b>									
SB 560-21-30 <i>21SB-30</i>	CABIN ALTITUDE BAROMETRIC SWITCH IMPROVEMENT			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-21-35	TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL						
	<b>MOC :</b>									
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION	KIKV		MANDATORY	MTH 12-Dec-2014 HRS 8544.7 LDG 6948					Complete
	<b>MOC :</b> COMPLIED WITH - ENVIRONMENTAL HOUR METER PREVIOUSLY INSTALLED.									
SL CIL-21-02	ENVIRONMENTAL HOUR METER INSTALLATION (SUPERSEDED BY CIL-21-02 R01)			OPTIONAL						
	<b>MOC :</b>									
SL 560-21-08 R01 <i>21SL-08 : 560R1</i>	CABIN TEMPERATURE SENSOR ORIENTATION INSPECTION (SUPERSEDED BY SL560-21-08 R02)	ICT		RECOMMENDED	MTH 20-Feb-1998 HRS 860		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 560-21-09 <i>21SL-09</i>	EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES	SWF		RECOMMENDED	MTH 27-Jul-2001 HRS 2854					Complete
	<b>MOC :</b> COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-21-10 <i>21SL-10</i>	OUTFLOW VALVE STATIC PRESSURE LINE INSPECTION/REPLACEMENT	SWF	RECOMMENDED	MTH 27-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-21-11 <i>21SL-11</i>	RAM AIR INLET DRAIN LINE INSPECTION (SUPERSEDED BY SL560-21-11 R01)	TEB	RECOMMENDED	MTH 21-Sep-2002 HRS 3417		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-21-16 <i>21SL-16</i>	AIR CONDITIONING - AIR CONDITIONING EXHAUST DOOR SHAFT SPACER INSPECTION		DISCRETIONARY	MTH		A/R			
<b>MOC :</b>									
SB 560-23-25 R01 <i>23SB-25 : 560R1</i>	HONEYWELL 8.33 KHZ COMMUNICATION RADIO INSTALLATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-23-26 R01 <i>23SB-26 : 560R1</i>	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION	TEB	OPTIONAL	MTH 05-May-2007 HRS 6946		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-23-27 R04 <i>23SB-27 : 560R4</i>	COCKPIT SPEAKER MUTE SWITCH INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-23-31 <i>23SB-31</i>	AERO-M ANTENNA NON-MAGNETIC SCREW REPLACEMENT	TEB	RECOMMENDED	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SB 560-23-32 R01 <i>23SB-32 : 560R1</i>	RNZ-850 NAVIGATION RADIO UPGRADE	TEB	MANDATORY	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-23-38 R02	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION		OPTIONAL			-			
<b>MOC :</b>									
SB 560-23-38	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION (SUPERSEDED BY 560-23-38 R01)		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SL 560-23-01 <i>23SL-01</i>	FAIRCHILD COCKPIT VOICE RECORDER FIELD SERVICE BULLETINS GACVR-005 AND GACVR-006		INFORMATIONAL	MTH		-			
<b>MOC : - NOT APPLICABLE.</b>									
SL 560-23-15 <i>23SL-15</i>	TRANSMITTAL OF AIRSHOW SERVICE BULLETIN 920720-1 AIRSHOW 400 DIGITAL INTERFACE UNIT	SWF	RECOMMENDED	MTH 22-Jan-2000 HRS 2031		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
SL 560-23-16 R01 <i>23SL-16 : 560R1</i>	AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE	TEB	RECOMMENDED	MTH 11-Jun-2004 HRS 4570		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-24-21 <i>24SB-21</i>	GCU START MODIFICATION (SUPERSEDED BY 560-24-21 R01)	SWF	RECOMMENDED	MTH 22-Jan-2000 HRS 2031		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-24-22 <i>24SB-22</i>	CIRCUIT BREAKER TERMINAL SCREW LENGTH INSPECTION/REPLACEMENT (SUPERSEDED BY 560-24-22 R01)	SWF	RECOMMENDED	MTH 27-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-24-27 <i>24SB-27</i>	WING WIRE ROUTING IMPROVEMENT/FLAP HYDRAULIC LINE INSPECTION (SUPERSEDED BY 560-24-27 R01)	SWF	RECOMMENDED	MTH 27-Jul-2001 HRS 2854		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-24-29 <i>24SB-29</i>	NO SMOKING LIGHT WIRING MODIFICATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-24-30 <i>24SB-30</i>	CIRCUIT BREAKER INSULATORS INSTALLATION	SWF	RECOMMENDED	MTH 27-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-24-33 <i>24SB-33</i>	CIRCUIT BREAKER PANEL MODIFICATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-24-37 R03 <i>24SB-37 : 560R3</i>	MAIN POWER WIRE ANCHOR IMPROVEMENT	TEB	RECOMMENDED	MTH 10-Jul-2005 HRS 5457		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-24-39 <i>24SB-39</i>	SEALED LEAD ACID BATTERY INSTALLATION	MCO	OPTIONAL	MTH 22-Oct-2008 HRS 7549		-			Complete
<b>MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.</b>									
SB 560-24-42 <i>24SB-42</i>	RELAY SHIELD INSTALLATION	TEB	MANDATORY	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-25-08 <i>25SB-08</i>	AFT JUMP SEAT INSTALLATION	*CF	OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-25-23 <i>25SB-23</i>	FLIGHT CREW SEAT PAN REINFORCEMENT		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-25-25 <i>25SB-25</i>	ESCAPE HATCH SIDEWALL PANEL INSTALL	SWF	RECOMMENDED	MTH 22-Jan-2000 HRS 2031		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-25-29 R01 <i>25SB-29 : 560R1</i>	GLARESHIELD LEATHER STRIP INSTALLATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-25-31 R02 <i>25SB-31</i>	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)		OPTIONAL			A/R			
<b>MOC :</b>									
SB 560-25-31 <i>25SB-31</i>	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560-25-31 R01)		SUPERSEDED			A/R			
<b>MOC :</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl	Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-25-32 R01 25SB-32 : 560R1	EQUIPMENT/FURNISHINGS - TOILET TRAY AND PAD INSTALLATION		OPTIONAL	MTH			A/R			
<b>MOC :</b>										
SL 560-25-06 25SL-06	EQUIPMENT/FURNISHINGS - CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY	TEB	OPTIONAL	MTH	05-May-2007 HRS 6946		A/R			N/A
<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560-25-09 25SL-09	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE		MANDATORY	MTH	12-Feb-2008 HRS 7471		A/R			N/A
<b>MOC :</b> NOT APPLICABLE										
SB 560-26-01 26SB-01	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	TEB	MANDATORY	DAYS	10-Jul-2005 HRS 5457		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
ASL 560-26-01 26ASL-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS	TEB	MANDATORY	MTH	06-Sep-2007 HRS 7232		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	KRBD	MANDATORY	MTH	28-May-2019 HRS 9464.6 LDG 7636		-			N/A
<b>MOC :</b> NOT APPLICABLE - SL CIL-26-01 R01 DOES NOT APPLY DUE TO PN 873364-1 SQUIBS INSTALLED.										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)		MANDATORY	MTH			-			
<b>MOC :</b>										
SB 560-27-10 27SB-10	ELEVATOR TRIM SECTOR ADJUSTABLE FRICTION BLOCK INSTALLATION	ICT	RECOMMENDED	MTH	23-Nov-1997 HRS 687		-			Complete
<b>MOC :</b> COMPLIED WITH										
SB 560-27-13 27SB-13	TRIM TAB ACTUATOR GREASE FITTING INSTALLATION	SWF	OPTIONAL	MTH	30-Jul-2001 HRS 2854		-			Complete
<b>MOC :</b> COMPLIED WITH										
SB 560-27-17 27SB-17	PITCH TRIM PRINTED CIRCUIT BOARD (PCB) IMPROVEMENT	TEB	MANDATORY	MTH	10-Jul-2005 HRS 5457		A/R			N/A
<b>MOC :</b> NOT APPLICABLE										
SB 560-27-22 27SB-22	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT IMPROVEMENT		DISCRETIONARY	MTH			A/R			
<b>MOC :</b>										
SB 560-27-23	FLIGHT CONTROLS - ELEVATOR BELLCRANK SUPPORT BRACKET INSPECTION AND REPAIR		MANDATORY	MTH			A/R			N/A
<b>MOC :</b> NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS -0539 THRU -0815.										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASL 560-27-10 27ASL10	ELECTRIC ELEVATOR TRIM RUNAWAY PROCEDURE	TEB	MANDATORY	MTH 14-Nov-2003 HRS 4180		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SL 560-27-06 27SL-06	RUDDER/AILERON INTERCONNECT BOLT INSPECTION (SUPERSEDED BY SL560-27-06 R01)	SWF	SUPERSEDED	MTH 03-Oct-1997 HRS 585		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-27-08 27SL-08	LOWER CABLE GUARD INSPECTION	TEB	RECOMMENDED	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-27-13 27SL-13	RUDDER PEDAL SUPPORT INSPECTION	TEB	RECOMMENDED	MTH 15-Dec-2006 HRS 6625		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-28-07 28SB-07	FUEL LINE SUPPORT INSTALLATION	SWF	RECOMMENDED	MTH 17-Oct-2000 HRS 2466		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-28-10 28SB-10	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	TEB	MANDATORY	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-28-12 28SB-12	FUEL - SINGLE POINT REFUELING LINE CLAMP INSTALLATION (SUPERSEDED BY 560-28-12 R01)	SWF	SUPERSEDED	MTH 31-Jul-2008 HRS 7541		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-28-14 R01 28SB-14	FUEL - FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY 560-28-14 R01)		RECOMMENDED	MTH	14	A/R			
<b>MOC :</b>									
ASL 560-28-07 28ASL07	SINGLE POINT REFUELING (SPR) TUBE INSPECTION (SUPERSEDED BY ASL560-28-07 R01)	TEB	SUPERSEDED	MTH 22-Nov-2005 HRS 5748		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-29-04 R01 29SB-04 : 560R1	HYDRAULIC TUBE REPLACEMENT	TEB	MANDATORY	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-29-05 29SB-05	LANDING GEAR RETURN LINE CHECK VALVE REPLACEMENT (SUPERSEDED BY 560-29-05 R01)	TEB	SUPERSEDED	MTH 21-Sep-2002 HRS 3417		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-29-08 R01 29SB-08	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT (SUPERSEDED BY 560-29-08 R01)		RECOMMENDED	MTH		A/R			
<b>MOC :</b>									
SB 560-29-08	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT (SUPERSEDED BY 560-29-08 R01)		RECOMMENDED			A/R			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-29-04 <i>29SL-04</i>	HYDRAULIC LINE INSTALLATION INSPECTION (SUPERSEDED BY SL560-29-04 R01)	SWF		SUPERSEDED	MTH 22-Jan-2000 HRS 2031		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-30-10 <i>30SB-10</i>	WINDSHIELD ANTI-ICE BLEED AIR SWITCH INSPECTION/REPLACEMENT	TEB		MANDATORY	MTH 21-Sep-2002 HRS 3417		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL CIL-30-01 R01	APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
<b>MOC :</b>										
SB 560-31-09 <i>31SB-09</i>	INADVERTENT POWER BRAKE LOW PRESSURE ANNUNCIATION	SWF		RECOMMENDED	MTH 27-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-31-15 <i>31SB-15</i>	INDICATING/RECORDING SYSTEMS - INSTRUMENT PANEL MODIFICATION FOR AOA TEST SWITCH			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
<b>MOC :</b>										
SB 560-32-03 R05 <i>32SB-03 : 560R5</i>	GRAVEL RUNWAY PROTECTION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-32-18 <i>32SB-18</i>	ANTI-SKID SYSTEM DIODE REMOVAL	SWF		RECOMMENDED	MTH 23-Jul-1998 HRS 1177		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-19 <i>32SB-19</i>	BRAKE MOTOR COUPLING REPLACEMENT	SWF		RECOMMENDED	MTH 23-Jul-1998 HRS 1177		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-20 <i>32SB-20</i>	BRAKE LINE REPLACEMENT (SUPERSEDED BY 560-32-20 R01)	TEB		SUPERSEDED	MTH 21-Sep-2002 HRS 3417		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-22 R02 <i>32SB-22 : 560R2</i>	LANDING GEAR ON GROUND OPERATION AND MODIFICATION (SUPERSEDED BY 560-32-22 R03)	SWF		SUPERSEDED	MTH 27-Jul-2001 HRS 2854		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-23 R01 <i>32SB-23 : 560R1</i>	BRAKE MASTER CYLINDER REPLACEMENT	TEB		OPTIONAL	MTH 07-Aug-2003 HRS 3984		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-27 R01 <i>32SB-27 : 560R1</i>	NLG ACTUATOR REPLACEMENT (SUPERSEDED BY 560-32-27 R02)	TEB		SUPERSEDED	MTH 06-Oct-2004 HRS 4870		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-32-27 R02 <i>32SB-27 : 560R2</i>	NLG ACTUATOR REPLACEMENT	TEB		MANDATORY	MTH 10-Mar-2005 HRS 5160		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-31 R01 <i>32SB-31 : 560R1</i>	PARKING BRAKE CABLE REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-32-33 <i>32SB-33</i>	LANDING GEAR - BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	TEB		RECOMMENDED	MTH 06-Sep-2007 HRS 7232		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-32-35 <i>32SB-35</i>	LANDING GEAR - MASTER CYLINDER IN-LINE FILTER INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-32-36 <i>32SB-36</i>	LANDING GEAR - BRAKE MASTER CYLINDER FITTING IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-32-42 R01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS			RECOMMENDED			-			
<b>MOC : DEFERRED - OWNER ELECTS NOT TO COMPLY WITH SERVICE BULLETIN AT THIS TIME.</b>										
SB 560-32-42	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS (SUPERSEDED BY 560-32-42 R01)			RECOMMENDED			-			
<b>MOC :</b>										
SL CIL-32-01	IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
<b>MOC :</b>										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	KIKV		RECOMMENDED	MTH 06-Jun-2016 HRS 8858.5 LDG 7230 ACH 338.8		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
<b>MOC :</b>										
SL 560-32-34 <i>32SL-34</i>	NOSE GEAR STEERING BUNGEE INSPECTION	SWF		RECOMMENDED	MTH 22-Jan-1999 HRS 1453		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-32-37 <i>32SL-37</i>	LANDING GEAR - NOSE LANDING GEAR ACTUATOR UNLOCK PRESSURE TEST	TEB		SUPERSEDED	MTH 07-Aug-2003 HRS 3984		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560-32-40 R01 <i>32SL-40 : 560R1</i>	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
<b>MOC :</b>										
SL 560-32-41 <i>32SL-41</i>	GOODRICH NOSE WHEEL INSPECTION/REPLACEMENT	TEB		MANDATORY	MTH 15-Dec-2006 HRS 6625		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-32-50 32SL-50	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	KPBI		MANDATORY	MTH 05-Jan-2012 HRS 7886.7 LDG 6399		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-33-04 R01 33SB-04 : 560R1	LANDING LIGHT BULB PROTECTION	*CF		OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-09 R03 33SB-09 : 560R3	WING TIP LANDING LIGHT INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-16 R01 33SB-16 : 560R1	EMERGENCY LIGHTING BATTERY PACK UPGRADE (SUPERSEDED BY 560-33-16 R02)	SWF		OPTIONAL	MTH 31-Jul-2008 HRS 7541		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-33-16 R04	EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-33-17 R01 33SB-17 : 560R1	MAIN LANDING GEAR LIGHT ASSEMBLY MODIFICATION	SWF		RECOMMENDED	MTH 03-Oct-1997 HRS 585		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560-33-21 33SB-21	DUAL CONTROL GLARESHIELD INDIRECT LIGHTING INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-22 33SB-22	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-24 33SB-24	CHART LIGHT MODIFICATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-33-31 33SB-31	LED TAIL FLOODLIGHT UPGRADE			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-33-32	LED REPLACEMENT LIGHT FOR THE BAGGAGE COMPARTMENT			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 560-33-33 R01	LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-33-33	LIGHTS - LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY (SUPERSEDED BY 560-33-33 R01)			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 560-33-35	LED LANDING GEAR INDICATION LIGHT INSTALLATION			OPTIONAL			A/R			
	<b>MOC :</b>									
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-33-07 33SL-07	TRANSMITTAL OF GRIMES AEROSPACE BY SL560-33-07 R01)	SWF	D7585-33-SB01, TAXI LIGHT ASSEMBLY, GRIMES PART NUMBER D7585-20, CESSNA 560 SERIES (SUPERSEDED SUPERSEDED	MTH 03-Oct-1997 HRS 585		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-104 34SB104	TCAS RAIN COVER INSTALLATION (SUPERSEDED BY 560-34-104 R01)	TEB	SUPERSEDED	MTH 06-Oct-2004 HRS 4870		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-106 34SB-106	TCAS RAIN COVER INSTALLATION	TEB	RECOMMENDED	MTH 22-Nov-2005 HRS 5748		-			Complete
<b>MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.</b>									
SB 560-34-107 R03 34SB-107 : 560R3	NAVIGATION - MARK VIII TERRAIN AWARENESS & WARNING SYSTEM (TAWS) INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-108 R02 34SB-108 : 560R2	NAVIGATION - MARK VII TERRAIN AWARENESS & WARNING SYSTEM (TAWS) INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-109 34SB-109	5 AMP-HOUR STANDBY GYRO BATTERY INSTALLATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-34-111 R02 34SB-111 : 560R2	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-114 R02 34SB-114 : 560R2	TRAFFIC COLLISION AND AVOIDANCE SYSTEM (TCAS) II AND HONEYWELL PRIMUS INSTALLATION FOR ELEMENTARY SURVEILLANCE		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-115 R02 34SB-115 : 560R2	TRAFFIC COLLISION AND AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER INSTALLATION FOR ENHANCED SURVEILLANCE (SUPERSEDED BY 560-34-115 R03)		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-115 R03 34SB-115 : 560R3	NAVIGATION - TRAFFIC COLLISION AND AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER INSTALLATION FOR ENHANCED SURVEILLANCE		OPTIONAL			-			
<b>MOC :</b>									
SB 560-34-122 R01 34SB-122 : 560R1	HONEYWELL TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-34-128 R03 34SB-128 : 560R3	NAVIGATION - ENHANCED SURVEILLANCE TRANSPONDER INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-131 34SB-131	RUNWAY AWARENESS AND ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION		OPTIONAL	MTH		A/R			
<b>MOC :</b>									
SB 560-34-133 34SB-133	NAVIGATION - UNIVERSAL AVIONICS UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 802.2		OPTIONAL	MTH		A/R			
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-34-138 R01 <i>34SB-138 : 560R1</i>	NAVIGATION - GNS-XDXLS FMS SOFTWARE UPGRADE TO MOD 8			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560-34-143 <i>34SB-143</i>	NAVIGATION - SPEED LIMITATION PLACARD INSTALLATION (SUPERSEDED BY 560-34-143 R01)	ICT		SUPERSEDED	MTH 05-Nov-2007 HRS 7236		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 560-34-154 R01	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS	KIKV		RECOMMENDED	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			Complete
<b>MOC :</b> COMPLIED WITH - FMS SOFTWARE 803.0 INSTALLED ON UNS-1. NO FURTHER ACTION REQUIRED.										
SB 560-34-154	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 560-34-154 R01)			RECOMMENDED			A/R			
<b>MOC :</b>										
SB 560-34-155 R01	UNIVERSAL FMS WAAS UPGRADE			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-155	UNIVERSAL FMS WAAS UPGRADE (SUPERSEDED BY 560-34-155 R01)			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-156 R01	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-156	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE						-			
<b>MOC :</b>										
SB 560-34-162	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-164 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560-34-164 R02)			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-164 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-164	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560-34-164 R01)			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-165	NAVIGATION - UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8			OPTIONAL			-			
<b>MOC :</b>										
SB 560-34-60 <i>34SB-60</i>	PRIMUS 870 RADAR GERMAN CERTIFICATIOON UPGRADE			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-34-62 <i>34SB-62</i>	GNS-X/ES UPGRADE	TEB		OPTIONAL	MTH 05-May-2007 HRS 6946		-			N/A
<b>MOC :</b> NOT APPLICABLE										





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-34-66 <i>34SB-66</i>	NUMBER 2 FLIGHT GUIDANCE COMPUTER WIRE BUNDLE ID TAG INSPECTION/REPLACEMENT	ICT	RECOMMENDED	MTH 08-May-1997 HRS 276		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-69 <i>34SB-69</i>	SAFE FLIGHT ANGLE-OF-ATTACK COMPUTER MODIFICATION (SUPERSEDED BY 560-34-69 R01)	SWF	SUPERSEDED	MTH 23-Jul-1998 HRS 1177		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-75 R01 <i>34SB-75 : 560R1</i>	STATIC PORT INSPECTION/MODIFICATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-34-76 <i>34SB-76</i>	IC-600 TO FMS DATA SWITCHING MODIFICATION		OPTIONAL	MTH		-			
<b>MOC :</b>									
SB 560-34-79 R01 <i>34SB-79 : 560R1</i>	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION (SUPERSEDED BY 560-34-79 R02)	SWF	SUPERSEDED	MTH 19-Jul-2000 HRS 2312		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-80 <i>34SB-80</i>	UNS-ICSP FMS SOFTWARE UPDATE TO 602.X	TEB	OPTIONAL	MTH 05-May-2007 HRS 6946		-			N/A
<b>MOC : NOT APPLICABLE</b>									
SB 560-34-81 <i>34SB-81</i>	HONEYWELL P-1000 PHASE IV SOFTWARE INSTALLATION	SWF	RECOMMENDED	MTH 19-Jul-2000 HRS 2312		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-82 <i>34SB-82</i>	GNS-XLS SOFTWARE MOD 4 UPGRADE	SWF	RECOMMENDED	MTH 22-Jan-2000 HRS 2031		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-84 R02 <i>34SB-84 : 560R2</i>	AVIONICS MASTER SWITCH REPLACEMENT	TEB	OPTIONAL	MTH 05-May-2007 HRS 6946		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-84 <i>34SB-84</i>	AVIONICS MASTER SWITCH REPLACEMENT (SUPERSEDED BY 560-34-84 R01)	TEB	SUPERSEDED	MTH 05-May-2007 HRS 6946		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-86 <i>34SB-86</i>	GNS-XL SOFTWARE MOD 4 UPGRADE	SWF	RECOMMENDED	MTH 22-Jan-2000 HRS 2031		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-88 <i>34SB-88</i>	ARINC COMPUTER MODIFICATION	SWF	RECOMMENDED	MTH 30-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-89 <i>34SB-89</i>	UNS-1K 603.4 SOFTWARE UPGRADE	TEB	RECOMMENDED	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-34-90 <i>34SB-90</i>	GNS-XL/XLS FMS MOD 6 SOFTWARE UPGRADE (SUPERSEDED BY 560-34-90 R01)	SWF	SUPERSEDED	MTH 30-Jul-2001 HRS 2854		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-91 <i>34SB-91</i>	TCAS II SOFTWARE CHANGE 7 UPGRADE (SUPERSEDED BY 560-34-91 R01)	TEB	SUPERSEDED	MTH 21-Sep-2002 HRS 3417		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-93 <i>34SB-93</i>	HONEYWELL P-1000 PHASE 5 SOFTWARE AND AUTOPILOT PITCH TRIM INSTALLATION (SUPERSEDED BY 560-34-93 R01)	SWF	SUPERSEDED	MTH 30-Jul-2001 HRS 2854		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-34-94 <i>34SB-94</i>	UNS-1CSP 603.4 SOFTWARE UPGRADE	TEB	RECOMMENDED	MTH 02-Oct-2001 HRS 2924		-			Complete
<b>MOC : COMPLIED WITH</b>									
ASL 560-34-21 <i>34ASL21</i>	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	TEB	MANDATORY	MTH 27-Feb-2003 HRS 3703		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
ASL 560-34-34 R03 <i>34ASL-34 : 560R3</i>	NAVIGATION - STALL WARNING SYSTEM CALIBRATION ADJUSTMENT AND IN-FLIGHT TEST PROCEDURES (SUPERSEDED BY ASL560-34-34 R04)	SWF	SUPERSEDED	MTH 06-Aug-2008 HRS 7541		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
ASL 560-34-35 R03 <i>34ASL-35 : 560R3</i>	NAVIGATION - STALL WARNING SYSTEM CALIBRATION, ADJUSTMENT, AND IN-FLIGHT TEST PROCEDURES	SWF	SUPERSEDED	MTH 31-Jul-2008 HRS 7541		A/R			N/A
<b>MOC : NOT APPLICABLE</b>									
SL CIL-34-01	TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.( )-34-3508		INFORMATIONAL			-			
<b>MOC :</b>									
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM	KIKV	MANDATORY	MTH 10-Jun-2015 HRS 8701.3 LDG 7095		-			Complete
<b>MOC : COMPLIED WITH - REMOVED OLD NAV COMPUTER P/N 7510100-731 S/N 03067087 AND INSTALLED 7510100-731 S/N 88080161 REPAIRED BY HONEYWELL UNDER WO# 5008384777 DATED 12 MAY 2015. THIS COMPLIES WITH CIL-4-03 R2.</b>									
SL CIL-34-03 R01	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R02)					-			
RECOMMENDED									
<b>MOC :</b>									
SL CIL-34-03 R02	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY					-			
INFORMATIONAL									
<b>MOC :</b>									
SL CIL-34-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R01)					-			
RECOMMENDED									
<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-34-23 R01 <i>34SL-23</i>	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE RECOMMENDED						-			
<b>MOC :</b>										
SL 560-34-23 <i>34SL-23</i>	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE (SUPERSEDED BY SL560-34-23 R01)	TEB		RECOMMENDED	MTH 11-Jun-2004 HRS 4570		-			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE										
SL 560-34-28 <i>34SL-28</i>	HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8 DISCRETIONARY			MTH			-			
<b>MOC :</b>										
SL 560-34-29 <i>34SL-29</i>	ELEMENTARY SURVEILLANCE TRANSPONDER PRODUCT IMPROVEMENT	SWF		MANDATORY	MTH 31-Jul-2008 HRS 7541		-			N/A
<b>MOC :</b> NOT APPLICABLE										
SL 560-34-36 <i>34SL-36</i>	NAVIGATION - TRANSMITTAL OF HONEYWELL SWB MST 67A-SW5 RECOMMENDED			MTH			A/R			
<b>MOC :</b>										
SL 560-34-40	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION INFORMATIONAL						-			
<b>MOC :</b>										
SB 560-35-01 R04 <i>35SB-01 : 560R4</i>	EROS OXYGEN MASK INSTALLATION *CF			OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560-35-09 R01 <i>35SB-09 : 560R1</i>	EROS MLD20-506 OXYGEN MASK INSTALLATION OPTIONAL				MTH		-			
<b>MOC :</b>										
SB 560-35-12 <i>35SB-12</i>	EROS MLD20-510 OXYGEN MASK INSTALLATION OPTIONAL				MTH		-			
<b>MOC :</b>										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 KIKV			MANDATORY	MTH 25-Mar-2016 DAYS 8828.2 HRS 7204 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED P/N AND S/N NOT INSTALLED.										
SL 560-35-04 <i>35SL-04</i>	PORTABLE OXYGEN CYLINDER MASK INSPECTION/REPLACEMENT SWF			RECOMMENDED	MTH 30-Jul-2001 HRS 2854		-			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560-35-06	OXYGEN - OXYGEN BOTTLE INSPECTION KFPR			INFORMATIONAL	MTH 03-Aug-2011 HRS 7752.4 LDG 6301		A/R			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH INSPECTION AND VERIFIED A THREE YEAR INTERVAL HAS BEEN MAINTAINED.										
SL 560-35-07 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 MANDATORY						-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-35-07 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KIKV		MANDATORY	MTH 04-Mar-2014 HRS 8244.7 LDG 6682		-			N/A
	<b>MOC :</b> NOT APPLICABLE - DOES NOT APPLY TO AFFECTED EQUIPMENT INSTALLED. P/N 174252-17 O2 MASKS INSTALLED, PILOTS S/N 01820 AND CO-PILOTS S/N 03242 PURITAIN- BENNETT'S INSTALLED.									
SL 560-35-07	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560-35-07 R01)			MANDATORY			-			
	<b>MOC :</b>									
SB 560-36-02 R01 36SB-02 : 560R1	DOOR SEAL VALVE REPLACEMENT AND WATER TRAP INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-36-03 R02 36SB-03 : 560R2	WIDE CARGO DOOR SEAL LINE WATER TRAP INSTALLATION (SUPERSEDED BY 560-36-03 R03)	TEB		SUPERSEDED	MTH 22-Nov-2005 HRS 5748		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE									
ASL 560-36-01 36SLA01	INSPECTION/REPLACEMENT OF PERISEAL	TEB		MANDATORY	MTH 19-Aug-1997 HRS 505		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB 560-52-04 R01 52SB-04 : 560R1	WIDE DOOR MODIFICATION INSTALLATION (SUPERSEDED BY 560-52-04 R02)			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560-52-04 R02	WIDE DOOR MODIFICATION INSTALLATION			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-52-08 R04	COMPOSITE DOOR STEP INSTALLATION			OPTIONAL			-			
	<b>MOC :</b>									
SB 560-52-12 52SB-12	DOORS - RAIN GUTTER FASTENER INSPECTION/REPLACEMENT (SUPERSEDED BY 560-52-12 R01)	SWF		SUPERSEDED	MTH 19-Jul-2000 HRS 2312		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB 560-52-17 R01 52SB-17 : 560R1	DOORS - IMPROVEMENT FOR THE CABIN ENTRY STEPS			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-52-18 52SB-18	INSTALLATION OF NOSE LANDING GEAR DOOR DEFLECTORS			OPTIONAL	MTH		-			
	<b>MOC :</b>									
ASL 560-52-05	DOORS - EMERGENCY EXIT INSPECTION	KPBI		MANDATORY	DAYS 05-Jan-2012 HRS 7886.7 LDG 6399		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB 560-53-07 R03 53SB-07 : 560R3	TAILCONE BALLAST INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560-53-25 53SB-25	TAILCONE BAGGAGE COMPARTMENT SUPPORT IMPROVEMENT (SUPERSEDED BY 560-53-25 R01)	SWF		SUPERSEDED	MTH 23-Jul-1998 HRS 1177		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-53-26 R01 <i>53SB-26 : 560R1</i>	LOWER STUB WING SKIN INSPECTION/REPAIR (SUPERSEDED BY 560-53-26 R02)	SWF	SUPERSEDED	MTH 22-Jan-2000 HRS 2031		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-53-26 R02 <i>53SB-26 : 560R2</i>	LOWER STUB WING SKIN INSPECTION/REPAIR	SWF	RECOMMENDED	MTH 30-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-53-27 <i>53SB-27</i>	CABIN ENTRANCE AFT DOORPOST INSPECTION/REPAIR	SWF	RECOMMENDED	MTH 19-Jul-2000 HRS 2312		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-53-28 <i>53SB-28</i>	FUSELAGE MOISTURE DRAIN INSTALLATION	SWF	OPTIONAL	MTH 19-Jul-2000 HRS 2312		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-53-29 R02 <i>53SB-29 : 560R2</i>	NOSE WHEEL STEERING BRACKET REPLACEMENT	SWF	MANDATORY	MTH 30-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-53-29 <i>53SB-29</i>	NOSE WHEEL STEERING BRACKET REPLACEMENT (SUPERSEDED BY 560-53-29 R01)	SWF	SUPERSEDED	MTH 22-Jan-2000 HRS 2031		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-53-34 <i>53SB-34</i>	WHEEL WELL BOX/SKIN GAP IMPROVEMENT		OPTIONAL	MTH		-			
<b>MOC :</b>									
SL 560-53-05 <i>53SL-05</i>	DORSAL FIN VANE INSPECTION	TEB	RECOMMENDED	MTH 22-Nov-2005 HRS 5748		-			Complete
<b>MOC : COMPLIED WITH</b>									
SL 560-53-06 <i>53SL-06</i>	INTERCOSTAL DRAINAGE PATH INSPECTION (SUPERSEDED BY SL560-53-06 R01)	TEB	RECOMMENDED	MTH 22-Nov-2005 HRS 5748		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-54-03 R01 <i>54SB-03 : 560R1</i>	ENGINE INLET DOUBLER INSTALLATION (SUPERSEDED BY 560-54-03 R02)	SWF	SUPERSEDED	MTH 22-Jan-2000 HRS 2031		A/R			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-54-04 R01 <i>54SB-04 : 560R1</i>	ENGINE INLET VAPOR BARRIER INSTALLATION	SWF	RECOMMENDED	MTH 30-Jul-2001 HRS 2854		-			Complete
<b>MOC : COMPLIED WITH</b>									
SB 560-55-04 <i>55SB-04</i>	STABILIZERS - ELEVATOR TIP BONDING STRIP INSTALLATION		DISCRETIONARY	MTH		A/R			
<b>MOC :</b>									
SL 560-55-03 R01	STABILIZERS - HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION (SUPERSEDED BY SL560-55-03 R02)	KIKV	MANDATORY	MTH 12-Dec-2014 HRS 8544.7 LDG 6948		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH SL 560-55-03 R1 HORIZONTAL STABILIZER BORE SCOPE INSPECTION. NO DISCREPANCIES NOTED AT THIS TIME.</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-55-03 R02	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION			MANDATORY	MTH		-			
	<b>MOC :</b>									
SL 560-55-03	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION (SUPERSEDED BY SL560-55-03 R01)			MANDATORY	MTH		-			
	<b>MOC :</b>									
SB 560-56-01 R01 <i>56SB-01 : 560R1</i>	COPILOT'S SIDE WINDOW INSPECTION AND REPAIR (SUPERSEDED BY 560-56-01 R02)	SWF		SUPERSEDED	MTH 30-Jul-2001 HRS 2854		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
ASL 560-56-01 <i>56ASL01</i>	WINDOWS - REQUIRED PRISM INSPECTION FOR COPILOT SIDE WINDOW	TEB		RECOMMENDED	MTH 04-Jan-2001 HRS 2572 LDG 2271		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 560-57-01 R01 <i>57SL-01 : 560R1</i>	NOTIFICATION OF LEADING EDGE SKIN REWORK REQUIREMENT WHEN A DEICE BOOT IS REMOVED	ICT		MANDATORY	MTH 05-Nov-2007 HRS 7236		-			Complete
	<b>MOC :</b> COMPLIED WITH									
ASL 560-30-07 <i>30SLA07</i>	APPROACH AND LANDING IN ICING CONDITIONS ADDITION TO FLIGHT MANUAL (SUPERSEDED BY ASL560-30-07 R01)	ICT		SUPERSEDED	MTH 17-Dec-1996 HRS 5		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 560-72-14 <i>72SL-14</i>	P&W SB JT15D-72-7527	SWF		INFORMATIONAL	MTH 23-Jul-1998 HRS 1177		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 560-72-16 <i>72SL-16</i>	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023	TEB		RECOMMENDED	MTH 26-Apr-2000 HRS 2242		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SL 560-72-20 R01 <i>72SL-20 : 560R1</i>	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SIL JT15D-032, BOOST ROTOR, P&WC SB JT15D-72-7569 REV 5, LOW COMPRESSOR ROTOR - REPLACEMENT/MODIFICATION OF (CANCELLED - REPLACED BY SL560-72-21)			RECOMMENDED	MTH 15-Dec-2006 HRS 6625		-			Complete
	<b>MOC :</b> COMPLIED WITH									
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R26)			RECOMMENDED			-			
	<b>MOC :</b>									
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R26)			RECOMMENDED			-			
	<b>MOC :</b>									
SB JT15D-72-7001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R27)			RECOMMENDED			-			
	<b>MOC :</b>									
SB JT15D-72-7001 R26 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY JT15D-72-7001 R27)			RECOMMENDED			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED						
	<b>MOC :</b>									
SB JT15D-72-7001 R27 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED						
	<b>MOC :</b>									
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY JT15D-72-7002 R43)			CATEGORY 3			A/R			
	<b>MOC :</b>									
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY JT15D-72-7002 R43)			CATEGORY 3			A/R			
	<b>MOC :</b>									
SB JT15D-72-7002 R43 E1	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3						
	<b>MOC :</b>									
SB JT15D-72-7002 R43 E2	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3						
	<b>MOC :</b>									
SB JT15D-72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R36)									
	<b>MOC :</b>									
SB JT15D-72-7003 R35 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R36)									
	<b>MOC :</b>									
SB JT15D-72-7003 R36 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R37)									
	<b>MOC :</b>									
SB JT15D-72-7003 R36 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R37)									
	<b>MOC :</b>									
SB JT15D-72-7003 R37 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R38)									
	<b>MOC :</b>									
SB JT15D-72-7003 R37 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R38)									
	<b>MOC :</b>									
SB JT15D-72-7003 R38 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R39)									
	<b>MOC :</b>									
SB JT15D-72-7003 R38 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R39)									
	<b>MOC :</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl	Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7003 R39 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R40)				RECOMMENDED		-			
	<b>MOC :</b>									
SB JT15D-72-7003 R39 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY JT15D-72-7003 R40)				RECOMMENDED		-			
	<b>MOC :</b>									
SB JT15D-72-7003 R40 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY				RECOMMENDED		A/R			
	<b>MOC :</b>									
SB JT15D-72-7003 R40 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY				RECOMMENDED		A/R			
	<b>MOC :</b>									
SB JT15D-72-7144 R20 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
	<b>MOC :</b>									
SB JT15D-72-7144 R20 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
	<b>MOC :</b>									
SB JT15D-72-7144 R21 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING				RECOMMENDED		-			
	<b>MOC :</b>									
SB JT15D-72-7144 R21 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING				RECOMMENDED		-			
	<b>MOC :</b>									
SB JT15D-72-7459 R01 E1	REPLACEMENT OF IGNITER (SUPERSEDED BY JT15D-72-7459 R02)				CATEGORY 8		A/R			
	<b>MOC :</b>									
SB JT15D-72-7459 R01 E2	REPLACEMENT OF IGNITER (SUPERSEDED BY JT15D-72-7459 R02)				CATEGORY 8		A/R			
	<b>MOC :</b>									
SB JT15D-72-7467 R01 E1	REPLACEMENT/MODIFICATION OF FLOW DIVIDER VALVE				CATEGORY 3		-			
	<b>MOC :</b>									
SB JT15D-72-7467 R01 E2	REPLACEMENT/MODIFICATION OF FLOW DIVIDER VALVE				CATEGORY 3		-			
	<b>MOC :</b>									
SB JT15D-72-7493 R04 E1	MODIFICATION/REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R05)				CATEGORY 8		-			
	<b>MOC :</b>									
SB JT15D-72-7493 R04 E2	MODIFICATION/REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R05)				CATEGORY 8		-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7493 R05 E1	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R06)			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7493 R05 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY JT15D-72-7493 R06)			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7493 R06 E1	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R04)			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7493 R06 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY SB JT15D-72-7526 R04)			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7526 R02 E1	MODIFICATION/REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R03)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7526 R02 E2	MODIFICATION/REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R03)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7526 R03 E1	MODIFICATION / REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R04)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7526 R03 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLES (SUPERSEDED BY JT15D-72-7526 R04)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7526 R04 E1	MODIFICATION / REPLACEMENT OF FUEL NOZZLES			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7526 R04 E2	MODIFICATION / REPLACEMENT OF FUEL NOZZLES			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7571 R02 E1	NEW LOW TURBINE DISC ASSEMBLY - INTRODUCTION OF			CATEGORY 9			A/R			
<b>MOC :</b>										
SB JT15D-72-7571 R02 E2	NEW LOW TURBINE DISC ASSEMBLY - INTRODUCTION OF			CATEGORY 9			A/R			
<b>MOC :</b>										
SB JT15D-72-7588 R02 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7588 R02 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
<b>MOC :</b>										
SB JT15D-72-7618 R02 E1	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7618 R02 E2	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7618 R03 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7618 R03 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7621 R01 E1	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7621 R01 E2	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7625 R01 E1	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
<b>MOC :</b>										
SB JT15D-72-7625 R01 E2	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
<b>MOC :</b>										
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET (SUPERSEDED BY JT15D-72-7625 R01)			CATEGORY 6			A/R			
<b>MOC :</b>										
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET (SUPERSEDED BY JT15D-72-7625 R01)			CATEGORY 6			A/R			
<b>MOC :</b>										
SB JT15D-72-7627 E1	REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7627 E2	REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7628 R01 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R02)			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7628 R01 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R02)			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7628 R02 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R03)			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7628 R02 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R03)			CATEGORY 6			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7628 R03 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7628 R03 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY			CATEGORY 6			-			
<b>MOC :</b>										
SB JT15D-72-7628 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R01)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7628 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY (SUPERSEDED BY JT15D-72-7628 R01)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7630 E1	INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER	KIKV		CATEGORY 3	MTH 04-Mar-2014 HRS 8244.7		-			N/A
<b>MOC :</b> NOT APPLICABLE - INSPECTED PER SB72-6230 AND FOUND AFFECTED SERIAL NUMBER NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
SB JT15D-72-7630 E2	INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER	KIKV		CATEGORY 3	MTH 04-Mar-2014 HRS 8244.8 LDG 6680		-			Complete
<b>MOC :</b> COMPLIED WITH - INSPECTED FUEL COOLED OIL COOLER ON #2 ENGINE AND FOUND AFFECTED FUEL COOLED OIL COOLER AFFECTED S/N NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
<b>MOC :</b>										
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
<b>MOC :</b>										
SB JT15D-72-7636 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7636 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7639 R01 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3			-			
<b>MOC :</b>										
SB JT15D-72-7639 R01 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3			-			
<b>MOC :</b>										
SB JT15D-72-7639 R02 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3			-			
<b>MOC :</b>										
SB JT15D-72-7639 R02 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7639 R03 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7639 R03 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7639 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4			-			
	<b>MOC :</b>									
SB JT15D-72-7639 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4			-			
	<b>MOC :</b>									
SB JT15D-72-7640 E1	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7640 E2	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7642 R01 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
	<b>MOC :</b>									
SB JT15D-72-7642 R01 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
	<b>MOC :</b>									
SB JT15D-72-7642 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS (SUPERSEDED BY JT15D-72-7642 R01)			CATEGORY 9			-			
	<b>MOC :</b>									
SB JT15D-72-7642 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS (SUPERSEDED BY JT15D-72-7642 R01)			CATEGORY 9			-			
	<b>MOC :</b>									
SB JT15D-72-7643 E1	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7643 E2	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7644 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7644 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7645 R01 E1	REPLACEMENT / MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
	<b>MOC :</b>									
SB JT15D-72-7645 R01 E2	REPLACEMENT / MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB JT15D-72-7645 E1	REPLACEMENT / MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY JT15D-72-7645 R01)			CATEGORY 7			-			
<b>MOC :</b>										
SB JT15D-72-7645 E2	REPLACEMENT / MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY JT15D-72-7645 R01)			CATEGORY 7			-			
<b>MOC :</b>										
SL 560-73-06 73SL-06	ENGINE FUEL CONTROL - TRANSMITTAL OF SL JT15D-021 AND P&WC SB JT15D-72-7561, TURBOFAN ENGINE FUEL CONTROL UNIT (OVERSPEED VALVE) - FIELD INSPECTION AND CLEANING	SWF		RECOMMENDED	MTH 21-Jan-2000 HRS 2031		-			Complete
<b>MOC :</b> COMPLIED WITH										
SL 560-73-11 73SL-11	ELDEC CORPORATION SERVICE LETTER SL9-231-73-04	TEB		INFORMATIONAL	MTH 22-Nov-2005 HRS 5748		-			Complete
<b>MOC :</b> COMPLIED WITH										
SL CIL-74-01 R01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R02)	KIKV		MANDATORY	DAYS 04-Mar-2014 HRS 8244.7 LDG 6682		-			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH SL CIL-74-01 R1 BY INSPECTION OF #1 ENGINE VERIFYING THAT IGNITION CABLE LEAD IS CLEAR OF THROTTLE.										
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R01)			MANDATORY	DAYS		-			
<b>MOC :</b>										
SL 560-74-02 74SL-02	IGNITION - TRANSMITTAL OF P&WC SB 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF	TEB		RECOMMENDED	MTH 04-Jan-2001 HRS 2572		-			Complete
<b>MOC :</b> COMPLIED WITH										
SB JT15D-72-7459 R02 E1	REPLACEMENT OF IGNITER			CATEGORY 8						A/R
<b>MOC :</b>										
SB JT15D-72-7459 R02 E2	REPLACEMENT OF IGNITER			CATEGORY 8						A/R
<b>MOC :</b>										
SB 560-76-01 R02 76SB-01 : 560R2	ENGINE SYNCHRONIZER CONTROLLER MODIFICATION	SWF		RECOMMENDED	MTH 22-Jan-2000 HRS 2031		-			Complete
<b>MOC :</b> COMPLIED WITH										
SB 560-78-04 78SB-04	THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		-			
<b>MOC :</b>										
SL 560-78-06 R01 78SL-06 : 560R1	TRANSMITTAL OF NORDAM SERVICE BULLETIN CIVT 78-2, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER	SWF		RECOMMENDED	MTH 23-Jul-1998 HRS 1177			A/R		Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 560-78-07 R01 78SL-07 : 560R1	TRANSMITTAL OF NORDAM SERVICE BULLETIN CIVT 78-3, REV 3 EXHAUST - THRUST REVERSER - REPLACEMENT OF ANTI-DRAG FAIRING ASSEMBLY	ICT		INFORMATIONAL	MTH 23-Nov-1997 HRS 687			A/R		Complete
<b>MOC :</b> COMPLIED WITH										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-80-03 R01 <i>80SB-03 : 560R1</i>	APC P/N 9912125-2 STARTER/GENERATOR INSPECTION/REPLACEMENT (SUPERSEDED BY 560-80-03 R02)	ICT		SUPERSEDED	MTH 20-Feb-1998 HRS 860		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 560-80-03 R02 <i>80SB-03 : 560R2</i>	APC P/N 9912125-2 STARTER/GENERATOR INSPECTION/REPLACEMENT	TEB		RECOMMENDED	MTH 21-May-1998 HRS 1087		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.</b>										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
<b>MOC :</b>										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
<b>MOC :</b>										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
<b>MOC :</b>										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
<b>MOC :</b>										





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1996-24-06 <i>30AD-01</i>	ICING COND ADDITION TO FM (SUPERSEDED BY 2006-22-05)	ICT	SUPERSEDED	MTH 17-Dec-1996 HRS 5		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 1997-05-03 <i>34AD-07</i>	APPLIANCE AD - GNS-XLS AND GNS-XL GPS (SUPERSEDED BY 1997-05-03 R01)	TEB	SUPERSEDED	MTH 19-Mar-1997 HRS 184		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 1998-04-38 <i>30AD-02</i>	SEVERE ICING PROCEDURES	TEB	MANDATORY	MTH 23-Apr-1998 HRS 1005		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 1998-25-10 <i>25AD-02</i>	APPLIANCE AD - AIRCRAFT BELTS, INC. (SUPERSEDED BY 1998-25-10 R01)	TEB	SUPERSEDED	MTH 18-Dec-1998 HRS 1404		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 1999-08-21 <i>35AD-03</i>	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM CO	TEB	MANDATORY	MTH 05-May-1999 HRS 1600		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE BY TYPE MANUFACTURER</b>									
FAA 2000-03-09 <i>34AD-09</i>	ICING COND FM INFORMATION	ICT	MANDATORY	MTH 05-May-2000 HRS 2251		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 2006-04-10 <i>26AD-02</i>	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.	TEB	MANDATORY	MTH 27-Mar-2006 HRS 6057		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 2006-06-03 <i>28AD-01</i>	PREVENT FUEL VAPOR IGNITION	TEB	MANDATORY	MTH 29-Mar-2006 HRS 6057		-			Complete
<b>MOC : COMPLIED WITH</b>									
FAA 2006-16-18 <i>34AD-16</i>	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	TEB	MANDATORY	MTH 05-Oct-2006 HRS 6551		A/R			N/A
<b>MOC : NOT APPLICABLE</b>									
FAA 2006-19-04 PARA(F) <i>34AD-17</i>	REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM)		MANDATORY	MTH 05-Oct-2006 HRS 6551		A/R			N/A
<b>MOC : NOT APPLICABLE</b>									
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	KDAL	MANDATORY	DAYS 01-Aug-2018 HRS 9339.7 LDG 7558		-			Complete
<b>MOC : COMPLIED WITH - COMPLIED WITH AD FAA 2013-09-11(G) CESSNA AIRCRAFT COMPANY: AMENDMENT 39-17453; DOCKET NO. FAA-2012-1001; DIRECTORATE IDENTIFIER 2012-NM-020-AD REPLACEMENT OF AIR CONDITIONING MOTOR BRUSHES.</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	KDAL	MANDATORY	DAYS 01-Aug-2018 HRS 9339.7 LDG 7558		-			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD FAA 2013-09-11(H) CESSNA AIRCRAFT COMPANY: AMENDMENT 39-17453; DOCKET NO. FAA-2012-1001; DIRECTORATE IDENTIFIER 2012-NM-020-AD REPLACEMENT OF AIR CONDITIONING MOTOR BRUSHES.									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	KRBD	MANDATORY	MTH 15-Aug-2019 HRS 9482.3 LDG 7652 ACH 611.4		500		1111.4	Complete 500
<b>MOC :</b> COMPLIED WITH - BRUSHES REPLACED A MOTOR OVERHAUL, ITEM 2 ABOVE. ACH TIME AT INSTALLATION IS 611.4									
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	KDAL	MANDATORY	MTH 01-Aug-2018 HRS 9339.7 LDG 7558		A/R			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD FAA 2013-09-11(K) CESSNA AIRCRAFT COMPANY: AMENDMENT 39-17453; DOCKET NO. FAA-2012-1001; DIRECTORATE IDENTIFIER 2012-NM-020-AD REPLACEMENT OF AIR CONDITIONING MOTOR BRUSHES.									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	KDAL	MANDATORY	MTH 01-Aug-2018 HRS 9339.7 LDG 7558		A/R			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD FAA 2013-09-11(L) CESSNA AIRCRAFT COMPANY: AMENDMENT 39-17453; DOCKET NO. FAA-2012-1001; DIRECTORATE IDENTIFIER 2012-NM-020-AD REPLACEMENT OF AIR CONDITIONING MOTOR BRUSHES.									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	KDAL	MANDATORY	DAYS 01-Aug-2018 HRS 9339.7 LDG 7558		-			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD FAA 2013-09-11(M) CESSNA AIRCRAFT COMPANY: AMENDMENT 39-17453; DOCKET NO. FAA-2012-1001; DIRECTORATE IDENTIFIER 2012-NM-020-AD REPLACEMENT OF AIR CONDITIONING MOTOR BRUSHES.									
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	KDAL	MANDATORY	MTH 01-Aug-2018 HRS 9339.7 LDG 7558		-			Complete
<b>MOC :</b> COMPLIED WITH - COMPLIED WITH AD FAA 2013-09-11 AIR CONDITIONING REPLACEMENT OF MOTOR BRUSHES. GAINED ACCESS TO AND REMOVED OLD BRUSHES P/N: 125117, NSN AND INSTALLED NEW BRUSHES P/N: 125117, NSN. RESTORED ACCESS AND OPS CHECKED AIR CONDITION SYSTEM WITH SATISFACTORY RESULTS. WORK ACCOMPLISHED IAW P/N: 1134400-9 ENVIRO C.M.M. 21-00-24 AND AD 2013-09-11.RECURRING AD EVERY 500 HRS, NEXT DUE 1044.8 HOBBS METER @ 544.8									
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	KIKV	MANDATORY	MTH 10-Nov-2015 DAYS 8739.7 HRS 7135 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A PER P/N FWA1134104-9. AFFECTED EQUIPMENT NOT INSTALLED.									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	KIKV	MANDATORY	MTH 10-Nov-2015 DAYS 8739.7 HRS 7135 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A PER P/N FWA1134104-9. AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	KIKV	MANDATORY	MTH 10-Nov-2015 HRS 8739.7 LDG 7135		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A PER P/N FWA1134104-9. AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)		MANDATORY			-			
<b>MOC :</b>									
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE		MANDATORY			-			
<b>MOC :</b>									
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	KIKV	MANDATORY	MTH 10-Nov-2015 DAYS 8739.7 HRS 7135 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A PER P/N FWA1134104-9. AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	KIKV	MANDATORY	MTH 10-Nov-2015 HRS 8739.7 LDG 7135		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A PER P/N FWA1134104-9. AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2003-23-02 34AD-14	THIS ACTION REQUIRES DISENGAGING AND TIE-STRAPPING THE PITCH TRIM AND AUTOPILOT SERVO (SERVO 1) CIRCUIT BREAKERS. THIS ACTION ALSO PROVIDES AN OPTIONAL INSPECTION AND FOLLOW-ON ACTIONS THAT, IF ACCOMPLISHED, TERMINATES THE REQUIREMENT TO DISENGAGE AND TIE-STRAP THOSE CIRCUIT BREAKERS	TEB	MANDATORY	MTH 14-Nov-2003 HRS 4180		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE									
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION		MANDATORY			-			
<b>MOC :</b>									
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	KIKV	MANDATORY	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			N/A
<b>MOC :</b> NOT APPLICABLE									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	KIKV	MANDATORY	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			N/A
<b>MOC : NOT APPLICABLE</b>									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	KIKV	MANDATORY	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			N/A
<b>MOC : NOT APPLICABLE</b>									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	KIKV	MANDATORY	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			N/A
<b>MOC : NOT APPLICABLE - N/A AFFECTED EQUIPMENT NOT INSTALLED.</b>									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KRBD		MTH 24-Oct-2018 HRS 9372.7 LDG 7576		-			N/A
<b>MOC : NOT APPLICABLE - FAA AIRWORTHINESS DIRECTIVE 2017-16-01 DATED OCTOBER 24, 2017 DOES NOT APPLY TO THIS AIRCRAFT. THE AFFECTED APPLIANCE IS NOT INSTALLED AT THIS TIME.</b>									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KRBD	MANDATORY	MTH 24-Oct-2018 HRS 9372.7 LDG 7576		-			N/A
<b>MOC : NOT APPLICABLE</b>									
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KRBD	MANDATORY	MTH 24-Oct-2018 HRS 9372.7 LDG 7576		-			N/A
<b>MOC : NOT APPLICABLE - FAA AIRWORTHINESS DIRECTIVE 2017-16-01 DATED OCTOBER 24, 2017 DOES NOT APPLY TO THIS AIRCRAFT. THE AFFECTED APPLIANCE IS NOT INSTALLED AT THIS TIME.</b>									
FAA 2003-26-14 26AD-01	APPLIANCE AD - THIS AD REQUIRES YOU TO REMOVE CERTAIN KIDDE AEROSPACE P/N 898052 HAND-HELD HALON FIRE EXTINGUISHERS FROM SERVICE.	TEB	MANDATORY	MTH 03-Feb-2004 HRS 4320			A/R		Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
FAA 2007-11-17 26AD-03	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES	TEB	MANDATORY	MTH 13-Jun-2007 HRS 7045			A/R		Complete
<b>MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.</b>									
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI WITH SERVICABLE UNIT	KFPR	MANDATORY	DAYS 13-Oct-2010 HRS 7733.6 LDG 6291			A/R		N/A
<b>MOC : NOT APPLICABLE - COMPLIED WITH AD BY INSPECTION AND FOUND THAT AD IS N/A DUE TO FIRE EXTINGUISHER MANUFACTURER</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2010-04-16 26AD-07	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI			MANDATORY	DAYS 13-Oct-2010 HRS 7733.6 LDG 6291		A/R			N/A
<b>MOC :</b> NOT APPLICABLE - COMPLIED WITH AD BY INSPECTION AND FOUND THAT AD IS N/A DUE TO FIRE EXTINGUISHER MANUFACTURER										
FAA 2007-23-13 34AD-19	INSPECT - ADJUSTMENT OF STALL WARNING SYSTEM (SUPERSEDED BY FAA 2008-26-04)	TEB		SUPERSEDED	MTH 12-Dec-2007 HRS 7343		A/R			Complete
<b>MOC :</b> COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
FAA 2008-26-04 34AD-24	INSTALL WARNING PLACARDS, PERFORM FUNCTIONAL TEST OF ANGLE OF ATTACK SYSTEM AND ADJUST CALIBRATION SETTINGS OF AOA SYSTEM AS REQUIRED.	FPR		AIRWORTHINESS	MTH 28-May-2009 HRS 7596		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
FAA 1998-25-02 34AD-08	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	TEB		MANDATORY	MTH 25-Jan-1999 HRS 1455		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
FAA 2001-23-17 34AD-10	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	TEB		MANDATORY	MTH 04-Feb-2002 HRS 3079		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2003-04-06 34AD-13	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2006-22-05)	TEB		SUPERSEDED	MTH 27-Feb-2003 HRS 3703		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
FAA 2006-16-18 R01 34AD-16 : 560R1	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD	SWF		AIRWORTHINESS	MTH 31-Jul-2008 HRS 7541		A/R			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2006-22-05 34AD-18	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2010-07-02)	SWF		MANDATORY	MTH 31-Jul-2008 HRS 7541		A/R			N/A
<b>MOC :</b> NOT APPLICABLE										
FAA 2010-07-02	APPLIANCE AD - PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	UNK		MANDATORY	MTH 14-Jan-2013 HRS 7953.8 LDG 6440		A/R			Complete
<b>MOC :</b> COMPLIED WITH - RECEIVED MODULES HAVE MOD T STATUS										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	KIKV		MANDATORY	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY	MTH		-			
<b>MOC :</b>										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	KIKV		MANDATORY	MTH 10-Jul-2015 HRS 8709.6 LDG 7105		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED EQUIPMENT NOT INSTALLED.										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KGGG		MANDATORY	MTH 25-Jul-2017 HRS 9113.9 LDG 7435 ACH 464.3		-			N/A
<b>MOC :</b> NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH ZODIAC CREW OXYGEN MASKS. PURITAN BENNETT MASKS P/N 174252-17 ARE INSTALLED AND THEREFOR THIS AIRWORTHINESS DIRECTIVE DOES NOT APPLY.										
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KGGG		MANDATORY	MTH 25-Jul-2017 HRS 9113.9 LDG 7435 ACH 464.3		-			N/A
<b>MOC :</b> NOT APPLICABLE - THIS AIRCRAFT IS NOT EQUIPPED WITH ZODIAC CREW OXYGEN MASKS. PURITAN BENNETT MASKS P/N 174252-17 ARE INSTALLED AND THEREFOR THIS AIRWORTHINESS DIRECTIVE DOES NOT APPLY.										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES			MANDATORY			-			
<b>MOC :</b>										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KIKV		MANDATORY	MTH 22-Dec-2015 DAYS 8750.2 HRS 7145 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED OXYGEN MASKS NOT INSTALLED.										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KIKV		MANDATORY	MTH 22-Dec-2015 DAYS 8750.2 HRS 7145 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED OXYGEN MASKS NOT INSTALLED.										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KIKV		MANDATORY	MTH 22-Dec-2015 DAYS 8750.2 HRS 7145 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED OXYGEN MASKS NOT INSTALLED.										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KIKV		MANDATORY	MTH 22-Dec-2015 DAYS 8750.2 HRS 7145 LDG		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED OXYGEN MASKS NOT INSTALLED.										





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KIKV	MANDATORY	MTH 22-Dec-2015 HRS 8750.2 LDG 7145		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED OXYGEN MASKS NOT INSTALLED.									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KIKV	MANDATORY	MTH 22-Dec-2015 HRS 8750.2 LDG 7145		-			N/A
<b>MOC :</b> NOT APPLICABLE - N/A AFFECTED OXYGEN MASKS NOT INSTALLED.									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAAAD 2017-18-12	KIKV	MANDATORY	MTH 08-Nov-2016 HRS 8997.1 LDG 7353 ACH 338.8		-			N/A
<b>MOC :</b> NOT APPLICABLE - AD DOES NOT APPLY AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAAAD 2017-18-12	KIKV	MANDATORY	MTH 08-Nov-2016 HRS 8997.1 LDG 7353 ACH 338.8		-			N/A
<b>MOC :</b> NOT APPLICABLE - AD DOES NOT APPLY AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAAAD 2017-18-12	KIKV	MANDATORY	MTH 08-Nov-2016 HRS 8997.1 LDG 7353 ACH 338.8		-			N/A
<b>MOC :</b> NOT APPLICABLE - AD DOES NOT APPLY AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAAAD 2017-18-12	KIKV	MANDATORY	MTH 08-Nov-2016 HRS 8997.1 LDG 7353 ACH 338.8		-			N/A
<b>MOC :</b> NOT APPLICABLE - AD DOES NOT APPLY AFFECTED EQUIPMENT NOT INSTALLED.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KDAL	MANDATORY	MTH 11-Apr-2018 HRS 9268.2 LDG 7519		-			N/A
<b>MOC :</b> NOT APPLICABLE - COMPLIED WITH FAA2017-18-12 B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT P/N: 119003-11 AND P/N: 119003-21 DOCKET NO. FAA-2017-0439; PRODUCT IDENTIFIER 2017-CE-010-AD; AMENDMENT 39-19021; AD2017-18-12 EFFECTIVE DATE: 16/OCT/2017 AS REQUIRED AND FOUND AD IS NOT APPLICABLE DUE TO EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT. NO FURTHER ACTION TAKEN.									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KDAL	MANDATORY	MTH 11-Apr-2018 HRS 9268.2 LDG 7519		-			N/A
<b>MOC :</b> NOT APPLICABLE - COMPLIED WITH FAA2017-18-12 B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT P/N: 119003-11 AND P/N: 119003-21 DOCKET NO. FAA-2017-0439; PRODUCT IDENTIFIER 2017-CE-010-AD; AMENDMENT 39-19021; AD2017-18-12 EFFECTIVE DATE: 16/OCT/2017 AS REQUIRED AND FOUND AD IS NOT APPLICABLE DUE TO EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT. NO FURTHER ACTION TAKEN.									





# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KDAL		MANDATORY	MTH 11-Apr-2018 HRS 9268.2 LDG 7519		-			N/A
<p><b>MOC :</b> NOT APPLICABLE - COMPLIED WITH FAA2017-18-12 B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT P/N: 119003-11 AND P/N: 119003-21 DOCKET NO. FAA-2017-0439; PRODUCT IDENTIFIER 2017-CE-010-AD; AMENDMENT 39-19021; AD2017-18-12 EFFECTIVE DATE: 16/OCT/2017 AS REQUIRED AND FOUND AD IS NOT APPLICABLE DUE TO EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT. NO FURTHER ACTION TAKEN.</p>										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KDAL		MANDATORY	MTH 11-Apr-2018 HRS 9268.2 LDG 7519		-			Complete
<p><b>MOC :</b> COMPLIED WITH - COMPLIED WITH FAA2017-18-12 B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT P/N: 119003-11 AND P/N: 119003-21 DOCKET NO. FAA-2017-0439; PRODUCT IDENTIFIER 2017-CE-010-AD; AMENDMENT 39-19021; AD2017-18-12 EFFECTIVE DATE: 16/OCT/2017 AS REQUIRED AND FOUND AD IS NOT APPLICABLE DUE TO EQUIPMENT IS NOT INSTALLED IN THE AIRCRAFT. NO FURTHER ACTION TAKEN.</p>										



# CESCOM 10 - Aircraft Status Report

Owner: **EXCHEQUER LAND AND CATTLE CO LLC**  
 Aircraft Model: **560 - CITATION ULTRA**  
 Aircraft Serial: **560-0395**  
 Unit: **0395** Reg No: **N324LM**  
 Airworthiness: **15-Dec-1996**  
 Print Date: **27-Aug-2019 2:48PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>9482.3</b>	<b>7652</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 1</b>	<b>9048</b>	<b>7312</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>ENG 2</b>	<b>9204.2</b>	<b>7422</b>	<b>15-Aug-2019</b>	<b>.15</b>
<b>AIR COND</b>	<b>611.4</b>		<b>15-Aug-2019</b>	<b>.22</b>

## Factory Installed

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
21FO-03 560	CABIN TEMP INDICATOR FACTORY OPTION		MTH		15-Dec-1996		-			
<i>21FO-03 : 560</i>		*CF		06A FO						