

Quick Change Transfer Case Gear Chart

<u>Set No.</u>	<u>Teeth</u>	<u>Ratio</u>	<u>W/1.545</u>	<u>W/2.000</u>	<u>W/2.500</u>
80	19\40	2.105	3.252	4.21	5.263
90	20\41	2.05	3.167	4.1	5.125
150	20\40	2	3.09	4	5
200	20\39	1.95	3.013	3.9	4.875
250	21\40	1.905	2.943	3.81	4.763
300	21\39	1.857	2.869	3.714	4.643
400	21\38	1.81	2.796	3.62	4.525
450	22\39	1.773	2.739	3.546	4.433
500	22\38	1.727	2.668	3.454	4.318
600	22\37	1.682	2.597	3.364	4.205
650	23\38	1.652	2.552	3.304	4.13
700	23\37	1.609	2.486	3.218	4.023
750	27\43	1.593	2.461	3.186	3.983
800	23\36	1.565	2.418	3.13	3.913
850	24\37	1.542	2.382	3.084	3.855
870	25\38	1.52	2.348	3.04	3.8
900	24\36	1.5	2.318	3	3.75
920	25\37	1.48	2.287	2.96	3.7
950	24\35	1.458	2.253	2.916	3.645
960	25\36	1.44	2.225	2.88	3.6
970	29\41	1.414	2.185	2.828	3.535
1000	25\35	1.4	2.163	2.8	3.5
1050	29\40	1.379	2.131	2.758	3.448
1100	25\34	1.36	2.101	2.72	3.4
1150	26\35	1.346	2.08	2.692	3.365
1200	26\34	1.308	2.021	2.616	3.27
1300	26\33	1.269	1.961	2.538	3.173
1350	27\34	1.259	1.945	2.518	3.148
1400	27\33	1.222	1.888	2.444	3.055
1500	27\32	1.185	1.831	2.37	2.963
1550	28\33	1.179	1.822	2.358	2.948
1600	28\32	1.143	1.766	2.286	2.858
1700	28\31	1.107	1.71	2.214	2.768
1750	29\32	1.103	1.704	2.206	2.758
1800	29\31	1.069	1.652	2.138	2.673
1900	29\30	1.034	1.598	2.068	2.585
2000	30\30	1	1.545	2	2.5