

Quick Change Transfer Case Gear Chart

Set No.	Teeth	Ratio	W/1.545	W/2.000	W/2.500	W/2.50 x 6.20
80	19\40	2.105	3.252	4.210	5.263	32.628
90	20\41	2.050	3.167	4.100	5.125	31.775
150	20\40	2.000	3.090	4.000	5.000	31.000
200	20\39	1.950	3.013	3.900	4.875	30.225
250	21\40	1.905	2.943	3.810	4.763	29.528
300	21\39	1.857	2.869	3.714	4.643	28.784
400	21\38	1.810	2.796	3.620	4.525	28.055
450	22\39	1.773	2.739	3.546	4.433	27.482
500	22\38	1.727	2.668	3.454	4.318	26.769
600	22\37	1.682	2.597	3.364	4.205	26.071
650	23\38	1.652	2.552	3.304	4.130	25.606
700	23\37	1.609	2.486	3.218	4.023	24.940
750	27\43	1.593	2.461	3.186	3.983	24.692
800	23\36	1.565	2.418	3.130	3.913	24.258
850	24\37	1.542	2.382	3.084	3.855	23.901
870	25\38	1.520	2.348	3.040	3.800	23.560
900	24\36	1.500	2.318	3.000	3.750	23.250
920	25\37	1.480	2.287	2.960	3.700	22.940
950	24\35	1.458	2.253	2.916	3.645	22.599
960	25\36	1.440	2.225	2.880	3.600	22.320
970	29\41	1.414	2.185	2.828	3.535	21.917
1000	25\35	1.400	2.163	2.800	3.500	21.700
1050	29\40	1.379	2.131	2.758	3.448	21.375
1100	25\34	1.360	2.101	2.720	3.400	21.080
1150	26\35	1.346	2.080	2.692	3.365	20.863
1200	26\34	1.308	2.021	2.616	3.270	20.274
1300	26\33	1.269	1.961	2.538	3.173	19.670
1350	27\34	1.259	1.945	2.518	3.148	19.515
1400	27\33	1.222	1.888	2.444	3.055	18.941
1500	27\32	1.185	1.831	2.370	2.963	18.368
1550	28\33	1.179	1.822	2.358	2.948	18.275
1600	28\32	1.143	1.766	2.286	2.858	17.717
1700	28\31	1.107	1.710	2.214	2.768	17.159
1750	29\32	1.103	1.704	2.206	2.758	17.097
1800	29\31	1.069	1.652	2.138	2.673	16.570
1900	29\30	1.034	1.598	2.068	2.585	16.027
2000	30\30	1.000	1.545	2.000	2.500	15.500