

**West Virginia Department of Health & Human
Resources
Berkeley County Health Department**



CHILD CARE CENTER INSPECTION REPORT

Establishment Information	
Facility Name Step Ahead Preschool	Facility Type Child Care Center
Licensee Name Lisa Carpenter	Facility Telephone # 304 263-6181
Facility Address 418 Stribling Rd Martinsburg , WV	Licensee Address ,

Establishment Details	
Adult to Child Ratio	4-5's=9/2; 5-8's 17/2; 2-3's 13/2=39/6

Inspection Information		
Inspection Type Routine	Inspection Date 06/23/2017	Total Time Spent 1.27

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

ObservedViolations

Total # 10

Repeated # 0

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: All rooms -several ceiling light bulbs need replaced

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: Prek 4-5's-several window blinds torn and blinds missing in 2-3's room

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: All rooms-window ledges need repaired and walls painted where paint is missing

5.1.B. - Child care center buildings or structures shall be of sound structure and maintained in good repair.

OBSERVATION: prek 4-5's yellow/red couch-seat torn

5.2.A - Floors, walls and ceilings shall be of easily cleanable construction.

OBSERVATION: wall vents need cleaned in rooms

5.2.A - Floors, walls and ceilings shall be of easily cleanable construction.

OBSERVATION: 5-8's restrooms-high dusting needed and dusting needed in 2-3's restrooms(baseboard)

5.2.A - Floors, walls and ceilings shall be of easily cleanable construction.

OBSERVATION: preK 4--5's-floor perimeters need cleaned

5.2.B - Toilet rooms and areas housing food service facilities shall have moisture-resistant, nonabsorbent floors.

OBSERVATION: prek 4-5 room-moisture around base of toilet in left side restroom and odor in right side restroom

5.2.E - Carpeting shall be securely attached or of a non-skid nature.

OBSERVATION: Prek 4-5's room-stripped rug edges frayed

5.3.E - Shielding or other effective means shall be used to protect the children from direct contact with radiators, registers, hot water pipes and similar hazards.

OBSERVATION: PreK 4-5's baseboard heater in left restroom needs safety cover

Inspection Outcome

Comments

Disclaimer

Person in Charge



Sanitarian



Amy ARE Edwards