Before and After Project

FASCO Model 30

I was able to repair the splinter in the upper limb, and I added a single wood overlay to the tips.
















Model 30 # 4924 64.

