

Home Office - 1717 East Erwin Street

Tyler, Texas 75702-6398

Office: (903) 595-4421 Lab: (903) 595-6402 Fax: (903) 595-6111

Area Offices

210 Beech Street	Texarkana, AR 71854	(870) 772-0013
707 West Cotton St.	Longview, TX 75604	(903) 758-0402
2000E Randol Mill Rd. Ste 613	Arlington, TX 76011	(817) 962-0048
8403 Cross Park Dr. Ste D-3	Austin, TX 78754	(512)-519-9312

Acct ID: WESTHENLY

Proj. No.: C7229169

Date Sampled: 04/01/2016

Report Date: 04/06/2016

Sampled By: TAYLOR, CHRIS

Project: West Henly Materials

By Order Of:

Location: Johnson City Plant

Order Number:

Client: West Henly Materials

Contractor:

REPORT: **Proctor**

LAB NO: 167


Material: 3/8 Screenings


Test Method: See Below

TEST RESULTS

Report No: 167

Page 1 of 4





Home Office - 1717 East Erwin Street

Tyler, Texas 75702-6398

Office: (903) 595-4421 Lab: (903) 595-6402 Fax: (903) 595-6111

Area Offices

210 Beech Street	Texarkana, AR 71854	(870) 772-0013
707 West Cotton St.	Longview, TX 75604	(903) 758-0402
2000E Randol Mill Rd. Ste 613	Arlington, TX 76011	(817) 962-0048
8403 Cross Park Dr. Ste D-3	Austin, TX 78754	(512)-519-9312

Acct ID: WESTHENLY

Proj. No.: C7229169

Date Sampled: 04/01/2016

Report Date: 04/06/2016

Sampled By: TAYLOR, CHRIS

Project: West Henly Materials

By Order Of:

Location: Johnson City Plant

Order Number:

Client: West Henly Materials

Contractor:

REPORT: Proctor

LAB NO: 167

Material: 3/8 Screenings

Test Method: See Below

TEST RESULTS

Report No: 167

Page 2 of 4

<u>% Moisture</u>	<u>Dry Density Lbs./Cu.Ft.</u>	<u>Sieve</u>	<u>% Passing</u>
8.1	120.0	Sieve No. 4:	80
10.8	126.3	Sieve No. 200	21
12.2	122.7		
14.5	117.7		
Optimum	Maximum		
10.7	126.3		


Color: Tan
Description: Silty, Clayey Sand with Gravel

Liquid Limit: 21
Plastic Limit: 16
Plasticity Index: 5
Group Symbol: SC-SM

Desc of Rammer: Mechanical

Preparation Method: Moist

Test Method (As Applicable): TEX 113-E, TEX 104-E, TEX 105-E, TEX 106-E, TEX 401-A, TEX 101-E



Home Office - 1717 East Erwin Street

Tyler, Texas 75702-6398

Office: (903) 595-4421 Lab: (903) 595-6402 Fax: (903) 595-6111

Area Offices

210 Beech Street	Texarkana, AR 71854	(870) 772-0013
707 West Cotton St.	Longview, TX 75604	(903) 758-0402
2000E Randol Mill Rd. Ste 613	Arlington, TX 76011	(817) 962-0048
8403 Cross Park Dr. Ste D-3	Austin, TX 78754	(512)-519-9312

Acct ID: WESTHENLY

Proj. No.: C7229169

Date Sampled: 04/01/2016

Report Date: 04/06/2016

Sampled By: TAYLOR, CHRIS

Project: West Henly Materials

By Order Of:

Location: Johnson City Plant

Order Number:

Client: West Henly Materials

Contractor:

REPORT: **Proctor**

LAB NO: 167


Material: 3/8 Screenings


Test Method: See Below

TEST RESULTS

Report No: 167

Page 3 of 4





Home Office - 1717 East Erwin Street

Tyler, Texas 75702-6398

Office: (903) 595-4421 Lab: (903) 595-6402 Fax: (903) 595-6111

Area Offices

210 Beech Street	Texarkana, AR 71854	(870) 772-0013
707 West Cotton St.	Longview, TX 75604	(903) 758-0402
2000E Randol Mill Rd. Ste 613	Arlington, TX 76011	(817) 962-0048
8403 Cross Park Dr. Ste D-3	Austin, TX 78754	(512)-519-9312

Acct ID: WESTHENLY

Proj. No.: C7229169

Date Sampled: 04/01/2016

Report Date: 04/06/2016

Sampled By: TAYLOR, CHRIS

Project: West Henly Materials

By Order Of:

Location: Johnson City Plant

Order Number:

Client: West Henly Materials

Contractor:

REPORT: Proctor

LAB NO: 167


Material: 3/8 Screenings

Test Method: See Below

TEST RESULTS

Report No: 167

Page 4 of 4



Respectfully Submitted,
ETTL Engineers & Consultants, Inc.

CHRIS TAYLOR, SET