#### College View Community Association Water Quality Report - 2018

This year, as in the years past, your tap water met all US Environmental Protection Agency and Illinois Environmental Protection Agency drinking water health standards. Our system safeguards its groundwater supply and we are pleased to report that the community had <u>No Violations</u> of any contaminant level or of any other water quality standard in the previous year. This report summarizes the quality of water that we provided last year, including details about where your water comes from, what it contains, and how it compares to standards set by regulatory agencies. College View Community Association provides you with this information because informed residents and neighbors are our best allies.

If you have any questions about this report or concerns about your water system please contact Carl Groth, President of College View Community Association at 1-815-838-9025. If you would like to learn more, you are welcome to attend any of our regularly scheduled meetings at the Miller Field House in College View Park on the third Tuesday of every month at 6:30 pm.

The College View subdivision is in Lockport Township, in the county of Will, state of Illinois, located one half mile from Rt. 53, north of Airport Road, and is supplied with water by community wells owned and operated by the College View Community Association, a not for profit organization. The water system consists of four shallow wells, three storage tanks, 9000 feet of water main, valves, and other related and necessary equipment needed for treatment, all located within our community. This system provides an adequate supply of water for the 190 homes in the community. In accordance with IEPA regulations, daily water samples are taken and measured for proper content of chlorine and fluoride. The association is responsible for maintenance of water mains and lines up to, but Not including the buffalo box, service line, and shut-off valve. It is the responsibility of the homeowner to provide a service line shut-off valve that is operational and above ground level, so that in case of an emergency it may be turned off for repairs.

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, persons with HIV/AIDS, or other immune system disorders, some elderly, and infants can be particularly at risk for infections. These people should seek advice about drinking water from their healthcare providers. US EPA/CDC guidelines on appropriate means to lessen the risk of infections by cryptosporidium, and other microbiological contaminants are available from the US EPA Safe Drinking Water Hotline @ 1-800-426-4791.

If present, elevated levels of lead can cause serious health issues, especially for pregnant woman and children. Lead in drinking water is primarily from materials in components in home plumbing. We cannot control the materials used in your home plumbing. There are no lead water mains or service lines in our community. When your water has been unused for several hours you can minimize the potential for lead exposure by flushing your tap for a couple of minutes before using it for drinking or cooking. If you are concerned about lead in your water you may wish to have it tested. For more information, you can call the US

EPA Safe Drinking Water Hotline @ 1-800-426-4791 or on-line internet @ http://www.epa.gov/safewater/lead.

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminates and its potential health effects can be obtained by calling the US EPA Safe Drinking Water Hotline @ 1-800-426-4791.

The sources of drinking water (both tap water and bottled water), include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it can dissolve naturally occurring minerals and radioactive materials, and can pick up substances resulting from the presence of animals or from human activities. Possible contaminants consist of:

- <u>Microbiological contaminants</u> such as viruses and bacteria, which may come from sewerage treatment plants, septic systems, agricultural livestock operations and wildlife.
- <u>Inorganic contaminants</u> such as salts and metals, which can be naturally occurring or can result from urban storm water runoff, industrial or domestic waste water discharges, oil or gas production, mining, or farming.
- <u>Pesticides/Herbicides-</u> which may come from a variety of sources such as agricultural, urban storm water runoff, and residential uses.
- Organic contaminants- including synthetic volatile organic chemicals which are by-products of industrial processes and petroleum production, they can also come from gas stations, urban storm water runoff and septic systems.
- <u>Radioactive contaminants</u> which may be naturally occurring or be the result of oil and gas production or mining activities.

In order to ensure that tap water is safe to drink, the US EPA prescribes regulations that limit the amount of certain contaminants in water provided by public water systems. FDA regulations establish limits in bottled water, which must provide the same protection for public health. In addition to the informational section of the water quality report, we have included for your review several tables. The tables will give you a better picture of contaminants that were tested but not detected.

Thank you,

Carl Groth

President, College View Community Association

## Regulated Contaminants

Disinfectants and	Collection	Highest Level			Y.COT			
Products	Date	Detected	Detected	37	MCF	Onits	Violation	Likely Source of Contamination
Chlorine	12/31/2018	0.4	0.3 - 0.5	MRDLG = 4	MRDL = 4	wāđ	z	Water additive used to control microbes.
Haloacetic Acids (HAA5)	2018	w	3.45 - 3.45	No goal for the total	60	qđđ	z	By-product of drinking water disinfection.
Total Trihalomethanes (TTHM)	2018	13	12.78 - 12.78	No goal for the total	80	qdd	Z	By-product of drinking water disinfection.
Inorganic Contaminants	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Arsenic	2018	1.6	0 1 1 6					
Barium	0 10	F- 0	0 - 1.6	0	10	व्वैत	N	Erosion of natural deposits; Runoff from orchards; Runoff from glass and electronics production wastes.
	8107	0.049	0.03 - 0.049	N	N	mdd	N	Discharge of drilling wastes; Discharge from metal refineries; Erosion of natural deposits.
100	2018	1.04	0.614 - 1.04	44	4.0	wđđ	И	Erosion of natural deposits; Water additive which promotes strong teeth; Discharge from fertilizer and aluminum factories
Western	2018	0.045	0 - 0.045		1.0	mďď	М	This contaminant is not currently regulated by the USEPA. However, the state regulates. Erosion of natural deposits.
	8107	19	0 - 19	150	150	qđđ	и	This contaminant is not currently regulated by the USEPA. However, the state regulates.  Erosion of natural deposits
Nitrogen]	2018	0.38	0.06 - 0.38	10	10	ppm	N	Runoff from fertilizer use; Leaching from septic tanks, sewage; Erosion of natural deposits.
perentum	2018	2.1	0 - 2.1	50	50	ਕ੍ਰੋਕੋ	N	Discharge from petroleum and metal refineries; Erosion of natural deposits; Discharge from
sodium	2018	64	15 - 64			wđđ	N	Brosion from naturally occuring deposits. Used in water softener regeneration.
zino	2018	0.17	0.037 - 0.17	Ŋ	.Un	wdd	z	This contaminant is not currently regulated by the USEPA. However, the state regulates. Naturally occurring discharge from metal
Contaminants	Collection	Highest Level F	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Combined Radium 226/228	2018	0.99	0.99 - 0.99	0	ហ	pci/L	N	Erosion of natural deposits.
Lead and Copper	Date Sampled	MCLG	Action Level (AL)	90th Percentile	# Sites Over AL	Units	Violation	n Likely Source of Contamination
Copper .	08/19/2016	1.3	Brosion of natural	0.17	0	wđđ	и	Erosion of natural deposits; Leaching from wood preservatives; Corrosion of household
	00/ +5/ 40+0	C	household	3.3	0	पर्वेंव	Z	Corrosion of household plumbing systems; Erosion of natural deposits.

## Inorganic Contaminants

						-							
The state of the s		Sodium	,	Manganese		Iron		Fluoride		Barium		Arsenic	TCCCONT.NAMEO
	2018		8102		2018			2018	6 1- 0	202		2018	Collection Date
	4. 0		36		0.65		and the state of t	1.09	0.051		1	7.8	Highest Level Detected
	46		36		0.65			1.09	0.051		č	7 8	Range of Levels Detected
			150				н	4	N		c		MCLG
			150		1.0		4.0		Ŋ		10		MCT
	mãa		<u>مِمْرَةً</u>		mád		mďď		ppm		ַלקּסָ		Units

# EM a

Treatment Technique or TT:

A required process intended to reduce the level of a contaminant in drinking water. milligrams per liter or parts per million - or one ounce in 7,350 gallons of water. micrograms per liter or parts per billion - or one ounce in 7,350,000 gallons of water.

: qdd

-			Detected	Detected	MCLG	MCL	Units
Т	Arsenic	2018	7.8	7.8	2	1	
				i	C	10	٩٩٥٥
	Barium	2018	0.051	0.051	2	ы	שממ
-	Fluoride	2018	1.09	1.09	A	4.0	uďď
	Iron	2018	0.65	0.65		1.0	mdd
	Manganese	2018	36	36	150	150	מֿמַפַ
	Sodium	2018	46	.4.6			mád
Wat	Water Quality T	Test Results	į.				
Def	Definitions:		The follow	The following tables contain scientific	cientific terms and	terms and measures, so	some of which may require explanation
Avg:	77		Regulatory	Regulatory compliance with some MCLs are based	e MCLs are based on	on running annual	al average of monthly samples.
Level			A Level 1 total coli	A Level 1 assessment is a study of the water system to identotal coliform bacteria have been found in our water system.	dy of the water sys	tem to identi	to identify potential problems and determine (if possible) why system.
Level	el 2 Assessment:		A Level 2 possible) system on	A Level 2 assessment is a ver possible) why an E. coli MCL v system on multiple occasions.	y detailed study of iolation has occurr	the water sy	A Level 2 assessment is a very detailed study of the water system to identify potential problems and determine (if possible) why an E. coli MCL violation has occurred and/or why total coliform bacteria have been found in our water system on multiple occasions.
Max	Maximum Contaminant	Level or MCL:	The highes using the	The highest level of a contaminant that is allowed in drinking water. using the best available treatment technology.	ment that is allowe	d in drinking	water. MCLs are set as close to the MCLGs as feasible
Max	Maximum Contaminant	: Level Goal or MCLG:		The level of a contaminant in drinking water below which there for a margin of safety.	drinking water belo	w which there	is no known or expected risk to health. MCLGs allow
Maxim MRDL:	imum residual di L:	Maximum residual disinfectant level or MRDL:	The	highest level of a disinfe infectant is necessary for	level of a disinfectant allowed in drinking water. T	inking water. l contaminants	There is convincing evidence that addition of a
Maxin	or	residual disinfectant level MRDLG:		a drinking benefits of	disinfectant below of disinfectants		water disinfectant below which there is no known or expected risk to health, MRDLGs do not the use of disinfectants to control microbial contaminants
na:			not applicable.				
mrem:	m:		millirems p	millirems per year (a measure of radiation absorbed by the body)	of radiation absorb	ed by the body	
מל ה	•						

## Source Water Assessment

protection efforts, you may access the IEPA web site at http://www.epa.state.il.us/cgi-bin/wp/swap-fact-sheets.pl. at the Miller Field House in College View Park or call Carl Groth, President at 1-815-838-9025. The source water assessment for our supply has been completed by the IEPA. To view a summary version of the completed source water assessment including the importance of source water, susceptibility to contamination, determination and documentation/recommendation of source water College View Community Association wants to keep you informed about your water quality. If you would like more information, please attend our regularly scheduled monthly meetings

### Source of Water

determination is based on a number of criteria including: monitoring conducted at the wells, monitoring conducted at the entry point to the distribution system, and the available hydrogeological ongoing remediation that may be of concern. The IEPA has determined that the source water obtained from College View Subdivision wells #1, #2, & #3, is susceptible to contamination. This data on the wells. Subdivision wells. Furthermore, information provided by the Leaking Underground Storage Tank and Remedial Project Management sections of the IEPA indicated several additional sites with Based on information obtained in a well site survey published in 1992 by the IEPA, nine potential sources of possible problem sites were identified within the survey area of College View