

**FOOD ESTABLISHMENT INSPECTION REPORT**

Violations cited in this report shall be corrected within the time frames specified below, but within a period not to exceed 72 hours of Priority items and 10 calendar days for Priority Foundation items or HACCP Plan deviations. (§ 64 C.S.R. 17-3.1.j.)

OBSERVATION TOTALS: PRIORITY: 0 CORE: 3 PRIORITY FOUNDATION: 0 TOTAL: 3

ESTABLISHMENT: Johnny's Boy LLC PERMIT NO.: \_\_\_\_\_ DATE: 8/29/2019  
 ADDRESS: 127 E. King Street CITY: Martinsburg STATE: WV ZIP: 25401  
 PERSON IN CHARGE/TITLE: JAY JOHNSON TELEPHONE: \_\_\_\_\_  
 RECEIVED BY (SIGNATURE): [Signature] SANITARIAN (SIGNATURE): [Signature]  
 INSPECTION TYPE: ROUTINE  FOLLOW-UP  COMPLAINT  OTHER: Opening TIME: 10:00 am

Corrected	Priority	Repeat	Code Reference	Violation Description/Remarks/Corrections
			6-501.11	Handsink (at bar) drain leaking and needs repaired.
			6-501.11	Flooring around bar needs replaced/repaired
			6-501.11	Holes in Men's bathroom wall need sealed/repaired
- Permit Given to Operate at this time -				
				Grease Trap Letter ✓
				Fire Safety ✓
				Pest Control ✓

Unit/Location/Item	Temp/PPM	Unit/Location/Item	Temp/PPM	Unit/Location/Item	Temp/PPM	Unit/Location/Item	Temp/PPM